

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
33	Chilliwack	3333033	A D RUNDLE MIDDLE SCHOOL	1	Gymnasium	1,020	Low/Moderate	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333033	A D RUNDLE MIDDLE SCHOOL	2	Classrooms	2,365	Moderate/High	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333033	A D RUNDLE MIDDLE SCHOOL	3	Shops	420	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
33	Chilliwack	3333033	A D RUNDLE MIDDLE SCHOOL	4	Classrooms	440	Moderate/High	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333033	A D RUNDLE MIDDLE SCHOOL	5	1999 Addition	?	Low	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333019	BERNARD ELEMENTARY	1	Post 1990 Addition	?	Low	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333019	BERNARD ELEMENTARY	2	Classroom Block	1,786	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
33	Chilliwack	3333019	BERNARD ELEMENTARY	3	Gymnasium	?	Moderate/High	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333021	CHANCE ALTERNATE	1	Classrooms and Administration	338	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
33	Chilliwack	3333013	CHEAM ELEMENTARY	1	Classrooms/Admin.	462	Moderate/High	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333013	CHEAM ELEMENTARY	2	Classrooms/Library	403	Moderate	Medium	Non Structural Upgrade Required	Medium	
33	Chilliwack	3333013	CHEAM ELEMENTARY	3	Gymnasium	315	Moderate/High	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333008	CHILLIWACK CENTRAL COMMUNITY ELEMENTARY	1	Gymnasium	810	Low/Moderate	N/A	Completed		
33	Chilliwack	3333008	CHILLIWACK CENTRAL COMMUNITY ELEMENTARY	2	Classrooms	3,000	High	N/A	Completed	N/A	
33	Chilliwack	3333004	CHILLIWACK MIDDLE SCHOOL	1	Gymnasium	1,164	Low/Moderate	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333004	CHILLIWACK MIDDLE SCHOOL	2	Shop	301	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
33	Chilliwack	3333004	CHILLIWACK MIDDLE SCHOOL	3	Classrooms-Renovated 1995	?	Low	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333004	CHILLIWACK MIDDLE SCHOOL	4	Classrooms-New 1995	?	Low	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333012	CHILLIWACK SECONDARY	1	2-Storey Classroom	3,450	High	N/A	Under Construction		
33	Chilliwack	3333012	CHILLIWACK SECONDARY	2	Vocational and Shops Buildings	5,040	Moderate/High	N/A	Under Construction		
33	Chilliwack	3333012	CHILLIWACK SECONDARY	3	Library and Music Buildings	765	Moderate	N/A	Under Construction		
33	Chilliwack	3333012	CHILLIWACK SECONDARY	4	Gymnasium/Washrooms	1,345	Low/Moderate	N/A	Under Construction	N/A	
33	Chilliwack	3333012	CHILLIWACK SECONDARY	5	2003 Maintenance Building	?	Low	N/A	Under Construction		
33	Chilliwack	3333012	CHILLIWACK SECONDARY	6	2004 Lobby Exercise addition	?	Low	N/A	Under Construction		
33	Chilliwack	3333009	CULTUS LAKE COMMUNITY SCHOOL	1	Gymnasium	428	Low	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333009	CULTUS LAKE COMMUNITY SCHOOL	2	Classrooms (West)	860	Moderate	Medium	Non Structural Upgrade Required	Medium	
33	Chilliwack	3333009	CULTUS LAKE COMMUNITY SCHOOL	3	Classrooms (North)	450	Moderate/High	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333009	CULTUS LAKE COMMUNITY SCHOOL	4	Classrooms (East)	420	Moderate/High	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333010	EAST CHILLIWACK ELEMENTARY	1	Gymnasium (Post 1993)	?	Low	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333010	EAST CHILLIWACK ELEMENTARY	2	Classrooms/Admin.	905	Moderate	Medium	Non Structural Upgrade Required	Medium	
33	Chilliwack	3333010	EAST CHILLIWACK ELEMENTARY	3	Classrooms (1993)	?	Low	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333030	F G LEARY ELEMENTARY	1	Classrooms	756	Moderate	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333030	F G LEARY ELEMENTARY	2	Classrooms (1974)	573	Low	Low	Meets Structural Life Safety Requirements	Medium	
33	Chilliwack	3333030	F G LEARY ELEMENTARY	3	Gymnasium/Classrooms (2001)	?	Low	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333064	KIPP CENTRE	1	Classrooms/Admin.	532	Moderate/High	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333064	KIPP CENTRE	2	Classrooms (East)	229	Moderate	Medium	Non Structural Upgrade Required	Medium	
33	Chilliwack	3333016	LITTLE MOUNTAIN ELEMENTARY	1	Gymnasium	425	Moderate	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333016	LITTLE MOUNTAIN ELEMENTARY	2	Classrooms (Central)	924	Moderate/High	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333016	LITTLE MOUNTAIN ELEMENTARY	3	Classrooms (East)	1,125	Moderate	Medium	Non Structural Upgrade Required	Medium	
33	Chilliwack	3333016	LITTLE MOUNTAIN ELEMENTARY	4	Classrooms (West)	615	Moderate	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333016	LITTLE MOUNTAIN ELEMENTARY	5	Classrooms (North) 1999	?	Low	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333028	MCCAMMON ELEMENTARY	1	Gymnasium	591	Moderate	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333028	MCCAMMON ELEMENTARY	2	1957 Classroom	1,890	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
33	Chilliwack	3333028	MCCAMMON ELEMENTARY	3	1990 Classrooms	1,605	Low/Moderate	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333028	MCCAMMON ELEMENTARY	4	1999 Classroom	?	Low	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333031	REGIONAL CORRESPONDENCE CENTRE	1	1962 Office Building	550	Moderate	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333031	REGIONAL CORRESPONDENCE CENTRE	2	2003 Office Building	?	Low	Low	Meets Structural Life Safety Requirements	Medium	
33	Chilliwack	3333031	REGIONAL CORRESPONDENCE CENTRE	3	Portable Buildings	?	Low	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333024	ROBERTSON ELEMENTARY	1	Gymnasium	460	Low/Moderate	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333024	ROBERTSON ELEMENTARY	2	1961/1970 Classrooms	1,450	Moderate	Medium	Non Structural Upgrade Required	Medium	
33	Chilliwack	3333024	ROBERTSON ELEMENTARY	3	2001 Classrooms	?	Low	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333006	ROBERTSON on Elm	1	Classroom/Administration	530	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
33	Chilliwack	3333001	ROSEDALE ELEMENTARY	1	Gymnasium	290	Moderate	N/A	Completed		
33	Chilliwack	3333001	ROSEDALE ELEMENTARY	2	1 Storey Classroom/Admin.	525	Moderate	N/A	Completed	N/A	
33	Chilliwack	3333001	ROSEDALE ELEMENTARY	3	3 Storey Classroom	810	High	N/A	Completed		
33	Chilliwack	3333023	ROSEDALE MIDDLE SCHOOL	1	Gymnasium	1,060	Low	N/A	Completed		
33	Chilliwack	3333023	ROSEDALE MIDDLE SCHOOL	2	2 Storey Classroom/Admin.	1,860	High	N/A	Completed		
33	Chilliwack	3333023	ROSEDALE MIDDLE SCHOOL	3	1 Storey Classroom	1,210	Moderate/High	N/A	Completed	N/A	
33	Chilliwack	3333023	ROSEDALE MIDDLE SCHOOL	4	Music Room	250	Low/Moderate	N/A	Completed		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
33	Chilliwack	3333005	SARDIS ELEMENTARY	1	1950 Gymnasium	520	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
33	Chilliwack	3333005	SARDIS ELEMENTARY	2	1955/1974 Classrooms	1,085	Moderate	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333005	SARDIS ELEMENTARY	3	1992 Classrooms	1,320	Low/Moderate	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333003	STRATHCONA ELEMENTARY	1	Gymnasium	345	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
33	Chilliwack	3333003	STRATHCONA ELEMENTARY	2	1970/71/74 Classrooms	1,740	Moderate	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333003	STRATHCONA ELEMENTARY	3	1961 Classrooms	250	Moderate/High	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333003	STRATHCONA ELEMENTARY	4	1996 Classrooms	?	Low	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333035	TYSON ELEMENTARY	1	Gymnasium	375	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
33	Chilliwack	3333035	TYSON ELEMENTARY	2	Classrooms (Centre)	1,140	Low	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333035	TYSON ELEMENTARY	3	Classrooms (East Wing)	730	Low	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333034	VEDDER MIDDLE SCHOOL	1	Classrooms & Administration	3,433	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
33	Chilliwack	3333034	VEDDER MIDDLE SCHOOL	2	Gym and Classrooms - 1993	?	Low	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333034	VEDDER MIDDLE SCHOOL	3	Gym - upgraded in 2004	?	Low	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333017	WATSON ELEMENTARY	1	Gymnasium	418	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
33	Chilliwack	3333017	WATSON ELEMENTARY	2	Classrooms (Centre)	1,395	Moderate	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333017	WATSON ELEMENTARY	3	Multi-Purpose	195	Moderate	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333017	WATSON ELEMENTARY	4	Classrooms (south & east)	895	Moderate	Medium	Non Structural Upgrade Required		
33	Chilliwack	3333017	WATSON ELEMENTARY	5	Classroom (North) 1999	?	Low	Low	Meets Structural Life Safety Requirements		
33	Chilliwack	3333015	YARROW COMMUNITY SCHOOL	1	Gymnasium	690	Low/Moderate	N/A	Completed	N/A	
33	Chilliwack	3333015	YARROW COMMUNITY SCHOOL	2	Classroom	2,390	High	N/A	Completed		
34	Abbotsford	3434025	ABBOTSFORD MIDDLE SCHOOL	1	West Classroom Building (1954/1959)	3,100	High	Medium	Non Structural Upgrade Required	Medium	
34	Abbotsford	3434025	ABBOTSFORD MIDDLE SCHOOL	2	Administration & Misc	1,900	Moderate/High	Medium	Non Structural Upgrade Required		
34	Abbotsford	3434025	ABBOTSFORD MIDDLE SCHOOL	3	Gym / Lunchroom & Misc	1,900	High	Medium	Non Structural Upgrade Required		
34	Abbotsford	3434025	ABBOTSFORD MIDDLE SCHOOL	4	Classroom Annex (1966)	1,250	Moderate/High	Medium	Non Structural Upgrade Required		
34	Abbotsford	3434022	ABBOTSFORD SENIOR SECONDARY	1	Gymnasium/Music	1,200	Moderate/High	N/A	Under Construction	N/A	
34	Abbotsford	3434022	ABBOTSFORD SENIOR SECONDARY	2	Entry Canopy and Cafeteria	1,020	Moderate/High	N/A	Under Construction		
34	Abbotsford	3434022	ABBOTSFORD SENIOR SECONDARY	3	North Classroom Wing	1,080	Low/Moderate	N/A	Under Construction		
34	Abbotsford	3434022	ABBOTSFORD SENIOR SECONDARY	4	West Classroom Wing	2,500	Moderate/High	N/A	Under Construction		
34	Abbotsford	3434022	ABBOTSFORD SENIOR SECONDARY	7	Administration Area	693	Low/Moderate	N/A	Under Construction		
34	Abbotsford	3434022	ABBOTSFORD SENIOR SECONDARY	8	Library (2001)	?	Low	N/A	Under Construction		
34	Abbotsford	3434022	ABBOTSFORD SENIOR SECONDARY	9	New Gymnasium/Classroom Wing (2001)	?	Low	N/A	Under Construction		
34	Abbotsford	3434022	ABBOTSFORD SENIOR SECONDARY	5	South 2 Storey Classroom Block	1,500	High	N/A	Under Construction		
34	Abbotsford	3434022	ABBOTSFORD SENIOR SECONDARY	6	Industrial Education Wing	2,000	Moderate/High	N/A	Under Construction		
34	Abbotsford	3434029	ABBOTSFORD TRADITIONAL SECONDARY (was Career Tec	1	Center classroom wing (1959)	1,938	High	High 1	Supported 2013	High 1	April 2013 - to start 2015.
34	Abbotsford	3434029	ABBOTSFORD TRADITIONAL SECONDARY (was Career Tec	2	West workshop wing (1959, 1966)	439	Moderate/High	Medium	Supported 2013		
34	Abbotsford	3434029	ABBOTSFORD TRADITIONAL SECONDARY (was Career Tec	3	Administration wing (1959)	955	Moderate/High	Medium	Supported 2013		
34	Abbotsford	3434029	ABBOTSFORD TRADITIONAL SECONDARY (was Career Tec	4	Gymnasium (1959,1974)	810	Moderate/High	Medium	Supported 2013		
34	Abbotsford	3434029	ABBOTSFORD TRADITIONAL SECONDARY (was Career Tec	5	Cafeteria (1968)	373	High	Medium	Supported 2013		
34	Abbotsford	3434029	ABBOTSFORD TRADITIONAL SECONDARY (was Career Tec	6	North wing (1968)	1,610	High	Medium	Supported 2013		
34	Abbotsford	3434029	ABBOTSFORD TRADITIONAL SECONDARY (was Career Tec	7	DND addition (1997)	?	Low	Low	Supported 2013		
34	Abbotsford	3434026	ABERDEEN ELEMENTARY	1	center east block (1955-1977)	558	Moderate/High	NA	Under Construction	NA	Supported 2012
34	Abbotsford	3434026	ABERDEEN ELEMENTARY	2	west wing (1955-1977)	715	High	NA	Under Construction		
34	Abbotsford	3434026	ABERDEEN ELEMENTARY	3	north wing (1981)	358	Low/Moderate	NA	Under Construction		
34	Abbotsford	3434026	ABERDEEN ELEMENTARY	4	gymnasium (1981)	387	Moderate	NA	Under Construction		
34	Abbotsford	3434026	ABERDEEN ELEMENTARY	5	multi purpose room (1992)	?	Low	NA	Under Construction		
34	Abbotsford	3434026	ABERDEEN ELEMENTARY	6	south wing (1992)	?	Low	NA	Under Construction		
34	Abbotsford	3434021	ALEXANDER ELEMENTARY	1	North Classroom Wing	792	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
34	Abbotsford	3434021	ALEXANDER ELEMENTARY	2	Gym	550	Moderate/High	Medium	Non Structural Upgrade Required		
34	Abbotsford	3434021	ALEXANDER ELEMENTARY	3	South Classroom Wing	818	Moderate/High	Medium	Non Structural Upgrade Required		
34	Abbotsford	3434021	ALEXANDER ELEMENTARY	4	Entrance and administration (1993)	?	Low	Low	Meets Structural Life Safety Requirements		
34	Abbotsford	3434021	ALEXANDER ELEMENTARY	5	East Classroom Wing (1993)	?	Low	Low	Meets Structural Life Safety Requirements		
34	Abbotsford	3434039	BAKERVIEW ELEMENTARY	1	Gymnasium (1972/1974)	395	Moderate/High	Medium	Inactive	Medium	
34	Abbotsford	3434039	BAKERVIEW ELEMENTARY	2	Single Storey Classrooms (1972)	800	Moderate/High	Medium	Inactive		
34	Abbotsford	3434039	BAKERVIEW ELEMENTARY	3	Two Storey Classrooms (1974)	1,325	High	Medium	Inactive		
34	Abbotsford	3434023	BARROWTOWN ELEMENTARY	1	Gym (1952)	235	Moderate	Medium	Non Structural Upgrade Required	Medium	
34	Abbotsford	3434023	BARROWTOWN ELEMENTARY	2	Main Building (1952)	649	Moderate	Medium	Non Structural Upgrade Required		
34	Abbotsford	3434049	BLUE JAY ELEMENTARY	1	Main Original Bldg (1989)	3,030	Moderate	Medium	Non Structural Upgrade Required	Medium	
34	Abbotsford	3434049	BLUE JAY ELEMENTARY	2	West Addition (2001)	?	Low	Low	Meets Structural Life Safety Requirements		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments	
34	Abbotsford	3434011	BRADNER ELEMENTARY	1	East Classrooms (1974)	193	Moderate	Medium	Non Structural Upgrade Required	Medium		
34	Abbotsford	3434011	BRADNER ELEMENTARY	2	Mid Classrooms (1968)	438	Moderate	Medium	Non Structural Upgrade Required			
34	Abbotsford	3434011	BRADNER ELEMENTARY	3	Staff Room and Offices (1972)	63	Low	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434011	BRADNER ELEMENTARY	4	South Classrooms (1961)	417	Moderate/High	Medium	Non Structural Upgrade Required			
34	Abbotsford	3434011	BRADNER ELEMENTARY	5	Two Story Storage and Classrooms (1925)	379	Moderate/High	Medium	Non Structural Upgrade Required			
34	Abbotsford	3434011	BRADNER ELEMENTARY	6	Gymnasium (1999)	?	Low	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434037	CENTENNIAL PARK ELEMENTARY	1	Original Classroom East (1968)	765	High	Medium	Non Structural Upgrade Required	Medium		
34	Abbotsford	3434037	CENTENNIAL PARK ELEMENTARY	2	Gymnasium and Misc. Rooms (1974)	765	High	Medium	Non Structural Upgrade Required			
34	Abbotsford	3434037	CENTENNIAL PARK ELEMENTARY	3	Two Storey Classrooms West (1974)	1,200	Moderate	Medium	Non Structural Upgrade Required			
34	Abbotsford	3434037	CENTENNIAL PARK ELEMENTARY	4	Changerooms & Storage N-W (1976)	170	Low/Moderate	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434037	CENTENNIAL PARK ELEMENTARY	5	1990 Additions at North S-W (1990)	830	Moderate	Medium	Non Structural Upgrade Required			
34	Abbotsford	3434047	CHIEF DAN GEORGE MIDDLE	1	East Block Single Storey Classrooms	3,112	Low/Moderate	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434047	CHIEF DAN GEORGE MIDDLE	2	Multi-Purpose Room	399	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low		
34	Abbotsford	3434047	CHIEF DAN GEORGE MIDDLE	3	West Block Single Story Classroom	?	Low	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434047	CHIEF DAN GEORGE MIDDLE	4	Art and Shop Rooms	?	Low	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434047	CHIEF DAN GEORGE MIDDLE	5	Gymnasium	?	Low	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434018	CLEARBROOK ELEMENTARY	1	East Multi-Purpose Room Addition (1989)	215	Moderate	Medium	Non Structural Upgrade Required			
34	Abbotsford	3434018	CLEARBROOK ELEMENTARY	2	West Classrooms Addition (1990)	980	Moderate	Medium	Non Structural Upgrade Required			
34	Abbotsford	3434018	CLEARBROOK ELEMENTARY	3	Staff and Special Ed Rooms (1976)	533	Moderate	Low	Meets Structural Life Safety Requirements	Low	November 2012 - Risk review of Block 3 has reduced risk from High 2 to Low.	
34	Abbotsford	3434018	CLEARBROOK ELEMENTARY	4	East Classrooms Addition (1981)	508	Moderate	Medium	Non Structural Upgrade Required			
34	Abbotsford	3434018	CLEARBROOK ELEMENTARY	5	Gymnasium (1981)	385	Low/Moderate	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434018	CLEARBROOK ELEMENTARY	6	North West Classrooms Addition (1981)	264	Low/Moderate	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434018	CLEARBROOK ELEMENTARY	7	Original Classrooms and Library (1951)	963	Moderate/High	Medium	Non Structural Upgrade Required			
34	Abbotsford	3434043	DORMICK PARK ELEMENTARY	1	N/E Classroom/Library Wing	1,100	Low/Moderate	Low	Meets Structural Life Safety Requirements		Low	
34	Abbotsford	3434043	DORMICK PARK ELEMENTARY	2	Gymnasium (Upgraded 1998)	?	Low	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434043	DORMICK PARK ELEMENTARY	3	West Classroom Wing (1998)	?	Low	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434045	DR THOMAS A SWIFT ELEMENTARY	1	Gymnasium (1979)	440	Low/Moderate	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434045	DR THOMAS A SWIFT ELEMENTARY	2	Classrooms / Admin (1979 & 1982)	795	Low	Low	Meets Structural Life Safety Requirements	Low		
34	Abbotsford	3434045	DR THOMAS A SWIFT ELEMENTARY	3	Classrooms (1993)	?	Low	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434012	DUNACH ELEMENTARY	1	Original West Wing (1925)	1,000	High	Medium	Non Structural Upgrade Required		Medium	
34	Abbotsford	3434012	DUNACH ELEMENTARY	2	Gym and Offices (1975)	520	Low	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434012	DUNACH ELEMENTARY	3	Classrooms East End (1982)	320	Low	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434028	GODSON ELEMENTARY SCHOOL	1	Small Gym	242	High	Medium	Non Structural Upgrade Required			
34	Abbotsford	3434028	GODSON ELEMENTARY SCHOOL	2	Original School	1,100	Moderate	Medium	Non Structural Upgrade Required	Medium		
34	Abbotsford	3434028	GODSON ELEMENTARY SCHOOL	3	East Classroom Addition	900	Moderate	Medium	Non Structural Upgrade Required			
34	Abbotsford	3434028	GODSON ELEMENTARY SCHOOL	4	West Classroom Addition	810	Low/Moderate	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434028	GODSON ELEMENTARY SCHOOL	5	Gym & Library Wing	810	Low/Moderate	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434031	JACKSON ELEMENTARY	1	South Wing	3,100	Low	N/A	Completed		N/A	
34	Abbotsford	3434031	JACKSON ELEMENTARY	2	East Side	200	Low	N/A	Completed			
34	Abbotsford	3434031	JACKSON ELEMENTARY	3	North Wing	550	Low	N/A	Completed			
34	Abbotsford	3434031	JACKSON ELEMENTARY	4	Gymnasium	400	High	N/A	Completed			
34	Abbotsford	3434044	JOHN MACLURE COMMUNITY SCHOOL	1	Gymnasium	390	Low/Moderate	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434044	JOHN MACLURE COMMUNITY SCHOOL	2	Administration	500	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium		
34	Abbotsford	3434044	JOHN MACLURE COMMUNITY SCHOOL	3	Two Storey Classroom Wing	1,975	Moderate	Medium	Non Structural Upgrade Required			
34	Abbotsford	3434019	KING TRADITIONAL ELEMENTARY	2	Gymnasium (2000)	?	Low	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434019	KING TRADITIONAL ELEMENTARY	3	East Classrooms (2000)	?	Low	Low	Meets Structural Life Safety Requirements		High 3	
34	Abbotsford	3434019	KING TRADITIONAL ELEMENTARY	1	Central Classrooms (1951)	975	Moderate/High	High 3	Structural Upgrade Required			
34	Abbotsford	3434033	MARGARET STENERSSEN ELEMENTARY	1	Classrooms / Admin (64, 67, 69, 71, 72)	1,450	Moderate/High	Medium	Non Structural Upgrade Required			
34	Abbotsford	3434033	MARGARET STENERSSEN ELEMENTARY	2	Gymnasium (1967, 1975)	390	Moderate/High	Medium	Non Structural Upgrade Required	Medium		
34	Abbotsford	3434033	MARGARET STENERSSEN ELEMENTARY	3	Library (1975)	240	Low	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434033	MARGARET STENERSSEN ELEMENTARY	4	Storage / Change (1975)	160	Low	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434033	MARGARET STENERSSEN ELEMENTARY	5	Classrooms South (1981)	470	Low	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434033	MARGARET STENERSSEN ELEMENTARY	6	Classrooms East (1997)	?	Low	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434027	MCMILLAN ELEMENTARY	1	Original Classrooms	525	Moderate/High	Medium	Non Structural Upgrade Required		Medium	
34	Abbotsford	3434027	MCMILLAN ELEMENTARY	2	North Classroom Addition	990	Low/Moderate	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434027	MCMILLAN ELEMENTARY	3	Gymnasium	372	Moderate	Medium	Non Structural Upgrade Required			
34	Abbotsford	3434027	MCMILLAN ELEMENTARY	4	South Classroom Addition (1993)	?	Low	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434003	MT LEHMAN ELEMENTARY	1	Original Two Storey (1910)	580	Moderate/High	Medium	Non Structural Upgrade Required	Medium		
34	Abbotsford	3434003	MT LEHMAN ELEMENTARY	2	Centre Classrooms (1968)	400	Low/Moderate	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434003	MT LEHMAN ELEMENTARY	3	Gymnasium (1975)	335	Low	Low	Meets Structural Life Safety Requirements			
34	Abbotsford	3434003	MT LEHMAN ELEMENTARY	4	West Wing (1994)	?	Low	Low	Meets Structural Life Safety Requirements			

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
34	Abbotsford	3434005	NORTH POPLAR FINE ARTS SCHOOL	1	East Wing (1968)	1,900	Low	Low	Meets Structural Life Safety Requirements	Low	
34	Abbotsford	3434005	NORTH POPLAR FINE ARTS SCHOOL	2	West Wing & Gym (1990)	1,200	Low	Low	Meets Structural Life Safety Requirements		
34	Abbotsford	3434014	PHILIP SHEFFIELD ELEMENTARY	1	classroom wing	986	High	Medium	Inactive	High 3	
34	Abbotsford	3434014	PHILIP SHEFFIELD ELEMENTARY	2	gymnasium (seismic upgrade 2001)	?	Low	Low	Inactive		
34	Abbotsford	3434014	PHILIP SHEFFIELD ELEMENTARY	3	Library wing	160	Moderate	High 3	Inactive		
34	Abbotsford	3434048	PRINCE CHARLES ELEMENTARY	1	Gym (1983)	420	Low	Low	Meets Structural Life Safety Requirements	Low	
34	Abbotsford	3434048	PRINCE CHARLES ELEMENTARY	2	Main building (1983)	2,132	Low	Low	Meets Structural Life Safety Requirements		
34	Abbotsford	3434048	PRINCE CHARLES ELEMENTARY	3	N/W corner and S/W corner (1992)	?	Low	Low	Meets Structural Life Safety Requirements		
34	Abbotsford	3434501	RESOURCE CENTRE	1	West wing (1959, 1966)	397	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
34	Abbotsford	3434501	RESOURCE CENTRE	2	East addition (1983)	151	Low	Low	Meets Structural Life Safety Requirements		
34	Abbotsford	3434032	ROSS ELEMENTARY	1	Center Classrooms (1969/1972)	800	Moderate	Medium	Non Structural Upgrade Required	Medium	
34	Abbotsford	3434032	ROSS ELEMENTARY	2	Gymnasium & Staff Room (1974)	400	Moderate	Medium	Non Structural Upgrade Required		
34	Abbotsford	3434032	ROSS ELEMENTARY	3	Multi-Purpose & Offices (1994)	?	Low	Low	Meets Structural Life Safety Requirements		
34	Abbotsford	3434032	ROSS ELEMENTARY	4	West Area Classrooms (1994)	?	Low	Low	Meets Structural Life Safety Requirements		
34	Abbotsford	3434050	SANDY HILL ELEMENTARY	1	Gymnasium (1990)	466	Moderate	Medium	Non Structural Upgrade Required	Medium	
34	Abbotsford	3434050	SANDY HILL ELEMENTARY	2	Kindergarten and change rooms (1990)	475	Moderate	Medium	Non Structural Upgrade Required		
34	Abbotsford	3434050	SANDY HILL ELEMENTARY	3	Classrooms and library (1990)	1,843	Moderate	Medium	Non Structural Upgrade Required		
34	Abbotsford	3434050	SANDY HILL ELEMENTARY	4	Classrooms addition (1990)	765	Moderate	Medium	Non Structural Upgrade Required		
34	Abbotsford	3434020	SIMPSON TRADITIONAL MIDDLE	1	S/E Library-Corridor (1951)	210	High	Medium	Partially Complete	Medium	
34	Abbotsford	3434020	SIMPSON TRADITIONAL MIDDLE	2	Main Core Area (1951/1969)	1,100	Moderate	Medium	Partially Complete		
34	Abbotsford	3434020	SIMPSON TRADITIONAL MIDDLE	3	N/E Classroom (1969)	130	High	Medium	Partially Complete		
34	Abbotsford	3434020	SIMPSON TRADITIONAL MIDDLE	4	N/W Drama Room (1981)	100	Low	Low	Partially Complete		
34	Abbotsford	3434020	SIMPSON TRADITIONAL MIDDLE	5	S/W Gym and Misc. (1981)	790	Low/Moderate	Low	Partially Complete		
34	Abbotsford	3434016	SOUTH POPLAR ELEMENTARY	1	Original Main Bldg (1933)	790	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
34	Abbotsford	3434016	SOUTH POPLAR ELEMENTARY	2	West Wing (1971)	360	Moderate	Medium	Non Structural Upgrade Required		
34	Abbotsford	3434016	SOUTH POPLAR ELEMENTARY	3	Gym (1994)	?	Low	Low	Meets Structural Life Safety Requirements		
34	Abbotsford	3434036	TEN BROECK ELEMENTARY	1	Original Building - Classrooms (1966)	300	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
34	Abbotsford	3434036	TEN BROECK ELEMENTARY	2	Enclosed Covered Play Area (1966, 1975)	100	Moderate	Medium	Non Structural Upgrade Required		
34	Abbotsford	3434036	TEN BROECK ELEMENTARY	3	Classrooms West (1971)	200	Moderate/High	Medium	Non Structural Upgrade Required		
34	Abbotsford	3434036	TEN BROECK ELEMENTARY	4	Classrooms / Admin (1969, 1977)	1,700	Moderate/High	Medium	Non Structural Upgrade Required		
34	Abbotsford	3434036	TEN BROECK ELEMENTARY	5	Gymnasium (1969, 1977)	475	Moderate/High	Medium	Non Structural Upgrade Required		
34	Abbotsford	3434036	TEN BROECK ELEMENTARY	6	Classrooms North (1993)	?	Low	Low	Meets Structural Life Safety Requirements		
34	Abbotsford	3434036	TEN BROECK ELEMENTARY	7	Entry Renovation (1993)	?	Low	Low	Meets Structural Life Safety Requirements		
34	Abbotsford	3434046	TERRY FOX ELEMENTARY	1	Original classroom wing (1981)	2,010	Moderate	Medium	Non Structural Upgrade Required	Medium	
34	Abbotsford	3434046	TERRY FOX ELEMENTARY	2	Gymnasium (1981)	382	Moderate/High	Medium	Non Structural Upgrade Required		
34	Abbotsford	3434046	TERRY FOX ELEMENTARY	3	West classroom addition (1991)	?	Low	Low	Meets Structural Life Safety Requirements		
34	Abbotsford	3434007	UPPER SUMAS ELEMENTARY	1	Classrooms	2,250	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
34	Abbotsford	3434007	UPPER SUMAS ELEMENTARY	2	Connector and washrooms	53	Low	Low	Meets Structural Life Safety Requirements		
34	Abbotsford	3434007	UPPER SUMAS ELEMENTARY	3	Gym	434	High	Medium	Non Structural Upgrade Required		
34	Abbotsford	3434041	W J MOUAT SECONDARY	1	North - West Wing (2001)	?	Low	N/A	Completed	N/A	
34	Abbotsford	3434041	W J MOUAT SECONDARY	2	South - East Wing (1987)	2,700	Moderate	N/A	Completed		
34	Abbotsford	3434041	W J MOUAT SECONDARY	3	Music Room (1981)	220	Low/Moderate	N/A	Completed		
34	Abbotsford	3434041	W J MOUAT SECONDARY	4	Original Single Storey (1974)	4,100	High	N/A	Completed		
34	Abbotsford	3434041	W J MOUAT SECONDARY	5	Original Two Storey (1974)	3,625	High	N/A	Completed		
34	Abbotsford	3434042	WILLIAM A. FRASER ELEMENTARY	1	1980 Addition NW	1,000	Low/Moderate	N/A	Completed	N/A	
34	Abbotsford	3434042	WILLIAM A. FRASER ELEMENTARY	2	1974 Addition SW	2,000	High	N/A	Completed		
34	Abbotsford	3434042	WILLIAM A. FRASER ELEMENTARY	3	Gymnasium	350	Low	N/A	Completed		
34	Abbotsford	3434042	WILLIAM A. FRASER ELEMENTARY	4	1992 Addition NE	450	Low	N/A	Completed		
34	Abbotsford	3434042	WILLIAM A. FRASER ELEMENTARY	5	(1992) Multipurpose Room	200	Low	N/A	Completed		
34	Abbotsford	3434038	YALE SECONDARY	1	Admin / Arts (1971?, ?, 1985, 2000)	1,820	High	High 3	Supported 2013	High 1	December 2012 - SPIR shows Block 2 risk increased from H2 to H1. April 13 - to start 2014.
34	Abbotsford	3434038	YALE SECONDARY	2	Orig Two Storey Classrooms (1971?)	1,080	High	High 1	Supported 2013		
34	Abbotsford	3434038	YALE SECONDARY	3	Original Shop (1971?)	640	Moderate	Medium	Supported 2013		
34	Abbotsford	3434038	YALE SECONDARY	4	Large Gym (unknown, 2000)	1,000	Low	Low	Supported 2013		
34	Abbotsford	3434038	YALE SECONDARY	5	Two Storey Classroom Addn (1985)	1,600	Low/Moderate	Low	Supported 2013		
34	Abbotsford	3434038	YALE SECONDARY	6	Cafeteria (1988)	380	Moderate	Medium	Supported 2013		
34	Abbotsford	3434038	YALE SECONDARY	7	Small Gym (1985)	260	Low	Low	Supported 2013		
34	Abbotsford	3434038	YALE SECONDARY	8	Shop Addition (1985)	640	Low	Low	Supported 2013		
34	Abbotsford	3434038	YALE SECONDARY	9	One Storey Classroom Addn (1988)	?	Moderate	Medium	Supported 2013		
34	Abbotsford	3434038	YALE SECONDARY	10	N. Two Storey Classroom, Theatre (2000)	?	Low	Low	Supported 2013		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
35	Langley	3535020	ALDERGROVE COMMUNITY SECONDARY SCHOOL	1	Gymnasium (West)	900	Moderate	Medium	Non Structural Upgrade Required	Medium	
35	Langley	3535020	ALDERGROVE COMMUNITY SECONDARY SCHOOL	2	Classrooms (West)	3,917	Moderate	Medium	Non Structural Upgrade Required		
35	Langley	3535020	ALDERGROVE COMMUNITY SECONDARY SCHOOL	3	Classrooms (North)	3,340	Moderate	Medium	Non Structural Upgrade Required		
35	Langley	3535020	ALDERGROVE COMMUNITY SECONDARY SCHOOL	4	Small Gymnasium	300	Moderate	Medium	Non Structural Upgrade Required		
35	Langley	3535020	ALDERGROVE COMMUNITY SECONDARY SCHOOL	5	Shops	920	Moderate	Medium	Non Structural Upgrade Required		
35	Langley	3535020	ALDERGROVE COMMUNITY SECONDARY SCHOOL	6	Gymnasium/Theatre	755	Moderate	Medium	Non Structural Upgrade Required		
35	Langley	3535020	ALDERGROVE COMMUNITY SECONDARY SCHOOL	7	Classrooms/Shops	3,130	Moderate/High	Medium	Non Structural Upgrade Required		
35	Langley	3535020	ALDERGROVE COMMUNITY SECONDARY SCHOOL	8	Library	?	Low	Low	Meets Structural Life Safety Requirements		
35	Langley	3535003	ALDERGROVE ELEMENTARY	1	Gymnasium	500	Low/Moderate	Low	Inactive	Medium	
35	Langley	3535003	ALDERGROVE ELEMENTARY	2	Library	216	Moderate/High	Medium	Inactive		
35	Langley	3535003	ALDERGROVE ELEMENTARY	3	2-Storey Classrooms	950	Moderate	Medium	Inactive		
35	Langley	3535003	ALDERGROVE ELEMENTARY	4	Classrooms - North/West	1,066	Moderate/High	Medium	Inactive		
35	Langley	3535003	ALDERGROVE ELEMENTARY	5	Classrooms - West	455	Moderate	Medium	Inactive		
35	Langley	3535003	ALDERGROVE ELEMENTARY	6	Classrooms - South/West	185	Moderate	Medium	Inactive		
35	Langley	3535047	ALEX HOPE ELEMENTARY	1	1988 Block 1	835	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
35	Langley	3535047	ALEX HOPE ELEMENTARY	2	1988 Block 2	563	Low/Moderate	Low	Meets Structural Life Safety Requirements		
35	Langley	3535047	ALEX HOPE ELEMENTARY	3	1988 Block 3	630	Low/Moderate	Low	Meets Structural Life Safety Requirements		
35	Langley	3535047	ALEX HOPE ELEMENTARY	4	1988 Block 4	577	Low	Low	Meets Structural Life Safety Requirements		
35	Langley	3535047	ALEX HOPE ELEMENTARY	5	1988 Block 5	1,600	Low/Moderate	Low	Meets Structural Life Safety Requirements		
35	Langley	3535038	ALICE BROWN ELEMENTARY	1	1976 Block 1	650	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
35	Langley	3535038	ALICE BROWN ELEMENTARY	2	1976 Block 2	1,450	Low/Moderate	Low	Meets Structural Life Safety Requirements		
35	Langley	3535038	ALICE BROWN ELEMENTARY	3	1976 Block 3	850	Moderate	Medium	Non Structural Upgrade Required		
35	Langley	3535007	APEX SECONDARY PROGRAM	1	1915 Block 1	980	Moderate/High	High 3	Structural Upgrade Required	High 3	
35	Langley	3535007	APEX SECONDARY PROGRAM	2	1970/1971 Block 2	240	Moderate/High	Medium	Non Structural Upgrade Required		
35	Langley	3535007	APEX SECONDARY PROGRAM	3	1970/1971 Block 3	680	Moderate/High	Medium	Non Structural Upgrade Required		
35	Langley	3535007	APEX SECONDARY (was OTTER ELEMENTARY)	1	1976 Block 1	240	Low/Moderate	Low	Meets Structural Life Safety Requirements	High 3	June 2013; Risk assessed as High 3 for Block 3.
35	Langley	3535007	APEX SECONDARY (was OTTER ELEMENTARY)	2	1976 Block 2	900	Low/Moderate	Low	Meets Structural Life Safety Requirements		
35	Langley	3535007	APEX SECONDARY (was OTTER ELEMENTARY)	3	1913 Block 3 (2 Classroom structure)	?	High	High 3	Structural Upgrade Required		
35	Langley	3535009	BELMONT ELEMENTARY	1	1971 Block 1	1,385	Low/Moderate	N/A	Completed	N/A	
35	Langley	3535009	BELMONT ELEMENTARY	2	2001 Block 2	120	Low	N/A	Completed		
35	Langley	3535009	BELMONT ELEMENTARY	3	1972 Block 3	595	Moderate/High	N/A	Completed		
35	Langley	3535009	BELMONT ELEMENTARY	4	1955/1972 Block 4	870	Moderate/High	N/A	Completed		
35	Langley	3535009	BELMONT ELEMENTARY	5	2001 Block 5	970	Low	N/A	Completed		
35	Langley	3535009	BELMONT ELEMENTARY	6	1972 Block 6	480	High	N/A	Completed		
35	Langley	3535033	BLACKLOCK ELEMENTARY	1	1971 Block 1	1,200	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
35	Langley	3535033	BLACKLOCK ELEMENTARY	2	1974 Block 2	428	Low/Moderate	Low	Meets Structural Life Safety Requirements		
35	Langley	3535033	BLACKLOCK ELEMENTARY	3	1974 Block 3	950	Low/Moderate	Low	Meets Structural Life Safety Requirements		
35	Langley	3535033	BLACKLOCK ELEMENTARY	4	1974 Block 4	690	Low/Moderate	Low	Meets Structural Life Safety Requirements		
35	Langley	3535035	BRADSHAW ELEMENTARY	1	Classroom / Admin	1,378	Low/Moderate	Low	Inactive	Medium	
35	Langley	3535035	BRADSHAW ELEMENTARY	2	Classrooms (West)	909	Moderate	Medium	Inactive		
35	Langley	3535035	BRADSHAW ELEMENTARY	3	Classrooms (East)	418	Low/Moderate	Low	Inactive		
35	Langley	3535035	BRADSHAW ELEMENTARY	4	Gymnasium (upgraded 2002)	?	Low	Low	Inactive		
35	Langley	3535036	BROOKSWOOD SECONDARY	1	1974 Block 1	7,800	Moderate/High	High 3	Structural Upgrade Required	High 3	
35	Langley	3535036	BROOKSWOOD SECONDARY	2	1982 Block 2	290	Moderate	Medium	Non Structural Upgrade Required		
35	Langley	3535036	BROOKSWOOD SECONDARY	3	1982/1986 Block 3	1,040	Moderate	Medium	Non Structural Upgrade Required		
35	Langley	3535036	BROOKSWOOD SECONDARY	4	1982/1986 Block 4	4,680	Moderate	Medium	Non Structural Upgrade Required		
35	Langley	3535036	BROOKSWOOD SECONDARY	5	Block 5 1990+/-	1,560	Low	Low	Meets Structural Life Safety Requirements		
35	Langley	3535036	BROOKSWOOD SECONDARY	6	Block 6 1990 +/-	910	Low	Low	Meets Structural Life Safety Requirements		
35	Langley	3535023	COGHLAN ELEMENTARY	1	1958 1-storey classroom	600	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
35	Langley	3535023	COGHLAN ELEMENTARY	2	1973 Gymnasium	260	Moderate	Medium	Non Structural Upgrade Required		
35	Langley	3535023	COGHLAN ELEMENTARY	3	1994 1-storey classroom	?	Low	Low	Meets Structural Life Safety Requirements		
35	Langley	3535018	COUNTY LINE ELEMENTARY	1	1947 1-storey classroom	975	Moderate/High	Medium	Inactive	Medium	
35	Langley	3535018	COUNTY LINE ELEMENTARY	2	1976 gymnasium	400	Low/Moderate	Low	Inactive		
35	Langley	3535018	COUNTY LINE ELEMENTARY	3	1986 1-storey classroom	330	Low/Moderate	Low	Inactive	High 3	
35	Langley	3535034	D W POPPY SECONDARY	1	1972 2-storey classroom	3,850	Moderate	High 3	Structural Upgrade Required		
35	Langley	3535034	D W POPPY SECONDARY	2	1979 2-storey classroom	3,900	Low/Moderate	Low	Meets Structural Life Safety Requirements		
35	Langley	3535034	D W POPPY SECONDARY	3	1972 1-storey classroom	825	Low/Moderate	High 3	Structural Upgrade Required		
35	Langley	3535034	D W POPPY SECONDARY	4	1972 gymnasium	820	Low/Moderate	Low	Meets Structural Life Safety Requirements		
35	Langley	3535034	D W POPPY SECONDARY	5	1988 Fine Arts	1,120	Low	Low	Meets Structural Life Safety Requirements		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments	
35	Langley	3535045	DOUGLAS PARK COMMUNITY	1	1981 Block 1	395	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium		
35	Langley	3535045	DOUGLAS PARK COMMUNITY	2	1981 Block 2	1,950	Low/Moderate	Low	Meets Structural Life Safety Requirements			
35	Langley	3535045	DOUGLAS PARK COMMUNITY	3	1991 Block 3	685	Moderate	Medium	Non Structural Upgrade Required			
35	Langley	3535045	DOUGLAS PARK COMMUNITY	4	1992 Block 4	330	Low	Low	Meets Structural Life Safety Requirements			
35	Langley	3535002	FORT LANGLEY ELEMENTARY	1	Original Structure	1,700	High	N/A	Completed	N/A		
35	Langley	3535002	FORT LANGLEY ELEMENTARY	2	Classroom Addition (1969, 71,76)	875	Moderate/High	N/A	Completed			
35	Langley	3535002	FORT LANGLEY ELEMENTARY	3	Covered play areas	240	Moderate	N/A	Completed			
35	Langley	3535002	FORT LANGLEY ELEMENTARY	4	Gymnasium (Seismic upgrade 2002)	?	Low	N/A	Completed			
35	Langley	3535017	GLENWOOD ELEMENTARY	1	1950 1-storey classroom	1,100	Moderate/High	Medium	Non Structural Upgrade Required	Medium	1916 block ONLY not in use.	
35	Langley	3535017	GLENWOOD ELEMENTARY	2	1963 gymnasium	380	Moderate/High	Medium	Non Structural Upgrade Required			
35	Langley	3535017	GLENWOOD ELEMENTARY	3	1916 2-storey classroom	400	High	High 2	Inactive			
35	Langley	3535031	H D STAFFORD MIDDLE SCHOOL (was Secondary)	1	1969 Block 1	2,300	Low/Moderate	High 3	Structural Upgrade Required	High 3		
35	Langley	3535031	H D STAFFORD MIDDLE SCHOOL (was Secondary)	2	1969 Block 2	860	Moderate	High 3	Structural Upgrade Required			
35	Langley	3535031	H D STAFFORD MIDDLE SCHOOL (was Secondary)	3	1969 Block 3	1,230	Low/Moderate	High 3	Structural Upgrade Required			
35	Langley	3535031	H D STAFFORD MIDDLE SCHOOL (was Secondary)	4	1971 Block 4	1,240	Low/Moderate	High 3	Structural Upgrade Required			
35	Langley	3535031	H D STAFFORD MIDDLE SCHOOL (was Secondary)	5	1991 Block 5	1,155	Low/Moderate	Low	Meets Structural Life Safety Requirements			
35	Langley	3535031	H D STAFFORD MIDDLE SCHOOL (was Secondary)	6	1991 Block 6	1,180	Low/Moderate	Low	Meets Structural Life Safety Requirements			
35	Langley	3535031	H D STAFFORD MIDDLE SCHOOL (was Secondary)	7	1991 Block 7	1,040	Low/Moderate	High 3	Structural Upgrade Required			
35	Langley	3535040	JAMES KENNEDY ELEMENTARY	1	1986 1-storey classroom	2,930	Low	Low	Meets Structural Life Safety Requirements	Low		
35	Langley	3535040	JAMES KENNEDY ELEMENTARY	2	1986 Gymnasium	430	Low	Low	Meets Structural Life Safety Requirements			
35	Langley	3535040	JAMES KENNEDY ELEMENTARY	3	2000 1-storey classroom	?	Low	Low	Meets Structural Life Safety Requirements			
35	Langley	3535029	LANGLEY FINE ARTS SCHOOL	1	Original structure	4,420	Moderate/High	N/A	Completed	N/A		
35	Langley	3535029	LANGLEY FINE ARTS SCHOOL	2	Original gym	950	High	N/A	Completed			
35	Langley	3535029	LANGLEY FINE ARTS SCHOOL	3	1995 addition	?	Low	N/A	Completed			
35	Langley	3535029	LANGLEY FINE ARTS SCHOOL	4	1998 addition	?	Low	N/A	Completed			
35	Langley	3535252	LANGLEY FUNDAMENTAL ELEMENTARY	1	Gymnasium, 1981 original construction, masonry walls	420	NA	High 2	Structural Upgrade Required	High 2	July 2013 - Risk assessed as	
35	Langley	3535252	LANGLEY FUNDAMENTAL ELEMENTARY	2	Classrooms, 1981 original construction, wood and some masonry	1,210	NA	Medium	Non Structural Upgrade Required			
35	Langley	3535252	LANGLEY FUNDAMENTAL ELEMENTARY	3	SW Classrooms, 1984 addition, wood and masonry	576	NA	Medium	Non Structural Upgrade Required			
35	Langley	3535252	LANGLEY FUNDAMENTAL ELEMENTARY	4	NW Classrooms, 1991 addition, wood construction substantially	875	NA	Medium	Non Structural Upgrade Required			
35	Langley	3535052	LANGLEY FUNDAMENTAL MIDDLE HIGH (was Elementary)	1	1992 Block 1	3,100	Low	Low	Meets Structural Life Safety Requirements	Low		
35	Langley	3535052	LANGLEY FUNDAMENTAL MIDDLE HIGH (was Elementary)	2	1992 Block 2	830	Low	Low	Meets Structural Life Safety Requirements			
35	Langley	3535052	LANGLEY FUNDAMENTAL MIDDLE HIGH (was Elementary)	3	2000 Block 3	560	Low	Low	Meets Structural Life Safety Requirements			
35	Langley	3535021	JAMES ANDERSON LEARNING CENTRE (was Langley Fundamental Middle)	1	1956/1961/1965/1969 Block 1	700	Moderate/High	Medium	Non Structural Upgrade Required	Medium		
35	Langley	3535021	JAMES ANDERSON LEARNING CENTRE (was Langley Fundamental Middle)	2	1971 Block 2	150	Moderate/High	Medium	Non Structural Upgrade Required			
35	Langley	3535021	JAMES ANDERSON LEARNING CENTRE (was Langley Fundamental Middle)	3	1973 Block 3	330	Moderate/High	Medium	Non Structural Upgrade Required			
35	Langley	3535046	LANGLEY MEADOWS ELEMENTARY	1	Gymnasium	450	Moderate	Medium	Non Structural Upgrade Required	Medium		
35	Langley	3535046	LANGLEY MEADOWS ELEMENTARY	2	Classrooms (West)	1,345	Moderate/High	Medium	Non Structural Upgrade Required			
35	Langley	3535046	LANGLEY MEADOWS ELEMENTARY	3	Classroom (Central)	850	Low/Moderate	Low	Meets Structural Life Safety Requirements			
35	Langley	3535046	LANGLEY MEADOWS ELEMENTARY	4	Classroom (East)	1,067	Low/Moderate	Low	Meets Structural Life Safety Requirements			
35	Langley	3535019	LANGLEY SECONDARY	1	1947 Block 1	1,320	Moderate/High	High 3	Supported 2013	High 2	April 2013 - to start 2014	
35	Langley	3535019	LANGLEY SECONDARY	2	1948 Block 2	3,300	Moderate/High	High 2	Supported 2013			
35	Langley	3535019	LANGLEY SECONDARY	3	1987 Block 3	1,770	Moderate	Medium	Supported 2013			
35	Langley	3535019	LANGLEY SECONDARY	4	1965 Block 4	1,210	Moderate	High 3	Supported 2013			
35	Langley	3535019	LANGLEY SECONDARY	5	1989 Block 5	1,720	Low/Moderate	Low	Supported 2013			
35	Langley	3535019	LANGLEY SECONDARY	6	1978 Block 6	140	Moderate/High	Medium	Supported 2013			
35	Langley	3535019	LANGLEY SECONDARY	7	1974 Block 7	890	Moderate	Medium	Supported 2013			
35	Langley	3535019	LANGLEY SECONDARY	8	1987 Block 8 Renovation	745	Low/Moderate	Low	Supported 2013			
35	Langley	3535019	LANGLEY SECONDARY	9	1948/1965 Block 9	825	Moderate/High	Medium	Supported 2013			
35	Langley	3535019	LANGLEY SECONDARY	10	1951 Block 10	785	Moderate/High	High 3	Supported 2013			
35	Langley	3535019	LANGLEY SECONDARY	11	1975 Block 11	340	Moderate	Medium	Supported 2013			
35	Langley	3535019	LANGLEY SECONDARY	12	1965 Block 12	870	Moderate/High	Medium	Supported 2013			
35	Langley	3535019	LANGLEY SECONDARY	13	1965 Block 13	150	Moderate	Medium	Supported 2013			
35	Langley	3535010	LOCHIEL U-CONNECT CENTRE	1	1974 1-storey classroom	670	Moderate	Medium	Non Structural Upgrade Required	Medium		
35	Langley	3535010	LOCHIEL U-CONNECT CENTRE	2	1974 gymnasium	225	Moderate/High	Medium	Non Structural Upgrade Required			
35	Langley	3535041	MOUNTAIN SECONDARY	1	1975 2-storey classroom	3,900	Moderate	High 3	Structural Upgrade Required	High 3		
35	Langley	3535041	MOUNTAIN SECONDARY	2	1975 1-storey classroom	990	Low/Moderate	High 3	Structural Upgrade Required			
35	Langley	3535041	MOUNTAIN SECONDARY	3	1975 gymnasium	820	Low/Moderate	Low	Meets Structural Life Safety Requirements			
35	Langley	3535041	MOUNTAIN SECONDARY	4	1985 shops add'n	890	Moderate	Medium	Non Structural Upgrade Required			
35	Langley	3535041	MOUNTAIN SECONDARY	5	1989 2-storey classroom	2,360	Low	Low	Meets Structural Life Safety Requirements			

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
35	Langley	3535001	MURRAYVILLE ELEMENTARY	1	Gymnasium	580	Moderate/High	Medium	Inactive		
35	Langley	3535001	MURRAYVILLE ELEMENTARY	2	Classroom - East	880	Moderate	Medium	Inactive	High 3	
35	Langley	3535001	MURRAYVILLE ELEMENTARY	3	Classroom / Admin	427	Low	Low	Inactive		
35	Langley	3535001	MURRAYVILLE ELEMENTARY	4	Classroom - West	1,010	High	High 3	Inactive		
35	Langley	3535037	NICOMEKL ELEMENTARY	1	Gymnasium	475	Moderate	Medium	Non Structural Upgrade Required		
35	Langley	3535037	NICOMEKL ELEMENTARY	2	Classroom and Admin (Central)	1,249	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
35	Langley	3535037	NICOMEKL ELEMENTARY	3	Classrooms (East)	888	Low/Moderate	Low	Meets Structural Life Safety Requirements		
35	Langley	3535037	NICOMEKL ELEMENTARY	4	Classroom / Multi purpose (2001)	?	Low	Low	Meets Structural Life Safety Requirements		
35	Langley	3535044	NOEL BOOTH ELEMENTARY	1	Gymnasium	400	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
35	Langley	3535044	NOEL BOOTH ELEMENTARY	2	Classrooms and Administration	2,403	Moderate	Medium	Non Structural Upgrade Required		
35	Langley	3535044	NOEL BOOTH ELEMENTARY	3	Classrooms	719	Low	Low	Meets Structural Life Safety Requirements		
35	Langley	3535015	NORTH OTTER ELEMENTARY	1	1971/1973 Block 1	570	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
35	Langley	3535015	NORTH OTTER ELEMENTARY	2	1964 Block 2	830	Moderate/High	Medium	Non Structural Upgrade Required		
35	Langley	3535015	NORTH OTTER ELEMENTARY	3	1990 Block 3	210	Low	Low	Meets Structural Life Safety Requirements		
35	Langley	3535015	NORTH OTTER ELEMENTARY	4	1971 Block 4	340	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
35	Langley	3535015	NORTH OTTER ELEMENTARY	5	1990 Block 5	105	Low	Low	Meets Structural Life Safety Requirements		
35	Langley	3535015	NORTH OTTER ELEMENTARY	6	1973/1981 Block 6	1,000	Moderate	Medium	Non Structural Upgrade Required		
35	Langley	3535015	NORTH OTTER ELEMENTARY	7	1990 Block 7	540	Low/Moderate	Low	Meets Structural Life Safety Requirements		
35	Langley	3535032	PARKSIDE CENTENNIAL ELEMENTARY	1	1971 2-storey classroom block	1,430	Low	Low	Meets Structural Life Safety Requirements	Low	
35	Langley	3535032	PARKSIDE CENTENNIAL ELEMENTARY	2	1974 1-storey classroom	1,680	Low/Moderate	Low	Meets Structural Life Safety Requirements		
35	Langley	3535032	PARKSIDE CENTENNIAL ELEMENTARY	3	1995 1-storey classroom	?	Low	Low	Meets Structural Life Safety Requirements		
35	Langley	3535026	PETERSON ROAD ELEMENTARY	1	1971 Block 1	500	High	N/A	Completed		
35	Langley	3535026	PETERSON ROAD ELEMENTARY	2	1974 Block 2	980	Moderate/High	N/A	Completed	N/A	
35	Langley	3535026	PETERSON ROAD ELEMENTARY	3	1962/1965 Block 3	695	Moderate/High	N/A	Completed		
35	Langley	3535026	PETERSON ROAD ELEMENTARY	4	1974 Block 4	420	Low/Moderate	N/A	Completed		
35	Langley	3535026	PETERSON ROAD ELEMENTARY	5	1974 Block 5	695	Low/Moderate	N/A	Completed		
35	Langley	3535042	SHORTREED COMMUNITY SCHOOL	1	1978 1-storey classroom	2,140	Moderate	High 3	Structural Upgrade Required		
35	Langley	3535042	SHORTREED COMMUNITY SCHOOL	2	1978 Gymnasium	400	Moderate/High	Medium	Non Structural Upgrade Required	High 3	
35	Langley	3535042	SHORTREED COMMUNITY SCHOOL	3	1981 1-storey classroom	700	Low	Low	Meets Structural Life Safety Requirements		
35	Langley	3535042	SHORTREED COMMUNITY SCHOOL	4	1999 1-storey classroom	?	Low	Low	Meets Structural Life Safety Requirements		
35	Langley	3535022	SIMONDS ELEMENTARY	1	Gymnasium	400	Low	Low	Meets Structural Life Safety Requirements	Medium	
35	Langley	3535022	SIMONDS ELEMENTARY	2	Classrooms (Central)	2,060	Moderate	Medium	Non Structural Upgrade Required		
35	Langley	3535022	SIMONDS ELEMENTARY	3	Classroom (West)	720	Low	Low	Meets Structural Life Safety Requirements		
35	Langley	3535022	SIMONDS ELEMENTARY	4	Classroom (North)	460	Moderate	Medium	Non Structural Upgrade Required		
35	Langley	3535027	SOUTH CARVOLTH ELEMENTARY	1	Gymnasium	295	Moderate	Medium	Inactive	Medium	
35	Langley	3535027	SOUTH CARVOLTH ELEMENTARY	2	Classrooms - West	266	Moderate	Medium	Inactive		
35	Langley	3535027	SOUTH CARVOLTH ELEMENTARY	3	Classrooms - East	500	Moderate/High	Medium	Inactive		
35	Langley	3535039	UPLANDS ELEMENTARY	1	1974/1975 Block 1	540	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
35	Langley	3535039	UPLANDS ELEMENTARY	2	1974/1977 Block 2	1,650	Moderate/High	Medium	Non Structural Upgrade Required		
35	Langley	3535039	UPLANDS ELEMENTARY	3	1975 Block 3	710	Moderate	Medium	Non Structural Upgrade Required		
35	Langley	3535043	WEST LANGLEY ELEMENTARY	1	1980 1-story classroom	2,700	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
35	Langley	3535043	WEST LANGLEY ELEMENTARY	2	1980 gymnasium	400	Moderate/High	Medium	Non Structural Upgrade Required		
35	Langley	3535016	WILLOUGHBY ELEMENTARY	1	1971 1-storey classroom	1,460	Moderate	Medium	Non Structural Upgrade Required	Medium	
35	Langley	3535016	WILLOUGHBY ELEMENTARY	2	1971 gymnasium	410	Low	Low	Meets Structural Life Safety Requirements		
35	Langley	3535016	WILLOUGHBY ELEMENTARY	3	1982 1-storey classroom	435	Low	Low	Meets Structural Life Safety Requirements		
35	Langley	3535016	WILLOUGHBY ELEMENTARY	4	1994 1-storey classroom	?	Low	Low	Meets Structural Life Safety Requirements		
35	Langley	3535016	WILLOUGHBY ELEMENTARY	5	2000 1-storey classroom	?	Low	Low	Meets Structural Life Safety Requirements		
35	Langley	3535024	WIX-BROWN ELEMENTARY	1	Gymnasium	484	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
35	Langley	3535024	WIX-BROWN ELEMENTARY	2	Classrooms - North	496	Moderate	Medium	Non Structural Upgrade Required		
35	Langley	3535024	WIX-BROWN ELEMENTARY	3	Administration	674	Moderate	Medium	Non Structural Upgrade Required		
35	Langley	3535024	WIX-BROWN ELEMENTARY	4	2-Storey Classrooms 2003	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636051	A H P MATTHEW ELEMENTARY	1	1957 2-storey classroom	2,680	High	N/A	Completed	N/A	
36	Surrey	3636051	A H P MATTHEW ELEMENTARY	2	1960 gymnasium	350	High	N/A	Completed		
36	Surrey	3636042	ANNIE DALE TRADITIONAL SCHOOL	1	1966 Gymnasium	365	High	Medium	Inactive	High 3	
36	Surrey	3636042	ANNIE DALE TRADITIONAL SCHOOL	2	1954 Classroom Block	1,405	Moderate/High	High 3	Inactive		
36	Surrey	3636042	ANNIE DALE TRADITIONAL SCHOOL	3	1890 Heritage and Portable	170	Moderate	Medium	Inactive		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
36	Surrey	3636162	BAYRIDGE ELEMENTARY	1	Gymnasium	400	Low/Moderate	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636162	BAYRIDGE ELEMENTARY	2	1990 Classrooms	2,460	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636162	BAYRIDGE ELEMENTARY	3	1999 Classrooms	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636069	BEAR CREEK ELEMENTARY	1	1964 1-storey classroom	800	Moderate/High	Medium	Non Structural Upgrade Required		
36	Surrey	3636069	BEAR CREEK ELEMENTARY	2	1964 gymnasium	400	High	High 3	Structural Upgrade Required	High 3	
36	Surrey	3636069	BEAR CREEK ELEMENTARY	3	1972 1-storey classroom	1,500	Moderate	Medium	Non Structural Upgrade Required		
36	Surrey	3636069	BEAR CREEK ELEMENTARY	4	1991 1-storey classroom	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636069	BEAR CREEK ELEMENTARY	5	2000 1-storey classroom	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636136	BERKSHIRE PARK ELEMENTARY	1	Gymnasium	400	Low/Moderate	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636136	BERKSHIRE PARK ELEMENTARY	2	1987 Classrooms	3,700	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636136	BERKSHIRE PARK ELEMENTARY	3	1999 Classrooms	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636107	BETTY HUFF ELEMENTARY	1	1976 1-storey classroom	2,700	Moderate	Medium	Non Structural Upgrade Required		
36	Surrey	3636107	BETTY HUFF ELEMENTARY	2	1976 Gymnasium	400	Moderate	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636107	BETTY HUFF ELEMENTARY	3	1980 1-storey classroom addition	475	Moderate	Medium	Non Structural Upgrade Required		
36	Surrey	3636107	BETTY HUFF ELEMENTARY	4	2000 1-storey classroom	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636128	BONACCORD ELEMENTARY	1	Old Classrooms	3,550	Moderate	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636128	BONACCORD ELEMENTARY	2	Gymnasium	370	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
36	Surrey	3636128	BONACCORD ELEMENTARY	3	2000 Classrooms	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636146	BROOKSIDE ELEMENTARY	1	Gymnasium	415	Low/Moderate	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636146	BROOKSIDE ELEMENTARY	2	1990 Classrooms	2,735	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636146	BROOKSIDE ELEMENTARY	3	1993 and 1999 Classrooms	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636073	CEDAR HILLS ELEMENTARY	1	1964 1-storey classroom	2,340	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636073	CEDAR HILLS ELEMENTARY	2	1964 gymnasium	440	High	Medium	Non Structural Upgrade Required		
36	Surrey	3636073	CEDAR HILLS ELEMENTARY	3	1999 1-storey classroom	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636013	CLAYTON ELEMENTARY	1	1955 classroom block	745	Moderate/High	N/A	Completed		
36	Surrey	3636013	CLAYTON ELEMENTARY	2	1964 gymnasium	250	Moderate/High	N/A	Completed	N/A	
36	Surrey	3636013	CLAYTON ELEMENTARY	3	1920 2-storey classroom block	400	Moderate/High	N/A	Completed		
36	Surrey	3636004	CLOVERDALE TRADITIONAL SCHOOL	1	Classrooms	1,650	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636004	CLOVERDALE TRADITIONAL SCHOOL	2	Gymnasium	670	High	Medium	Non Structural Upgrade Required		
36	Surrey	3636004	CLOVERDALE TRADITIONAL SCHOOL	3	Washrooms	42	Moderate	Medium	Non Structural Upgrade Required		
36	Surrey	3636012	COLEBROOK ELEMENTARY	1	1940, 1965, 1967 Classroom Blocks	600	Moderate/High	N/A	Completed		
36	Surrey	3636012	COLEBROOK ELEMENTARY	2	1967, 1987 Gymnasium	360	High	N/A	Completed	N/A	
36	Surrey	3636012	COLEBROOK ELEMENTARY	3	1921, 1987, 2000 Classroom Blocks	?	Low	N/A	Completed		
36	Surrey	3636498	CRESCENT PARK ANNEX (36031)	1	Classroom Block	300	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636031	CRESCENT PARK ELEMENTARY	1	1947 2-storey	2,120	High	Medium	Non Structural Upgrade Required		
36	Surrey	3636031	CRESCENT PARK ELEMENTARY	2	1963 gymnasium	460	Moderate/High	Medium	Non Structural Upgrade Required		
36	Surrey	3636031	CRESCENT PARK ELEMENTARY	3	1967 1-storey classroom	380	Moderate/High	Medium	Non Structural Upgrade Required		
36	Surrey	3636031	CRESCENT PARK ELEMENTARY	4	1980 1-storey classroom	210	Low/Moderate	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636031	CRESCENT PARK ELEMENTARY	5	1974 2-storey classroom	340	Moderate	Medium	Non Structural Upgrade Required		
36	Surrey	3636058	DAVID BRANKIN ELEMENTARY	1	3 Storey Classroom	3,540	Moderate/High	High 3	Structural Upgrade Required	High 3	
36	Surrey	3636058	DAVID BRANKIN ELEMENTARY	2	1 Storey Classrooms	2,385	Low/Moderate	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636058	DAVID BRANKIN ELEMENTARY	3	Gymnasium Washrooms	350	Low/Moderate	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636058	DAVID BRANKIN ELEMENTARY	4	Gymnasium	600	Moderate	High 3	Structural Upgrade Required		
36	Surrey	3636074	DISCOVERY ELEMENTARY	1	1966 Classroom/Admin	1,070	High	N/A	Completed		
36	Surrey	3636074	DISCOVERY ELEMENTARY	2	1966 Gymnasium	340	High	N/A	Completed	N/A	
36	Surrey	3636074	DISCOVERY ELEMENTARY	3	1970 Classrooms	415	High	N/A	Completed		
36	Surrey	3636122	DON CHRISTIAN ELEMENTARY	1	1981 1-storey classroom	2,900	Low	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636122	DON CHRISTIAN ELEMENTARY	2	1981 Gymnasium	375	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636037	DR F D SINCLAIR ELEMENTARY	1	1955 2-storey classroom	1,500	High	N/A	Completed		
36	Surrey	3636037	DR F D SINCLAIR ELEMENTARY	2	1958 2-storey classroom	1,650	High	N/A	Completed	N/A	
36	Surrey	3636037	DR F D SINCLAIR ELEMENTARY	3	1958 gymnasium	400	High	N/A	Completed		
36	Surrey	3636037	DR F D SINCLAIR ELEMENTARY	4	2000 2-storey classroom	?	Low	N/A	Completed		
36	Surrey	3636105	EARL MARRIOTT SECONDARY	1	3-storey classroom & gymnasium	?	Low	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636101	EAST CLAYTON ELEMENTARY	1	1970 1-storey classroom	730	Moderate	Medium	Inactive	Medium	
36	Surrey	3636101	EAST CLAYTON ELEMENTARY	2	1971 gymnasium	225	Moderate/High	Medium	Inactive		
36	Surrey	3636018	EAST KENSINGTON ELEMENTARY	1	2 Storey Classroom	416	High	N/A	Completed		
36	Surrey	3636018	EAST KENSINGTON ELEMENTARY	2	1 Storey Classroom/Library	700	Moderate/High	N/A	Completed	N/A	
36	Surrey	3636018	EAST KENSINGTON ELEMENTARY	3	Gymnasium/Administration	375	Moderate/High	N/A	Completed		
36	Surrey	3636084	ELLEDALE ELEMENTARY	1	Gymnasium	276	High	N/A	Completed		
36	Surrey	3636084	ELLEDALE ELEMENTARY	2	1968 Classrooms	935	Moderate/High	N/A	Completed		
36	Surrey	3636084	ELLEDALE ELEMENTARY	3	1993 Classrooms	310	Low	N/A	Completed	N/A	
36	Surrey	3636084	ELLEDALE ELEMENTARY	4	Portable Unit	90	Low/Moderate	N/A	Completed		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
36	Surrey	3636067	ERMA STEPHENSON ELEMENTARY	1	1963 1-storey classroom	740	Moderate	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636067	ERMA STEPHENSON ELEMENTARY	2	1963 classroom & Gymnasium	2,045	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636026	FLEETWOOD ELEMENTARY	1	East Classrooms	460	Moderate	Medium	Inactive	Medium	
36	Surrey	3636026	FLEETWOOD ELEMENTARY	2	Central Classrooms/Admin.	1,320	Moderate/High	Medium	Inactive		
36	Surrey	3636026	FLEETWOOD ELEMENTARY	3	Gymnasium	380	Moderate/High	Medium	Inactive		
36	Surrey	3636026	FLEETWOOD ELEMENTARY	4	2 Storey West Classrooms	1,070	Moderate/High	Medium	Inactive		
36	Surrey	3636106	FRANK HURT SECONDARY	1	Gymnasium	1,780	Moderate/High	N/A	Completed	N/A	
36	Surrey	3636106	FRANK HURT SECONDARY	2	3-storey Classroom	7,560	Low/Moderate	N/A	Completed		
36	Surrey	3636106	FRANK HURT SECONDARY	3	Cafeteria and Shops	3,000	Low/Moderate	N/A	Completed		
36	Surrey	3636106	FRANK HURT SECONDARY	4	Leased Gymnasium	450	Low	N/A	Completed		
36	Surrey	3636106	FRANK HURT SECONDARY	5	Art Building	?	Low	N/A	Completed		
36	Surrey	3636142	FRASER WOOD ELEMENTARY	1	Gymnasium	400	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636142	FRASER WOOD ELEMENTARY	2	1989 Classrooms	2,550	Low/Moderate	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636142	FRASER WOOD ELEMENTARY	3	New Classrooms	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636090	GEORGE GREENAWAY ELEMENTARY	1	Gymnasium	400	Moderate	High 3	Structural Upgrade Required	High 3	
36	Surrey	3636090	GEORGE GREENAWAY ELEMENTARY	2	1975 Classrooms	2,960	Moderate	Medium	Non Structural Upgrade Required		
36	Surrey	3636090	GEORGE GREENAWAY ELEMENTARY	3	1992 Classrooms	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636082	GEORGES VANIER ELEMENTARY	1	1967 Classroom/Admin	1,650	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636082	GEORGES VANIER ELEMENTARY	2	Gymnasium	430	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636082	GEORGES VANIER ELEMENTARY	3	1989 Classrooms	700	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636082	GEORGES VANIER ELEMENTARY	4	1999 Classrooms	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636016	GRANDVIEW HEIGHTS ELEMENTARY	1	1922 Annex	125	Moderate/High	Medium	Inactive	Medium	
36	Surrey	3636016	GRANDVIEW HEIGHTS ELEMENTARY	2	Gymnasium	350	Moderate	Medium	Inactive		
36	Surrey	3636016	GRANDVIEW HEIGHTS ELEMENTARY	3	Classrooms	1,520	Moderate	Medium	Inactive		
36	Surrey	3636043	GREEN TIMBERS ELEMENTARY	1	1955 2-storey classroom	1,260	High	N/A	Completed	N/A	
36	Surrey	3636043	GREEN TIMBERS ELEMENTARY	2	1958 2-storey classroom	1,360	High	N/A	Completed		
36	Surrey	3636043	GREEN TIMBERS ELEMENTARY	3	1958 gymnasium	330	High	N/A	Completed		
36	Surrey	3636043	GREEN TIMBERS ELEMENTARY	4	1980 2-storey classroom	460	Moderate	N/A	Completed		
36	Surrey	3636043	GREEN TIMBERS ELEMENTARY	5	1990 2-storey classroom	?	Low	N/A	Completed		
36	Surrey	3636047	GUILDFORD PARK SECONDARY	1	1&2-storey classroom & Gymnasium	?	Low	N/A	Completed	N/A	
36	Surrey	3636047	GUILDFORD PARK SECONDARY	2	1-storey Main Hall	460	Moderate	N/A	Completed		
36	Surrey	3636056	H T THRIFT ELEMENTARY	1	East Wing Classroom (1958)	1,700	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636056	H T THRIFT ELEMENTARY	2	West Wing Classroom (1967)	1,400	Moderate/High	Medium	Non Structural Upgrade Required		
36	Surrey	3636056	H T THRIFT ELEMENTARY	3	Gymnasium/Library	1,450	Low/Moderate	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636019	HALLS PRAIRIE ELEMENTARY	1	1956 single-storey classroom	470	Moderate	N/A	Completed	N/A	
36	Surrey	3636019	HALLS PRAIRIE ELEMENTARY	2	1964 gymnasium	265	Moderate	N/A	Completed		
36	Surrey	3636019	HALLS PRAIRIE ELEMENTARY	3	1975 classroom block	290	Moderate	N/A	Completed		
36	Surrey	3636019	HALLS PRAIRIE ELEMENTARY	4	1930 2-storey classroom block	440	High	N/A	Completed		
36	Surrey	3636029	HAROLD BISHOP ELEMENTARY	1	1963 & 1991 Classroom & Gym	2,700	Low	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636029	HAROLD BISHOP ELEMENTARY	2	1999 1-storey classroom	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636071	HENRY BOSE ELEMENTARY	1	1964 1-storey classroom	3,200	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636071	HENRY BOSE ELEMENTARY	2	1964 gymnasium	550	High	Medium	Non Structural Upgrade Required		
36	Surrey	3636071	HENRY BOSE ELEMENTARY	3	1979 single-storey classroom	450	Low/Moderate	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636001	HJORTH ROAD ELEMENTARY	1	1954 2-storey Classroom block	1,460	High	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636001	HJORTH ROAD ELEMENTARY	2	1964 gymnasium	420	Moderate	Medium	Non Structural Upgrade Required		
36	Surrey	3636001	HJORTH ROAD ELEMENTARY	3	1964 2-storey classroom block	425	High	Medium	Non Structural Upgrade Required		
36	Surrey	3636001	HJORTH ROAD ELEMENTARY	4	1909 2-storey classroom block	460	High	Medium	Non Structural Upgrade Required		
36	Surrey	3636081	HOLLY ELEMENTARY	1	1967 1-storey classroom	2,600	Moderate	High 3	Structural Upgrade Required	High 3	
36	Surrey	3636081	HOLLY ELEMENTARY	2	1967 gymnasium	400	Moderate/High	Medium	Non Structural Upgrade Required		
36	Surrey	3636081	HOLLY ELEMENTARY	3	2000 1-storey classroom	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636034	J T BROWN ELEMENTARY	1	1955 Classrooms	1,260	Moderate/High	High 2	Structural Upgrade Required	High 2	November 2012 - Review changed risk for Block 2 from M to H3 and for Block 3 from M to H2.
36	Surrey	3636034	J T BROWN ELEMENTARY	2	1958 Gymnasium	340	Moderate/High	High 3	Structural Upgrade Required		
36	Surrey	3636034	J T BROWN ELEMENTARY	3	1958 Classrooms	950	Moderate/High	High 2	Structural Upgrade Required		
36	Surrey	3636062	JAMES ARDIEL ELEMENTARY	1	Classrooms - Old	2,680	Moderate	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636062	JAMES ARDIEL ELEMENTARY	2	Gymnasium	450	High	Medium	Non Structural Upgrade Required		
36	Surrey	3636062	JAMES ARDIEL ELEMENTARY	3	Library/Washrooms/Mechanical	950	Moderate/High	Medium	Non Structural Upgrade Required		
36	Surrey	3636062	JAMES ARDIEL ELEMENTARY	4	Classrooms - New	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636089	JESSIE LEE ELEMENTARY	1	1973 single-storey classroom	900	Moderate	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636089	JESSIE LEE ELEMENTARY	2	1973 gymnasium	575	Moderate	Medium	Non Structural Upgrade Required		
36	Surrey	3636089	JESSIE LEE ELEMENTARY	3	1980 2-storey classroom	800	Moderate	Medium	Non Structural Upgrade Required		
36	Surrey	3636089	JESSIE LEE ELEMENTARY	4	2000 2-storey classroom	?	Low	Low	Meets Structural Life Safety Requirements		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
36	Surrey	3636045	JOHNSTON HEIGHTS SECONDARY	1	2-storey classrooms & Gymnasium	15,600	Low	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636040	K B WOODWARD ELEMENTARY	1	Gymnasium	735	High	N/A	Completed		
36	Surrey	3636040	K B WOODWARD ELEMENTARY	2	2 Storey Classroom	2,210	Moderate/High	N/A	Completed	N/A	
36	Surrey	3636040	K B WOODWARD ELEMENTARY	3	1 Storey Classroom	500	Moderate	N/A	Completed		
36	Surrey	3636040	K B WOODWARD ELEMENTARY	4	Portable Units	270	Low/Moderate	N/A	Completed		
36	Surrey	3636132	KENNEDY TRAIL ELEMENTARY	1	Gymnasium	480	Moderate	N/A	Completed		
36	Surrey	3636132	KENNEDY TRAIL ELEMENTARY	2	1987 Classrooms	1,560	Low/Moderate	N/A	Completed	N/A	
36	Surrey	3636132	KENNEDY TRAIL ELEMENTARY	3	1992 Classrooms	?	Low	N/A	Completed		
36	Surrey	3636006	KENSINGTON PRAIRIE ELEMENTARY	1	2 Storey Classroom	640	Moderate/High	Medium	Inactive		
36	Surrey	3636006	KENSINGTON PRAIRIE ELEMENTARY	2	Gymnasium	256	Moderate	Medium	Inactive		
36	Surrey	3636006	KENSINGTON PRAIRIE ELEMENTARY	3	1 Storey Classrooms	646	Moderate	Medium	Inactive	Medium	
36	Surrey	3636006	KENSINGTON PRAIRIE ELEMENTARY	4	Portable Units	180	Low/Moderate	Low	Inactive		
36	Surrey	3636079	L A MATHESON SECONDARY	1	Block1	?	Low	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636117	LARONDE ELEMENTARY	1	1-storey classroom & gymnasium	3,500	Low	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636055	LENA SHAW ELEMENTARY	1	single storey classroom & gymnasium	4,750	Low	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636041	LORD TWEEDSMUIR SECONDARY	1	Classroom Block & Gymnasium	?	Low	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636129	M B SANFORD ELEMENTARY	1	1985 Classroom & Gymnasium	3,650	Low	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636129	M B SANFORD ELEMENTARY	2	2001 Classroom	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636130	MAPLE GREEN ELEMENTARY	1	Gymnasium	400	Low/Moderate	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636130	MAPLE GREEN ELEMENTARY	2	Classrooms	3,400	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636061	MARTHA CURRIE ELEMENTARY	1	1962 1-storey classroom	5,800	Moderate/High	Medium	Non Structural Upgrade Required		
36	Surrey	3636061	MARTHA CURRIE ELEMENTARY	2	1962 gymnasium	750	High	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636140	MARTHA JANE NORRIS ELEMENTARY	1	Gymnasium	400	Low/Moderate	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636140	MARTHA JANE NORRIS ELEMENTARY	2	Classrooms	4,030	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636054	MARY JANE SHANNON ELEMENTARY	1	Gymnasium	350	High	High 3	Structural Upgrade Required		
36	Surrey	3636054	MARY JANE SHANNON ELEMENTARY	2	2 Storey Classroom	1,630	Moderate/High	Medium	Non Structural Upgrade Required		
36	Surrey	3636054	MARY JANE SHANNON ELEMENTARY	3	Lunch Room	200	Moderate/High	Medium	Non Structural Upgrade Required	High 3	
36	Surrey	3636054	MARY JANE SHANNON ELEMENTARY	4	Change Room	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636054	MARY JANE SHANNON ELEMENTARY	5	Classroom/Covered Walkway	2,300	Moderate/High	Medium	Non Structural Upgrade Required		
36	Surrey	3636063	MCLEOD ROAD ELEMENTARY	1	1962 1-storey classroom	850	High	N/A	Completed		
36	Surrey	3636063	MCLEOD ROAD ELEMENTARY	2	1962 gymnasium	260	High	N/A	Completed		
36	Surrey	3636063	MCLEOD ROAD ELEMENTARY	3	1967 1-storey classroom	185	Moderate	N/A	Completed		
36	Surrey	3636063	MCLEOD ROAD ELEMENTARY	4	1980 1-storey classroom	360	Low/Moderate	N/A	Completed		
36	Surrey	3636050	MOUNTAINVIEW MONTESSORI	1	1965 Gymnasium	350	Moderate	N/A	Completed		
36	Surrey	3636050	MOUNTAINVIEW MONTESSORI	2	Modular Buildings	2,795	Low/Moderate	N/A	Completed		
36	Surrey	3636072	NEWTON ELEMENTARY	1	Gymnasium	480	High	Medium	Non Structural Upgrade Required		
36	Surrey	3636072	NEWTON ELEMENTARY	2	Old Classrooms	2,975	Moderate	Medium	Non Structural Upgrade Required		
36	Surrey	3636072	NEWTON ELEMENTARY	3	New Classrooms	?	Low	Low	Meets Structural Life Safety Requirements	Medium	
36	Surrey	3636072	NEWTON ELEMENTARY	4	1999 1-storey classroom	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636138	NORTH RIDGE ELEMENTARY SCHOOL	1	Gymnasium	400	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636138	NORTH RIDGE ELEMENTARY SCHOOL	2	1990 Classrooms	1,680	Low	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636138	NORTH RIDGE ELEMENTARY SCHOOL	3	1999 Classrooms	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636170	OCEAN CLIFF ELEMENTARY SCHOOL	1	Classrooms/Admin.	2,540	Low/Moderate	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636170	OCEAN CLIFF ELEMENTARY SCHOOL	2	Gymnasium	375	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636064	OLD YALE ROAD ELEMENTARY	1	Gymnasium	460	High	Medium	Non Structural Upgrade Required		
36	Surrey	3636064	OLD YALE ROAD ELEMENTARY	2	Classrooms	3,740	High	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636064	OLD YALE ROAD ELEMENTARY	3	Portable Unit	90	Low/Moderate	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636137	PANORAMA PARK ELEMENTARY	1	1987 Classroom & Gymnasium	2,200	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636137	PANORAMA PARK ELEMENTARY	2	2000 Classroom	?	Low	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636070	PEACE ARCH ELEMENTARY	1	Gymnasium	400	Moderate/High	Medium	Non Structural Upgrade Required		
36	Surrey	3636070	PEACE ARCH ELEMENTARY	2	Classrooms	2,500	High	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636070	PEACE ARCH ELEMENTARY	3	1993 Library Addition	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636002	PORT KELLS ELEMENTARY	1	2 Storey Classrooms	900	Moderate/High	Medium	Non Structural Upgrade Required		
36	Surrey	3636002	PORT KELLS ELEMENTARY	2	Gymnasium	250	Moderate	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636002	PORT KELLS ELEMENTARY	3	1 Storey Classrooms	980	Moderate	Medium	Non Structural Upgrade Required		
36	Surrey	3636044	PRINCE CHARLES ELEMENTARY	1	Gymnasium	540	Low	Medium	Non Structural Upgrade Required		
36	Surrey	3636044	PRINCE CHARLES ELEMENTARY	2	2-Storey Classroom 1954	1,400	Moderate/High	High 3	Structural Upgrade Required	High 3	
36	Surrey	3636044	PRINCE CHARLES ELEMENTARY	3	2 Storey Classrooms 1957	2,130	Moderate	Medium	Non Structural Upgrade Required		
36	Surrey	3636022	QUEEN ELIZABETH SECONDARY	1	Shops	2,440	Low	High 3	Structural Upgrade Required		
36	Surrey	3636022	QUEEN ELIZABETH SECONDARY	2	1967 Classrooms	5,700	Low/Moderate	High 3	Structural Upgrade Required	High 3	
36	Surrey	3636022	QUEEN ELIZABETH SECONDARY	3	1997 Classrooms and Gymnasium	?	Low	Low	Meets Structural Life Safety Requirements		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
36	Surrey	3636036	RAY SHEPHERD ELEMENTARY	1	Gymnasium	530	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636036	RAY SHEPHERD ELEMENTARY	2	2 Storey Classroom	970	Moderate/High	Medium	Non Structural Upgrade Required		
36	Surrey	3636036	RAY SHEPHERD ELEMENTARY	3	1 Storey Classroom	880	High	Medium	Non Structural Upgrade Required		
36	Surrey	3636036	RAY SHEPHERD ELEMENTARY	4	Covered Play Area	200	Moderate/High	Medium	Non Structural Upgrade Required		
36	Surrey	3636036	RAY SHEPHERD ELEMENTARY	5	1 Storey Classroom (2001)	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636059	RIVERDALE ELEMENTARY	1	Gymnasium / Stage	760	High	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636059	RIVERDALE ELEMENTARY	2	Classroom / Administration Areas	1,523	High	Medium	Non Structural Upgrade Required		
36	Surrey	3636059	RIVERDALE ELEMENTARY	3	Classroom / Covered Play Areas	922	High	Medium	Non Structural Upgrade Required		
36	Surrey	3636059	RIVERDALE ELEMENTARY	4	Classroom Areas	1,275	High	Medium	Non Structural Upgrade Required		
36	Surrey	3636077	ROYAL HEIGHTS ELEMENTARY	1	Classroom & Gymnasium	3,700	Low	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636049	SEMIAHMOO SECONDARY	1	1989 Classroom & Gymnasium	11,360	Low	Low	Meets Structural Life Safety Requirements	Medium	
36	Surrey	3636049	SEMIAHMOO SECONDARY	2	1966 2-storey classroom	1,450	Moderate	Medium	Non Structural Upgrade Required		
36	Surrey	3636049	SEMIAHMOO SECONDARY	3	1978 2-storey classroom	2,200	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636060	SENATOR REID ELEMENTARY	1	Gymnasium	417	High	N/A	Completed		
36	Surrey	3636060	SENATOR REID ELEMENTARY	2	Classrooms (1961, 1966)	1,890	High	N/A	Completed		N/A
36	Surrey	3636060	SENATOR REID ELEMENTARY	3	1999 Classrooms	?	Low	N/A	Completed		
36	Surrey	3636143	SERPENTINE HEIGHTS ELEMENTARY	1	Classroom & Gymnasium	3,050	Low	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636118	SOUTH MERIDIAN ELEMENTARY	1	Classrooms/Admin.	2,540	Low	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636118	SOUTH MERIDIAN ELEMENTARY	2	Gymnasium	375	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636109	STRAWBERRY HILL ELEMENTARY	1	Classroom & Gymnasium	5,300	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636425	STUDENT SUPPORT CENTRE	1	1949 2-storey classroom	1,550	High	Medium	Non Structural Upgrade Required	Medium	
36	Surrey	3636425	STUDENT SUPPORT CENTRE	2	1962 gymnasium	450	High	Medium	Non Structural Upgrade Required		
36	Surrey	3636425	STUDENT SUPPORT CENTRE	3	1944 2-storey classroom	640	Moderate/High	Medium	Non Structural Upgrade Required		
36	Surrey	3636021	SULLIVAN ELEMENTARY	1	1949 2-storey classroom	1,100	High	N/A	Completed	N/A	
36	Surrey	3636021	SULLIVAN ELEMENTARY	2	1965 gymnasium	250	Moderate/High	N/A	Completed		
36	Surrey	3636021	SULLIVAN ELEMENTARY	3	1982 2-storey classroom	440	Low/Moderate	N/A	Completed		
36	Surrey	3636021	SULLIVAN ELEMENTARY	4	2000 1-storey modular	?	Low	N/A	Completed		
36	Surrey	3636038	SUNNYSIDE ELEMENTARY	1	1 Storey Classrooms	583	Moderate	N/A	Completed	N/A	
36	Surrey	3636038	SUNNYSIDE ELEMENTARY	2	Gymnasium	350	Moderate/High	N/A	Completed		
36	Surrey	3636038	SUNNYSIDE ELEMENTARY	3	2 Storey Classrooms	920	Moderate/High	N/A	Completed		
36	Surrey	3636080	SURREY TRADITIONAL SCHOOL	1	Gymnasium / Stage	839	High	N/A	Completed	N/A	
36	Surrey	3636080	SURREY TRADITIONAL SCHOOL	2	Classroom / Administration Areas	1,533	High	N/A	Completed		
36	Surrey	3636080	SURREY TRADITIONAL SCHOOL	3	Classroom Areas	2,815	High	N/A	Completed		
36	Surrey	3636080	SURREY TRADITIONAL SCHOOL	4	Classroom Areas	1,311	High	N/A	Completed		
36	Surrey	3636053	T E SCOTT ELEMENTARY	1	1957 2-storey classroom	1,850	High	N/A	Completed	N/A	
36	Surrey	3636053	T E SCOTT ELEMENTARY	2	1965 gymnasium	460	Moderate/High	N/A	Completed		
36	Surrey	3636116	W E KINVIG ELEMENTARY	1	Gymnasium	400	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636116	W E KINVIG ELEMENTARY	2	Classrooms	2,970	Low/Moderate	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636057	WILLIAM WATSON ELEMENTARY	1	1958 single-storey classroom	970	Low	Low	Meets Structural Life Safety Requirements	Low	
36	Surrey	3636057	WILLIAM WATSON ELEMENTARY	2	1973 Multi-purpose	214	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636057	WILLIAM WATSON ELEMENTARY	3	1989 classroom & gymnasium	1,350	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636057	WILLIAM WATSON ELEMENTARY	4	1999 classroom	?	Low	Low	Meets Structural Life Safety Requirements		
36	Surrey	3636145	WOODLAND PARK ELEMENTARY	1	Classroom & Gymnasium	3,575	Low	Low	Meets Structural Life Safety Requirements	Low	
37	Delta	3737009	ANNIEVILLE ELEMENTARY	1	Gymnasium	420	Low	Low	Meets Structural Life Safety Requirements	Low	
37	Delta	3737009	ANNIEVILLE ELEMENTARY	2	Classroom	3,620	Low	Low	Meets Structural Life Safety Requirements		
37	Delta	3737019	BEACH GROVE ELEMENTARY	1	Gymnasium	700	Low	Low	Meets Structural Life Safety Requirements	Medium	
37	Delta	3737019	BEACH GROVE ELEMENTARY	2	Classroom/Administration	1,550	Moderate	Medium	Non Structural Upgrade Required		
37	Delta	3737019	BEACH GROVE ELEMENTARY	3	Classroom 2000	?	Low	Low	Meets Structural Life Safety Requirements		
37	Delta	3737029	BROOKE ELEMENTARY SCHOOL	1	Classroom Block	3,000	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
37	Delta	3737029	BROOKE ELEMENTARY SCHOOL	2	Gymnasium/Admin.	860	Moderate/High	Medium	Non Structural Upgrade Required		
37	Delta	3737034	BURNSVIEW JR SECONDARY	1	Classroom Block	2,840	High	N/A	Completed	N/A	
37	Delta	3737034	BURNSVIEW JR SECONDARY	2	Central (Science)	2,080	High	N/A	Completed		
37	Delta	3737034	BURNSVIEW JR SECONDARY	3	Shop Wing	1,100	High	N/A	Completed		
37	Delta	3737034	BURNSVIEW JR SECONDARY	4	Gymnasium and Cafeteria	1,650	Low/Moderate	N/A	Completed		
37	Delta	3737022	CHALMERS ELEMENTARY	1	Gymnasium, Change Room, Admin.	820	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
37	Delta	3737022	CHALMERS ELEMENTARY	2	Classroom, Library (Centre)	1,420	Moderate/High	Medium	Non Structural Upgrade Required		
37	Delta	3737022	CHALMERS ELEMENTARY	3	Classrooms (South-West)	650	Moderate	Medium	Non Structural Upgrade Required		
37	Delta	3737022	CHALMERS ELEMENTARY	4	Classrooms (North)	1,810	Low	Low	Meets Structural Life Safety Requirements		
37	Delta	3737015	CLIFF DRIVE ELEMENTARY	1	Classrooms	3,300	Low/Moderate	Low	Meets Structural Life Safety Requirements		Low
37	Delta	3737015	CLIFF DRIVE ELEMENTARY	2	Gymnasium	550	Low/Moderate	Low	Meets Structural Life Safety Requirements		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
37 Delta		3737039	COUGAR CANYON ELEMENTARY	1	Gymnasium	490	Low	Low	Meets Structural Life Safety Requirements	Low	
37 Delta		3737039	COUGAR CANYON ELEMENTARY	2	Classrooms (East)	2,592	Low	Low	Meets Structural Life Safety Requirements		
37 Delta		3737039	COUGAR CANYON ELEMENTARY	3	Classrooms (West)	1,175	Low	Low	Meets Structural Life Safety Requirements		
37 Delta		3737010	DELTA MANOR ELEMENTARY	1	Gymnasium	530	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
37 Delta		3737010	DELTA MANOR ELEMENTARY	2	2-Storey Classroom	1,865	Low/Moderate	Low	Meets Structural Life Safety Requirements		
37 Delta		3737010	DELTA MANOR ELEMENTARY	3	1-Storey Classroom/Administration	1,406	Low/Moderate	Low	Meets Structural Life Safety Requirements		
37 Delta		3737003	DELTA SECONDARY	1	Gymnasium	1,349	Low/Moderate	Low	Supported 2013	High 1	April 2013 - to start 2014.
37 Delta		3737003	DELTA SECONDARY	2	Theatre	2,326	Moderate	High 2	Supported 2013		
37 Delta		3737003	DELTA SECONDARY	3	Administration	589	Low/Moderate	Low	Supported 2013		
37 Delta		3737003	DELTA SECONDARY	4	Art Wing/Music Room	1,772	Low/Moderate	High 1	Supported 2013		
37 Delta		3737003	DELTA SECONDARY	5	Mechanical and Wood Shops	754	Moderate/High	High 1	Supported 2013		
37 Delta		3737003	DELTA SECONDARY	6	Library	660	Moderate/High	Medium	Supported 2013		
37 Delta		3737003	DELTA SECONDARY	7	Shops (1997 Upgrade)	?	Low	Low	Supported 2013		
37 Delta		3737003	DELTA SECONDARY	8	New Gymnasium (2001)	?	Low	Low	Supported 2013		
37 Delta		3737003	DELTA SECONDARY	9	Classroom (1993, 2000)	?	Low	Low	Supported 2013		
37 Delta		3737003	DELTA SECONDARY	10	Science Wing (1992, 1994)	?	Low	Low	Supported 2013		
37 Delta		3737021	DELVIEW JR SECONDARY	1	Gymnasium	935	Low/Moderate	N/A	Completed	N/A	
37 Delta		3737021	DELVIEW JR SECONDARY	2	Science Rooms	963	Moderate/High	N/A	Completed		
37 Delta		3737021	DELVIEW JR SECONDARY	3	Library	590	Moderate/High	N/A	Completed		
37 Delta		3737021	DELVIEW JR SECONDARY	4	Aux. Gym and Cafeteria	665	Moderate/High	N/A	Completed		
37 Delta		3737021	DELVIEW JR SECONDARY	5	Classrooms	4,850	Moderate/High	N/A	Completed		
37 Delta		3737017	DEVON GARDENS ELEMENTARY	1	Classroom Block	2,620	High	N/A	Completed	N/A	
37 Delta		3737017	DEVON GARDENS ELEMENTARY	2	Gymnasium	820	Low	N/A	Completed		
37 Delta		3737014	ENGLISH BLUFF ELEMENTARY	1	Gymnasium	390	Low	Low	Meets Structural Life Safety Requirements	Medium	
37 Delta		3737014	ENGLISH BLUFF ELEMENTARY	2	2-Storey Classroom	1,750	Moderate/High	Medium	Non Structural Upgrade Required		
37 Delta		3737014	ENGLISH BLUFF ELEMENTARY	3	Single Storey Classroom/Administration	770	Moderate	Medium	Non Structural Upgrade Required		
37 Delta		3737026	GIBSON ELEMENTARY	1	Classroom Block	3,223	Moderate/High	High 3	Structural Upgrade Required	High 3	
37 Delta		3737026	GIBSON ELEMENTARY	2	Gym Block	709	Moderate/High	High 3	Structural Upgrade Required		
37 Delta		3737026	GIBSON ELEMENTARY	3	2000 Classroom Block Addition	?	Low	Low	Meets Structural Life Safety Requirements		
37 Delta		3737024	GRAY ELEMENTARY	1	Classroom, Library (North)	1,560	Moderate	Medium	Non Structural Upgrade Required	Medium	
37 Delta		3737024	GRAY ELEMENTARY	2	Gymnasium, Administration	745	Moderate/High	Medium	Non Structural Upgrade Required		
37 Delta		3737024	GRAY ELEMENTARY	3	Classrooms (South-West)	1,830	Moderate/High	Medium	Non Structural Upgrade Required		
37 Delta		3737025	HAWTHORNE ELEMENTARY	1	Gymnasium	545	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
37 Delta		3737025	HAWTHORNE ELEMENTARY	2	Classrooms	3,020	Moderate/High	Medium	Non Structural Upgrade Required		
37 Delta		3737025	HAWTHORNE ELEMENTARY	3	Classrooms - Portable	450	Low	Low	Meets Structural Life Safety Requirements		
37 Delta		3737008	HEATH ELEMENTARY	1	Gymnasium	620	Low	Low	Meets Structural Life Safety Requirements	Medium	
37 Delta		3737008	HEATH ELEMENTARY	2	Single Storey Classroom	880	Moderate/High	Medium	Non Structural Upgrade Required		
37 Delta		3737008	HEATH ELEMENTARY	3	2-Storey Classroom	2,200	Moderate/High	Medium	Non Structural Upgrade Required		
37 Delta		3737023	HELLINGS ELEMENTARY	1	Classrooms	2,980	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
37 Delta		3737023	HELLINGS ELEMENTARY	2	Gymnasium/Change Room Addition	550	Moderate/High	Medium	Non Structural Upgrade Required		
37 Delta		3737023	HELLINGS ELEMENTARY	3	Multi-Purpose, Office Addition - 1999	?	Low	Low	Meets Structural Life Safety Requirements		
37 Delta		3737035	HOLLY ELEMENTARY	1	Gymnasium	400	Low	Low	Meets Structural Life Safety Requirements	Medium	
37 Delta		3737035	HOLLY ELEMENTARY	2	Classrooms (East)	2,030	Moderate/High	Medium	Non Structural Upgrade Required		
37 Delta		3737035	HOLLY ELEMENTARY	3	Classrooms/Multipurpose room	1,080	Low	Low	Meets Structural Life Safety Requirements		
37 Delta		3737035	HOLLY ELEMENTARY	4	1999 Classroom (West)	?	Low	Low	Meets Structural Life Safety Requirements		
37 Delta		3737030	JARVIS ELEMENTARY	1	Gymnasium	400	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
37 Delta		3737030	JARVIS ELEMENTARY	2	Classroom, Multi Purpose	1,830	Moderate/High	Medium	Non Structural Upgrade Required		
37 Delta		3737030	JARVIS ELEMENTARY	3	Classroom, Library	815	Moderate/High	Medium	Non Structural Upgrade Required		
37 Delta		3737030	JARVIS ELEMENTARY	4	Classrooms - North	540	Moderate	Medium	Non Structural Upgrade Required		
37 Delta		3737001	LADNER ELEMENTARY	1	Gymnasium	440	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
37 Delta		3737001	LADNER ELEMENTARY	2	2-Storey Classroom	2,580	Low/Moderate	Low	Meets Structural Life Safety Requirements		
37 Delta		3737001	LADNER ELEMENTARY	3	1-Storey Classroom	880	Moderate	Medium	Non Structural Upgrade Required		
37 Delta		3737032	MCCLOSKEY ELEMENTARY	1	Classroom/Administration	3,300	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
37 Delta		3737032	MCCLOSKEY ELEMENTARY	2	Gymnasium	400	Low/Moderate	Low	Meets Structural Life Safety Requirements		
37 Delta		3737032	MCCLOSKEY ELEMENTARY	3	Classroom - 2000	?	Low	Low	Meets Structural Life Safety Requirements		
37 Delta		3737012	NORTH DELTA SENIOR SECONDARY	1	Shops	2,120	Moderate	Medium	Non Structural Upgrade Required	Medium	
37 Delta		3737012	NORTH DELTA SENIOR SECONDARY	2	Classrooms	2,300	Moderate	Medium	Non Structural Upgrade Required		
37 Delta		3737012	NORTH DELTA SENIOR SECONDARY	3	Drama/Cafeteria	2,620	Moderate	Medium	Non Structural Upgrade Required		
37 Delta		3737012	NORTH DELTA SENIOR SECONDARY	4	Music room	490	Moderate	Medium	Non Structural Upgrade Required		
37 Delta		3737012	NORTH DELTA SENIOR SECONDARY	5	Library	210	Moderate/High	Medium	Non Structural Upgrade Required		
37 Delta		3737012	NORTH DELTA SENIOR SECONDARY	6	Automotive Shop	850	High	Medium	Non Structural Upgrade Required		
37 Delta		3737012	NORTH DELTA SENIOR SECONDARY	7	Gymnasium/Classrooms/Canopy - 2001	?	Low	Low	Meets Structural Life Safety Requirements		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
37	Delta	3737027	PEBBLE HILL ELEMENTARY	1	Gymnasium	390	Low	Low	Meets Structural Life Safety Requirements	Medium	
37	Delta	3737027	PEBBLE HILL ELEMENTARY	2	Classrooms	2,700	Moderate	Medium	Non Structural Upgrade Required		
37	Delta	3737041	PINEWOOD ELEMENTARY	1	Gymnasium	782	Moderate	N/A	Completed	N/A	
37	Delta	3737041	PINEWOOD ELEMENTARY	2	Classrooms	1,845	Low	N/A	Completed		
37	Delta	3737041	PINEWOOD ELEMENTARY	3	Library/Multipurpose	440	Moderate	N/A	Completed		
37	Delta	3737041	PINEWOOD ELEMENTARY	4	Classrooms (2000)	?	Low	N/A	Completed		
37	Delta	3737033	PORT GUICHON ELEMENTARY	1	Classrooms	2,460	Moderate/High	N/A	Completed	N/A	
37	Delta	3737033	PORT GUICHON ELEMENTARY	2	Gymnasium	890	Moderate/High	N/A	Completed		
37	Delta	3737007	RICHARDSON ELEMENTARY	1	Classrooms	1,500	Low	Low	Meets Structural Life Safety Requirements	Low	
37	Delta	3737007	RICHARDSON ELEMENTARY	2	Gym/Classrooms/Admin. Area - 1998	?	Low	Low	Meets Structural Life Safety Requirements		
37	Delta	3737038	SANDS JR SECONDARY	1	Gymnasium	1,620	Low	Low	Meets Structural Life Safety Requirements	Low	
37	Delta	3737038	SANDS JR SECONDARY	2	Classrooms	6,080	Low/Moderate	Low	Meets Structural Life Safety Requirements		
37	Delta	3737038	SANDS JR SECONDARY	3	Shops	920	Low/Moderate	Low	Meets Structural Life Safety Requirements		
37	Delta	3737040	SEAQUAM SECONDARY	1	Gymnasium	1,375	Moderate	Medium	Non Structural Upgrade Required		
37	Delta	3737040	SEAQUAM SECONDARY	2	Small Gymnasium	940	Moderate	Medium	Non Structural Upgrade Required	Medium	
37	Delta	3737040	SEAQUAM SECONDARY	3	North Wing	7,935	Moderate	Medium	Non Structural Upgrade Required		
37	Delta	3737040	SEAQUAM SECONDARY	4	Theatre/Music	2,220	Moderate	Medium	Non Structural Upgrade Required		
37	Delta	3737040	SEAQUAM SECONDARY	5	Classrooms (Central Wing)	2,168	Moderate	Medium	Non Structural Upgrade Required		
37	Delta	3737040	SEAQUAM SECONDARY	6	Shops	2,595	Moderate	Medium	Non Structural Upgrade Required		
37	Delta	3737037	SOUTH DELTA SECONDARY	1	Gymnasium	1,320	Low/Moderate	NA	Under Construction		
37	Delta	3737037	SOUTH DELTA SECONDARY	2	Auditorium	1,450	Moderate/High	NA	Under Construction	NA	Supported 2012
37	Delta	3737037	SOUTH DELTA SECONDARY	3	Cafeteria	1,230	Moderate/High	NA	Under Construction		
37	Delta	3737037	SOUTH DELTA SECONDARY	4	Two Storey Classrooms	4,100	Moderate/High	NA	Under Construction		
37	Delta	3737037	SOUTH DELTA SECONDARY	5	Classrooms	2,600	Moderate	NA	Under Construction		
37	Delta	3737037	SOUTH DELTA SECONDARY	6	Shops	1,290	Moderate	NA	Under Construction		
37	Delta	3737037	SOUTH DELTA SECONDARY	7	Classrooms/Small Gymnasium (2003)	?	Low	NA	Under Construction		
37	Delta	3737018	SOUTH PARK ELEMENTARY	1	Gymnasium	410	Low	Low	Meets Structural Life Safety Requirements	Medium	
37	Delta	3737018	SOUTH PARK ELEMENTARY	2	Classroom	3,250	Moderate	Medium	Non Structural Upgrade Required		
37	Delta	3737013	SUNSHINE HILLS ELEMENTARY	1	2 storey classrooms (West)	1,900	High	N/A	Completed	N/A	
37	Delta	3737013	SUNSHINE HILLS ELEMENTARY	2	Classrooms (East)	1,280	Moderate/High	N/A	Completed		
37	Delta	3737013	SUNSHINE HILLS ELEMENTARY	3	Gymnasium	450	Low/Moderate	N/A	Completed		
37	Delta	3737013	SUNSHINE HILLS ELEMENTARY	4	Classrooms (South)	500	Moderate/High	N/A	Completed		
37	Delta	3737013	SUNSHINE HILLS ELEMENTARY	5	Covered play area	?	Low	N/A	Completed		
38	Richmond	3838020	ALFRED B DIXON ELEMENTARY	1	West Wing	444	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838020	ALFRED B DIXON ELEMENTARY	2	South Wing	771	Moderate/High	Medium	Non Structural Upgrade Required		
38	Richmond	3838020	ALFRED B DIXON ELEMENTARY	3	North Wing	1,290	Moderate/High	Medium	Non Structural Upgrade Required		
38	Richmond	3838020	ALFRED B DIXON ELEMENTARY	4	Covered Play Area	227	Moderate/High	Medium	Non Structural Upgrade Required		
38	Richmond	3838020	ALFRED B DIXON ELEMENTARY	5	Activity Room	1,130	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838014	BLUNDELL ELEMENTARY	1	North Classroom Wing	900	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838014	BLUNDELL ELEMENTARY	2	Gymnasium	430	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838014	BLUNDELL ELEMENTARY	3	South & East Classroom Wings	1,300	Moderate/High	Medium	Non Structural Upgrade Required		
38	Richmond	3838045	CHARLES E LONDON SECONDARY	1	Classrooms, Gymnasium and Administration	6,336	Low	Low	Meets Structural Life Safety Requirements	Low	
38	Richmond	3838045	CHARLES E LONDON SECONDARY	2	Multipurpose and Classrooms	2,610	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838045	CHARLES E LONDON SECONDARY	3	Gymnasium	1,630	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838029	DANIEL WOODWARD ELEMENTARY	1	original classrooms	725	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838029	DANIEL WOODWARD ELEMENTARY	2	Classroom additions	1,300	Moderate/High	Medium	Non Structural Upgrade Required		
38	Richmond	3838029	DANIEL WOODWARD ELEMENTARY	3	gymnasium	450	Low/Moderate	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838030	DONALD E MCKAY ELEMENTARY	1	West Classroom Wing	1,132	Moderate/High	High 3	Structural Upgrade Required	High 3	
38	Richmond	3838030	DONALD E MCKAY ELEMENTARY	2	East Classroom Wing	522	Moderate	Medium	Non Structural Upgrade Required		
38	Richmond	3838030	DONALD E MCKAY ELEMENTARY	3	Gymnasium	348	Low/Moderate	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838030	DONALD E MCKAY ELEMENTARY	4	North Addition (2001)	?	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838036	ecole des Navigateurs (ALEXANDER KILGOUR ELEMENTARY	1	North Classroom Wing and Administration	1,109	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838036	ecole des Navigateurs (ALEXANDER KILGOUR ELEMENTARY	2	1975 Classroom Wing Addition	515	Low/Moderate	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838036	ecole des Navigateurs (ALEXANDER KILGOUR ELEMENTARY	3	Storage, Changing Rooms and Kitchen Addition	144	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838036	ecole des Navigateurs (ALEXANDER KILGOUR ELEMENTARY	4	Gymnasium	406	Moderate	Medium	Non Structural Upgrade Required		
38	Richmond	3838008	GARDEN CITY ELEMENTARY	1	original classroom block	1,500	Moderate/High	N/A	Completed	N/A	
38	Richmond	3838008	GARDEN CITY ELEMENTARY	2	gymnasium	600	Low/Moderate	N/A	Completed		
38	Richmond	3838008	GARDEN CITY ELEMENTARY	3	Classroom additions	1,000	High	N/A	Completed		
38	Richmond	3838037	HOWARD DE BECK ELEMENTARY	1	1990 original school	1,500	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
38	Richmond	3838037	HOWARD DE BECK ELEMENTARY	2	1990 gymnasium	400	Low/Moderate	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838037	HOWARD DE BECK ELEMENTARY	3	1999 addition	?	Low	Low	Meets Structural Life Safety Requirements		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
38	Richmond	3838031	HUGH BOYD SECONDARY	1	Administration, Classroom and Gymnasium	5,200	Low	Low	Meets Structural Life Safety Requirements	Medium	
38	Richmond	3838031	HUGH BOYD SECONDARY	2	Classroom Block	3,950	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838031	HUGH BOYD SECONDARY	3	Gymnasium	883	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838031	HUGH BOYD SECONDARY	4	Workshops	1,080	High	Medium	Non Structural Upgrade Required		
38	Richmond	3838033	HUGH MCROBERTS SECONDARY	1	SMALL GYMNASIUM	712	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
38	Richmond	3838033	HUGH MCROBERTS SECONDARY	2	MUSIC ROOM	478	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838033	HUGH MCROBERTS SECONDARY	3	GYMNASIUM	705	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838033	HUGH MCROBERTS SECONDARY	4	CENTRAL TEACHING	5,855	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838033	HUGH MCROBERTS SECONDARY	5	SW CLASSROOMS	658	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838033	HUGH MCROBERTS SECONDARY	6	SOUTH SHOPS	231	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838033	HUGH MCROBERTS SECONDARY	7	EAST CLASSROOMS	3,352	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838025	JAMES GILMORE ELEMENTARY	1	One-storey Classrooms and Administration	2,225	Moderate/High	High 3	Supported 2013	High 2	April 2013 - to start 2013.
38	Richmond	3838025	JAMES GILMORE ELEMENTARY	3	Activity Room, Changing Rooms and Storages	813	Low	Medium	Supported 2013		
38	Richmond	3838025	JAMES GILMORE ELEMENTARY	4	1969 Classroom Wing	650	Moderate/High	High 3	Supported 2013		
38	Richmond	3838025	JAMES GILMORE ELEMENTARY	2	1963, 1964 Two-storey Classroom Wing Addition	978	Moderate/High	High 2	Supported 2013		
38	Richmond	3838040	JAMES MCKINNEY ELEMENTARY	1	West block	841	Low	Low	Meets Structural Life Safety Requirements	Medium	
38	Richmond	3838040	JAMES MCKINNEY ELEMENTARY	2	Central block	1,251	High	Medium	Non Structural Upgrade Required		
38	Richmond	3838040	JAMES MCKINNEY ELEMENTARY	3	East block	1,518	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838013	JAMES THOMPSON ELEMENTARY	1	North East Classroom Wing	470	High	Medium	Non Structural Upgrade Required	High 3	
38	Richmond	3838013	JAMES THOMPSON ELEMENTARY	2	Gymnasium	435	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838013	JAMES THOMPSON ELEMENTARY	3	South West Classroom Wing	700	Moderate/High	Medium	Non Structural Upgrade Required		
38	Richmond	3838013	JAMES THOMPSON ELEMENTARY	4	North West Classroom Wing	459	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838013	JAMES THOMPSON ELEMENTARY	5	Administration Wing	120	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838013	JAMES THOMPSON ELEMENTARY	6	Central Block	365	Moderate/High	High 3	Structural Upgrade Required		
38	Richmond	3838013	JAMES THOMPSON ELEMENTARY	7	East Central Classroom Wing	383	Moderate/High	Medium	Non Structural Upgrade Required		
38	Richmond	3838013	JAMES THOMPSON ELEMENTARY	8	South East Classroom Wing	470	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838013	JAMES THOMPSON ELEMENTARY	9	Covered Play Area	240	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838016	JAMES WHITESIDE ELEMENTARY	1	Original Classrooms	1,800	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838016	JAMES WHITESIDE ELEMENTARY	2	Gym Addition	450	Moderate	Medium	Non Structural Upgrade Required		
38	Richmond	3838016	JAMES WHITESIDE ELEMENTARY	3	Classroom Additions	425	Moderate/High	Medium	Non Structural Upgrade Required		
38	Richmond	3838052	JOHN G DIEFENBAKER ELEMENTARY	1	South East Classroom Wing	2,200	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838052	JOHN G DIEFENBAKER ELEMENTARY	2	Relocatable Classroom Blocks	420	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838052	JOHN G DIEFENBAKER ELEMENTARY	3	West Classroom Wing	640	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838021	JOHN T ERRINGTON ELEMENTARY	1	Main Building	1,800	Moderate	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838021	JOHN T ERRINGTON ELEMENTARY	2	Gymnasium Addition	550	Moderate/High	Medium	Non Structural Upgrade Required		
38	Richmond	3838021	JOHN T ERRINGTON ELEMENTARY	3	1975 Gymnasium Addition	1,000	Moderate	Medium	Non Structural Upgrade Required		
38	Richmond	3838048	KINGSWOOD ELEMENTARY	1	original classroom block	1,500	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
38	Richmond	3838048	KINGSWOOD ELEMENTARY	2	gymnasium	700	Low/Moderate	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838048	KINGSWOOD ELEMENTARY	3	classroom additions	1,000	Low/Moderate	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838041	MANOAH STEVES ELEMENTARY	1	Administration Wing	190	High	High 3	Structural Upgrade Required	High 3	
38	Richmond	3838041	MANOAH STEVES ELEMENTARY	2	South & West Classroom Wing	1,405	Moderate/High	High 3	Structural Upgrade Required		
38	Richmond	3838041	MANOAH STEVES ELEMENTARY	3	North Classroom Wing	1,430	Low/Moderate	Medium	Non Structural Upgrade Required		
38	Richmond	3838041	MANOAH STEVES ELEMENTARY	4	Gymnasium	405	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838046	MAPLE LANE ELEMENTARY	1	Classroom Wing (1974,1982) & Administration	1,600	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838046	MAPLE LANE ELEMENTARY	2	North Classroom Addition	401	Low/Moderate	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838046	MAPLE LANE ELEMENTARY	3	Gymnasium	384	Moderate	Medium	Non Structural Upgrade Required		
38	Richmond	3838044	MATTHEW MCNAIR SECONDARY	1	Original Classrooms	6,500	Moderate	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838044	MATTHEW MCNAIR SECONDARY	2	Original Gymnasium	725	Moderate	Medium	Non Structural Upgrade Required		
38	Richmond	3838044	MATTHEW MCNAIR SECONDARY	3	Classroom Addition	1,500	Moderate	Medium	Non Structural Upgrade Required		
38	Richmond	3838044	MATTHEW MCNAIR SECONDARY	4	1993 & 1995 Additions	?	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	???	MITCHELL ELEMENTARY	2	1960 Annex		NA	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	???	MITCHELL ELEMENTARY	3	1975 Gym		NA	Medium	Non Structural Upgrade Required		
38	Richmond	???	MITCHELL ELEMENTARY	4	1991 Addition		NA	Low	Meets Structural Life Safety Requirements		
38	Richmond	???	MITCHELL ELEMENTARY	5	1999 Addition		NA	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838047	QUILCHENA ELEMENTARY	1	Classroom Wing (1974,1982) and Administration	1,583	Moderate/High	High 3	Structural Upgrade Required	High 3	
38	Richmond	3838047	QUILCHENA ELEMENTARY	2	West Classroom Addition (1988)	401	Low/Moderate	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838047	QUILCHENA ELEMENTARY	3	Gymnasium	384	Moderate	Medium	Non Structural Upgrade Required		
38	Richmond	3838024	R C PALMER SECONDARY	1	Original Gymnasium	100	Moderate	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838024	R C PALMER SECONDARY	2	1965 Shops Addition	750	Moderate	Medium	Non Structural Upgrade Required		
38	Richmond	3838024	R C PALMER SECONDARY	3	1976 Classroom Addition	4,300	Moderate	Medium	Non Structural Upgrade Required		
38	Richmond	3838024	R C PALMER SECONDARY	4	1998 addition	?	Low	Low	Meets Structural Life Safety Requirements		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
38	Richmond	3838009	R M GRAUER ELEMENTARY	1	Gymnasium	436	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838009	R M GRAUER ELEMENTARY	2	Two-storey Classroom Wing	1,784	High	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838009	R M GRAUER ELEMENTARY	3	One-storey Classroom Wing	2,131	Moderate	Medium	Non Structural Upgrade Required		
38	Richmond	3838051	RIDEAU PARK ELEMENTARY	1	Classroom Wing	1,452	Low	Low	Meets Structural Life Safety Requirements	Low	
38	Richmond	3838051	RIDEAU PARK ELEMENTARY	2	Gymnasium	244	Low/Moderate	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838017	ROBERT J TAIT ELEMENTARY	1	Original Classrooms	1,000	Moderate	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838017	ROBERT J TAIT ELEMENTARY	2	Gymnasium Addition	425	Moderate	Medium	Non Structural Upgrade Required		
38	Richmond	3838017	ROBERT J TAIT ELEMENTARY	3	Phase I, II, III Additions	?	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838035	SAMUEL BRIGHOUSE ELEMENTARY	1	West Classroom Wing	720	Moderate/High	N/A	Completed		
38	Richmond	3838035	SAMUEL BRIGHOUSE ELEMENTARY	2	East Classroom Wing	720	Moderate/High	N/A	Completed		
38	Richmond	3838035	SAMUEL BRIGHOUSE ELEMENTARY	3	Gymnasium	875	High	N/A	Completed	N/A	
38	Richmond	3838035	SAMUEL BRIGHOUSE ELEMENTARY	4	Multipurpose / Library Wing	635	High	N/A	Completed		
38	Richmond	3838035	SAMUEL BRIGHOUSE ELEMENTARY	5	North Classroom Wing	1,635	Moderate/High	N/A	Completed		
38	Richmond	3838035	SAMUEL BRIGHOUSE ELEMENTARY	6	Covered Play Area	146	Moderate/High	N/A	Completed		
38	Richmond	3838010	SEA ISLAND ELEMENTARY	1	Original School	1,500	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838010	SEA ISLAND ELEMENTARY	2	Gymnasium Addition	550	Low/Moderate	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838012	SIDAWAY ELEMENTARY	1	original classrooms	600	Moderate/High	Medium	Inactive	Medium	
38	Richmond	3838012	SIDAWAY ELEMENTARY	2	classroom addition	400	Moderate/High	Medium	Inactive		
38	Richmond	3838012	SIDAWAY ELEMENTARY	3	gymnasium	300	Moderate	Medium	Inactive		
38	Richmond	3838018	STEVESTON SECONDARY	1	Original School	5,300	Moderate/High	N/A	Completed		
38	Richmond	3838018	STEVESTON SECONDARY	2	Gymnasium	900	Moderate/High	N/A	Completed	N/A	
38	Richmond	3838018	STEVESTON SECONDARY	3	1977 Plus Additions	1,500	Moderate	N/A	Completed		
38	Richmond	3838019	THOMAS KIDD ELEMENTARY	1	Original Classrooms	2,000	Moderate	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838019	THOMAS KIDD ELEMENTARY	2	Gymnasium Addition	450	Low/Moderate	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838053	TOMEKICHI HOMMA ELEMENTARY	1	1989 Original School	3,908	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
38	Richmond	3838053	TOMEKICHI HOMMA ELEMENTARY	2	2000 East Classroom Wing Addition	324	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838023	TOMSETT ELEMENTARY	1	1959 classrooms	700	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838023	TOMSETT ELEMENTARY	2	1988 gymnasium addition	700	Low/Moderate	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838023	TOMSETT ELEMENTARY	3	1999 addition	?	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838027	W D FERRIS ELEMENTARY	1	Original Classrooms	1,000	Moderate	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838027	W D FERRIS ELEMENTARY	2	Gym Addition	225	Low/Moderate	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838027	W D FERRIS ELEMENTARY	3	Classrooms Addition	900	Moderate	Medium	Non Structural Upgrade Required		
38	Richmond	3838027	W D FERRIS ELEMENTARY	4	1990 Addition	1,000	Moderate	Medium	Non Structural Upgrade Required		
38	Richmond	3838026	WALTER LEE ELEMENTARY	1	Original Classrooms	1,200	Moderate	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838026	WALTER LEE ELEMENTARY	2	Gymnasium Addition	450	Low/Moderate	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838026	WALTER LEE ELEMENTARY	3	Classroom Addition	1,200	Moderate/High	Medium	Non Structural Upgrade Required		
38	Richmond	3838026	WALTER LEE ELEMENTARY	4	1999 Addition	700	Low	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838049	WESTWIND ELEMENTARY	1	West Classroom Wing	1,440	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838049	WESTWIND ELEMENTARY	2	East Classroom Wing	1,150	Moderate/High	Medium	Non Structural Upgrade Required		
38	Richmond	3838049	WESTWIND ELEMENTARY	3	North East Classroom Wing	460	Moderate/High	Medium	Non Structural Upgrade Required		
38	Richmond	3838049	WESTWIND ELEMENTARY	4	Gymnasium Block	550	Moderate/High	Medium	Non Structural Upgrade Required		
38	Richmond	3838049	WESTWIND ELEMENTARY	5	Multipurpose Wing	190	Low/Moderate	Medium	Non Structural Upgrade Required		
38	Richmond	3838043	WILLIAM BRIDGE ELEMENTARY	1	original classroom block	2,600	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838043	WILLIAM BRIDGE ELEMENTARY	2	gymnasium & change rooms	650	Moderate/High	Medium	Non Structural Upgrade Required		
38	Richmond	3838015	WILLIAM COOK ELEMENTARY	1	Original classroom building	900	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
38	Richmond	3838015	WILLIAM COOK ELEMENTARY	2	1962, 1964, 1971 classrooms	800	Moderate/High	Medium	Non Structural Upgrade Required		
38	Richmond	3838015	WILLIAM COOK ELEMENTARY	3	Gymnasium	425	Low/Moderate	Low	Meets Structural Life Safety Requirements		
38	Richmond	3838015	WILLIAM COOK ELEMENTARY	4	1999 Addition	?	Low	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939032	ADMIRAL SEYMOUR ELEMENTARY	1	1902 Classroom	2,900	Moderate/High	High 1	Structural Upgrade Required	High 1	
39	Vancouver	3939032	ADMIRAL SEYMOUR ELEMENTARY	2	1907 Classroom	1,350	Moderate/High	High 2	Structural Upgrade Required		
39	Vancouver	3939032	ADMIRAL SEYMOUR ELEMENTARY	3	Gymnasium/Cafeteria	900	Moderate/High	High 3	Structural Upgrade Required		
39	Vancouver	3939067	BAYVIEW COMMUNITY ELEMENTARY	1	Classrooms	3,630	High	High 1	Supported 2013	High 1	April 2013 - to start 2015.
39	Vancouver	3939067	BAYVIEW COMMUNITY ELEMENTARY	2	Gymnasium	495	High	High 1	Supported 2013		
39	Vancouver	3939067	BAYVIEW COMMUNITY ELEMENTARY	3	Multipurpose	400	High	High 2	Supported 2013		
39	Vancouver	3939130	BRITANNIA COMMUNITY ELEMENTARY	1	Classroom	1,900	Moderate	N/A	Completed	N/A	
39	Vancouver	3939004	BRITANNIA COMMUNITY SECONDARY	1	CLASSROOM BLOCK (1911)	6,763	Moderate	Low	Meets Structural Life Safety Requirements	High 1	
39	Vancouver	3939004	BRITANNIA COMMUNITY SECONDARY	2	EXTENSION (1965)	4,090	High	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939004	BRITANNIA COMMUNITY SECONDARY	3	SCIENCE ADDITION (1973)	400	Low	High 1	Structural Upgrade Required		
39	Vancouver	3939004	BRITANNIA COMMUNITY SECONDARY	4	GYMNASIUM WING (1954)	2,800	Moderate	Medium	Non Structural Upgrade Required		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
39	Vancouver	3939088	CAPTAIN JAMES COOK ELEMENTARY	1	North Classrooms	1,700	High	N/A	Completed		
39	Vancouver	3939088	CAPTAIN JAMES COOK ELEMENTARY	2	Gymnasium	465	Moderate/High	N/A	Completed		
39	Vancouver	3939088	CAPTAIN JAMES COOK ELEMENTARY	3	Library	310	Moderate/High	N/A	Completed	N/A	
39	Vancouver	3939088	CAPTAIN JAMES COOK ELEMENTARY	4	Interior Classrooms	1,070	High	N/A	Completed		
39	Vancouver	3939088	CAPTAIN JAMES COOK ELEMENTARY	5	South Classrooms	?	Low	N/A	Completed		
39	Vancouver	3939094	CARNARVON COMMUNITY ELEMENTARY	1	Gymnasium	756	High	High 3	Structural Upgrade Required		
39	Vancouver	3939094	CARNARVON COMMUNITY ELEMENTARY	2	Central Classroom/Library	1,485	Moderate/High	High 3	Structural Upgrade Required	High 3	
39	Vancouver	3939094	CARNARVON COMMUNITY ELEMENTARY	3	South Classrooms	1,584	Moderate/High	High 3	Structural Upgrade Required		
39	Vancouver	3939137	CHAMPLAIN HEIGHTS ANNEX	1	Gymnasium	467	Moderate	Medium	Non Structural Upgrade Required	Medium	
39	Vancouver	3939137	CHAMPLAIN HEIGHTS ANNEX	2	Classrooms	1,100	Moderate	Medium	Non Structural Upgrade Required		
39	Vancouver	3939128	CHAMPLAIN HEIGHTS COMMUNITY ELEMENTARY	1	Classrooms	2,127	High	High 3	Structural Upgrade Required		
39	Vancouver	3939128	CHAMPLAIN HEIGHTS COMMUNITY ELEMENTARY	2	Gymnasium	510	Moderate/High	High 3	Structural Upgrade Required		
39	Vancouver	3939128	CHAMPLAIN HEIGHTS COMMUNITY ELEMENTARY	3	Community Facilities Addition	465	Moderate/High	High 3	Structural Upgrade Required	High 3	
39	Vancouver	3939128	CHAMPLAIN HEIGHTS COMMUNITY ELEMENTARY	4	West Addition	?	Low	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939124	CHARLES DICKENS ANNEX	1	Gym	167	High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939124	CHARLES DICKENS ANNEX	2	Classroom	1,143	High	Medium	Non Structural Upgrade Required	Medium	
39	Vancouver	3939059	CHARLES DICKENS ELEMENTARY	1	Classroom Wing	4,300	High	N/A	Completed		
39	Vancouver	3939059	CHARLES DICKENS ELEMENTARY	2	Gymnasium Wing	1,000	High	N/A	Completed	N/A	
39	Vancouver	3939117	CHIEF MAQUINNA ANNEX	1	Classroom	1,215	Moderate/High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939117	CHIEF MAQUINNA ANNEX	2	Gymnasium	165	Moderate	Medium	Non Structural Upgrade Required	Medium	
39	Vancouver	3939089	CHIEF MAQUINNA ELEMENTARY	1	1959 Two Storey Classroom	980	Moderate	High 3	Structural Upgrade Required		
39	Vancouver	3939089	CHIEF MAQUINNA ELEMENTARY	2	1959 Classroom	480	Moderate	Medium	Structural Upgrade Required		
39	Vancouver	3939089	CHIEF MAQUINNA ELEMENTARY	3	1952 Classroom	1,230	Moderate	High 3	Non Structural Upgrade Required	High 3	November 2012 - Corrected by APEGBC based on 2010 assessment data. Overall risk rating reduced from High 1 to High 3
39	Vancouver	3939089	CHIEF MAQUINNA ELEMENTARY	4	1959 Gymnasium	380	Moderate/High	Medium	Structural Upgrade Required		
39	Vancouver	3939060	DAVID LIVINGSTONE ELEMENTARY	1	Main Building	1,653	High	High 1	Structural Upgrade Required		
39	Vancouver	3939060	DAVID LIVINGSTONE ELEMENTARY	2	Classrooms	1,665	Moderate/High	High 1	Structural Upgrade Required	High 1	
39	Vancouver	3939060	DAVID LIVINGSTONE ELEMENTARY	3	Gymnasium	717	Low/Moderate	Medium	Non Structural Upgrade Required		
39	Vancouver	3939035	DAVID LLOYD GEORGE ELEMENTARY	1	Original Building	3,300	High	High 1	Supported 2013		
39	Vancouver	3939035	DAVID LLOYD GEORGE ELEMENTARY	2	1954 Addition	1,534	Moderate	High 3	Supported 2013	High 1	April 2013 - to start 2015.
39	Vancouver	3939090	DAVID OPPENHEIMER ELEMENTARY	1	East Classroom	2,200	Moderate	Medium	Non Structural Upgrade Required		
39	Vancouver	3939090	DAVID OPPENHEIMER ELEMENTARY	2	West Classroom	1,215	Moderate	Medium	Non Structural Upgrade Required	Medium	
39	Vancouver	3939090	DAVID OPPENHEIMER ELEMENTARY	3	Gymnasium	700	High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939018	DAVID THOMPSON SECONDARY	1	Auditorium, classroom	1,850	High	High 2	Supported 2013		April 2013 - to start 2013.
39	Vancouver	3939018	DAVID THOMPSON SECONDARY	2	South wing classroom	4,100	High	High 1	Supported 2013		
39	Vancouver	3939018	DAVID THOMPSON SECONDARY	3	West wing classroom	3,200	Moderate	High 1	Supported 2013		
39	Vancouver	3939018	DAVID THOMPSON SECONDARY	4	Gymnasium and change rooms	2,350	High	High 1	Supported 2013		
39	Vancouver	3939018	DAVID THOMPSON SECONDARY	5	Multi-purpose (shops, cafeteria)	3,000	Moderate/High	High 2	Supported 2013	High 1	
39	Vancouver	3939018	DAVID THOMPSON SECONDARY	6	Workshops	1,250	High	High 3	Supported 2013		
39	Vancouver	3939018	DAVID THOMPSON SECONDARY	7	NW Wing classroom	1,550	High	High 1	Supported 2013		
39	Vancouver	3939018	DAVID THOMPSON SECONDARY	8	Shop	420	Moderate/High	Medium	Supported 2013		
39	Vancouver	3939095	DR A R LORD ELEMENTARY	1	Classroom	1,590	Moderate/High	High 3	Structural Upgrade Required		
39	Vancouver	3939095	DR A R LORD ELEMENTARY	2	Gymnasium	1,465	High	High 3	Structural Upgrade Required	High 3	
39	Vancouver	3939095	DR A R LORD ELEMENTARY	3	Annex Building	1,200	Moderate	Medium	Non Structural Upgrade Required		
39	Vancouver	3939105	DR GEORGE M WEIR ELEMENTARY	1	Classroom Wing	2,050	High	High 3	Supported (May 2012)		
39	Vancouver	3939105	DR GEORGE M WEIR ELEMENTARY	2	Library Wing	315	High	Medium	Supported (May 2012)		
39	Vancouver	3939105	DR GEORGE M WEIR ELEMENTARY	3	Gymnasium Wing	610	High	High 1	Supported (May 2012)	High 1	
39	Vancouver	3939105	DR GEORGE M WEIR ELEMENTARY	4	Classroom Wing	?	Low	Low	Supported (May 2012)		
39	Vancouver	3939115	DR H N MACCORKINDALE ELEM	1	South Classroom Wing	1,140	Moderate/High	High 2	Structural Upgrade Required		
39	Vancouver	3939115	DR H N MACCORKINDALE ELEM	2	North Classroom Wing	1,750	High	High 2	Structural Upgrade Required	High 2	
39	Vancouver	3939115	DR H N MACCORKINDALE ELEM	3	Gymnasium Wing	920	High	High 2	Structural Upgrade Required		
39	Vancouver	3939097	DR R E MCKECHNIE ELEMENTARY	1	Original Building - Gym	555	Moderate	Medium	Non Structural Upgrade Required		
39	Vancouver	3939097	DR R E MCKECHNIE ELEMENTARY	2	Original Building - Classroom - Office	1,410	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
39	Vancouver	3939097	DR R E MCKECHNIE ELEMENTARY	3	South Addition - Classroom	455	Moderate/High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939097	DR R E MCKECHNIE ELEMENTARY	4	South Addition - Lunchroom	320	Moderate/High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939104	DR. ANNIE B. JAMIESON ELEMENTARY	1	Old Building - Classrooms - Office	1,692	High	High 2	Supported 2013		
39	Vancouver	3939104	DR. ANNIE B. JAMIESON ELEMENTARY	2	First South Addition - Classrooms	822	Moderate/High	High 1	Supported 2013		April 2013 - to start 2014.
39	Vancouver	3939104	DR. ANNIE B. JAMIESON ELEMENTARY	3	Old Building - Gym	1,032	Moderate/High	High 3	Supported 2013	High 1	
39	Vancouver	3939104	DR. ANNIE B. JAMIESON ELEMENTARY	4	Second South Addition	?	Low	Low	Supported 2013		
39	Vancouver	3939132	ECOLE JULES QUESNEL ELEMENTARY	1	Main Classrooms	1,950	High	N/A	Completed		
39	Vancouver	3939132	ECOLE JULES QUESNEL ELEMENTARY	2	South Classrooms	1,050	High	N/A	Completed	N/A	
39	Vancouver	3939132	ECOLE JULES QUESNEL ELEMENTARY	3	Gymnasium	600	High	N/A	Completed		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
39	Vancouver	3939071	EDITH CAVELL ELEMENTARY	1	Classroom	2,200	High	High 1	Supported 2013	High 1	April 2013 - to start 2015.
39	Vancouver	3939071	EDITH CAVELL ELEMENTARY	2	Gymnasium	700	Moderate	High 1	Supported 2013		
39	Vancouver	3939044	EMILY CARR ELEMENTARY	1	84A	1,420	High	High 3	Structural Upgrade Required	High 1	
39	Vancouver	3939044	EMILY CARR ELEMENTARY	3	Main Building	1,475	Moderate/High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939044	EMILY CARR ELEMENTARY	2	84D	480	Moderate	Medium	Non Structural Upgrade Required		
39	Vancouver	3939044	EMILY CARR ELEMENTARY	4	Gymnasium	765	Moderate	High 1	Structural Upgrade Required		
39	Vancouver	3939022	ERIC HAMBER SECONDARY	1	Classroom	6,700	Moderate/High	High 1	Supported 2013	High 1	April 2013 - to start 2015.
39	Vancouver	3939022	ERIC HAMBER SECONDARY	2	Auditorium - Classroom	1,900	High	High 2	Supported 2013		
39	Vancouver	3939022	ERIC HAMBER SECONDARY	3	Gymnasium	1,650	High	High 3	Supported 2013		
39	Vancouver	3939022	ERIC HAMBER SECONDARY	4	Cafeteria - Administration	1,310	Moderate/High	High 1	Supported 2013		
39	Vancouver	3939022	ERIC HAMBER SECONDARY	5	Workshop	930	Moderate	High 1	Supported 2013		
39	Vancouver	3939022	ERIC HAMBER SECONDARY	6	Workshop	240	High	High 3	Supported 2013		
39	Vancouver	3939022	ERIC HAMBER SECONDARY	7	Library - Lecture Hall	6,700	Moderate	High 1	Supported 2013		
39	Vancouver	3939022	ERIC HAMBER SECONDARY	8	Gym	300	High	High 3	Supported 2013		
39	Vancouver	3939022	ERIC HAMBER SECONDARY	9		1,403		High 2	Supported 2013		
39	Vancouver	3939022	ERIC HAMBER SECONDARY	10		889		High 1	Supported 2013		
39	Vancouver	3939022	ERIC HAMBER SECONDARY	11		485		High 3	Supported 2013		
39	Vancouver	3939022	ERIC HAMBER SECONDARY	12		471		High 3	Supported 2013		
39	Vancouver	3939136	FALSE CREEK ELEMENTARY	1	Classrooms	5,200	High	High 2	Structural Upgrade Required	High 2	
39	Vancouver	3939136	FALSE CREEK ELEMENTARY	2	Gymnasium	1,300	Moderate/High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939051	FLORENCE NIGHTINGALE ELEMENTARY	1	Original Building	3,372	High	High 1	Structural Upgrade Required	High 1	
39	Vancouver	3939051	FLORENCE NIGHTINGALE ELEMENTARY	2	North Addition - Gym	540	Moderate	High 1	Structural Upgrade Required		
39	Vancouver	3939100	G T CUNNINGHAM ELEMENTARY	1	East Classroom	1,550	Moderate	Medium	Non Structural Upgrade Required	High 1	
39	Vancouver	3939100	G T CUNNINGHAM ELEMENTARY	2	North Classroom	1,365	Moderate/High	High 3	Structural Upgrade Required		
39	Vancouver	3939100	G T CUNNINGHAM ELEMENTARY	3	Gymnasium	780	Moderate	High 1	Structural Upgrade Required		
39	Vancouver	3939100	G T CUNNINGHAM ELEMENTARY	4	2002 Addition	?	Low	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939121	GARIBALDI ANNEX	1	Classroom	1,160	High	Medium	Non Structural Upgrade Required	Medium	
39	Vancouver	3939121	GARIBALDI ANNEX	2	Activity/Office	485	Moderate	Medium	Non Structural Upgrade Required		
39	Vancouver	3939121	GARIBALDI ANNEX	3	Washrooms	132	Moderate/High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939116	GENERAL BROCK ANNEX	1	Main Building	1,774	Moderate	N/A	Completed	N/A	
39	Vancouver	3939037	GENERAL BROCK ELEMENTARY	1	15A-classroom	1,920	Moderate/High	High 3	Structural Upgrade Required		
39	Vancouver	3939037	GENERAL BROCK ELEMENTARY	2	15B-classroom	405	Moderate	High 3	Structural Upgrade Required	High 2	
39	Vancouver	3939037	GENERAL BROCK ELEMENTARY	3	15C addition-Classrooms	1,200	Moderate/High	High 2	Structural Upgrade Required		
39	Vancouver	3939037	GENERAL BROCK ELEMENTARY	4	15C-gym	1,340	Moderate	Medium	Non Structural Upgrade Required		
39	Vancouver	3939052	GENERAL GORDON ELEMENTARY	1	Classroom	4,000	High	High 1	Proceeding to Construction	High 1	
39	Vancouver	3939052	GENERAL GORDON ELEMENTARY	2	Gymnasium/Auditorium	455	High	High 1	Proceeding to Construction		
39	Vancouver	3939052	GENERAL GORDON ELEMENTARY	3	Multipurpose/Lunchroom	265	Moderate/High	High 3	Proceeding to Construction		
39	Vancouver	3939045	GENERAL WOLFE ELEMENTARY	1	Main Building	3,651	High	High 1	Supported 2013	High 1	April 2013 - to start 2015.
39	Vancouver	3939045	GENERAL WOLFE ELEMENTARY	2	Gymnasium	747	Moderate	Medium	Supported 2013		
39	Vancouver	3939045	GENERAL WOLFE ELEMENTARY	3	Wood Frame Classrooms	335	Moderate/High	High 3	Supported 2013	High 1	
39	Vancouver	3939014	GLADSTONE SECONDARY	1	East Wing Classroom	4,200	High	High 1	Structural Upgrade Required		
39	Vancouver	3939014	GLADSTONE SECONDARY	2	Middle Wing Classroom	2,350	High	High 1	Structural Upgrade Required		
39	Vancouver	3939014	GLADSTONE SECONDARY	3	Shops	1,250	High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939014	GLADSTONE SECONDARY	4	Cafeteria	1,100	Moderate/High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939014	GLADSTONE SECONDARY	5	North Wing Classroom - Auditorium	5,050	High	High 3	Structural Upgrade Required		
39	Vancouver	3939014	GLADSTONE SECONDARY	6	Gymnasiums and Classroom	2,700	High	High 2	Structural Upgrade Required		
39	Vancouver	3939014	GLADSTONE SECONDARY	7	Workshops	1,900	High	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939109	GRAHAM BRUCE COMMUNITY ELEMENTARY	1	Original (1963)	1,725	Moderate/High	High 3	Structural Upgrade Required	High 1	
39	Vancouver	3939109	GRAHAM BRUCE COMMUNITY ELEMENTARY	2	Extension (1968)	1,620	Low	High 1	Structural Upgrade Required		
39	Vancouver	3939076	GRANDVIEW ELEMENTARY	1	1926 Classroom	2,100	High	High 1	Structural Upgrade Required	High 1	
39	Vancouver	3939076	GRANDVIEW ELEMENTARY	2	Cafeteria/Auditorium	200	Moderate/High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939076	GRANDVIEW ELEMENTARY	3	Gymnasium	370	Low/Moderate	High 3	Structural Upgrade Required		
39	Vancouver	3939076	GRANDVIEW ELEMENTARY	4	Library	185	Low/Moderate	High 3	Structural Upgrade Required		
39	Vancouver	3939061	HASTINGS COMMUNITY ELEMENTARY	1	Classroom Block	4,080	Low	Low	Meets Structural Life Safety Requirements	Low	
39	Vancouver	3939061	HASTINGS COMMUNITY ELEMENTARY	2	1996 Link	?	Low	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939061	HASTINGS COMMUNITY ELEMENTARY	3	Gym	750	Low	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939061	HASTINGS COMMUNITY ELEMENTARY	4	2003 addition	?	Low	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939053	HENRY HUDSON ELEMENTARY	1	Main Classroom	3,930	High	High 1	Structural Upgrade Required	High 1	
39	Vancouver	3939053	HENRY HUDSON ELEMENTARY	2	Gymnasium/stage	660	Moderate	High 3	Structural Upgrade Required		
39	Vancouver	3939053	HENRY HUDSON ELEMENTARY	3		140		High 3	Structural Upgrade Required		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
39	Vancouver	3939063	J. W. SEXSMITH COMMUNITY ELEMENTARY	1	North addition-Gym	1,552	High	N/A	Completed	N/A	
39	Vancouver	3939063	J. W. SEXSMITH COMMUNITY ELEMENTARY	2	South addition-Classrooms	1,314	Moderate/High	N/A	Completed		
39	Vancouver	3939063	J. W. SEXSMITH COMMUNITY ELEMENTARY	3	old building-office-classroom-library	2,291	High	N/A	Completed		
39	Vancouver	3939063	J. W. SEXSMITH COMMUNITY ELEMENTARY	4	Wood frame building	204	Moderate/High	N/A	Completed	Medium	
39	Vancouver	3939118	JOHN HENDERSON ANNEX	1	Classroom Wing	760	Moderate/High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939118	JOHN HENDERSON ANNEX	2	Administrative Wing	475	Moderate/High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939118	JOHN HENDERSON ANNEX	3	Gymnasium Wing	160	Moderate/High	Medium	Non Structural Upgrade Required	High 3	
39	Vancouver	3939106	JOHN HENDERSON ELEMENTARY	1	(1954) ORIGINAL	1,565	Moderate/High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939106	JOHN HENDERSON ELEMENTARY	2	(1962) EXTENSION 1	2,015	Moderate/High	High 3	Structural Upgrade Required		
39	Vancouver	3939106	JOHN HENDERSON ELEMENTARY	3	(POST 1990) EXTENSION 2	?	Low	Low	Meets Structural Life Safety Requirements	N/A	
39	Vancouver	3939062	JOHN NORQUAY ELEMENTARY	1	Main Building	5,421	Low/Moderate	N/A	Completed		
39	Vancouver	3939062	JOHN NORQUAY ELEMENTARY	2	1994 Addition	?	Low	N/A	Completed		
39	Vancouver	3939062	JOHN NORQUAY ELEMENTARY	3	Gymnasium	785	Moderate	N/A	Completed	High 1	
39	Vancouver	3939062	JOHN NORQUAY ELEMENTARY	4	1999 Addition	?	Low	N/A	Completed		
39	Vancouver	3939007	JOHN OLIVER SECONDARY	1	East Wing Classrooms (1953)	4,428	High	High 2	Supported		
39	Vancouver	3939007	JOHN OLIVER SECONDARY	2	Auditorium (1953)	2,103	High	High 3	Supported	High 1	November 2012 - Detailed study (SPIR) changed number of blocks from 11 to 9. Overall risk remains as High 1 for the facility.
39	Vancouver	3939007	JOHN OLIVER SECONDARY	3	Shops & Cafeteria (1953)	2,578	Moderate/High	High 1	Supported		
39	Vancouver	3939007	JOHN OLIVER SECONDARY	4	North & West Wing Classrooms (1948)	7,125	High	High 1	Supported		
39	Vancouver	3939007	JOHN OLIVER SECONDARY	5	Gymnasium & Library (1948)	m2 (Lib)	High	High 1	Supported		
39	Vancouver	3939007	JOHN OLIVER SECONDARY	6	Small Gymnasium (1939)	960	Moderate/High	High 3	Supported		
39	Vancouver	3939007	JOHN OLIVER SECONDARY	7	Vocational Shops (1965)	1,875	High	High 1	Supported		
39	Vancouver	3939007	JOHN OLIVER SECONDARY	8	Drama (1925)	198	High	High 2	Supported		
39	Vancouver	3939007	JOHN OLIVER SECONDARY	9	Learning Centres (1926)	1,530	High	High 1	Supported		
39	Vancouver	3939113	KERRISDALE ANNEX	1	Activity Room	461	Moderate/High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939113	KERRISDALE ANNEX	2	Central Classroom	461	Moderate/High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939113	KERRISDALE ANNEX	3	East Classrooms	487	Moderate/High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939038	KERRISDALE ELEMENTARY	1	Original (1921)	2,770	High	N/A	Completed	N/A	
39	Vancouver	3939038	KERRISDALE ELEMENTARY	2	Extension (1924)	830	High	N/A	Completed		
39	Vancouver	3939038	KERRISDALE ELEMENTARY	3	Addition (1956)	1,800	Moderate	N/A	Completed		
39	Vancouver	3939016	KILLARNEY SECONDARY	3	1956 Cafeteria and Gym	3,460	High	High 1	Supported 2013	High 1	April 2013 - to start 2013.
39	Vancouver	3939016	KILLARNEY SECONDARY	4	1961 Classroom/Auditorium	3,730	Moderate/High	High 1	Supported 2013		
39	Vancouver	3939016	KILLARNEY SECONDARY	5	1961 Gym/Shop Addition	1,265	Moderate/High	High 1	Supported 2013		
39	Vancouver	3939016	KILLARNEY SECONDARY	6	1967 Science/Shops	3,080	Moderate/High	High 1	Supported 2013		
39	Vancouver	3939016	KILLARNEY SECONDARY	1	1956 Classroom	8,000	Moderate/High	High 2	Supported 2013		
39	Vancouver	3939016	KILLARNEY SECONDARY	2	1956 Workshop	1,600	Moderate/High	High 2	Supported 2013		
39	Vancouver	3939001	KING GEORGE SECONDARY	1	Classrooms	5,200	High	High 1	Structural Upgrade Required	High 1	
39	Vancouver	3939001	KING GEORGE SECONDARY	2	Gymnasium	1,670	Low/Moderate	High 3	Structural Upgrade Required		
39	Vancouver	3939006	KITSILANO SECONDARY	1	Shops	3,000	High	High 3	Proceeding to Construction	High 1	
39	Vancouver	3939006	KITSILANO SECONDARY	2	South Gymnasium	965	High	Medium	Proceeding to Construction		
39	Vancouver	3939006	KITSILANO SECONDARY	3	Metalworks & Drama	750	High	High 1	Proceeding to Construction		
39	Vancouver	3939006	KITSILANO SECONDARY	4	Change Rooms	1,900	Low/Moderate	High 2	Proceeding to Construction		
39	Vancouver	3939006	KITSILANO SECONDARY	5	Auditorium/North Gym	1,850	High	High 1	Proceeding to Construction		
39	Vancouver	3939006	KITSILANO SECONDARY	6	East Classrooms	4,190	High	High 2	Proceeding to Construction		
39	Vancouver	3939006	KITSILANO SECONDARY	7	West Classrooms	3,480	High	High 2	Proceeding to Construction		
39	Vancouver	3939006	KITSILANO SECONDARY	8	S.W. Classrooms	1,895	High	High 2	Proceeding to Construction		
39	Vancouver	3939054	LAURA SECORD ELEMENTARY	1	Main Building	5,784	High	N/A	Completed	N/A	
39	Vancouver	3939054	LAURA SECORD ELEMENTARY	2	Auditorium	320	High	N/A	Completed		
39	Vancouver	3939054	LAURA SECORD ELEMENTARY	3	Change Rooms	253	Moderate/High	N/A	Completed		
39	Vancouver	3939054	LAURA SECORD ELEMENTARY	4	Gymnasium	586	Low/Moderate	N/A	Completed		
39	Vancouver	3939054	LAURA SECORD ELEMENTARY	5	Recent Addition	?	Low	N/A	Completed		
39	Vancouver	3939043	L'ECOLE BILINGUE ELEMENTARY	1	Main Building	3,510	High	High 1	Proceeding to Construction	High 1	January 2013; Proceeding to Construction
39	Vancouver	3939043	L'ECOLE BILINGUE ELEMENTARY	2	Gymnasium	682	High	High 3	Proceeding to Construction		
39	Vancouver	3939069	LORD BEACONSFIELD ELEMENTARY	1	Classroom	2,745	High	High 1	Structural Upgrade Required	High 1	
39	Vancouver	3939069	LORD BEACONSFIELD ELEMENTARY	2	Gymnasium	640	High	High 3	Structural Upgrade Required		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments		
39	Vancouver	3939008	LORD BYNG SECONDARY	1	East Classroom Block	2,200	Low/Moderate	Low	Meets Structural Life Safety Requirements	High 3			
39	Vancouver	3939008	LORD BYNG SECONDARY	2	Centre Classroom Block	1,970	Low/Moderate	Low	Meets Structural Life Safety Requirements				
39	Vancouver	3939008	LORD BYNG SECONDARY	3	West Classroom Block	2,770	Low/Moderate	Low	Meets Structural Life Safety Requirements				
39	Vancouver	3939008	LORD BYNG SECONDARY	4	Workshops	840	Moderate/High	Medium	Non Structural Upgrade Required				
39	Vancouver	3939008	LORD BYNG SECONDARY	5	Gymnasium	1,500	Moderate/High	High 3	Structural Upgrade Required				
39	Vancouver	3939008	LORD BYNG SECONDARY	6	Cafeteria	840	Moderate/High	Medium	Non Structural Upgrade Required				
39	Vancouver	3939008	LORD BYNG SECONDARY	7	Auditorium	1,440	Moderate/High	High 3	Structural Upgrade Required				
39	Vancouver	3939008	LORD BYNG SECONDARY	8	Library	?	Low	Low	Meets Structural Life Safety Requirements				
39	Vancouver	3939008	LORD BYNG SECONDARY	9	North-east Gym	?	Low	Low	Meets Structural Life Safety Requirements				
39	Vancouver	3939070	LORD KITCHENER ELEMENTARY	1	Classroom Block	2,345	High	N/A	Completed	N/A	Completed Fall 2012		
39	Vancouver	3939070	LORD KITCHENER ELEMENTARY	2	Gymnasium	764	High	N/A	Completed				
39	Vancouver	3939070	LORD KITCHENER ELEMENTARY	3	North Classroom Addition	1,185	High	N/A	Completed				
39	Vancouver	3939070	LORD KITCHENER ELEMENTARY	4	Wood Frame Bldg.	933	Moderate/High	N/A	Completed				
39	Vancouver	3939046	LORD NELSON ELEMENTARY	1	Classroom - North	3,370	High	High 1	Supported	High 1			
39	Vancouver	3939046	LORD NELSON ELEMENTARY	2	Classroom - South	1,250	High	High 1	Supported				
39	Vancouver	3939046	LORD NELSON ELEMENTARY	3	Gymnasium	700	Moderate/High	Medium	Supported				
39	Vancouver	3939129	LORD ROBERTS ANNEX	1	Classrooms/Gym	1,723	Moderate/High	Medium	Non Structural Upgrade Required	Medium			
39	Vancouver	3939031	LORD ROBERTS ELEMENTARY	1	Classrooms	5,200	Low	Low	Meets Structural Life Safety Requirements	Medium			
39	Vancouver	3939031	LORD ROBERTS ELEMENTARY	2	Gymnasium	700	Low	Low	Meets Structural Life Safety Requirements				
39	Vancouver	3939031	LORD ROBERTS ELEMENTARY	3	Classroom Addition	1,700	High	Medium	Non Structural Upgrade Required				
39	Vancouver	3939114	LORD SELKIRK ANNEX	1	Classroom	1,400	High	High 3	Structural Upgrade Required	High 3			
39	Vancouver	3939114	LORD SELKIRK ANNEX	2	Gym	160	High	High 3	Structural Upgrade Required				
39	Vancouver	3939039	LORD SELKIRK ELEMENTARY	1	Brick Building	3,360	Low	Low	Meets Structural Life Safety Requirements	High 3			
39	Vancouver	3939039	LORD SELKIRK ELEMENTARY	2	Gym	650	Low	Low	Meets Structural Life Safety Requirements				
39	Vancouver	3939039	LORD SELKIRK ELEMENTARY	3	Old Frame Building	1,350	Moderate/High	High 3	Structural Upgrade Required				
39	Vancouver	3939039	LORD SELKIRK ELEMENTARY	4	Portables Building	175	Moderate/High	Medium	Non Structural Upgrade Required				
39	Vancouver	3939039	LORD SELKIRK ELEMENTARY	5	South Wing	?	Low	Low	Meets Structural Life Safety Requirements				
39	Vancouver	3939028	LORD STRATHCONA COMMUNITY ELEMENTARY	1	Junior Building	1,950	High	High 2	Supported		High 1		
39	Vancouver	3939028	LORD STRATHCONA COMMUNITY ELEMENTARY	2	Senior Building	4,200	High	High 1	Supported				
39	Vancouver	3939028	LORD STRATHCONA COMMUNITY ELEMENTARY	3	Auditorium	950	High	High 1	Supported				
39	Vancouver	3939028	LORD STRATHCONA COMMUNITY ELEMENTARY	4	Primary Building	2,000	High	High 1	Supported				
39	Vancouver	3939028	LORD STRATHCONA COMMUNITY ELEMENTARY	5	Administration Building	4,500	Moderate/High	High 3	Supported	High 1			
39	Vancouver	3939047	LORD TENNYSON ELEMENTARY	1	Classrooms	2,717	High	High 1	Supported 2013				
39	Vancouver	3939047	LORD TENNYSON ELEMENTARY	2	Gymnasium	710	High	High 1	Supported 2013		High 1	April 2013 - to start 2014.	
39	Vancouver	3939047	LORD TENNYSON ELEMENTARY	3	Changeroom/Addition	330	Moderate	High 3	Supported 2013	High 1			
39	Vancouver	3939074	MAPLE GROVE ELEMENTARY	1	Classroom	3,100	Moderate/High	High 1	Supported 2013				
39	Vancouver	3939074	MAPLE GROVE ELEMENTARY	2	Gym - Lunchroom - Classroom	1,800	Moderate/High	High 1	Supported 2013	High 1	April 2013 - to start 2014.		
39	Vancouver	3939127	MOUNT PLEASANT ELEMENTARY	1	Classroom	2,770	High	High 3	Structural Upgrade Required	High 3			
39	Vancouver	3939127	MOUNT PLEASANT ELEMENTARY	2	Gymnasium	545	Moderate/High	Medium	Non Structural Upgrade Required				
39	Vancouver	3939101	NOOTKA COMMUNITY ELEMENTARY	1	South East Classrooms	640	Moderate/High	Medium	Non Structural Upgrade Required	High 3			
39	Vancouver	3939101	NOOTKA COMMUNITY ELEMENTARY	2	Administration Wing	305	Moderate	Medium	Non Structural Upgrade Required				
39	Vancouver	3939101	NOOTKA COMMUNITY ELEMENTARY	3	Activity Room	200	High	Medium	Non Structural Upgrade Required				
39	Vancouver	3939101	NOOTKA COMMUNITY ELEMENTARY	4	North Classrooms	1,290	High	High 3	Structural Upgrade Required				
39	Vancouver	3939101	NOOTKA COMMUNITY ELEMENTARY	5	Gymnasium	655	High	High 3	Structural Upgrade Required				
39	Vancouver	3939101	NOOTKA COMMUNITY ELEMENTARY	6	South West Classrooms	?	Low	Low	Meets Structural Life Safety Requirements				
39	Vancouver	3939012	POINT GREY SECONDARY	1	Classrooms	9,962	High	High 1	Supported 2013	High 1	April 2013 - to start 2015.		
39	Vancouver	3939012	POINT GREY SECONDARY	2	Gymnasium	1,075	Low/Moderate	High 2	Supported 2013				
39	Vancouver	3939012	POINT GREY SECONDARY	3	Shops	1,484	Low	High 1	Supported 2013				
39	Vancouver	3939012	POINT GREY SECONDARY	4	Science Block	1,213	High	High 3	Supported 2013				
39	Vancouver	3939012	POINT GREY SECONDARY	5		1,458		High 1	Supported 2013				
39	Vancouver	3939019	PRINCE OF WALES SECONDARY	1	West wing classroom	1,820	High	High 3	Supported 2013	High 1	Block 7 now part of Block 6 April 2013 - to start 2015.		
39	Vancouver	3939019	PRINCE OF WALES SECONDARY	2	Auditorium, library and classroom	3,800	High	High 3	Supported 2013				
39	Vancouver	3939019	PRINCE OF WALES SECONDARY	3	East Wing classroom	2,370	High	High 1	Supported 2013				
39	Vancouver	3939019	PRINCE OF WALES SECONDARY	4	Workshop	750	Low/Moderate	High 2	Supported 2013				
39	Vancouver	3939019	PRINCE OF WALES SECONDARY	5	Cafeteria - Lab	1,700	Moderate/High	High 2	Supported 2013				
39	Vancouver	3939019	PRINCE OF WALES SECONDARY	6	Gymnasium	1,640	High	High 1	Supported 2013				
39	Vancouver	3939019	PRINCE OF WALES SECONDARY	7	Trafalgar annex - mini school	700	Moderate/High	NA	Supported 2013				
39	Vancouver	3939040	QUEEN ALEXANDRA ELEMENTARY	1	Classroom	3,095	Moderate	High 2	Structural Upgrade Required			High 1	
39	Vancouver	3939040	QUEEN ALEXANDRA ELEMENTARY	2	Gymnasium	410	Moderate	High 1	Structural Upgrade Required				
39	Vancouver	3939040	QUEEN ALEXANDRA ELEMENTARY	3	Lunchroom	225	Moderate	Medium	Non Structural Upgrade Required				

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
39	Vancouver	3939110	QUEEN ELIZABETH ANNEX	1	Classrooms	1,295	High	High 3	Structural Upgrade Required	High 3	
39	Vancouver	3939080	QUEEN ELIZABETH ELEMENTARY	1	East Gymnasium	488	High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939080	QUEEN ELIZABETH ELEMENTARY	2	East Classrooms	775	Moderate/High	High 3	Structural Upgrade Required		
39	Vancouver	3939080	QUEEN ELIZABETH ELEMENTARY	3	Central Block	800	Moderate/High	High 3	Structural Upgrade Required		
39	Vancouver	3939080	QUEEN ELIZABETH ELEMENTARY	4	West Gymnasium	500	Moderate/High	High 3	Structural Upgrade Required		
39	Vancouver	3939080	QUEEN ELIZABETH ELEMENTARY	5	West Classrooms	775	Moderate/High	High 3	Structural Upgrade Required		
39	Vancouver	3939080	QUEEN ELIZABETH ELEMENTARY	6	1957 South Addition	825	Moderate/High	High 3	Structural Upgrade Required		
39	Vancouver	3939080	QUEEN ELIZABETH ELEMENTARY	7	1967 South Addition	825	Moderate/High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939080	QUEEN ELIZABETH ELEMENTARY	8	1957 West Addition	350	Moderate/High	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939041	QUEEN MARY ELEMENTARY	1	Original Classroom	1,829	High	High 1	Proceeding to Construction		
39	Vancouver	3939041	QUEEN MARY ELEMENTARY	2	East Classroom Bldg.	1,862	High	Medium	Proceeding to Construction		October 2012 - Proceeding to Construction
39	Vancouver	3939041	QUEEN MARY ELEMENTARY	3	Classroom Addition	555	High	High 3	Proceeding to Construction		
39	Vancouver	3939041	QUEEN MARY ELEMENTARY	4	Gymnasium	915	Moderate/High	High 3	Proceeding to Construction		
39	Vancouver	3939107	QUEEN VICTORIA ANNEX	1	Gym	160	Moderate/High	High 3	Structural Upgrade Required		
39	Vancouver	3939107	QUEEN VICTORIA ANNEX	2	Classroom Ground	1,090	High	High 3	Structural Upgrade Required		
39	Vancouver	3939107	QUEEN VICTORIA ANNEX	3	Classroom Elevated	540	Moderate	Medium	Non Structural Upgrade Required		
39	Vancouver	3939075	QUILCHENA ELEMENTARY	1	Central Classrooms	1,911	High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939075	QUILCHENA ELEMENTARY	2	North Wing Addition	627	High	High 1	Structural Upgrade Required		
39	Vancouver	3939075	QUILCHENA ELEMENTARY	3	Gymnasium	758	Moderate/High	High 1	Structural Upgrade Required		
39	Vancouver	3939077	RENFREW COMMUNITY ELEMENTARY	1	Classroom Wing	2,500	Moderate/High	High 1	Supported 2013		
39	Vancouver	3939077	RENFREW COMMUNITY ELEMENTARY	2	Classroom Wing	2,500	Moderate/High	High 1	Supported 2013		
39	Vancouver	3939077	RENFREW COMMUNITY ELEMENTARY	3	Gymnasium Wing	1,120	High	High 2	Supported 2013		
39	Vancouver	3939077	RENFREW COMMUNITY ELEMENTARY	4	Classroom Wing	?	Low	Low	Supported 2013		
39	Vancouver	3939077	RENFREW COMMUNITY ELEMENTARY	5	Classroom Wing	?	Low	Low	Supported 2013		
39	Vancouver	3939083	SHANNON PARK ANNEX	1	Classroom	960	Moderate	Medium	Inactive		
39	Vancouver	3939072	SHAUGHNESSY ELEMENTARY	1	Classrooms	3,300	Moderate	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939072	SHAUGHNESSY ELEMENTARY	2	Multi-Purpose	500	Moderate	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939072	SHAUGHNESSY ELEMENTARY	3	Gymnasium	1,000	Low/Moderate	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939042	SIMON FRASER ELEMENTARY	1	Gymnasium	870	Moderate/High	N/A	Completed		
39	Vancouver	3939042	SIMON FRASER ELEMENTARY	2	Classrooms	1,730	Low/Moderate	N/A	Completed		
39	Vancouver	3939079	SIR ALEXANDER MACKENZIE ELEM	1	Classroom Wing	4,230	Moderate/High	High 2	Supported 2013		
39	Vancouver	3939079	SIR ALEXANDER MACKENZIE ELEM	2	Gymnasium Wing	820	High	High 1	Supported 2013		
39	Vancouver	3939079	SIR ALEXANDER MACKENZIE ELEM	3	Classroom Wing	?	Low	Low	Supported 2013		
39	Vancouver	3939093	SIR CHARLES KINGSFORD-SMITH	1	Classroom Wing	3,140	High	High 1	Supported (May 2012)		
39	Vancouver	3939093	SIR CHARLES KINGSFORD-SMITH	3	Gymnasium Wing	900	Moderate/High	High 2	Supported (May 2012)		
39	Vancouver	3939093	SIR CHARLES KINGSFORD-SMITH	2	Administrative Wing	340	Moderate	Medium	Supported (May 2012)		
39	Vancouver	3939017	SIR CHARLES TUPPER SECONDARY	1	Auditorium - Classroom	3,500	Low	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939017	SIR CHARLES TUPPER SECONDARY	2	Cafeteria - Classroom	6,700	Low	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939017	SIR CHARLES TUPPER SECONDARY	3	Shops - Labs - Gymnasium	5,300	Low	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939017	SIR CHARLES TUPPER SECONDARY	4	Workshops - Gymnasium	3,500	High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939030	SIR GUY CARLETON COMMUNITY ELEMENTARY	1	Classroom Wing	2,415	High	Medium	Supported		
39	Vancouver	3939030	SIR GUY CARLETON COMMUNITY ELEMENTARY	2	Classroom Wing	1,600	High	High 1	Supported		
39	Vancouver	3939030	SIR GUY CARLETON COMMUNITY ELEMENTARY	3	Classroom Wing	200	Moderate/High	High 1	Supported		
39	Vancouver	3939030	SIR GUY CARLETON COMMUNITY ELEMENTARY	4	Classroom Wing	130	Moderate/High	Medium	Supported		
39	Vancouver	3939030	SIR GUY CARLETON COMMUNITY ELEMENTARY	5	Gymnasium Wing	690	High	High 2	Supported		
39	Vancouver	3939120	SIR JAMES DOUGLAS ANNEX	1	Building 131	1,580	Moderate/High	N/A	Completed		
39	Vancouver	3939064	SIR JAMES DOUGLAS ELEMENTARY	1	Main Building	2,250	High	N/A	Completed		
39	Vancouver	3939064	SIR JAMES DOUGLAS ELEMENTARY	2	North Addition - Classroom	370	Moderate/High	N/A	Completed		
39	Vancouver	3939064	SIR JAMES DOUGLAS ELEMENTARY	3	Gym	1,900	Moderate	N/A	Completed		
39	Vancouver	3939065	SIR JOHN FRANKLIN COMMUNITY	1	Classroom	3,255	High	High 1	Structural Upgrade Required		
39	Vancouver	3939065	SIR JOHN FRANKLIN COMMUNITY	2	Gymnasium	430	Moderate/High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939065	SIR JOHN FRANKLIN COMMUNITY	3	Lunchroom	215	Moderate/High	High 3	Structural Upgrade Required		
39	Vancouver	3939073	SIR MATTHEW BEGBIE ELEMENTARY	1	Gymnasium/Classroom	5,600	High	High 1	Supported		
39	Vancouver	3939108	SIR RICHARD MCBRIDE ANNEX	1	Classroom	1,520	High	High 3	Structural Upgrade Required		
39	Vancouver	3939108	SIR RICHARD MCBRIDE ANNEX	2	Gym	161	High	High 3	Structural Upgrade Required		
39	Vancouver	3939048	SIR RICHARD MCBRIDE ELEMENTARY	1	Brick Building	3,300	Low	N/A	Completed		
39	Vancouver	3939048	SIR RICHARD MCBRIDE ELEMENTARY	2	Gymnasium	710	Low	N/A	Completed		
39	Vancouver	3939048	SIR RICHARD MCBRIDE ELEMENTARY	3	South Woodframe Building	700	High	N/A	Completed		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
39	Vancouver	3939066	SIR SANDFORD FLEMING ELEM	1	Classroom Addition	2,590	Low/Moderate	High 1	Supported		
39	Vancouver	3939066	SIR SANDFORD FLEMING ELEM	2	Original Building	3,040	High	High 1	Supported		
39	Vancouver	3939066	SIR SANDFORD FLEMING ELEM	3	Gymnasium	800	Moderate	High 1	Supported	High 1	
39	Vancouver	3939066	SIR SANDFORD FLEMING ELEM	4	Wood Frame Classrooms	412	Moderate	Medium	Supported		
39	Vancouver	3939066	SIR SANDFORD FLEMING ELEM	5	Recent Addition	?	Low	Low	Supported		
39	Vancouver	3939049	SIR WILFRED GRENFELL COMMUNITY SCHOOL	1	Classroom Wing	2,050	Moderate/High	High 1	Supported (May 2012)		
39	Vancouver	3939049	SIR WILFRED GRENFELL COMMUNITY SCHOOL	2	Administrative Wing	800	Moderate	Medium	Supported (May 2012)		
39	Vancouver	3939049	SIR WILFRED GRENFELL COMMUNITY SCHOOL	3	Gymnasium Wing	810	High	High 2	Supported (May 2012)	High 1	
39	Vancouver	3939049	SIR WILFRED GRENFELL COMMUNITY SCHOOL	4	Classroom Wing	440	Moderate/High	High 3	Supported (May 2012)		
39	Vancouver	3939049	SIR WILFRED GRENFELL COMMUNITY SCHOOL	5	Classroom Wing	?	Low	Low	Supported (May 2012)		
39	Vancouver	3939122	SIR WILFRID LAURIER ANNEX	1	Main Building	971	Moderate/High	N/A	Completed	N/A	
39	Vancouver	3939122	SIR WILFRID LAURIER ANNEX	2	Gymnasium	295	Moderate/High	N/A	Completed		
39	Vancouver	3939085	SIR WILFRID LAURIER ELEMENTARY	1	Main Classrooms	3,270	Low/Moderate	N/A	Completed		
39	Vancouver	3939085	SIR WILFRID LAURIER ELEMENTARY	2	Gymnasium	561	Moderate	N/A	Completed	N/A	
39	Vancouver	3939085	SIR WILFRID LAURIER ELEMENTARY	3	1999 Addition	?	Low	N/A	Completed	N/A	
39	Vancouver	3939085	SIR WILFRID LAURIER ELEMENTARY	4	Laurier Mini School	785	Moderate/High	N/A	Completed		
39	Vancouver	3939033	SIR WILLIAM MACDONALD ELEM	1	Classrooms	3,200	Moderate/High	High 1	Structural Upgrade Required	High 1	
39	Vancouver	3939033	SIR WILLIAM MACDONALD ELEM	2	Gymnasium	400	High	High 1	Structural Upgrade Required		
39	Vancouver	3939086	SIR WILLIAM OSLER ELEMENTARY	1	Two Storey Classroom (1953)	1,650	Moderate/High	High 1	Structural Upgrade Required		
39	Vancouver	3939086	SIR WILLIAM OSLER ELEMENTARY	2	Library & Classrooms (1953)	440	Moderate	High 1	Structural Upgrade Required	High 1	April 2013 - risk updated for some blocks based on rept from APEGBC, however, overall school risk remains unchanged as a H1
39	Vancouver	3939086	SIR WILLIAM OSLER ELEMENTARY	3	Gymnasium (1974)	700	High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939086	SIR WILLIAM OSLER ELEMENTARY	4	Main Building - Classrooms & Activity Room (1950)	1,300	Moderate	High 3	Structural Upgrade Required		
39	Vancouver	3939015	SIR WINSTON CHURCHILL SEC	1	Auditorium	1,442	Low/Moderate	High 3	Structural Upgrade Required		
39	Vancouver	3939015	SIR WINSTON CHURCHILL SEC	2	Classrooms	9,660	Moderate	High 3	Structural Upgrade Required		
39	Vancouver	3939015	SIR WINSTON CHURCHILL SEC	3	Shops	2,727	Low/Moderate	High 1	Structural Upgrade Required	High 1	
39	Vancouver	3939015	SIR WINSTON CHURCHILL SEC	4	Gymnasium	2,000	Low/Moderate	High 3	Structural Upgrade Required		
39	Vancouver	3939015	SIR WINSTON CHURCHILL SEC	5	Small Gymnasium	1,090	Low/Moderate	High 3	Structural Upgrade Required		
39	Vancouver	3939015	SIR WINSTON CHURCHILL SEC	6	1999 Addition	?	Low	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939058	SIR WM VAN HORNE ELEMENTARY	1	ORIGINAL (1911)	3,318	Low	Low	Meets Structural Life Safety Requirements	Low	
39	Vancouver	3939058	SIR WM VAN HORNE ELEMENTARY	2	EXTENSION (1950)	1,973	Low	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939055	SOUTH HILL EDUCATION CENTRE	1	ORIGINAL	1,670	Moderate	High 3	Inactive	High 3	
39	Vancouver	3939055	SOUTH HILL EDUCATION CENTRE	2	GYMNASIUM BLOCK	943	Moderate	High 3	Inactive		
39	Vancouver	3939087	SOUTHLANDS ELEMENTARY	3	Gymnasium	714	High	High 1	Structural Upgrade Required	High 1	
39	Vancouver	3939087	SOUTHLANDS ELEMENTARY	1	Central Classroom Block	1,476	High	High 2	Structural Upgrade Required		
39	Vancouver	3939087	SOUTHLANDS ELEMENTARY	2	South Classrooms	563	High	High 2	Structural Upgrade Required		
39	Vancouver	3939102	TECUMSEH ANNEX	1	Classroom Wing	880	Moderate/High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939102	TECUMSEH ANNEX	2	Administrative Wing	165	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
39	Vancouver	3939102	TECUMSEH ANNEX	3	Gymnasium Wing	170	Moderate/High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939050	TECUMSEH ELEMENTARY	1	Classroom Wing	3,900	High	Medium	Non Structural Upgrade Required		
39	Vancouver	3939050	TECUMSEH ELEMENTARY	2	Gymnasium Wing	1,050	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
39	Vancouver	3939050	TECUMSEH ELEMENTARY	3	Classroom Wing	?	Low	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939050	TECUMSEH ELEMENTARY	4	Classroom Wing	?	Low	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939010	TEMPLETON SECONDARY	1	1926/28 Main Building	10,000	Moderate/High	High 2	Supported 2013		April 2013 - to start 2015.
39	Vancouver	3939010	TEMPLETON SECONDARY	2	1926/28 1-storey	1,800	Moderate/High	High 1	Supported 2013		
39	Vancouver	3939010	TEMPLETON SECONDARY	3	1962 Classroom	2,300	Moderate/High	Medium	Supported 2013	High 1	
39	Vancouver	3939010	TEMPLETON SECONDARY	4	1962 Gymnasium	1,600	Moderate/High	High 1	Supported 2013		
39	Vancouver	3939010	TEMPLETON SECONDARY	5	1962/63 Workshops	1,200	High	High 3	Supported 2013		
39	Vancouver	3939010	TEMPLETON SECONDARY	6		2,190		High 3	Supported 2013		
39	Vancouver	3939082	THUNDERBIRD ELEMENTARY	1	Classrooms - West	1,570	Moderate	High 3	Structural Upgrade Required		
39	Vancouver	3939082	THUNDERBIRD ELEMENTARY	2	Classroom - East	1,700	Moderate/High	High 3	Structural Upgrade Required	High 3	
39	Vancouver	3939082	THUNDERBIRD ELEMENTARY	3	Gymnasium	650	Moderate/High	High 3	Structural Upgrade Required		
39	Vancouver	3939082	THUNDERBIRD ELEMENTARY	4	Multi-Purpose	?	Low	Low	Meets Structural Life Safety Requirements		
39	Vancouver	3939112	TILlicum ELEMENTARY ANNEX	1	Classroom (1065/1969)	1,940	Moderate/High	High 1	Structural Upgrade Required	High 1	
39	Vancouver	3939112	TILlicum ELEMENTARY ANNEX	2	Gymnasium (1965)	170	Moderate/High	High 1	Structural Upgrade Required		
39	Vancouver	3939084	TRAFALGAR ELEMENTARY	1	South Classrooms	1,525	Moderate/High	N/A	Completed		
39	Vancouver	3939084	TRAFALGAR ELEMENTARY	2	Gymnasium	1,110	Moderate/High	N/A	Completed	N/A	
39	Vancouver	3939084	TRAFALGAR ELEMENTARY	3	North Classrooms	2,530	High	N/A	Completed		
39	Vancouver	3939119	TYEE ELEMENTARY	1	Classroom	1,800	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
39	Vancouver	3939119	TYEE ELEMENTARY	2	Gym	220	Moderate/High	Medium	Non Structural Upgrade Required		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments	
39	Vancouver	3939024	UNIVERSITY HILL SECONDARY	1	Workshops	440	High	N/A	Completed	N/A		
39	Vancouver	3939024	UNIVERSITY HILL SECONDARY	2	Gymnasium	1,170	Moderate/High	N/A	Completed			
39	Vancouver	3939024	UNIVERSITY HILL SECONDARY	3	Auditorium	585	Moderate/High	N/A	Completed			
39	Vancouver	3939024	UNIVERSITY HILL SECONDARY	4	Administration	480	Moderate	N/A	Completed			
39	Vancouver	3939024	UNIVERSITY HILL SECONDARY	5	North Classrooms	850	Moderate	N/A	Completed			
39	Vancouver	3939024	UNIVERSITY HILL SECONDARY	6	South Classrooms	1,030	Moderate	N/A	Completed			
39	Vancouver	3939011	VANCOUVER TECHNICAL SECONDARY	1	Main Classroom West Wing	9,000	High	N/A	Completed	N/A		
39	Vancouver	3939011	VANCOUVER TECHNICAL SECONDARY	2	Main Classroom East Wing	5,300	High	N/A	Completed			
39	Vancouver	3939011	VANCOUVER TECHNICAL SECONDARY	3	Woodwork Shop	6,150	High	N/A	Completed			
39	Vancouver	3939011	VANCOUVER TECHNICAL SECONDARY	4	Music Room	300	Low	N/A	Completed			
39	Vancouver	3939011	VANCOUVER TECHNICAL SECONDARY	5	Auto Shop and Home Economics	3,320	High	N/A	Completed			
39	Vancouver	3939011	VANCOUVER TECHNICAL SECONDARY	6	Gymnasium and Cafeteria	6,100	Low	N/A	Completed			
39	Vancouver	3939056	WALTER MOBERLY ELEMENTARY	1	Gymnasium	450	Moderate/High	N/A	Completed	N/A		
39	Vancouver	3939056	WALTER MOBERLY ELEMENTARY	2	1950 Addition	1,230	High	N/A	Completed			
39	Vancouver	3939056	WALTER MOBERLY ELEMENTARY	3	1946 Classrooms	2,980	High	N/A	Completed			
39	Vancouver	3939056	WALTER MOBERLY ELEMENTARY	4	Post 1992 Additions	?	Low	N/A	Completed			
39	Vancouver	3939401	WAVERLEY ANNEX	1	ORIGINAL	1,315	Moderate	High 3	Structural Upgrade Required	High 3		
39	Vancouver	3939099	WAVERLEY ELEMENTARY	1	North Classroom Wing	1,750	Moderate/High	High 2	Supported 2013	High 1	April 2013 - to start 2015.	
39	Vancouver	3939099	WAVERLEY ELEMENTARY	2	South Classroom Wing	1,400	Moderate	High 2	Supported 2013			
39	Vancouver	3939099	WAVERLEY ELEMENTARY	3	Gymnasium Wing	745	High	High 1	Supported 2013			
39	Vancouver	3939020	WINDERMERE COMMUNITY SECONDARY	1	Workshop Block on West Side (1960)	835	Moderate/High	High 2	Non Structural Upgrade Required	High 1	April 2013 - risk updated for some blocks based on rept from APEGBC, however, overall school risk remains unchanged as a H1	
39	Vancouver	3939020	WINDERMERE COMMUNITY SECONDARY	2	Auditorium (1960)	1,170	High	High 2	Structural Upgrade Required			
39	Vancouver	3939020	WINDERMERE COMMUNITY SECONDARY	3	South-West Wing Classroom (1060)	2,050	Moderate/High	High 3	Non Structural Upgrade Required			
39	Vancouver	3939020	WINDERMERE COMMUNITY SECONDARY	4	Cafeteria - Administration (1060)	1,630	High	High 1	Structural Upgrade Required			
39	Vancouver	3939020	WINDERMERE COMMUNITY SECONDARY	5	North and West Wing Classrooms (1960)	5,450	Moderate/High	High 3	Non Structural Upgrade Required			
39	Vancouver	3939020	WINDERMERE COMMUNITY SECONDARY	6	East Wing Classrooms	1,640	Moderate/High	Medium	Non Structural Upgrade Required			
39	Vancouver	3939020	WINDERMERE COMMUNITY SECONDARY	7	North East Wing Classrooms (1970)	1,710	Moderate	High 2	Non Structural Upgrade Required			
39	Vancouver	3939020	WINDERMERE COMMUNITY SECONDARY	8	Gymnasium (1960)	1,450	High	High 2	Structural Upgrade Required			
39	Vancouver	3939020	WINDERMERE COMMUNITY SECONDARY	9	South Shops (1970)	500	Moderate	High 2	Structural Upgrade Required			
40	New Westminster	4040010	CONNAUGHT HEIGHTS ELEMENTARY	1	single-storey classroom	850	Moderate/High	Medium	Non Structural Upgrade Required	Medium		
40	New Westminster	4040010	CONNAUGHT HEIGHTS ELEMENTARY	2	gymnasium	350	Moderate	Medium	Non Structural Upgrade Required			
40	New Westminster	4040010	CONNAUGHT HEIGHTS ELEMENTARY	3	multipurpose	125	Moderate	Medium	Non Structural Upgrade Required			
40	New Westminster	4040009	F W HOWAY ELEMENTARY	1	single-storey classroom	950	Moderate	High 2	Supported 2013	High 2	November 2012 - Block 1 increased from M to H2 and Block 3 from M to H3.	
40	New Westminster	4040009	F W HOWAY ELEMENTARY	2	gymnasium	353	Moderate	High 3	Supported 2013			
40	New Westminster	4040009	F W HOWAY ELEMENTARY	3	changerooms	300	Moderate	Medium	Supported 2013	High 2	April 2013 - to start 2015.	
40	New Westminster	4040011	HUME PARK SCHOOL	1	two-storey classroom	515	High	High 2	Structural Upgrade Required			
40	New Westminster	4040001	LORD KELVIN ELEMENTARY	1	1963 single-storey classroom	3,000	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium		
40	New Westminster	4040001	LORD KELVIN ELEMENTARY	2	1963 gymnasium	450	Moderate/High	Medium	Non Structural Upgrade Required			
40	New Westminster	4040001	LORD KELVIN ELEMENTARY	3	2000 1-storey Classroom. Add'n	?	Low	Low	Meets Structural Life Safety Requirements			
40	New Westminster	4040004	LORD TWEEDSMUIR ELEMENTARY	1	two-storey classroom	1,250	Low	Low	Meets Structural Life Safety Requirements	Low		
40	New Westminster	4040004	LORD TWEEDSMUIR ELEMENTARY	2	Gymnasium	?	Low	Low	Meets Structural Life Safety Requirements			
40	New Westminster	4040004	LORD TWEEDSMUIR ELEMENTARY	3	Single-storey Classroom	?	High 1	Low	Meets Structural Life Safety Requirements			
40	New Westminster	4040008	NEW WESTMINSTER SECONDARY	1	Two-Storey Classroom	12,000	High	Medium	Supported	Medium		
40	New Westminster	4040008	NEW WESTMINSTER SECONDARY	2	Small Gymnasium & Cafeteria	1,100	High	Medium	Supported			
40	New Westminster	4040008	NEW WESTMINSTER SECONDARY	3	1952 Single-Storey Cafeteria	500	Moderate/High	Medium	Supported			
40	New Westminster	4040008	NEW WESTMINSTER SECONDARY	4	1955 Single-Storey Administration	700	Moderate/High	Medium	Supported			
40	New Westminster	4040008	NEW WESTMINSTER SECONDARY	5	1972 Single-Storey Automotive Shops	535	Moderate	Medium	Supported			
40	New Westminster	4040008	NEW WESTMINSTER SECONDARY	6	1969 Single-Storey Band Rooms	550	Moderate	Medium	Supported			
40	New Westminster	4040008	NEW WESTMINSTER SECONDARY	7	North & South Large Gyms and Theatre	2,500	High	Medium	Supported			
40	New Westminster	4040008	NEW WESTMINSTER SECONDARY	8	1965 Library & Administration	2,350	Moderate/High	Medium	Supported			
40	New Westminster	4040008	NEW WESTMINSTER SECONDARY	9	1965 Single-Storey Shops	2,200	Moderate/High	Medium	Supported			
40	New Westminster	4040007	QAYQAYT ELEMENTARY (was John Robson)	1	1928 3-storey classroom	2,900	Moderate/High	NA	Under Construction		NA	March 2013; A new school on new site (Qayqayt Elementary) wil replace the existing elementary. The existing site will house a new middle school.
40	New Westminster	4040007	QAYQAYT ELEMENTARY (was John Robson)	2	1928 Gymnasium	400	Moderate/High	NA	Under Construction			
40	New Westminster	4040007	QAYQAYT ELEMENTARY (was John Robson)	3	1971 single-storey classroom	100	Moderate	NA	Under Construction			
40	New Westminster	4040012	QUEEN ELIZABETH ELEMENTARY	1	1987 Single-storey Classroom	2,400	Low	Low	Meets Structural Life Safety Requirements		Low	
40	New Westminster	4040012	QUEEN ELIZABETH ELEMENTARY	2	1987 Gymnasium	375	Low	Low	Meets Structural Life Safety Requirements			
40	New Westminster	4040003	RICHARD MCBRIDE ELEMENTARY	1	1929 two-storey classroom	3,235	Moderate/High	High 2	Supported 2013	High 2	December 2012 - Risk reviewed at SD request. Increased risk to Block 1 from M to H2 & Block 2 from M to H3.	
40	New Westminster	4040003	RICHARD MCBRIDE ELEMENTARY	2	1929 gymnasium	432	High	High 3	Supported 2013			

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments	
41	Burnaby	4141005	ALPHA SECONDARY	1	Gymnasium	1,290	Moderate/High	Medium	Supported (May 2012)	High 1		
41	Burnaby	4141005	ALPHA SECONDARY	2	Classroom	1,390	Moderate	Medium	Supported (May 2012)			
41	Burnaby	4141005	ALPHA SECONDARY	3	Small gymnasium	680	High	Medium	Supported (May 2012)			
41	Burnaby	4141005	ALPHA SECONDARY	4	2 storey classroom	3,730	High	High 2	Supported (May 2012)			
41	Burnaby	4141005	ALPHA SECONDARY	5	3 storey classroom	3,410	High	High 1	Supported (May 2012)			
41	Burnaby	4141005	ALPHA SECONDARY	6	Shops	1,140	Moderate/High	Medium	Supported (May 2012)			
41	Burnaby	4141015	ARMSTRONG ELEMENTARY	1	Gymnasium	490	High	Medium	Non Structural Upgrade Required	High 3		
41	Burnaby	4141015	ARMSTRONG ELEMENTARY	2	Classroom	3,430	Moderate	High 3	Structural Upgrade Required			
41	Burnaby	4141016	AUBREY ELEMENTARY	1	Gymnasium	450	Moderate	Medium	Non Structural Upgrade Required	Medium		
41	Burnaby	4141016	AUBREY ELEMENTARY	2	Classroom	1,230	Moderate	Medium	Non Structural Upgrade Required			
41	Burnaby	4141016	AUBREY ELEMENTARY	3	Classroom	1,805	Moderate/High	Medium	Non Structural Upgrade Required			
41	Burnaby	4141017	BRANTFORD ELEMENTARY	1	Gymnasium	320	Moderate/High	N/A	Completed	N/A		
41	Burnaby	4141017	BRANTFORD ELEMENTARY	2	Classrooms	1,325	Moderate/High	N/A	Completed			
41	Burnaby	4141018	BRENTWOOD PARK ELEMENTARY	1	Gymnasium	335	Moderate/High	Medium	Non Structural Upgrade Required	Medium		
41	Burnaby	4141018	BRENTWOOD PARK ELEMENTARY	2	Classroom	3,150	Moderate/High	Medium	Non Structural Upgrade Required			
41	Burnaby	4141018	BRENTWOOD PARK ELEMENTARY	3	Classroom	234	Moderate/High	Medium	Non Structural Upgrade Required			
41	Burnaby	4141019	BUCKINGHAM ELEMENTARY	1	Gymnasium	465	Moderate/High	Medium	Non Structural Upgrade Required	Medium		
41	Burnaby	4141019	BUCKINGHAM ELEMENTARY	2	Classroom	1,560	Moderate/High	Medium	Non Structural Upgrade Required			
41	Burnaby	4141001	BURNABY CENTRAL SECONDARY	1	Large Gymnasium	2,690	High	N/A	Completed	N/A		
41	Burnaby	4141001	BURNABY CENTRAL SECONDARY	2	3 Storey Classroom	6,610	High	N/A	Completed			
41	Burnaby	4141001	BURNABY CENTRAL SECONDARY	3	4 Storey Classroom	1,930	High	N/A	Completed			
41	Burnaby	4141001	BURNABY CENTRAL SECONDARY	4	Shops	1,280	Moderate/High	N/A	Completed			
41	Burnaby	4141001	BURNABY CENTRAL SECONDARY	5	Small Gymnasium	360	Moderate	N/A	Completed	High 1	April 2013 - to start 2014.	
41	Burnaby	4141002	BURNABY NORTH SECONDARY	1	Large Gymnasium	1,910	High	Medium	Supported 2013			
41	Burnaby	4141002	BURNABY NORTH SECONDARY	2	3 Storey Classroom	6,740	High	High 1	Supported 2013			
41	Burnaby	4141002	BURNABY NORTH SECONDARY	3	Shops	2,300	High	Medium	Supported 2013			
41	Burnaby	4141002	BURNABY NORTH SECONDARY	4	South Gymnasium	640	High	Medium	Supported 2013			
41	Burnaby	4141002	BURNABY NORTH SECONDARY	5	2 Storey Classroom	4,550	High	High 3	Supported 2013			
41	Burnaby	4141002	BURNABY NORTH SECONDARY	6	Classroom/Administration	1,820	Moderate/High	Medium	Supported 2013			
41	Burnaby	4141062	BURNABY SOUTH SECONDARY	1	Whole School	20,950	Low/Moderate	Low	Meets Structural Life Safety Requirements			Low
41	Burnaby	4141020	CAMERON ELEMENTARY	1	Gymnasium	430	Moderate/High	Medium	Non Structural Upgrade Required	Medium		
41	Burnaby	4141020	CAMERON ELEMENTARY	2	Classroom	2,070	Moderate	Medium	Non Structural Upgrade Required			
41	Burnaby	4141066	CANADA WAY EDUCATION CENTRE	1	Whole School	1,390	Moderate	Medium	Non Structural Upgrade Required	Medium		
41	Burnaby	4141021	CAPITOL HILL ELEMENTARY	1	Gymnasium	475	Moderate	N/A	Completed	N/A		
41	Burnaby	4141021	CAPITOL HILL ELEMENTARY	2	Two Storey Classroom	1,825	Moderate/High	N/A	Completed			
41	Burnaby	4141021	CAPITOL HILL ELEMENTARY	3	Two Storey Classroom	2,330	Moderate/High	N/A	Completed			
41	Burnaby	4141021	CAPITOL HILL ELEMENTARY	4	Two Storey Classroom	1,200	High	N/A	Completed			
41	Burnaby	4141007	CARIBOO HILL SECONDARY	1	Gymnasium	1,300	Moderate	N/A	Completed	N/A		
41	Burnaby	4141007	CARIBOO HILL SECONDARY	2	2 Storey Classroom	2,600	High	N/A	Completed			
41	Burnaby	4141007	CARIBOO HILL SECONDARY	3	3-Storey Classroom	2,130	High	N/A	Completed			
41	Burnaby	4141007	CARIBOO HILL SECONDARY	4	1 Storey Classroom	430	Moderate/High	N/A	Completed			
41	Burnaby	4141007	CARIBOO HILL SECONDARY	5	Shops	1,670	High	N/A	Completed			
41	Burnaby	4141007	CARIBOO HILL SECONDARY	6	Auditorium	730	High	N/A	Completed			
41	Burnaby	4141007	CARIBOO HILL SECONDARY	7	2 Storey Classroom	2,360	High	N/A	Completed			
41	Burnaby	4141022	CASCADE HEIGHTS ELEMENTARY	1	Gymnasium	450	Moderate/High	Medium	Non Structural Upgrade Required	High 3		
41	Burnaby	4141022	CASCADE HEIGHTS ELEMENTARY	2	Classroom	2,400	Moderate	Medium	Non Structural Upgrade Required			
41	Burnaby	4141022	CASCADE HEIGHTS ELEMENTARY	3	Classroom	400	Moderate/High	High 3	Structural Upgrade Required			
41	Burnaby	4141022	CASCADE HEIGHTS ELEMENTARY	4	Classrooms (1999)	?	Low	Low	Meets Structural Life Safety Requirements			
41	Burnaby	4141023	CHAFFEY-BURKE ELEMENTARY	1	Gymnasium	815	High	N/A	Completed	N/A		
41	Burnaby	4141023	CHAFFEY-BURKE ELEMENTARY	2	Classrooms	3,430	High	N/A	Completed			
41	Burnaby	4141024	CLINTON ELEMENTARY	1	Gymnasium	430	Moderate/High	Medium	Non Structural Upgrade Required	Medium		
41	Burnaby	4141024	CLINTON ELEMENTARY	2	Classroom	3,260	Moderate	Medium	Non Structural Upgrade Required			
41	Burnaby	4141025	CONFEDERATION PARK ELEMENTARY	1	Gymnasium	550	Moderate	Medium	Non Structural Upgrade Required	Medium		
41	Burnaby	4141025	CONFEDERATION PARK ELEMENTARY	2	Classroom	1,440	Moderate	Medium	Non Structural Upgrade Required			
41	Burnaby	4141026	DOUGLAS ROAD ELEMENTARY	1	Gymnasium	455	Moderate/High	N/A	Completed	N/A		
41	Burnaby	4141026	DOUGLAS ROAD ELEMENTARY	2	2 storey classroom	1,110	High	N/A	Completed			
41	Burnaby	4141026	DOUGLAS ROAD ELEMENTARY	3	2 storey classroom	1,060	Moderate/High	N/A	Completed			
41	Burnaby	4141026	DOUGLAS ROAD ELEMENTARY	4	Kindergarten	200	Moderate/High	N/A	Completed			

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
41	Burnaby	4141008	EDMONDS COMMUNITY	1	Gymnasium	1,660	Moderate/High	N/A	Completed		
41	Burnaby	4141008	EDMONDS COMMUNITY	2	2-Storey Classroom	2,800	Moderate/High	N/A	Completed		
41	Burnaby	4141008	EDMONDS COMMUNITY	3	1-Storey Classroom	460	Moderate/High	N/A	Completed	N/A	
41	Burnaby	4141008	EDMONDS COMMUNITY	4	1-Storey Classroom	140	Moderate/High	N/A	Completed		
41	Burnaby	4141008	EDMONDS COMMUNITY	5	2-Storey Classroom	2,620	High	N/A	Completed		
41	Burnaby	4141060	FOREST GROVE ELEMENTARY	1	Gymnasium	490	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141060	FOREST GROVE ELEMENTARY	2	Classroom	2,990	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
41	Burnaby	4141060	FOREST GROVE ELEMENTARY	3	Classroom	280	Low/Moderate	Low	Meets Structural Life Safety Requirements		
41	Burnaby	4141029	GILMORE COMMUNITY ELEMENTARY	1	Gymnasium	520	Moderate	N/A	Completed		
41	Burnaby	4141029	GILMORE COMMUNITY ELEMENTARY	2	1913 Classroom	1,890	Low/Moderate	N/A	Completed		
41	Burnaby	4141029	GILMORE COMMUNITY ELEMENTARY	3	Library wing	1,340	High	N/A	Completed	High 1	
41	Burnaby	4141029	GILMORE COMMUNITY ELEMENTARY	4	1928 Classroom	730	High	N/A	Completed		
41	Burnaby	4141029	GILMORE COMMUNITY ELEMENTARY	5	Primary classroom	750	Low/Moderate	N/A	Completed		
41	Burnaby	4141030	GILPIN ELEMENTARY	1	Gymnasium	630	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141030	GILPIN ELEMENTARY	2	Classroom / Admin	930	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
41	Burnaby	4141030	GILPIN ELEMENTARY	3	Classroom	960	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141031	GLENWOOD ELEMENTARY	1	Gymnasium	280	High	Medium	Non Structural Upgrade Required		
41	Burnaby	4141031	GLENWOOD ELEMENTARY	2	Classroom	940	Moderate/High	Medium	Non Structural Upgrade Required	High 3	
41	Burnaby	4141031	GLENWOOD ELEMENTARY	3	Classroom	165	Moderate/High	High 3	Structural Upgrade Required		
41	Burnaby	4141032	INMAN ELEMENTARY	1	Gymnasium	470	Low	Low	Meets Structural Life Safety Requirements		
41	Burnaby	4141032	INMAN ELEMENTARY	2	Classroom	1,510	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141032	INMAN ELEMENTARY	3	2 Storey Classroom	830	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
41	Burnaby	4141032	INMAN ELEMENTARY	4	Classroom 2003	?	Low	Low	Meets Structural Life Safety Requirements		
41	Burnaby	4141033	KITCHENER ELEMENTARY	1	Gymnasium	500	Low/Moderate	Low	Meets Structural Life Safety Requirements		
41	Burnaby	4141033	KITCHENER ELEMENTARY	2	1923 classroom	1,950	Low/Moderate	Low	Meets Structural Life Safety Requirements		
41	Burnaby	4141033	KITCHENER ELEMENTARY	3	Primary gymnasium	290	Moderate/High	Medium	Non Structural Upgrade Required	High 3	
41	Burnaby	4141033	KITCHENER ELEMENTARY	4	Primary classroom	1,740	Moderate	High 3	Structural Upgrade Required		
41	Burnaby	4141034	LAKEVIEW ELEMENTARY	1	Gymnasium	420	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141034	LAKEVIEW ELEMENTARY	2	2-Storey Classroom	1,840	High	Medium	Non Structural Upgrade Required	Medium	
41	Burnaby	4141034	LAKEVIEW ELEMENTARY	3	1-Storey Classroom	440	Moderate/High	Medium	Non Structural Upgrade Required		
41	Burnaby	4141035	LOCHDALE COMMUNITY	1	Gymnasium	560	Moderate/High	Medium	Non Structural Upgrade Required		
41	Burnaby	4141035	LOCHDALE COMMUNITY	2	Classroom/Administration	1,260	Moderate	Medium	Non Structural Upgrade Required	Medium	
41	Burnaby	4141035	LOCHDALE COMMUNITY	3	Classroom	1,070	Moderate/High	Medium	Non Structural Upgrade Required		
41	Burnaby	4141036	LYNDHURST ELEMENTARY	1	Gymnasium	200	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141036	LYNDHURST ELEMENTARY	2	Classroom	550	Moderate	Medium	Non Structural Upgrade Required	Medium	
41	Burnaby	4141036	LYNDHURST ELEMENTARY	3	2 Storey Classroom	970	Moderate/High	Medium	Non Structural Upgrade Required		
41	Burnaby	4141067	MARIAN EDUCATION CENTRE	1	Gymnasium	920	Moderate	Medium	Inactive		
41	Burnaby	4141067	MARIAN EDUCATION CENTRE	2	Classroom	2,430	High	High 1	Inactive	High 1	
41	Burnaby	4141037	MARLBOROUGH ELEMENTARY	1	Primary Gymnasium	350	Moderate/High	Medium	Non Structural Upgrade Required		
41	Burnaby	4141037	MARLBOROUGH ELEMENTARY	2	Primary Classrooms	3,340	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141037	MARLBOROUGH ELEMENTARY	3	West Gymnasium	720	Moderate	Medium	Non Structural Upgrade Required	High 3	
41	Burnaby	4141037	MARLBOROUGH ELEMENTARY	4	3-Storey Classroom	3,030	Moderate/High	High 3	Structural Upgrade Required		
41	Burnaby	4141037	MARLBOROUGH ELEMENTARY	5	Single Storey Classroom	1,600	Moderate/High	Medium	Non Structural Upgrade Required		
41	Burnaby	4141038	MAYWOOD COMMUNITY SCHOOL	1	Gymnasium	420	Moderate/High	Medium	Non Structural Upgrade Required		
41	Burnaby	4141038	MAYWOOD COMMUNITY SCHOOL	2	Classroom/Admin.	500	Moderate/High	High 3	Structural Upgrade Required		
41	Burnaby	4141038	MAYWOOD COMMUNITY SCHOOL	3	Club Metro	420	Moderate	Medium	Non Structural Upgrade Required	High 3	
41	Burnaby	4141038	MAYWOOD COMMUNITY SCHOOL	4	Single storey modular wing	?	Low	Low	Meets Structural Life Safety Requirements		
41	Burnaby	4141038	MAYWOOD COMMUNITY SCHOOL	5	2 storey 1998 classroom	?	Low	Low	Meets Structural Life Safety Requirements		
41	Burnaby	4141056	MONTECITO ELEMENTARY	2	Classroom/Administration	1,540	High	High 1	Supported 2013		
41	Burnaby	4141056	MONTECITO ELEMENTARY	1	Gymnasium	410	Moderate	Medium	Supported 2013	High 1	April 2013 - to start 2013.
41	Burnaby	4141039	MORLEY ELEMENTARY	1	Gymnasium	490	Low	Low	Meets Structural Life Safety Requirements		
41	Burnaby	4141039	MORLEY ELEMENTARY	2	Classroom	3,050	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141039	MORLEY ELEMENTARY	3	Classroom	290	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
41	Burnaby	4141039	MORLEY ELEMENTARY	4	Classroom (1999)	?	Low	Low	Meets Structural Life Safety Requirements		
41	Burnaby	4141011	MOSCROP JR SECONDARY	1	Gymnasium	650	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141011	MOSCROP JR SECONDARY	2	3-Storey Classroom	7,185	Low/Moderate	High 3	Structural Upgrade Required	High 3	November 2012 - Risk reviewed at SD request. H3 risk for blocks 2 & 3 confirmed.
41	Burnaby	4141011	MOSCROP JR SECONDARY	3	2-Storey Classroom	2,000	Low/Moderate	High 3	Structural Upgrade Required		
41	Burnaby	4141011	MOSCROP JR SECONDARY	4	2001 Additions	?	Low	Low	Meets Structural Life Safety Requirements		
41	Burnaby	4141040	NELSON ELEMENTARY	1	Gymnasium	790	Moderate/High	Medium	Non Structural Upgrade Required		
41	Burnaby	4141040	NELSON ELEMENTARY	2	2-Storey Classroom	1,800	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
41	Burnaby	4141040	NELSON ELEMENTARY	3	2-Storey Classroom	1,090	Moderate/High	Medium	Non Structural Upgrade Required		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
41	Burnaby	4141041	PARKCREST ELEMENTARY	1	Gymnasium	430	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141041	PARKCREST ELEMENTARY	2	1 Storey classroom	930	Moderate	Medium	Non Structural Upgrade Required	High 3	
41	Burnaby	4141041	PARKCREST ELEMENTARY	3	2 Storey classroom	1,880	High	High 3	Structural Upgrade Required		
41	Burnaby	4141044	ROSSER ELEMENTARY	1	Gymnasium	430	Moderate/High	High 3	Structural Upgrade Required	High 3	
41	Burnaby	4141044	ROSSER ELEMENTARY	2	Classroom	1,660	Moderate/High	Medium	Non Structural Upgrade Required		
41	Burnaby	4141045	SCHOU - RESOURCE CENTRE	1	Gymnasium	480	Moderate	Medium	Non Structural Upgrade Required	Medium	
41	Burnaby	4141045	SCHOU - RESOURCE CENTRE	2	1914 classroom	1,160	Moderate/High	Medium	Non Structural Upgrade Required		
41	Burnaby	4141046	SEAFORTH ELEMENTARY	1	Gymnasium	450	Low/Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141046	SEAFORTH ELEMENTARY	2	Classroom/Administration	1,100	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141046	SEAFORTH ELEMENTARY	3	Classroom	680	Moderate/High	High 3	Structural Upgrade Required	High 3	
41	Burnaby	4141046	SEAFORTH ELEMENTARY	4	Classroom	640	Low/Moderate	Low	Meets Structural Life Safety Requirements		
41	Burnaby	4141046	SEAFORTH ELEMENTARY	5	Classroom (1993)	?	Low	Low	Meets Structural Life Safety Requirements		
41	Burnaby	4141047	SECOND STREET COMMUNITY	1	Gymnasium	560	Moderate/High	Medium	Non Structural Upgrade Required		
41	Burnaby	4141047	SECOND STREET COMMUNITY	2	2-Storey Classroom	2,580	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
41	Burnaby	4141047	SECOND STREET COMMUNITY	3	2-Storey Classroom (1999)	?	Low	Low	Meets Structural Life Safety Requirements		
41	Burnaby	4141061	SOUTH SLOPE ELEMENTARY	1	Gymnasium	640	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141061	SOUTH SLOPE ELEMENTARY	2	Single Storey Classroom	1,320	Moderate	Medium	Non Structural Upgrade Required	Medium	
41	Burnaby	4141061	SOUTH SLOPE ELEMENTARY	3	Two Storey Classroom	2,870	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141048	SPERLING ELEMENTARY	1	Gymnasium	335	Moderate	Medium	Non Structural Upgrade Required	Medium	
41	Burnaby	4141048	SPERLING ELEMENTARY	2	Classroom	2,380	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141057	STONE CREEK ELEMENTARY	1	Gymnasium	500	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141057	STONE CREEK ELEMENTARY	2	Classrooms	2,180	High	High 3	Structural Upgrade Required	High 3	
41	Burnaby	4141057	STONE CREEK ELEMENTARY	3	Classroom	?	Low	Low	Meets Structural Life Safety Requirements		
41	Burnaby	4141049	STRIDE AVENUE ELEMENTARY	4	2-Storey Classroom	1,430	High	High 1	Supported 2013	High 1	April 2013 - to start 2015.
41	Burnaby	4141049	STRIDE AVENUE ELEMENTARY	1	Gymnasium	630	Moderate	Medium	Supported 2013		
41	Burnaby	4141049	STRIDE AVENUE ELEMENTARY	2	2-Storey Classroom	1,280	Moderate/High	Medium	Supported 2013		
41	Burnaby	4141049	STRIDE AVENUE ELEMENTARY	3	1-Storey Classroom	450	Moderate	Medium	Supported 2013		
41	Burnaby	4141050	SUNCREST ELEMENTARY	1	Gymnasium	330	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
41	Burnaby	4141050	SUNCREST ELEMENTARY	2	Classroom	2,130	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141052	TWELFTH AVENUE ELEMENTARY	1	Gymnasium	510	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141052	TWELFTH AVENUE ELEMENTARY	2	Library	260	Moderate	Medium	Non Structural Upgrade Required	Medium	
41	Burnaby	4141052	TWELFTH AVENUE ELEMENTARY	3	1958, 1962 Classrooms	970	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141052	TWELFTH AVENUE ELEMENTARY	4	1964, 1967, 1969 Classrooms	1,200	Moderate/High	Medium	Non Structural Upgrade Required		
41	Burnaby	4141053	WESTRIDGE ELEMENTARY	1	Gymnasium	330	Moderate	Medium	Non Structural Upgrade Required		
41	Burnaby	4141053	WESTRIDGE ELEMENTARY	2	Classroom	2,330	Moderate	Medium	Non Structural Upgrade Required	Medium	
41	Burnaby	4141053	WESTRIDGE ELEMENTARY	3	Classroom	380	Moderate/High	Medium	Non Structural Upgrade Required		
41	Burnaby	4141054	WINDSOR ELEMENTARY	1	Gymnasium	560	Moderate/High	Medium	Non Structural Upgrade Required		
41	Burnaby	4141054	WINDSOR ELEMENTARY	2	2 Storey Classroom	2,320	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
41	Burnaby	4141054	WINDSOR ELEMENTARY	3	1 Storey Classroom	700	Moderate	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242005	ALBION ELEMENTARY	1	Gymnasium	400	Moderate	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242005	ALBION ELEMENTARY	2	Classroom - East	1,085	Moderate	Medium	Non Structural Upgrade Required	Medium	
42	Maple Ridge/Pitt Meadows	4242005	ALBION ELEMENTARY	3	Classroom - North/West	620	Moderate	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242005	ALBION ELEMENTARY	4	Classroom - South/West	585	Low/Moderate	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242005	ALBION ELEMENTARY	5	Classroom Addition 2000	?	Low	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242035	ALOUETTE ELEMENTARY	1	Gymnasium	405	Moderate	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242035	ALOUETTE ELEMENTARY	2	Classrooms (1989)	2,540	Moderate	Medium	Non Structural Upgrade Required	Medium	
42	Maple Ridge/Pitt Meadows	4242035	ALOUETTE ELEMENTARY	3	Classrooms (1999)	?	Low	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242028	ARTHUR PEAKE CENTRE	1	Activity Room	149	Low/Moderate	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242028	ARTHUR PEAKE CENTRE	2	Classrooms/Administration	293	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
42	Maple Ridge/Pitt Meadows	4242028	ARTHUR PEAKE CENTRE	3	Classrooms (North)	140	Low/Moderate	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242031	DAVIE JONES ELEMENTARY	1	Gymnasium	575	Moderate	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242031	DAVIE JONES ELEMENTARY	2	1976 Classrooms	2,330	Moderate	Medium	Non Structural Upgrade Required	Medium	
42	Maple Ridge/Pitt Meadows	4242031	DAVIE JONES ELEMENTARY	3	1989 Classrooms	500	Low	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242008	ERIC LANGTON ELEMENTARY	1	Gymnasium	500	Moderate/High	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242008	ERIC LANGTON ELEMENTARY	2	Classrooms - Centre	1,130	Moderate	Medium	Non Structural Upgrade Required	Medium	
42	Maple Ridge/Pitt Meadows	4242008	ERIC LANGTON ELEMENTARY	3	Classrooms - North	805	Moderate/High	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242008	ERIC LANGTON ELEMENTARY	4	Library	285	Moderate/High	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242008	ERIC LANGTON ELEMENTARY	5	Classrooms - East	800	Moderate	Medium	Non Structural Upgrade Required		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
42	Maple Ridge/Pitt Meadows	4242009	FAIRVIEW ELEMENTARY	1	Classrooms (West)	907	Low/Moderate	Low	Meets Structural Life Safety Requirements	High 3	
42	Maple Ridge/Pitt Meadows	4242009	FAIRVIEW ELEMENTARY	2	Gymnasium & Classrooms	814	Moderate	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242009	FAIRVIEW ELEMENTARY	3	Classrooms (East wing)	1,032	Moderate/High	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242009	FAIRVIEW ELEMENTARY	4	Classrooms & Admin. (N/E)	692	Moderate	High 3	Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242002	GARIBALDI SECONDARY	1	Gymnasium	2,000	Moderate	N/A	Completed	N/A	
42	Maple Ridge/Pitt Meadows	4242002	GARIBALDI SECONDARY	2	Administration Wing	770	Moderate	N/A	Completed		
42	Maple Ridge/Pitt Meadows	4242002	GARIBALDI SECONDARY	3	Classrooms - 2-Storey	2,612	High	N/A	Completed		
42	Maple Ridge/Pitt Meadows	4242002	GARIBALDI SECONDARY	4	Classrooms and Administration	393	Moderate/High	N/A	Completed		
42	Maple Ridge/Pitt Meadows	4242002	GARIBALDI SECONDARY	5	Shops	1,664	Moderate	N/A	Completed		
42	Maple Ridge/Pitt Meadows	4242002	GARIBALDI SECONDARY	6	Classrooms - 1 Storey	1,647	Moderate	N/A	Completed		
42	Maple Ridge/Pitt Meadows	4242002	GARIBALDI SECONDARY	7	Cafeteria & Science Wing	1,340	Moderate	N/A	Completed		
42	Maple Ridge/Pitt Meadows	4242002	GARIBALDI SECONDARY	8	Auditorium - Upgraded in 1993	?	Low	N/A	Completed		
42	Maple Ridge/Pitt Meadows	4242010	GLENWOOD ELEMENTARY	1	Classrooms-South wing	1,670	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
42	Maple Ridge/Pitt Meadows	4242010	GLENWOOD ELEMENTARY	2	Gymnasium	436	Low/Moderate	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242010	GLENWOOD ELEMENTARY	3	Classrooms-North wing	1,367	Low/Moderate	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242011	GOLDEN EARS ELEMENTARY	1	Gymnasium	415	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
42	Maple Ridge/Pitt Meadows	4242011	GOLDEN EARS ELEMENTARY	2	Classrooms-West	790	Moderate/High	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242011	GOLDEN EARS ELEMENTARY	3	Classrooms-East	950	Moderate	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242011	GOLDEN EARS ELEMENTARY	4	Classrooms-South/West	465	Moderate/High	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242011	GOLDEN EARS ELEMENTARY	5	Administration/Classrooms-1996	?	Low	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242011	GOLDEN EARS ELEMENTARY	6	Classrooms-South/East-1999	?	Low	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242036	HARRY HOOGE ELEMENTARY	1	Gymnasium	395	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
42	Maple Ridge/Pitt Meadows	4242036	HARRY HOOGE ELEMENTARY	2	Classrooms/Admin/Other	2,635	Low/Moderate	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242036	HARRY HOOGE ELEMENTARY	3	Classroom addition (1992)	?	Low	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242033	HIGHLAND PARK ELEMENTARY	1	Gymnasium and Services	552	Moderate	Medium	Non Structural Upgrade Required	Medium	
42	Maple Ridge/Pitt Meadows	4242033	HIGHLAND PARK ELEMENTARY	2	Classrooms and Administration	1,044	Low/Moderate	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242033	HIGHLAND PARK ELEMENTARY	3	Classrooms	1,208	Low/Moderate	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242032	LAITY VIEW ELEMENTARY	1	Classrooms (1978 & 1981)	1,920	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
42	Maple Ridge/Pitt Meadows	4242032	LAITY VIEW ELEMENTARY	2	Gymnasium	520	Moderate	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242032	LAITY VIEW ELEMENTARY	3	Classrooms & Library (1991)	1,420	Low	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242032	LAITY VIEW ELEMENTARY	4	Classrooms (2001)	?	Low	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242014	MAPLE RIDGE ELEMENTARY	1	Washrooms/Change rooms	600	Moderate	Medium	Non Structural Upgrade Required	Medium	
42	Maple Ridge/Pitt Meadows	4242014	MAPLE RIDGE ELEMENTARY	2	Classrooms	1,200	Moderate/High	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242014	MAPLE RIDGE ELEMENTARY	3	Gymnasium	465	Moderate/High	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242014	MAPLE RIDGE ELEMENTARY	4	Classrooms 1993	?	Low	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242001	MAPLE RIDGE SECONDARY	1	Gymnasium	995	High	Medium	Non Structural Upgrade Required	Medium	
42	Maple Ridge/Pitt Meadows	4242001	MAPLE RIDGE SECONDARY	2	West Wing (Science)	3,315	Low/Moderate	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242001	MAPLE RIDGE SECONDARY	3	SE Classroom Block	?	Low	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242001	MAPLE RIDGE SECONDARY	4	Arts and Shops Block	?	Low	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242016	MOUNT CRESCENT ELEMENTARY	1	Classroom (North)	960	Low	Low	Inactive	Medium	
42	Maple Ridge/Pitt Meadows	4242016	MOUNT CRESCENT ELEMENTARY	2	Gymnasium	578	Moderate	Medium	Inactive		
42	Maple Ridge/Pitt Meadows	4242016	MOUNT CRESCENT ELEMENTARY	3	Classroom (Central)	276	Moderate	Medium	Inactive		
42	Maple Ridge/Pitt Meadows	4242016	MOUNT CRESCENT ELEMENTARY	4	Classroom (West)	364	Moderate	Medium	Inactive		
42	Maple Ridge/Pitt Meadows	4242016	MOUNT CRESCENT ELEMENTARY	5	Classrooms	1,000	Moderate	Medium	Inactive		
42	Maple Ridge/Pitt Meadows	4242016	MOUNT CRESCENT ELEMENTARY	6	Classroom (1999 addition)	?	Low	Low	Inactive		
42	Maple Ridge/Pitt Meadows	4242017	PITT MEADOWS ELEMENTARY	1	Gymnasium	620	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
42	Maple Ridge/Pitt Meadows	4242017	PITT MEADOWS ELEMENTARY	2	Classroom (North)	1,413	Moderate/High	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242017	PITT MEADOWS ELEMENTARY	3	Classroom (South)	687	Moderate	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242017	PITT MEADOWS ELEMENTARY	4	Classroom (West)	?	Low	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242017	PITT MEADOWS ELEMENTARY	5	Classroom (South-West)	221	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
42	Maple Ridge/Pitt Meadows	4242003	PITT MEADOWS SECONDARY	1	Gymnasium	1,866	Moderate	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242003	PITT MEADOWS SECONDARY	2	Exercise Room	840	Low	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242003	PITT MEADOWS SECONDARY	3	Classrooms	3,750	Moderate	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242003	PITT MEADOWS SECONDARY	4	Library and Classrooms	1,610	Moderate/High	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242003	PITT MEADOWS SECONDARY	5	Shops	945	Moderate	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242003	PITT MEADOWS SECONDARY	6	Administration	953	Moderate/High	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242003	PITT MEADOWS SECONDARY	7	Multi-Purpose	1,372	Moderate/High	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242003	PITT MEADOWS SECONDARY	8	Classrooms - Upgraded 1999	?	Low	Low	Meets Structural Life Safety Requirements		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
42	Maple Ridge/Pitt Meadows	4242034	RIVERSIDE ELEMENTARY	1	Gymnasium	400	Moderate/High	Medium	Inactive		
42	Maple Ridge/Pitt Meadows	4242034	RIVERSIDE ELEMENTARY	2	Classrooms (South)	1,840	Low	Low	Inactive	Medium	
42	Maple Ridge/Pitt Meadows	4242034	RIVERSIDE ELEMENTARY	3	Classrooms (North)	1,720	Low	Low	Inactive		
42	Maple Ridge/Pitt Meadows	4242020	WEBSTERS CORNER ELEMENTARY	1	Gymnasium (upgraded 1993)	?	Low	Low	Meets Structural Life Safety Requirements		
42	Maple Ridge/Pitt Meadows	4242020	WEBSTERS CORNER ELEMENTARY	2	Classroom (East) upgraded 1993	?	Low	Low	Meets Structural Life Safety Requirements	Medium	
42	Maple Ridge/Pitt Meadows	4242020	WEBSTERS CORNER ELEMENTARY	3	Classroom (South)	590	Moderate	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242020	WEBSTERS CORNER ELEMENTARY	4	Multi Purpose/Classroom	180	Moderate	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242004	WESTVIEW SECONDARY	1	Classrooms/Multipurpose	4,420	Moderate	High 3	Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242004	WESTVIEW SECONDARY	2	Gymnasium	1,595	Moderate	Medium	Non Structural Upgrade Required	High 3	
42	Maple Ridge/Pitt Meadows	4242004	WESTVIEW SECONDARY	3	Classrooms/Library	2,600	Moderate	Medium	Non Structural Upgrade Required		
42	Maple Ridge/Pitt Meadows	4242004	WESTVIEW SECONDARY	4	Classrooms/Shops - 1995, 1999	?	Low	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343002	ANMORE ELEMENTARY	1	Classrooms	1,063	Moderate	N/A	Completed		
43	Coquitlam	4343002	ANMORE ELEMENTARY	2	Old Gymnasium	172	Moderate	N/A	Completed	N/A	
43	Coquitlam	4343002	ANMORE ELEMENTARY	3	New Gymnasium	?	Low	N/A	Completed		
43	Coquitlam	4343005	BAKER DRIVE ELEMENTARY	1	1969 2-storey classroom	1,960	High	N/A	Completed	N/A	
43	Coquitlam	4343005	BAKER DRIVE ELEMENTARY	2	1969 gymnasium	400	High	N/A	Completed		
43	Coquitlam	4343093	BANTING MIDDLE	1	Gymnasium	616	Moderate/High	Medium	Supported (May 2012)		
43	Coquitlam	4343093	BANTING MIDDLE	2	Shops and Cafeteria	1,878	Moderate/High	High 3	Supported (May 2012)		
43	Coquitlam	4343093	BANTING MIDDLE	3	Classrooms & Administration	2,026	Moderate/High	High 1	Supported (May 2012)	High 1	
43	Coquitlam	4343093	BANTING MIDDLE	4	Classrooms	1,844	Moderate/High	High 1	Supported (May 2012)		
43	Coquitlam	4343093	BANTING MIDDLE	5	Shops and Music Room	934	Moderate/High	Medium	Supported (May 2012)		
43	Coquitlam	4343006	BIRCHLAND ELEMENTARY	1	Gymnasium	400	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
43	Coquitlam	4343006	BIRCHLAND ELEMENTARY	2	Classroom/Admin	3,310	Low/Moderate	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343010	CAPE HORN ELEMENTARY	1	North Classroom	980	Moderate	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343010	CAPE HORN ELEMENTARY	2	Activity Room	585	High	Medium	Non Structural Upgrade Required	Medium	
43	Coquitlam	4343010	CAPE HORN ELEMENTARY	3	South Classroom	1,270	Moderate	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343011	CEDAR DRIVE ELEMENTARY	1	Gymnasium	400	High	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343011	CEDAR DRIVE ELEMENTARY	2	Classrooms (South)	629	Moderate	High 3	Structural Upgrade Required	High 3	
43	Coquitlam	4343011	CEDAR DRIVE ELEMENTARY	3	Classrooms /Admin (1994 upgrade)	?	Low	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343076	CENTENNIAL SECONDARY	1	1965 2-storey classroom	8,440	High	High 3	Proceeding to Construction		
43	Coquitlam	4343076	CENTENNIAL SECONDARY	2	1968 2-storey classroom	2,130	High	High 1	Proceeding to Construction		
43	Coquitlam	4343076	CENTENNIAL SECONDARY	3	1965 shops	1,770	High	High 1	Proceeding to Construction	High 1	
43	Coquitlam	4343076	CENTENNIAL SECONDARY	4	1965 gym / theatre	3,490	Low/Moderate	High 3	Proceeding to Construction		
43	Coquitlam	4343076	CENTENNIAL SECONDARY	5	1970 2-storey classroom	1,900	High	High 1	Proceeding to Construction		
43	Coquitlam	4343076	CENTENNIAL SECONDARY	6	2001 gym	?	Low	Low	Proceeding to Construction		
43	Coquitlam	4343012	CENTRAL ELEMENTARY	1	1954-1973 Classrooms & gymnasium	2,400	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
43	Coquitlam	4343012	CENTRAL ELEMENTARY	2	1993 & 2001 Additions	?	Low	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343014	COLLEGE PARK ELEMENTARY	1	Gym	250	Moderate/High	Medium	Inactive		
43	Coquitlam	4343014	COLLEGE PARK ELEMENTARY	2	1971 Classroom	1,180	High	High 3	Inactive	High 3	
43	Coquitlam	4343014	COLLEGE PARK ELEMENTARY	3	1976 Classroom	250	Low	Low	Inactive		
43	Coquitlam	4343078	COMO LAKE MIDDLE	1	Main Building	4,360	High	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343078	COMO LAKE MIDDLE	2	Gymnasium	1,700	High	Medium	Non Structural Upgrade Required	Medium	
43	Coquitlam	4343078	COMO LAKE MIDDLE	3	Classroom	1,650	Moderate/High	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343060	COQUITLAM ALTERNATE BASIC EDUCATION (CABE)	1	Original Classroom Building	325	Moderate	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343060	COQUITLAM ALTERNATE BASIC EDUCATION (CABE)	2	1965 & 1969 Addition	500	Moderate	Medium	Non Structural Upgrade Required	Medium	
43	Coquitlam	4343060	COQUITLAM ALTERNATE BASIC EDUCATION (CABE)	3	1979 Addition	350	Moderate	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343015	CORONATION PARK ELEMENTARY	1	Gymnasium	540	High	High 3	Inactive		
43	Coquitlam	4343015	CORONATION PARK ELEMENTARY	2	Classrooms/Admin	2,060	Moderate	High 3	Inactive	High 3	
43	Coquitlam	4343015	CORONATION PARK ELEMENTARY	3	Montessori	120	Low/Moderate	High 3	Inactive		
43	Coquitlam	4343080	DR. CHARLES BEST SECONDARY	1	1969 3-storey classroom	4,900	Moderate/High	High 3	Structural Upgrade Required		
43	Coquitlam	4343080	DR. CHARLES BEST SECONDARY	2	1969 1-storey classroom	2,300	Moderate	High 3	Structural Upgrade Required		
43	Coquitlam	4343080	DR. CHARLES BEST SECONDARY	3	1969 Cafeteria & Gymnasium	1,180	Moderate	High 3	Structural Upgrade Required	High 3	
43	Coquitlam	4343080	DR. CHARLES BEST SECONDARY	4	1999 2-storey classroom	?	Low	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343080	DR. CHARLES BEST SECONDARY	5	1999 gymnasium	?	Low	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343020	EAGLE RIDGE ELEMENTARY	1	Original Classroom	1,400	High	N/A	Completed		
43	Coquitlam	4343020	EAGLE RIDGE ELEMENTARY	2	Gymnasium	430	Moderate/High	N/A	Completed	N/A	
43	Coquitlam	4343020	EAGLE RIDGE ELEMENTARY	3	1984 Two Storey Addition	650	Low/Moderate	N/A	Completed		
43	Coquitlam	4343020	EAGLE RIDGE ELEMENTARY	4	2004 repair to fire damage	?	Low	N/A	Completed		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
43	Coquitlam	4343019	GLENAYRE ELEMENTARY	1	East Classroom	1,560	Moderate	Medium	Non Structural Upgrade Required	High 3	
43	Coquitlam	4343019	GLENAYRE ELEMENTARY	2	West Classroom	1,755	Moderate/High	High 3	Structural Upgrade Required		
43	Coquitlam	4343019	GLENAYRE ELEMENTARY	3	Gymnasium	400	Moderate	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343021	HARBOUR VIEW ELEMENTARY	1	1963 1-storey classroom	2,230	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
43	Coquitlam	4343021	HARBOUR VIEW ELEMENTARY	2	1970 1-storey classrooms	390	Moderate	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343021	HARBOUR VIEW ELEMENTARY	3	1963 gymnasium	350	Moderate/High	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343022	HAZEL TREMBATH ELEMENTARY	1	Classroom	2,825	Low	Low	Meets Structural Life Safety Requirements	Low	
43	Coquitlam	4343022	HAZEL TREMBATH ELEMENTARY	2	Gymnasium	485	Low	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343024	HILLCREST MIDDLE	1	Classrooms	2,487	High	High 3	Structural Upgrade Required	High 3	
43	Coquitlam	4343024	HILLCREST MIDDLE	2	Multipurpose Room	567	Moderate	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343024	HILLCREST MIDDLE	3	Shops	920	Moderate	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343024	HILLCREST MIDDLE	4	Classrooms & Gym -'98 Addition	?	Low	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343026	IOCO SCHOOL	1	Activity Room	260	Moderate/High	Medium	Inactive	Medium	
43	Coquitlam	4343026	IOCO SCHOOL	2	Classrooms	800	Moderate/High	Medium	Inactive		
43	Coquitlam	4343027	IRVINE ELEMENTARY	2	South - Classroom	930	Moderate/High	Medium	Supported 2013	High 2	April 2013 - to start 2015.
43	Coquitlam	4343027	IRVINE ELEMENTARY	3	West - Gym	420	Moderate/High	High 3	Supported 2013		
43	Coquitlam	4343027	IRVINE ELEMENTARY	1	North - Classroom	2,380	Moderate/High	High 2	Supported 2013		
43	Coquitlam	4343029	JAMES PARK ELEMENTARY	1	Gymnasium	475	High	N/A	Completed	N/A	
43	Coquitlam	4343029	JAMES PARK ELEMENTARY	2	Classrooms (West)	1,284	High	N/A	Completed		
43	Coquitlam	4343029	JAMES PARK ELEMENTARY	3	Classrooms (East)	652	High	N/A	Completed		
43	Coquitlam	4343029	JAMES PARK ELEMENTARY	4	Classrooms (South-East)	1,018	Moderate/High	N/A	Completed		
43	Coquitlam	4343031	KILMER ELEMENTARY	1	West Classroom	2,260	Low	Low	Meets Structural Life Safety Requirements	Low	
43	Coquitlam	4343031	KILMER ELEMENTARY	2	East Administration and Gym	?	Low	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343033	LEIGH ELEMENTARY	1	Gymnasium	511	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
43	Coquitlam	4343033	LEIGH ELEMENTARY	2	Classrooms (North)	811	Moderate/High	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343033	LEIGH ELEMENTARY	3	Classrooms (West)	893	Moderate/High	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343033	LEIGH ELEMENTARY	4	Classrooms and Administration	1,385	Moderate	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343032	LINCOLN ELEMENTARY	1	Classrooms	1,212	High	High 1	Inactive	High 1	
43	Coquitlam	4343032	LINCOLN ELEMENTARY	2	Gymnasium	238	High	High 1	Inactive		
43	Coquitlam	4343034	LORD BADEN-POWELL ELEMENTARY	1	Gymnasium	740	High	N/A	Completed	N/A	
43	Coquitlam	4343034	LORD BADEN-POWELL ELEMENTARY	2	Classrooms - East	1,720	High	N/A	Completed		
43	Coquitlam	4343034	LORD BADEN-POWELL ELEMENTARY	3	Classrooms - West	975	High	N/A	Completed		
43	Coquitlam	4343081	MAILLARD MIDDLE	1	Original Building	3,150	High	N/A	Completed	N/A	
43	Coquitlam	4343081	MAILLARD MIDDLE	2	Gymnasium	525	High	N/A	Completed		
43	Coquitlam	4343081	MAILLARD MIDDLE	3	1999 Addition	?	Low	N/A	Completed		
43	Coquitlam	4343091	MAPLE CREEK MIDDLE	1	Gymnasium	807	Low/Moderate	High 3	Structural Upgrade Required	High 2	December 2012 - Re-assessment of gymnasium changed risk from L to H3.
43	Coquitlam	4343091	MAPLE CREEK MIDDLE	3	Classrooms - 1999 Addition	?	Low	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343091	MAPLE CREEK MIDDLE	2	Classrooms	4,314	High	High 2	Structural Upgrade Required		
43	Coquitlam	4343036	MARY HILL ELEMENTARY	1	South Classroom	1,560	High	High 3	Structural Upgrade Required	High 3	
43	Coquitlam	4343036	MARY HILL ELEMENTARY	2	North Classroom	1,250	Moderate/High	High 3	Structural Upgrade Required		
43	Coquitlam	4343036	MARY HILL ELEMENTARY	3	Gymnasium	350	Moderate/High	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343037	MEADOWBROOK ELEMENTARY	1	1975 1-storey classroom	2,060	Low	N/A	Completed	N/A	
43	Coquitlam	4343037	MEADOWBROOK ELEMENTARY	2	1967 gymnasium	350	Moderate	N/A	Completed		
43	Coquitlam	4343038	MILLER PARK COMMUNITY SCHOOL	1	East - Classroom	970	High	N/A	Completed	N/A	
43	Coquitlam	4343038	MILLER PARK COMMUNITY SCHOOL	2	North - Gym	415	Moderate/High	N/A	Completed		
43	Coquitlam	4343038	MILLER PARK COMMUNITY SCHOOL	3	West - Classroom	1,980	High	N/A	Completed		
43	Coquitlam	4343039	MILLSIDE ELEMENTARY	1	Main Building	1,860	Moderate/High	Medium	Inactive	Medium	
43	Coquitlam	4343039	MILLSIDE ELEMENTARY	2	Annex	1,020	Low	Low	Inactive		
43	Coquitlam	4343090	MINNEKHADA MIDDLE	1	Main Building	4,550	High	High 1	Supported 2013	High 1	April 2013 - to start 2014.
43	Coquitlam	4343090	MINNEKHADA MIDDLE	2	Gymnasium	3,200	Moderate/High	High 2	Supported 2013		
43	Coquitlam	4343090	MINNEKHADA MIDDLE	3	Technical/Art	1,120	Moderate	High 2	Supported 2013		
43	Coquitlam	4343084	MONTGOMERY MIDDLE	1	Main Building	4,560	High	High 1	Supported 2013	High 1	April 2013 - to start 2015.
43	Coquitlam	4343084	MONTGOMERY MIDDLE	3	Classroom Addition	2,050	High	High 1	Supported 2013		
43	Coquitlam	4343084	MONTGOMERY MIDDLE	2	Music/Industrial Arts	1,160	Moderate/High	Medium	Supported 2013		
43	Coquitlam	4343043	MOODY ELEMENTARY	1	1950 1-storey classroom	1,780	Moderate/High	High 2	Structural Upgrade Required	High 2	November 2012 - Risk re-assessment changed Block 1 from M to H2, Block 2 from M to H3, and for Block 3 from M to L (poor soils).
43	Coquitlam	4343043	MOODY ELEMENTARY	2	2-storey classroom	1,016	High	High 3	Structural Upgrade Required		
43	Coquitlam	4343043	MOODY ELEMENTARY	3	1976 gymnasium	610	Moderate/High	Low	Meets Structural Life Safety Requirements		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
43	Coquitlam	4343086	MOODY MIDDLE	1	Classrooms	2,988	High	Medium	Proceeding to Construction	High 3	
43	Coquitlam	4343086	MOODY MIDDLE	2	Industrial Arts	1,507	Moderate/High	Medium	Proceeding to Construction		
43	Coquitlam	4343086	MOODY MIDDLE	3	Gymnasium & Cafeteria	2,194	High	High 3	Proceeding to Construction		
43	Coquitlam	4343086	MOODY MIDDLE	4	Learning Resource Center	539	High	High 3	Proceeding to Construction		
43	Coquitlam	4343086	MOODY MIDDLE	5	New Gym Addition	255	Low	Low	Proceeding to Construction		
43	Coquitlam	4343045	MOUNTAIN MEADOWS ELEMENTARY	1	Original structure 1987	1,665	Moderate	Medium	Non Structural Upgrade Required	Medium	
43	Coquitlam	4343045	MOUNTAIN MEADOWS ELEMENTARY	2	Gymnasium	402	Moderate	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343045	MOUNTAIN MEADOWS ELEMENTARY	3	Addition 1989	1,326	Moderate	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343044	MOUNTAIN VIEW ELEMENTARY	1	Single storey classrooms	1,600	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
43	Coquitlam	4343044	MOUNTAIN VIEW ELEMENTARY	2	Gymnasium	510	High	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343044	MOUNTAIN VIEW ELEMENTARY	3	Two storey classrooms	1,200	High	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343046	MUNDY ROAD ELEMENTARY	1	Classroom Additions	1,810	Low	Low	Meets Structural Life Safety Requirements	Low	
43	Coquitlam	4343046	MUNDY ROAD ELEMENTARY	2	Original Building	640	Low	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343046	MUNDY ROAD ELEMENTARY	3	Multi-Purpose Room	500	Low	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343047	NESTOR ELEMENTARY	1	Gymnasium	360	Low/Moderate	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343047	NESTOR ELEMENTARY	2	Classrooms/library	2,069	Low/Moderate	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343047	NESTOR ELEMENTARY	3	Classrooms (South)	923	Moderate	Medium	Non Structural Upgrade Required	Medium	
43	Coquitlam	4343047	NESTOR ELEMENTARY	4	Admin./Kindergarten (post 1992)	?	Low	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343048	PANORAMA HEIGHTS ELEMENTARY	1	Gymnasium	490	Low	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343048	PANORAMA HEIGHTS ELEMENTARY	2	Classrooms	2,750	Low	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343048	PANORAMA HEIGHTS ELEMENTARY	3	Central Hallway	175	Low	Low	Meets Structural Life Safety Requirements	Low	
43	Coquitlam	4343049	PARKLAND ELEMENTARY	1	North-West Block	1,500	Moderate	N/A	Completed		
43	Coquitlam	4343049	PARKLAND ELEMENTARY	2	South-East Block	2,000	Low/Moderate	N/A	Completed		
43	Coquitlam	4343050	PINETREE WAY ELEMENTARY	1	Gymnasium	546	Low	Low	Meets Structural Life Safety Requirements	Low	
43	Coquitlam	4343050	PINETREE WAY ELEMENTARY	2	Classrooms - West	1,183	Low	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343050	PINETREE WAY ELEMENTARY	3	Rotunda at Entrance	415	Low	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343050	PINETREE WAY ELEMENTARY	4	Classrooms - East	1,081	Low/Moderate	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343082	PITT RIVER MIDDLE	1	Main Building	4,700	High	N/A	Under Construction		
43	Coquitlam	4343082	PITT RIVER MIDDLE	2	North Gym	490	High	N/A	Under Construction	N/A	
43	Coquitlam	4343082	PITT RIVER MIDDLE	3	East Classroom	1,460	High	N/A	Under Construction		
43	Coquitlam	4343082	PITT RIVER MIDDLE	4	Music Room	240	High	N/A	Under Construction		
43	Coquitlam	4343082	PITT RIVER MIDDLE	5	Shop Wing	600	High	N/A	Under Construction		
43	Coquitlam	4343051	PLEASANTSIDE ELEMENTARY	1	Gymnasium	320	High	N/A	Completed		
43	Coquitlam	4343051	PLEASANTSIDE ELEMENTARY	2	1967 and 1976 Classrooms	1,860	High	N/A	Completed	N/A	
43	Coquitlam	4343051	PLEASANTSIDE ELEMENTARY	3	1980 Classrooms	300	Moderate	N/A	Completed		
43	Coquitlam	4343088	PORT MOODY SECONDARY	1	North Classroom Block	2,000	Low/Moderate	High 3	Structural Upgrade Required		
43	Coquitlam	4343088	PORT MOODY SECONDARY	2	South Classroom Block	1,500	Low/Moderate	High 3	Structural Upgrade Required	High 3	
43	Coquitlam	4343088	PORT MOODY SECONDARY	3	Gymnasium / Music / Media Rooms	2,000	Low	Low	Meets Structural Life Safety Requirements		
43	Coquitlam	4343053	PORTER STREET ELEMENTARY	1	Classroom Block	2,840	High	N/A	Completed	N/A	
43	Coquitlam	4343053	PORTER STREET ELEMENTARY	2	Gym Block	520	Moderate/High	N/A	Completed		
43	Coquitlam	4343023	R C MACDONALD ELEMENTARY	1	Classroom Block	1,040	Moderate	N/A	Completed	N/A	
43	Coquitlam	4343023	R C MACDONALD ELEMENTARY	2	Gym Block	230	Moderate	N/A	Completed		
43	Coquitlam	4343054	RANCH PARK ELEMENTARY	1	1962 1-storey classroom	2,440	Moderate/High	N/A	Completed	N/A	
43	Coquitlam	4343054	RANCH PARK ELEMENTARY	2	1962 gymnasium	435	High	N/A	Completed		
43	Coquitlam	4343055	ROCHESTER ELEMENTARY	1	Classroom	2,970	Low	N/A	Completed	N/A	
43	Coquitlam	4343055	ROCHESTER ELEMENTARY	2	Gymnasium	315	High	N/A	Completed		
43	Coquitlam	4343055	ROCHESTER ELEMENTARY	3	Dressing Rooms	190	Moderate/High	N/A	Completed		
43	Coquitlam	4343056	ROY STIBBS ELEMENTARY	1	Single Storey Admin	450	Moderate/High	N/A	Completed		
43	Coquitlam	4343056	ROY STIBBS ELEMENTARY	2	Gymnasium	300	Moderate/High	N/A	Completed		
43	Coquitlam	4343056	ROY STIBBS ELEMENTARY	3	1994 Two-Storey Classroom	?	Low	N/A	Completed	N/A	
43	Coquitlam	4343058	SEAVIEW COMMUNITY SCHOOL	1	1964 & 1966 classrooms	1,500	Moderate/High	N/A	Completed		
43	Coquitlam	4343058	SEAVIEW COMMUNITY SCHOOL	2	1966 Activity Room	750	High	N/A	Completed	N/A	
43	Coquitlam	4343058	SEAVIEW COMMUNITY SCHOOL	3	1968 classrooms	1,200	High	N/A	Completed		
43	Coquitlam	4343066	VANIER ELEMENTARY	1	Classroom	2,800	Moderate	High 3	Inactive	High 3	
43	Coquitlam	4343066	VANIER ELEMENTARY	2	Gym	520	High	High 3	Inactive		
43	Coquitlam	4343069	WALTON ELEMENTARY	1	Original Structure	2,320	Moderate	Medium	Non Structural Upgrade Required	Medium	
43	Coquitlam	4343069	WALTON ELEMENTARY	2	School Addition	1,400	Moderate	Medium	Non Structural Upgrade Required		
43	Coquitlam	4343070	WESTWOOD ELEMENTARY	1	Original 1969 structure	1,500	High	N/A	Completed		
43	Coquitlam	4343070	WESTWOOD ELEMENTARY	2	1992 Gymnasium Addition	480	Low/Moderate	N/A	Completed	N/A	
43	Coquitlam	4343070	WESTWOOD ELEMENTARY	3	1992 Classroom BBlock Addition	1,035	Low/Moderate	N/A	Completed		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
44	North Vancouver	4444022	ARGYLE SECONDARY	1	1960 two-storey classroom	4,550	High	High 3	Supported (May 2012)	High 1	March 2013 - Blocks 2 & 6 risk increased from M to H2
44	North Vancouver	4444022	ARGYLE SECONDARY	2	1960 gymnasium	700	High	High 2	Supported (May 2012)		
44	North Vancouver	4444022	ARGYLE SECONDARY	3	1969 three-storey classroom	4,000	High	High 1	Supported (May 2012)		
44	North Vancouver	4444022	ARGYLE SECONDARY	4	1969 gymnasium	1,150	Moderate/High	High 3	Supported (May 2012)		
44	North Vancouver	4444022	ARGYLE SECONDARY	5	1969 two-storey classroom	750	Moderate/High	High 3	Supported (May 2012)		
44	North Vancouver	4444022	ARGYLE SECONDARY	6	1966 single-storey shop wing	1,700	Moderate/High	High 2	Supported (May 2012)		
44	North Vancouver	4444022	ARGYLE SECONDARY	7	2000 Library & Cafeteria Add'n	?	Low	Low	Supported (May 2012)		
44	North Vancouver	4444020	BALMORAL JR SECONDARY	1	1959 Three-Storey Classroom	5,220	Moderate/High	High 3	Structural Upgrade Required	High 3	
44	North Vancouver	4444020	BALMORAL JR SECONDARY	2	1959 Gymnasium	800	Moderate/High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444020	BALMORAL JR SECONDARY	3	1959 Two-Storey Administration	1,775	Moderate/High	High 3	Structural Upgrade Required		
44	North Vancouver	4444041	BLUERIDGE ELEMENTARY	1	SW Classrooms	1,140	Moderate	Medium	Inactive	Medium	
44	North Vancouver	4444041	BLUERIDGE ELEMENTARY	2	NW Classrooms	820	Low/Moderate	Low	Inactive		
44	North Vancouver	4444041	BLUERIDGE ELEMENTARY	3	SE Gymnasium	650	Low	Low	Inactive		
44	North Vancouver	4444041	BLUERIDGE ELEMENTARY	4	NE Classrooms	830	Moderate	Medium	Inactive		
44	North Vancouver	4444043	BOUNDARY COMMUNITY ELEMENTARY	1	West Classrooms	840	Moderate	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444043	BOUNDARY COMMUNITY ELEMENTARY	2	Gymnasium	880	Moderate	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444043	BOUNDARY COMMUNITY ELEMENTARY	3	Library & Multi-Purpose	550	Moderate	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444043	BOUNDARY COMMUNITY ELEMENTARY	4	East Classrooms	1,050	Low	Low	Meets Structural Life Safety Requirements	Medium	
44	North Vancouver	4444024	BRAEMAR ELEMENTARY	1	East Classrooms	1,240	High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444024	BRAEMAR ELEMENTARY	2	West and Central Classrooms	1,840	Moderate/High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444024	BRAEMAR ELEMENTARY	3	Gymnasium	700	Moderate	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444024	BRAEMAR ELEMENTARY	4	Library and Multi-Purpose	920	Low	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444037	BROOKSBANK ELEMENTARY	1	North Classroom Wing	950	Moderate/High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444037	BROOKSBANK ELEMENTARY	2	South Classroom Wing	950	Moderate/High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444037	BROOKSBANK ELEMENTARY	3	Central Classrooms and Gymnasium	1,500	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
44	North Vancouver	4444014	CANYON HEIGHTS ELEMENTARY	1	gymnasium	680	Low	N/A	Completed		
44	North Vancouver	4444014	CANYON HEIGHTS ELEMENTARY	2	1-storey classroom/admin.	920	Moderate	N/A	Completed		
44	North Vancouver	4444014	CANYON HEIGHTS ELEMENTARY	3	2-storey classroom block	2,440	Moderate/High	N/A	Completed	N/A	
44	North Vancouver	4444008	CAPILANO ELEMENTARY	1	original 2-storey classroom	1,400	High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444008	CAPILANO ELEMENTARY	2	1958 gymnasium	350	Moderate	Medium	Non Structural Upgrade Required	Medium	
44	North Vancouver	4444008	CAPILANO ELEMENTARY	3	1958/1963 2-storey classroom	900	High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444008	CAPILANO ELEMENTARY	4	Two-Storey Classroom	?	Low	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444023	CARISBROOKE ELEMENTARY	1	1959 two-storey classroom	1,700	High	N/A	Completed	N/A	
44	North Vancouver	4444023	CARISBROOKE ELEMENTARY	2	1959 classroom	350	High	N/A	Completed		
44	North Vancouver	4444023	CARISBROOKE ELEMENTARY	3	1962 two-storey classroom add'n	600	High	N/A	Completed		
44	North Vancouver	4444023	CARISBROOKE ELEMENTARY	4	1969 library	200	Moderate	N/A	Completed		
44	North Vancouver	4444023	CARISBROOKE ELEMENTARY	5	2001 Gymnasium & Administration	?	Low	N/A	Completed		
44	North Vancouver	4444036	CARSON GRAHAM SECONDARY	1	1964 Administration/ Classroom Wing	3,740	High	N/A	Completed		
44	North Vancouver	4444036	CARSON GRAHAM SECONDARY	2	1964 Gymnasium	1,900	High	N/A	Completed		
44	North Vancouver	4444036	CARSON GRAHAM SECONDARY	3	1964 Vocational	1,595	High	N/A	Completed	N/A	Completed Fall 2012
44	North Vancouver	4444036	CARSON GRAHAM SECONDARY	4	1964 Electronics Wing	410	Low	N/A	Completed		
44	North Vancouver	4444036	CARSON GRAHAM SECONDARY	5	1964 Shops Wing	1,260	High	N/A	Completed		
44	North Vancouver	4444036	CARSON GRAHAM SECONDARY	6	1966/1973 Classroom Addition	2,000	High	N/A	Completed		
44	North Vancouver	4444036	CARSON GRAHAM SECONDARY	7	1966 Vocational Wing Addition	1,200	High	N/A	Completed		
44	North Vancouver	4444036	CARSON GRAHAM SECONDARY	8	2001 Gymnasium/Administration Add'n	?	Low	N/A	Completed		
44	North Vancouver	4444027	CLEVELAND ELEMENTARY	1	1962 two-storey classroom	2,500	Low	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444027	CLEVELAND ELEMENTARY	2	1962 gymnasium	400	Low	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444027	CLEVELAND ELEMENTARY	3	1967 single-storey classroom	1,100	Moderate/High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444027	CLEVELAND ELEMENTARY	4	1988 single-storey multi-purpose	170	Low	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444000	CONTINUING ED SD 44	1	1955 Two-Storey Classroom	2,500	Low	Low	Meets Structural Life Safety Requirements	Medium	
44	North Vancouver	4444000	CONTINUING ED SD 44	2	1955 Gymnasium	830	Low	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444000	CONTINUING ED SD 44	3	1955 Single-Storey Administration	1,000	Moderate	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444000	CONTINUING ED SD 44	4	1955 Single-Storey Maintenance Stores	3,300	Moderate	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444000	CONTINUING ED SD 44	5	1955 Single-Storey Cafeteria	500	Low	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444049	COVE CLIFF ELEMENTARY	1	Classrooms	1,980	Low	Low	Meets Structural Life Safety Requirements	Low	
44	North Vancouver	4444049	COVE CLIFF ELEMENTARY	2	Gymnasium	650	Low	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444530	CURRICULUM SERVICE CENTER	1	1962 Single-Storey Curriculum Ctr	1,000	Moderate	Medium	Non Structural Upgrade Required	Medium	
44	North Vancouver	4444530	CURRICULUM SERVICE CENTER	2	1965 Gymnasium	200	Moderate/High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444530	CURRICULUM SERVICE CENTER	3	1977 Single-Storey Curriculum Ctr	200	Moderate	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444048	DOROTHY LYNAS ELEMENTARY	1	1990 Classroom & Gymnasium	4,500	Low	Low	Meets Structural Life Safety Requirements	Low	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
44	North Vancouver	4444017	EASTVIEW ELEMENTARY	1	North Classrooms	1,100	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
44	North Vancouver	4444017	EASTVIEW ELEMENTARY	2	West Gymnasium and Multi-Purpose	1,075	Moderate	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444017	EASTVIEW ELEMENTARY	3	South Central Classrooms	1,250	Moderate/High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444017	EASTVIEW ELEMENTARY	4	Activity Area & East Classrooms	700	Low	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444035	FROMME ELEMENTARY	1	Classrooms	2,800	Low/Moderate	Low	Inactive	Medium	
44	North Vancouver	4444035	FROMME ELEMENTARY	2	Gymnasium	350	Moderate	Medium	Inactive		
44	North Vancouver	4444025	HANDSWORTH SECONDARY	1	North Classrooms	3,900	High	High 1	Supported 2013	High 1	April 2013 - to start 2015.
44	North Vancouver	4444025	HANDSWORTH SECONDARY	2	East Classrooms	1,470	High	High 1	Supported 2013		
44	North Vancouver	4444025	HANDSWORTH SECONDARY	3	South East Classrooms	990	Moderate	Medium	Supported 2013		
44	North Vancouver	4444025	HANDSWORTH SECONDARY	8	Central Library and Classrooms	2,850	Low/Moderate	Low	Supported 2013		
44	North Vancouver	4444025	HANDSWORTH SECONDARY	4	Cafeteria	840	High	High 2	Supported 2013		
44	North Vancouver	4444025	HANDSWORTH SECONDARY	5	Automotive	250	Moderate	High 2	Supported 2013		
44	North Vancouver	4444025	HANDSWORTH SECONDARY	6	Main Gymnasium	1,750	High	High 2	Supported 2013		
44	North Vancouver	4444025	HANDSWORTH SECONDARY	7	West Gymnasium & Music Room	740	Moderate/High	High 2	Supported 2013		
44	North Vancouver	4444011	HIGHLANDS ELEMENTARY	1	1950 1&2 storey classrm & Admin	2,000	Moderate/High	N/A	Completed	N/A	
44	North Vancouver	4444011	HIGHLANDS ELEMENTARY	2	1959 gymnasium	375	Moderate/High	N/A	Completed		
44	North Vancouver	4444011	HIGHLANDS ELEMENTARY	3	1952 single-storey classroom	335	Moderate	N/A	Completed		
44	North Vancouver	4444011	HIGHLANDS ELEMENTARY	4	1952 gymnasium	215	Moderate/High	N/A	Completed		
44	North Vancouver	4444011	HIGHLANDS ELEMENTARY	5	1953 Two-storey classroom	1,300	Moderate/High	N/A	Completed		
44	North Vancouver	4444006	KEITH LYNN ALTERNATIVE SECONDARY	1	1951 single-storey classroom	500	Moderate	Medium	Inactive	High 3	
44	North Vancouver	4444006	KEITH LYNN ALTERNATIVE SECONDARY	2	1958 gymnasium	550	High	High 3	Inactive		
44	North Vancouver	4444006	KEITH LYNN ALTERNATIVE SECONDARY	3	1915/1964 two-storey classroom	1,350	High	Medium	Inactive		
44	North Vancouver	4444006	KEITH LYNN ALTERNATIVE SECONDARY	4	1972 Library addition	150	Moderate	Medium	Inactive		
44	North Vancouver	4444034	LARSON ELEMENTARY	1	1964 two-storey classroom	1,750	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
44	North Vancouver	4444034	LARSON ELEMENTARY	2	1964 gymnasium	375	Moderate	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444034	LARSON ELEMENTARY	3	1965 single-storey classroom	800	Low/Moderate	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444034	LARSON ELEMENTARY	4	Two-Storey Classroom & Gym Add'n	?	Low	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444002	LONSDALE ELEMENTARY	1	1911 Classroom Block	2,046	High	High 3	Inactive	High 3	
44	North Vancouver	4444002	LONSDALE ELEMENTARY	2	1967 Library Addition	230	High	Medium	Inactive		
44	North Vancouver	4444002	LONSDALE ELEMENTARY	3	1957 Gymnasium	410	Moderate	Medium	Inactive		
44	North Vancouver	4444002	LONSDALE ELEMENTARY	4	Annex	840	Moderate/High	Medium	Inactive		
44	North Vancouver	4444046	LYNNMOUR COMMUNITY SCHOOL	1	West Classrooms	830	Moderate	Medium	Non Structural Upgrade Required	Medium	
44	North Vancouver	4444046	LYNNMOUR COMMUNITY SCHOOL	2	Central Classrooms	900	Moderate	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444046	LYNNMOUR COMMUNITY SCHOOL	3	East Gymnasium	390	Moderate	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444046	LYNNMOUR COMMUNITY SCHOOL	4	East Classrooms	680	Low	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444031	MONTROYAL ELEMENTARY	1	South Classrooms	1,160	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
44	North Vancouver	4444031	MONTROYAL ELEMENTARY	2	Central Classrooms	1,000	High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444031	MONTROYAL ELEMENTARY	3	North Music and Multi-Purpose	370	Low	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444031	MONTROYAL ELEMENTARY	4	North Gymnasium	600	Moderate	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444013	NORGATE COMMUNITY ELEMENTARY	1	1951 single-storey classroom	1,300	Moderate	Medium	Non Structural Upgrade Required	Medium	
44	North Vancouver	4444013	NORGATE COMMUNITY ELEMENTARY	2	1958 Gymnasium - 2001 upgrade	?	Low	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444013	NORGATE COMMUNITY ELEMENTARY	3	2001 Single-storey Classroom	?	Low	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444013	NORGATE COMMUNITY ELEMENTARY	4	1969 library	175	Moderate	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444506	OUTDOOR SCHOOL	1	Cafeteria and Office	690	High	Medium	Non Structural Upgrade Required	Medium	
44	North Vancouver	4444506	OUTDOOR SCHOOL	2	Activity Room	300	Low/Moderate	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444506	OUTDOOR SCHOOL	3	Conference	675	Moderate	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444506	OUTDOOR SCHOOL	4	Barn	230	Moderate/High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444506	OUTDOOR SCHOOL	5	Lab	350	Moderate/High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444044	PLYMOUTH ELEMENTARY	1	Administration/ Gymnasium Block	780	Moderate	Medium	Inactive	High 2	
44	North Vancouver	4444044	PLYMOUTH ELEMENTARY	2	1969 Classroom Block	1,180	Moderate/High	High 2	Inactive		
44	North Vancouver	4444044	PLYMOUTH ELEMENTARY	3	1975 Classroom Block	1,000	Moderate/High	Medium	Inactive		
44	North Vancouver	4444005	QUEEN MARY ELEMENTARY	1	South Classrooms	3,900	Moderate/High	N/A	Under Construction	N/A	
44	North Vancouver	4444005	QUEEN MARY ELEMENTARY	2	North Gymnasium	350	Moderate/High	N/A	Under Construction		
44	North Vancouver	4444016	QUEENSBURY ELEMENTARY	1	1955 Wing	1,200	High	Medium	Non Structural Upgrade Required	Medium	
44	North Vancouver	4444016	QUEENSBURY ELEMENTARY	2	1958 Addition	580	Moderate/High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444016	QUEENSBURY ELEMENTARY	3	gymnasium and administration	600	Moderate/High	Medium	Non Structural Upgrade Required		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
44	North Vancouver	4444040	RIDGEWAY ANNEX	1	Classroom Block	650	Moderate/High	High 3	Inactive	High 3	
44	North Vancouver	4444040	RIDGEWAY ANNEX	2	Gymnasium Block	285	Moderate/High	Medium	Inactive		
44	North Vancouver	4444003	RIDGEWAY ELEMENTARY	1	Main Block (1911)	1,970	High	N/A	Completed	N/A	
44	North Vancouver	4444003	RIDGEWAY ELEMENTARY	2	North Addition (1920)	800	High	N/A	Completed		
44	North Vancouver	4444003	RIDGEWAY ELEMENTARY	3	South Addition (1920)	800	High	N/A	Completed		
44	North Vancouver	4444003	RIDGEWAY ELEMENTARY	4	East Block (1944)	975	High	N/A	Completed		
44	North Vancouver	4444003	RIDGEWAY ELEMENTARY	5	Gymnasium Block (1959)	360	Moderate/High	N/A	Completed		
44	North Vancouver	4444029	ROSS ROAD ELEMENTARY	1	South Classrooms	1,040	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
44	North Vancouver	4444029	ROSS ROAD ELEMENTARY	2	Central Classrooms and Library	1,800	High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444029	ROSS ROAD ELEMENTARY	3	North Classrooms	420	Moderate/High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444029	ROSS ROAD ELEMENTARY	4	Gymnasium	450	Moderate/High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444029	ROSS ROAD ELEMENTARY	5	East Building	390	Low/Moderate	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444029	ROSS ROAD ELEMENTARY	6	Covered Play Area	160	High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444047	SEYCOVE SECONDARY COMMUNITY SCHOOL	1	2-storey upper classroom	2,700	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
44	North Vancouver	4444047	SEYCOVE SECONDARY COMMUNITY SCHOOL	2	Gymnasium block	1,700	Moderate	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444047	SEYCOVE SECONDARY COMMUNITY SCHOOL	3	Shops/ Library/ Office Wing	2,100	High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444047	SEYCOVE SECONDARY COMMUNITY SCHOOL	4	2001 Addition	?	Low	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444019	SEYMOUR HEIGHTS ELEMENTARY	1	South Classrooms	1,200	Moderate/High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444019	SEYMOUR HEIGHTS ELEMENTARY	2	North Classrooms	1,000	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
44	North Vancouver	4444019	SEYMOUR HEIGHTS ELEMENTARY	3	East Gymnasium	480	Moderate	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444019	SEYMOUR HEIGHTS ELEMENTARY	4	West Library	150	Low/Moderate	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444032	SHERWOOD PARK ELEMENTARY	1	1963 two-storey classroom	4,000	High	Medium	Non Structural Upgrade Required	Medium	
44	North Vancouver	4444032	SHERWOOD PARK ELEMENTARY	2	1963 gymnasium	400	Moderate/High	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444032	SHERWOOD PARK ELEMENTARY	3	1976 two-storey classroom add'n	600	Moderate	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444032	SHERWOOD PARK ELEMENTARY	4	1999 Two-storey Classroom	?	Low	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444021	UPPER LYNN ELEMENTARY	1	Classrooms	2,800	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
44	North Vancouver	4444021	UPPER LYNN ELEMENTARY	2	Gymnasium	460	Low/Moderate	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444021	UPPER LYNN ELEMENTARY	3	Library	170	Low/Moderate	Medium	Non Structural Upgrade Required		
44	North Vancouver	4444021	UPPER LYNN ELEMENTARY	4	Administration	920	Low	Low	Meets Structural Life Safety Requirements		
44	North Vancouver	4444009	WESTVIEW ELEMENTARY	1	Classrooms	1,880	Moderate/High	N/A	Completed		
44	North Vancouver	4444009	WESTVIEW ELEMENTARY	2	Gymnasium	350	Moderate/High	N/A	Completed	N/A	
44	North Vancouver	4444009	WESTVIEW ELEMENTARY	3	Covered Play Area	100	Moderate/High	N/A	Completed		
44	North Vancouver	4444026	WINDSOR SECONDARY	1	1959 3-storey classroom	3,500	Low/Moderate	High 3	Supported 2013	High 1	November 2012 - Risk reviewed at SD request as school was previously upgraded. H3 risk for blocks 1 and 2 confirmed. Block 8 risk increased from H2 to H1. April 2013 - to start 2013.
44	North Vancouver	4444026	WINDSOR SECONDARY	2	1959 2-storey classroom	1,930	Low/Moderate	High 3	Supported 2013		
44	North Vancouver	4444026	WINDSOR SECONDARY	3	1971 2-storey classroom	1,500	Low/Moderate	Low	Supported 2013		
44	North Vancouver	4444026	WINDSOR SECONDARY	4	1972 2-storey classroom	930	Low/Moderate	Low	Supported 2013		
44	North Vancouver	4444026	WINDSOR SECONDARY	5	1959 Gymnasium	960	Low	Low	Supported 2013		
44	North Vancouver	4444026	WINDSOR SECONDARY	6	1973 Gymnasium	440	Moderate	Medium	Supported 2013		
44	North Vancouver	4444026	WINDSOR SECONDARY	7	1972 2-storey shops	1,055	Moderate	Medium	Supported 2013		
44	North Vancouver	4444026	WINDSOR SECONDARY	8	1967 3-storey classroom	1,050	High	High 1	Supported 2013		
45	West Vancouver	4545019	BOWEN ISLAND COMMUNITY SCHOOL	1	Original Block	2,470	Low	Low	Meets Structural Life Safety Requirements	Low	
45	West Vancouver	4545019	BOWEN ISLAND COMMUNITY SCHOOL	2	1998 Addition	?	Low	Low	Meets Structural Life Safety Requirements		
45	West Vancouver	4545020	CAULFEILD ELEMENTARY	1	Original Block	2,054	Low	Low	Meets Structural Life Safety Requirements	Medium	
45	West Vancouver	4545020	CAULFEILD ELEMENTARY	2	1959 Gymnasium	498	Moderate	Medium	Non Structural Upgrade Required		
45	West Vancouver	4545020	CAULFEILD ELEMENTARY	3	1998 Addition	?	Low	Low	Meets Structural Life Safety Requirements		
45	West Vancouver	4545025	CEDARDALE CENTRE	1	Original Block	1,300	Low	Low	Meets Structural Life Safety Requirements	Medium	
45	West Vancouver	4545025	CEDARDALE CENTRE	2	1965 Activity Room Block	850	Moderate	Medium	Non Structural Upgrade Required		
45	West Vancouver	4545030	CHARTWELL ELEMENTARY	1	Original Block	600	Low	Low	Meets Structural Life Safety Requirements	Medium	
45	West Vancouver	4545030	CHARTWELL ELEMENTARY	2	1976 Activity Room Block	550	Moderate	Medium	Non Structural Upgrade Required		
45	West Vancouver	4545035	CYPRESS PARK PRIMARY	1	Original Block	1,042	Low	Low	Meets Structural Life Safety Requirements	Low	
45	West Vancouver	4545040	EAGLE HARBOUR PRIMARY	1	Original Block	1,072	Low	Low	Meets Structural Life Safety Requirements	Medium	
45	West Vancouver	4545040	EAGLE HARBOUR PRIMARY	2	1977 Activity Room Block	597	Moderate	Medium	Non Structural Upgrade Required		
45	West Vancouver	4545045	GLENEAGLES ELEMENTARY	1	1950,1960,1967 Additions	2,996	Low	Low	Meets Structural Life Safety Requirements	Low	
45	West Vancouver	4545055	HOLLYBURN ELEMENTARY	1	1936 Block	1,726	Low	Low	Meets Structural Life Safety Requirements	Low	
45	West Vancouver	4545055	HOLLYBURN ELEMENTARY	2	1955,1959,1963,1967 Additions	1,812	Low	Low	Meets Structural Life Safety Requirements		
45	West Vancouver	4545503	INGLEWOOD ANNEX	1	1957 Building	1,472	Moderate	Medium	Non Structural Upgrade Required	Medium	
45	West Vancouver	4545060	IRWIN PARK ELEMENTARY	1	1955 Bldg;1964, 1966 Additions	4,500	Moderate	Medium	Non Structural Upgrade Required	Medium	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
45	West Vancouver	4545062	LIONS BAY COMMUNITY SCHOOL	1	1976 Bldg	614	Low	Low	Meets Structural Life Safety Requirements	Low	
45	West Vancouver	4545062	LIONS BAY COMMUNITY SCHOOL	2	1976 Activity Room	335	Low/Moderate	Low	Meets Structural Life Safety Requirements		
45	West Vancouver	4545065	PAULINE JOHNSON ELEMENTARY	1	1922 Bldg, 1943,1949 Additions	3,285	Low	Low	Meets Structural Life Safety Requirements	Low	
45	West Vancouver	4545070	RIDGEVIEW ELEMENTARY	1	1950 Bldg, 1960 Addition	2,690	Low	Low	Meets Structural Life Safety Requirements	Medium	
45	West Vancouver	4545070	RIDGEVIEW ELEMENTARY	2	1964 Detached North Wing	555	Moderate	Medium	Non Structural Upgrade Required		
45	West Vancouver	4545010	SENTINEL SECONDARY	1	1962 North Wing, 1969 Addition	2,480	Low	High 3	Structural Upgrade Required	High 3	November 2012 - Risk for all blocks changed from L to H3 (Unreinforced masonry internal walls). Note: school upgraded in mid 90's but interior walls not dealt with.
45	West Vancouver	4545010	SENTINEL SECONDARY	2	1962 South Wing, 1967 Addition	4,283	Low	High 3	Structural Upgrade Required		
45	West Vancouver	4545010	SENTINEL SECONDARY	3	1962 Gym and 1969 Addition	2,248	Low	High 3	Structural Upgrade Required		
45	West Vancouver	4545010	SENTINEL SECONDARY	4	Cafeteria Wing	600	Low	High 3	Structural Upgrade Required		
45	West Vancouver	4545075	WEST BAY ELEMENTARY	1	1952 Building, 1955,1965 Additio	2,576	Low	Low	Meets Structural Life Safety Requirements	Medium	
45	West Vancouver	4545075	WEST BAY ELEMENTARY	2	1955 Activity Room	531	Moderate	Medium	Non Structural Upgrade Required		
45	West Vancouver	4545015	WEST VANCOUVER SECONDARY	1	1957 Building	1,574	High	N/A	Completed	N/A	
45	West Vancouver	4545015	WEST VANCOUVER SECONDARY	2	East Classroom Wing	?	Low	N/A	Completed		
45	West Vancouver	4545015	WEST VANCOUVER SECONDARY	3	Middle Classroom Wing	?	Low	N/A	Completed		
45	West Vancouver	4545015	WEST VANCOUVER SECONDARY	4	West Classroom Wing	?	Low	N/A	Completed		
45	West Vancouver	4545015	WEST VANCOUVER SECONDARY	5	1999 Gymnasium	?	Low	N/A	Completed		
45	West Vancouver	4545015	WEST VANCOUVER SECONDARY	6	Music/Drama Wing	?	Low	N/A	Completed		
45	West Vancouver	4545015	WEST VANCOUVER SECONDARY	7	Industrial Education Building	?	Low	N/A	Completed		
45	West Vancouver	4545015	WEST VANCOUVER SECONDARY	8	Kay Meek Centre for the Performing Arts	?	Low	N/A	Completed		
45	West Vancouver	4545080	WESTCOT ELEMENTARY	1	1957, 1959, 1964 Building	3,128	Moderate	Medium	Non Structural Upgrade Required	Medium	
46	Sunshine Coast	4646018	CEDAR GROVE ELEMENTARY	1	Classroom/Admin.	1,072	Moderate	Medium	Non Structural Upgrade Required	Medium	
46	Sunshine Coast	4646018	CEDAR GROVE ELEMENTARY	2	Gymnasium	770	Low/Moderate	Low	Meets Structural Life Safety Requirements		
46	Sunshine Coast	4646018	CEDAR GROVE ELEMENTARY	3	Classroom	1,110	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
46	Sunshine Coast	4646017	CHATELECH SECONDARY	1	Classroom	3,136	Moderate	Medium	Non Structural Upgrade Required		
46	Sunshine Coast	4646017	CHATELECH SECONDARY	2	Shops	1,222	Moderate	Medium	Non Structural Upgrade Required	Medium	
46	Sunshine Coast	4646017	CHATELECH SECONDARY	3	Classroom (1996)	?	Low	Low	Meets Structural Life Safety Requirements		
46	Sunshine Coast	4646017	CHATELECH SECONDARY	4	Classroom/Admin/Theatre/Gymnasium	?	Low	Low	Meets Structural Life Safety Requirements	Medium	
46	Sunshine Coast	4646011	DAVIS BAY ELEMENTARY	1	Classroom/Admin.	980	Low	Low	Meets Structural Life Safety Requirements		
46	Sunshine Coast	4646011	DAVIS BAY ELEMENTARY	2	Gymnasium	360	Moderate	Medium	Non Structural Upgrade Required	Medium	
46	Sunshine Coast	4646011	DAVIS BAY ELEMENTARY	3	Classroom Annex	236	Moderate	Medium	Non Structural Upgrade Required		
46	Sunshine Coast	4646008	ELPHINSTONE SECONDARY	1	Gymnasium/Classroom	5,695	Low/Moderate	Medium	Non Structural Upgrade Required	Medium	
46	Sunshine Coast	4646008	ELPHINSTONE SECONDARY	2	Shop/Classroom	910	Moderate/High	Medium	Non Structural Upgrade Required		
46	Sunshine Coast	4646008	ELPHINSTONE SECONDARY	3	Metal Shop	350	Moderate	Medium	Non Structural Upgrade Required	Medium	
46	Sunshine Coast	4646008	ELPHINSTONE SECONDARY	4	Classroom (East)	1,590	Moderate/High	Medium	Non Structural Upgrade Required		
46	Sunshine Coast	4646001	GIBSONS ELEMENTARY	1	Classrooms/Admin.	2,770	Moderate	NA	Under Construction	NA	
46	Sunshine Coast	4646001	GIBSONS ELEMENTARY	2	Classrooms/Admin.	2,100	Moderate/High	NA	Under Construction		
46	Sunshine Coast	4646001	GIBSONS ELEMENTARY	3	Gymnasium	340	Moderate/High	NA	Under Construction		
46	Sunshine Coast	4646013	HALFMOON BAY ELEMENTARY	1	Classrooms/Administration	1,862	Low	Low	Meets Structural Life Safety Requirements	Medium	
46	Sunshine Coast	4646013	HALFMOON BAY ELEMENTARY	2	Gymnasium	401	Low	Low	Meets Structural Life Safety Requirements		
46	Sunshine Coast	4646013	HALFMOON BAY ELEMENTARY	3	Classroom Pod	340	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
46	Sunshine Coast	4646013	HALFMOON BAY ELEMENTARY	4	Portables	?	Low	Low	Meets Structural Life Safety Requirements		
46	Sunshine Coast	4646000	HERITAGE LEARNING CENTRE	1	Classrooms	825	Low	Low	Meets Structural Life Safety Requirements	Low	
46	Sunshine Coast	4646015	LANGDALE ELEMENTARY	1	Classrooms/Admin.	1,150	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
46	Sunshine Coast	4646015	LANGDALE ELEMENTARY	2	Gymnasium	410	Low	Low	Meets Structural Life Safety Requirements		
46	Sunshine Coast	4646007	MADEIRA PARK ELEMENTARY	1	Classrooms/Admin.	780	Moderate/High	N/A	Completed	N/A	
46	Sunshine Coast	4646007	MADEIRA PARK ELEMENTARY	2	Classrooms	605	High	N/A	Completed		
46	Sunshine Coast	4646007	MADEIRA PARK ELEMENTARY	3	Gymnasium	258	Moderate/High	N/A	Completed		
46	Sunshine Coast	4646012	PENDER HARBOUR ELEM-SEC	1	Classrooms/Shops/Administration	1,440	Moderate	Medium	Non Structural Upgrade Required	Medium	
46	Sunshine Coast	4646012	PENDER HARBOUR ELEM-SEC	2	Gymnasium/Mezzanine	1,978	Low/Moderate	Low	Meets Structural Life Safety Requirements		
46	Sunshine Coast	4646009	ROBERTS CREEK ELEMENTARY	1	Classrooms	796	Moderate	Medium	Non Structural Upgrade Required	Medium	
46	Sunshine Coast	4646009	ROBERTS CREEK ELEMENTARY	2	Classrooms/Admin.	335	Low	Low	Meets Structural Life Safety Requirements		
46	Sunshine Coast	4646009	ROBERTS CREEK ELEMENTARY	3	Classrooms	840	Low/Moderate	Low	Meets Structural Life Safety Requirements		
46	Sunshine Coast	4646009	ROBERTS CREEK ELEMENTARY	4	Multipurpose Room	209	Low	Low	Meets Structural Life Safety Requirements		
46	Sunshine Coast	4646009	ROBERTS CREEK ELEMENTARY	5	Gymnasium/Community Rooms	824	Moderate/High	Medium	Non Structural Upgrade Required		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
46	Sunshine Coast	4646003	SECHELT ELEMENTARY (leased to CSF)	1	Classrooms/Annex	815	Moderate	Medium	Non Structural Upgrade Required	Medium	
46	Sunshine Coast	4646003	SECHELT ELEMENTARY	2	Library	280	Moderate	Medium	Non Structural Upgrade Required		
46	Sunshine Coast	4646003	SECHELT ELEMENTARY	3	Gymnasium	750	Moderate	Medium	Non Structural Upgrade Required		
46	Sunshine Coast	4646003	SECHELT ELEMENTARY	4	Classrooms/Admin.	920	Moderate/High	Medium	Non Structural Upgrade Required		
46	Sunshine Coast	4646003	SECHELT ELEMENTARY	5	Classrooms/Admin.	535	Moderate/High	Medium	Non Structural Upgrade Required		
46	Sunshine Coast	4646003	SECHELT ELEMENTARY	6	Classrooms	138	Moderate	Medium	Non Structural Upgrade Required		
46	Sunshine Coast	4646016	WEST SECHELT ELEMENTARY	1	Classrooms/Admin.	445	Moderate	Medium	Non Structural Upgrade Required	Medium	
46	Sunshine Coast	4646016	WEST SECHELT ELEMENTARY	2	Classrooms/Community Rooms	1,208	Low/Moderate	Low	Meets Structural Life Safety Requirements		
46	Sunshine Coast	4646016	WEST SECHELT ELEMENTARY	3	Gymnasium	374	Low	Low	Meets Structural Life Safety Requirements		
47	Powell River	4747010	EDGEHILL ELEMENTARY	1	Classroom/Administration	1,580	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
47	Powell River	4747010	EDGEHILL ELEMENTARY	2	Gymnasium	300	Moderate/High	Medium	Non Structural Upgrade Required		
47	Powell River	4747013	HENDERSON ELEMENTARY	1	Classroom/Administration	1,520	High	High 1	Supported 2013	High 1	November 2012 - Block 1 risk confirmed as H1.
47	Powell River	4747013	HENDERSON ELEMENTARY	2	Gymnasium	232	Moderate/High	Medium	Supported 2013		
47	Powell River	4747001	JAMES THOMSON ELEMENTARY	1	Classrooms	820	Moderate	Medium	Non Structural Upgrade Required	Medium	November 2012 - Reviewed at SD request. Risk for all blocks confirmed; schools retains M risk.
47	Powell River	4747001	JAMES THOMSON ELEMENTARY	2	Gymnasium	532	Moderate/High	Medium	Non Structural Upgrade Required		
47	Powell River	4747001	JAMES THOMSON ELEMENTARY	3	Classrooms/Administration	1,123	Moderate	Medium	Non Structural Upgrade Required		
47	Powell River	4747001	JAMES THOMSON ELEMENTARY	4	Music Room	112	Moderate/High	Medium	Non Structural Upgrade Required		
47	Powell River	4747015	KELLY CREEK COMMUNITY SCHOOL	1	Classrooms/Administration	620	Moderate	Medium	Non Structural Upgrade Required		
47	Powell River	4747015	KELLY CREEK COMMUNITY SCHOOL	2	Classrooms	860	Moderate/High	Medium	Non Structural Upgrade Required		
47	Powell River	4747015	KELLY CREEK COMMUNITY SCHOOL	3	Gymnasium	300	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
47	Powell River	4747012	MAX CAMERON SECONDARY	1	Classroom/Administration	2,497	High	Medium	Inactive		
47	Powell River	4747012	MAX CAMERON SECONDARY	2	Gymnasium	1,060	Moderate	Medium	Inactive		
47	Powell River	4747012	MAX CAMERON SECONDARY	3	Classroom	1,212	Moderate	Medium	Inactive		
47	Powell River	4747012	MAX CAMERON SECONDARY	4	Band Room	252	Moderate	Medium	Inactive		
47	Powell River	4747012	MAX CAMERON SECONDARY	5	Classroom/Shops	2,128	Moderate/High	Medium	Inactive	Medium	
47	Powell River	4747020	OCEANVIEW MIDDLE SCHOOL	1	Classrooms/Administration	4,018	Moderate/High	Medium	Non Structural Upgrade Required		
47	Powell River	4747020	OCEANVIEW MIDDLE SCHOOL	2	Gymnasium	847	Low	Low	Meets Structural Life Safety Requirements		
47	Powell River	4747020	OCEANVIEW MIDDLE SCHOOL	3	Music Room	143	Low	Low	Meets Structural Life Safety Requirements	Medium	
47	Powell River	4747014	TEXADA ELEMENTARY, MIDDLE & SECONDARY	1	Classrooms/Administration/Shops	1,225	Moderate/High	Medium	Non Structural Upgrade Required		
47	Powell River	4747014	TEXADA ELEMENTARY, MIDDLE & SECONDARY	2	Change Rooms	305	Moderate	Medium	Non Structural Upgrade Required	Medium	
47	Powell River	4747014	TEXADA ELEMENTARY, MIDDLE & SECONDARY	3	Gymnasium	670	Moderate/High	Medium	Non Structural Upgrade Required		
47	Powell River	4747014	TEXADA ELEMENTARY, MIDDLE & SECONDARY	4	Elementary Classrooms	690	Moderate	Medium	Non Structural Upgrade Required		
47	Powell River	4747011	WESTVIEW ELEMENTARY (was GRIEF POINT)	1	Classrooms/Administration	1,620	Moderate/High	N/A	Completed	N/A	
47	Powell River	4747011	WESTVIEW ELEMENTARY (was GRIEF POINT)	2	Change Rooms/Storage	168	Low/Moderate	N/A	Completed		
47	Powell River	4747011	WESTVIEW ELEMENTARY (was GRIEF POINT)	3	Gymnasium	300	Moderate/High	N/A	Completed		
48	Sea to Sky	4848014	BLACKWATER CREEK ELEMENTARY	1	Classroom	200	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
48	Sea to Sky	4848016	DON ROSS SECONDARY	1	Gymnasium	1,250	Moderate	Medium	Non Structural Upgrade Required		
48	Sea to Sky	4848016	DON ROSS SECONDARY	2	Classroom - Centre	2,780	Moderate	Medium	Non Structural Upgrade Required	Medium	
48	Sea to Sky	4848016	DON ROSS SECONDARY	3	Shops - South	800	Moderate/High	Medium	Non Structural Upgrade Required		
48	Sea to Sky	4848016	DON ROSS SECONDARY	4	Classroom & Library 2001	?	Low	Low	Meets Structural Life Safety Requirements		
48	Sea to Sky	4848018	GARIBALDI HIGHLANDS ELEMENTARY	1	Original structure	1,416	Moderate	Medium	Non Structural Upgrade Required	Medium	
48	Sea to Sky	4848018	GARIBALDI HIGHLANDS ELEMENTARY	2	1995 Addition	?	Low	Low	Meets Structural Life Safety Requirements		
48	Sea to Sky	4848018	GARIBALDI HIGHLANDS ELEMENTARY	3	1999 Addition	?	Low	Low	Meets Structural Life Safety Requirements		
48	Sea to Sky	4848018	GARIBALDI HIGHLANDS ELEMENTARY	4	Gymnasium	460	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
48	Sea to Sky	4848004	HOWE SOUND SECONDARY	1	Multi purpose / Library / Drama	?	Low	Low	Meets Structural Life Safety Requirements		
48	Sea to Sky	4848004	HOWE SOUND SECONDARY	2	2 storey classroom	1,530	Low	Low	Meets Structural Life Safety Requirements		
48	Sea to Sky	4848004	HOWE SOUND SECONDARY	3	Gym addition	?	Low	Low	Meets Structural Life Safety Requirements		
48	Sea to Sky	4848004	HOWE SOUND SECONDARY	4	Original gym structure	975	High	Medium	Non Structural Upgrade Required		
48	Sea to Sky	4848004	HOWE SOUND SECONDARY	5	Shop wing	1,262	High	Medium	Non Structural Upgrade Required		
48	Sea to Sky	4848004	HOWE SOUND SECONDARY	6	Music room	785	Low	Low	Meets Structural Life Safety Requirements		
48	Sea to Sky	4848004	HOWE SOUND SECONDARY	7	Science / Language	842	High	Medium	Non Structural Upgrade Required		
48	Sea to Sky	4848008	MAMQUAM ELEMENTARY	1	Gymnasium	435	Low	Low	Meets Structural Life Safety Requirements		
48	Sea to Sky	4848008	MAMQUAM ELEMENTARY	2	Classroom (South)	1,435	Moderate/High	Medium	Non Structural Upgrade Required		
48	Sea to Sky	4848008	MAMQUAM ELEMENTARY	3	Classroom (North)	1,135	Moderate/High	Medium	Non Structural Upgrade Required	N/A	
48	Sea to Sky	4848020	MYRTLE PHILIP COMMUNITY SCHOOL	1	Classroom	2,010	Moderate/High	N/A	Completed		
48	Sea to Sky	4848020	MYRTLE PHILIP COMMUNITY SCHOOL	2	Gymnasium	2,072	Moderate	N/A	Completed		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
48	Sea to Sky	4848011	SQUAMISH ELEMENTARY	1	Gymnasium	420	Low	Low	Meets Structural Life Safety Requirements		
48	Sea to Sky	4848011	SQUAMISH ELEMENTARY	2	Classrooms, Admin.	1,480	Low	Low	Meets Structural Life Safety Requirements		
48	Sea to Sky	4848011	SQUAMISH ELEMENTARY	3	Classrooms, Library, Cov. play	440	Low	Low	Meets Structural Life Safety Requirements	Low	
48	Sea to Sky	4848011	SQUAMISH ELEMENTARY	4	Classrooms (2001)	?	Low	Low	Meets Structural Life Safety Requirements		
48	Sea to Sky	4848012	STAWAMUS ELEMENTARY	1	Gymnasium	425	Low	Low	Meets Structural Life Safety Requirements		
48	Sea to Sky	4848012	STAWAMUS ELEMENTARY	2	Classrooms (South East)	1,260	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
48	Sea to Sky	4848012	STAWAMUS ELEMENTARY	3	Classrooms (North)	520	Moderate/High	Medium	Non Structural Upgrade Required		
48	Sea to Sky	4848019	VALLEYCLIFFE ELEMENTARY	1	Gymnasium	560	Low/Moderate	Low	Meets Structural Life Safety Requirements		
48	Sea to Sky	4848019	VALLEYCLIFFE ELEMENTARY	2	Classrooms/Admin.	1,860	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
49	Central Coast	4949004	BELLA COOLA ELEMENTARY	1	Gymnasium	230	Moderate	Medium	Non Structural Upgrade Required		
49	Central Coast	4949004	BELLA COOLA ELEMENTARY	2	Classrooms	990	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
49	Central Coast	4949004	BELLA COOLA ELEMENTARY	3	Portables	?	Low	Low	Meets Structural Life Safety Requirements		
49	Central Coast	4949005	NUSATSUM ELEMENTARY	1	Whole School	2,180	Low	Low	Meets Structural Life Safety Requirements	Low	
49	Central Coast	4949007	SHEARWATER ELEMENTARY	1	Classrooms	260	Low	Low	Meets Structural Life Safety Requirements	Low	
49	Central Coast	4949002	SIR ALEXANDER MACKENZIE SEC	1	Gymnasium	360	Low	Low	Meets Structural Life Safety Requirements		
49	Central Coast	4949002	SIR ALEXANDER MACKENZIE SEC	2	Classrooms	2,100	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
50	Haida Gwaii	5050004	AGNES L MATHERS ELEM-JR SEC	1	Gymnasium	730	Moderate	Medium	Non Structural Upgrade Required	Medium	
50	Haida Gwaii	5050004	AGNES L MATHERS ELEM-JR SEC	2	Classrooms	1,430	Moderate	Medium	Non Structural Upgrade Required		
50	Haida Gwaii	5050001	GEORGE M DAWSON SECONDARY	1	Gymnasium/Shops	2,231	Low	Low	Meets Structural Life Safety Requirements		
50	Haida Gwaii	5050001	GEORGE M DAWSON SECONDARY	2	Library Block	374	Moderate	Medium	Non Structural Upgrade Required	Medium	
50	Haida Gwaii	5050001	GEORGE M DAWSON SECONDARY	3	Classrooms - East	1,138	Moderate	Medium	Non Structural Upgrade Required		
50	Haida Gwaii	5050001	GEORGE M DAWSON SECONDARY	4	Classrooms - West	581	Moderate	Medium	Non Structural Upgrade Required		
50	Haida Gwaii	5050002	PORT CLEMENTS ELEMENTARY	1	Gymnasium	670	Moderate	Medium	Non Structural Upgrade Required		
50	Haida Gwaii	5050002	PORT CLEMENTS ELEMENTARY	2	Classroom	620	Moderate	N/A	Completed	N/A	
50	Haida Gwaii	5050008	TAHAYGHEN ELEMENTARY	1	Gymnasium	642	Low	Low	Meets Structural Life Safety Requirements		
50	Haida Gwaii	5050008	TAHAYGHEN ELEMENTARY	2	Entrance/Change Rooms	569	Low	Low	Meets Structural Life Safety Requirements	Medium	
50	Haida Gwaii	5050008	TAHAYGHEN ELEMENTARY	3	Classroom Block	2,446	High	Medium	Non Structural Upgrade Required		
52	Prince Rupert	5252003	CONRAD STREET ELEMENTARY	1	Main Building	1,875	Low/Moderate	Low	Meets Structural Life Safety Requirements		
52	Prince Rupert	5252003	CONRAD STREET ELEMENTARY	2	Office/Library Wing	720	Low	Low	Meets Structural Life Safety Requirements	Medium	
52	Prince Rupert	5252003	CONRAD STREET ELEMENTARY	3	Activity Wing	420	Low	Low	Meets Structural Life Safety Requirements		
52	Prince Rupert	5252003	CONRAD STREET ELEMENTARY	4	Southeast Wing	765	Moderate	Medium	Non Structural Upgrade Required		
52	Prince Rupert	5252012	KANATA ELEMENTARY	1	Gym	450	Moderate	Medium	Inactive		
52	Prince Rupert	5252012	KANATA ELEMENTARY	2	East Classrooms	380	Moderate/High	Medium	Inactive	Medium	
52	Prince Rupert	5252012	KANATA ELEMENTARY	3	North Wing	860	Moderate/High	Medium	Inactive		
52	Prince Rupert	5252012	KANATA ELEMENTARY	4	West Classrooms	500	Moderate/High	Medium	Inactive		
52	Prince Rupert	5252014	PINERIDGE ELEMENTARY	1	Gym	401	Low	Low	Meets Structural Life Safety Requirements	Low	
52	Prince Rupert	5252014	PINERIDGE ELEMENTARY	2	Class room	2,120	Low	Low	Meets Structural Life Safety Requirements		
52	Prince Rupert	5252005	PORT EDWARD ELEMENTARY	1	Gym Play Area	515	Moderate	Medium	Non Structural Upgrade Required		
52	Prince Rupert	5252005	PORT EDWARD ELEMENTARY	2	Offices	400	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
52	Prince Rupert	5252005	PORT EDWARD ELEMENTARY	3	Classrooms	1,725	Moderate/High	Medium	Non Structural Upgrade Required		
52	Prince Rupert	5252005	PORT EDWARD ELEMENTARY	4	Dressing Room Addition	110	Low/Moderate	Low	Meets Structural Life Safety Requirements		
52	Prince Rupert	5252009	PRINCE RUPERT SECONDARY	1	Music	155	Low	Low	Meets Structural Life Safety Requirements		
52	Prince Rupert	5252009	PRINCE RUPERT SECONDARY	2	Gym and Stage	1,020	Low	Low	Meets Structural Life Safety Requirements		
52	Prince Rupert	5252009	PRINCE RUPERT SECONDARY	3	Adjacent Gym Rooms	700	Moderate/High	Medium	Non Structural Upgrade Required	Medium	December 2012 - Risk under review at SD request.
52	Prince Rupert	5252009	PRINCE RUPERT SECONDARY	4	Drafting and Art	310	Moderate/High	Medium	Non Structural Upgrade Required		
52	Prince Rupert	5252009	PRINCE RUPERT SECONDARY	5	Original & SW Classrooms	3,130	Moderate/High	Medium	Non Structural Upgrade Required		
52	Prince Rupert	5252009	PRINCE RUPERT SECONDARY	6	Food/Textiles Addition	765	Low	Low	Meets Structural Life Safety Requirements		
52	Prince Rupert	5252009	PRINCE RUPERT SECONDARY	7	Auto Wing	400	Low/Moderate	Low	Meets Structural Life Safety Requirements		
52	Prince Rupert	5252009	PRINCE RUPERT SECONDARY	8	Covered Walkway	380	Low/Moderate	Low	Meets Structural Life Safety Requirements		
52	Prince Rupert	5252009	PRINCE RUPERT SECONDARY	9	Southeast Industrial Wing	800	Moderate	Medium	Non Structural Upgrade Required		
52	Prince Rupert	5252006	ROOSEVELT PARK ELEMENTARY	1	Class Rooms	2,490	Low	Low	Meets Structural Life Safety Requirements		
52	Prince Rupert	5252006	ROOSEVELT PARK ELEMENTARY	2	Activity Rooms	440	Low	Low	Meets Structural Life Safety Requirements	Low	
52	Prince Rupert	5252006	ROOSEVELT PARK ELEMENTARY	3	Dressing Room	115	Low	Low	Meets Structural Life Safety Requirements		
52	Prince Rupert	5252006	ROOSEVELT PARK ELEMENTARY	4	Offices	?	Low	Low	Meets Structural Life Safety Requirements		
52	Prince Rupert	5252008	SEAL COVE ELEMENTARY	1	Original School Classrooms	760	Moderate	Medium	Inactive		
52	Prince Rupert	5252008	SEAL COVE ELEMENTARY	2	Library	240	Low/Moderate	Low	Inactive	Medium	
52	Prince Rupert	5252008	SEAL COVE ELEMENTARY	3	Two Room Addition	255	Low/Moderate	Low	Inactive		
52	Prince Rupert	5252008	SEAL COVE ELEMENTARY	4	Western Classrooms	570	High	Medium	Inactive		
52	Prince Rupert	5252008	SEAL COVE ELEMENTARY	5	Gym and Changerooms	790	High	Medium	Inactive		
52	Prince Rupert	5252010	WESTVIEW ELEMENTARY	1	Gym	372	Low	Low	Meets Structural Life Safety Requirements		
52	Prince Rupert	5252010	WESTVIEW ELEMENTARY	2	Change Rooms	175	Low	Low	Meets Structural Life Safety Requirements	Medium	
52	Prince Rupert	5252010	WESTVIEW ELEMENTARY	3	Classrooms	1,990	Moderate/High	Medium	Non Structural Upgrade Required		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
61	Greater Victoria	6161062	ARBUTUS MIDDLE SCHOOL	1	Main Classrooms	4,708	Moderate/High	High 2	Structural Upgrade Required	High 2	
61	Greater Victoria	6161062	ARBUTUS MIDDLE SCHOOL	2	Gymnasium	750	High	High 2	Structural Upgrade Required		
61	Greater Victoria	6161062	ARBUTUS MIDDLE SCHOOL	3	New Addition	411	Moderate/High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161051	BRAEFOOT ELEMENTARY	1	Central Classrooms	450	Moderate/High	Medium	Non Structural Upgrade Required	High 2	
61	Greater Victoria	6161051	BRAEFOOT ELEMENTARY	2	East Wing	2,080	High	High 2	Structural Upgrade Required		
61	Greater Victoria	6161051	BRAEFOOT ELEMENTARY	3	Activity Wing	?	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161011	BURNSIDE COMMUNITY	1	Original Building	1,430	High	Medium	Inactive	Medium	
61	Greater Victoria	6161011	BURNSIDE COMMUNITY	2	Gymnasium	370	Low	Low	Inactive		
61	Greater Victoria	6161047	CAMPUS VIEW ELEMENTARY	1	Administration Block	310	Moderate	Medium	Non Structural Upgrade Required	Medium	
61	Greater Victoria	6161047	CAMPUS VIEW ELEMENTARY	2	North Classroom Wing	1,100	Low/Moderate	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161047	CAMPUS VIEW ELEMENTARY	3	Gymnasium	390	Low/Moderate	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161047	CAMPUS VIEW ELEMENTARY	4	Centre Classroom Block	1,060	Moderate	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161047	CAMPUS VIEW ELEMENTARY	5	West Classroom Block	360	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161025	CEDAR HILL MIDDLE	1	Original Building	1,140	High	High 2	Supported 2013	High 2	April 2013 - to start 2015.
61	Greater Victoria	6161025	CEDAR HILL MIDDLE	2	North Classroom Block	1,440	High	High 2	Supported 2013		
61	Greater Victoria	6161025	CEDAR HILL MIDDLE	3	Gymnasium	720	Moderate	Medium	Supported 2013		
61	Greater Victoria	6161025	CEDAR HILL MIDDLE	4	Centre Shops	830	Moderate	Medium	Supported 2013		
61	Greater Victoria	6161025	CEDAR HILL MIDDLE	5	North/South Shops	860	Low	Medium	Supported 2013		
61	Greater Victoria	6161025	CEDAR HILL MIDDLE	6	Band/Music Block	280	Low/Moderate	Medium	Supported 2013		
61	Greater Victoria	6161025	CEDAR HILL MIDDLE	7	South Classroom Block	1,430	Low	Medium	Supported 2013		
61	Greater Victoria	6161035	CENTRAL MIDDLE SCHOOL	1	South Wing	3,600	Moderate/High	N/A	Completed	N/A	
61	Greater Victoria	6161035	CENTRAL MIDDLE SCHOOL	2	Gymnasium	1,165	High	N/A	Completed		
61	Greater Victoria	6161035	CENTRAL MIDDLE SCHOOL	3	Main Entrance	400	Moderate/High	N/A	Completed		
61	Greater Victoria	6161035	CENTRAL MIDDLE SCHOOL	4	East Wing	1,750	Moderate/High	N/A	Completed		
61	Greater Victoria	6161035	CENTRAL MIDDLE SCHOOL	5	Power Mechanics Shop	160	High	N/A	Completed		
61	Greater Victoria	6161035	CENTRAL MIDDLE SCHOOL	6	South East Wing	430	Low	N/A	Completed		
61	Greater Victoria	6161035	CENTRAL MIDDLE SCHOOL	7	Band Room	90	Moderate	N/A	Completed		
61	Greater Victoria	6161019	CLOVERDALE ELEMENTARY	1	North East Wing	480	Moderate/High	Medium	Supported 2013	High 1	November 2012 - Block 3 risk increased from M to H1. April 2013 - to start 2015.
61	Greater Victoria	6161019	CLOVERDALE ELEMENTARY	2	North Wing	480	Low/Moderate	Low	Supported 2013		
61	Greater Victoria	6161019	CLOVERDALE ELEMENTARY	3	Central Classrooms	2,000	Moderate/High	High 1	Supported 2013		
61	Greater Victoria	6161019	CLOVERDALE ELEMENTARY	4	Gymnasium	430	Low	Low	Supported 2013		
61	Greater Victoria	6161010	CRAIGFLOWER ELEMENTARY	1	Main Classrooms	1,712	Moderate/High	High 2	Structural Upgrade Required	High 2	
61	Greater Victoria	6161010	CRAIGFLOWER ELEMENTARY	2	Library	130	Low/Moderate	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161010	CRAIGFLOWER ELEMENTARY	3	Gymnasium	405	High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161010	CRAIGFLOWER ELEMENTARY	4	Storage	45	Moderate	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161010	CRAIGFLOWER ELEMENTARY	5	Special Edu. Room	15	Moderate/High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161037	DEAN HEIGHTS ALTERNATE (#99015)	1	Administration Block	900	Moderate	Medium	Non Structural Upgrade Required	Medium	
61	Greater Victoria	6161028	DONCASTER ELEMENTARY	1	West Classrooms	1,170	High	Medium	Non Structural Upgrade Required	N/A	
61	Greater Victoria	6161028	DONCASTER ELEMENTARY	2	Gymnasium	400	High	N/A	Completed		
61	Greater Victoria	6161028	DONCASTER ELEMENTARY	3	North Classrooms	1,800	Moderate/High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161028	DONCASTER ELEMENTARY	4	South Classrooms	1,600	Moderate/High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161048	ESQUIMALT SECONDARY	1	Main Classrooms	9,400	Moderate	Medium	Non Structural Upgrade Required	Medium	
61	Greater Victoria	6161048	ESQUIMALT SECONDARY	2	Gymnasium	1,000	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161048	ESQUIMALT SECONDARY	3	Kitchen/Lunchroom/Shop	1,029	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161048	ESQUIMALT SECONDARY	4	Auditorium/Music	1,360	Low	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161030	FRANK HOBBS ELEMENTARY	1	Centre Block	1,130	Moderate	Medium	Non Structural Upgrade Required	Medium	
61	Greater Victoria	6161030	FRANK HOBBS ELEMENTARY	2	South Classroom Wing	1,230	Moderate	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161030	FRANK HOBBS ELEMENTARY	3	East Classroom Block	370	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161030	FRANK HOBBS ELEMENTARY	4	Gymnasium	490	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161005	GEORGE JAY ELEMENTARY	1	Original Building	2,970	High	High 1	Supported 2013	High 1	November 2012 - Block 1 risk increased from M to H1. April 2013 - to start 2013.
61	Greater Victoria	6161005	GEORGE JAY ELEMENTARY	2	West Classrooms	1,980	High	High 1	Supported 2013		
61	Greater Victoria	6161038	GLANFORD MIDDLE	1	North Classrooms	1,350	High	Medium	Non Structural Upgrade Required	Medium	
61	Greater Victoria	6161038	GLANFORD MIDDLE	2	South Classrooms	1,070	Moderate/High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161038	GLANFORD MIDDLE	3	Gymnasium	?	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161038	GLANFORD MIDDLE	4	West Classrooms	?	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161039	GORDON HEAD MIDDLE	1	Classrooms	2,700	High	N/A	Completed	N/A	
61	Greater Victoria	6161039	GORDON HEAD MIDDLE	2	Gymnasium	520	High	N/A	Completed		
61	Greater Victoria	6161039	GORDON HEAD MIDDLE	3	81 Addition	450	Low	N/A	Completed		
61	Greater Victoria	6161052	HILLCREST ELEMENTARY	1	South Classroom Block	1,810	Low	Low	Meets Structural Life Safety Requirements	Low	
61	Greater Victoria	6161052	HILLCREST ELEMENTARY	2	Centre Block	1,400	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161052	HILLCREST ELEMENTARY	3	Gymnasium	440	Low/Moderate	Low	Meets Structural Life Safety Requirements		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
61	Greater Victoria	6161033	JAMES BAY COMMUNITY	1	Classrooms North	1,300	High	N/A	Completed		
61	Greater Victoria	6161033	JAMES BAY COMMUNITY	2	Classrooms South	1,350	Low	N/A	Completed	N/A	
61	Greater Victoria	6161033	JAMES BAY COMMUNITY	3	Gymnasium	?	Low	N/A	Completed		
61	Greater Victoria	6161042	LAKE HILL ELEMENTARY	1	Classrooms	2,560	High	Medium	Non Structural Upgrade Required	Medium	
61	Greater Victoria	6161042	LAKE HILL ELEMENTARY	2	Gymnasium	440	Moderate	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161064	LAMBRICK PARK SECONDARY	1	Main Classrooms	5,120	Low	High 2	Structural Upgrade Required		
61	Greater Victoria	6161064	LAMBRICK PARK SECONDARY	2	Gymnasium	1,100	Low	High 2	Structural Upgrade Required	High 2	
61	Greater Victoria	6161064	LAMBRICK PARK SECONDARY	3	South Classrooms	1,720	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161003	LAMPSON ELEMENTARY	1	Original Building	4,010	Low	Low	Meets Structural Life Safety Requirements	Low	
61	Greater Victoria	6161036	LANSLOWNE MIDDLE SCHOOL	1	East Classrooms	3,830	High	N/A	Completed		
61	Greater Victoria	6161036	LANSLOWNE MIDDLE SCHOOL	2	Gymnasium	1,410	Moderate	N/A	Completed	N/A	
61	Greater Victoria	6161036	LANSLOWNE MIDDLE SCHOOL	3	Drama	280	Low	N/A	Completed		
61	Greater Victoria	6161036	LANSLOWNE MIDDLE SCHOOL	4	Shops	570	Moderate	N/A	Completed		
61	Greater Victoria	6161040	MACAULAY ELEMENTARY	3	West Wing	1,450	Moderate/High	High 3	Structural Upgrade Required		
61	Greater Victoria	6161040	MACAULAY ELEMENTARY	4	East Wing	1,775	High	High 3	Structural Upgrade Required	High 3	
61	Greater Victoria	6161040	MACAULAY ELEMENTARY	1	South Wing Classrooms	1,600	High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161040	MACAULAY ELEMENTARY	2	Gymnasium	510	High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161092	MAINTENANCE & DISTRIBUTION	2	Building 1 - Central	1,115	High	Medium	Non Structural Upgrade Required	Medium	
61	Greater Victoria	6161092	MAINTENANCE & DISTRIBUTION	3	Building 2	460	High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161012	MARGARET JENKINS ELEMENTARY	1	Main Building	2,220	High	N/A	Completed		
61	Greater Victoria	6161012	MARGARET JENKINS ELEMENTARY	2	Annex	180	High	N/A	Completed	N/A	
61	Greater Victoria	6161012	MARGARET JENKINS ELEMENTARY	3	South Classrooms	1,280	High	N/A	Completed		
61	Greater Victoria	6161046	MARIGOLD ELEMENTARY	1	Offices	230	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161046	MARIGOLD ELEMENTARY	2	Classrooms	1,850	Moderate	Medium	Non Structural Upgrade Required	Medium	
61	Greater Victoria	6161046	MARIGOLD ELEMENTARY	3	Library/New Classrooms	380	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161046	MARIGOLD ELEMENTARY	4	Gymnasium	430	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161027	MCKENZIE ELEMENTARY	1	North Wing	1,450	Moderate/High	N/A	Completed		
61	Greater Victoria	6161027	MCKENZIE ELEMENTARY	2	New Gymnasium	450	Moderate	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161027	MCKENZIE ELEMENTARY	3	Central Classrooms	550	High	Medium	Non Structural Upgrade Required	N/A	
61	Greater Victoria	6161027	MCKENZIE ELEMENTARY	4	Old Gymnasium	250	Moderate/High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161027	MCKENZIE ELEMENTARY	5	East Wing	810	High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161015	MONTEREY MIDDLE	1	Original Building	2,150	High	N/A	Completed		
61	Greater Victoria	6161015	MONTEREY MIDDLE	2	North Classrooms	1,050	Low	N/A	Completed	N/A	
61	Greater Victoria	6161015	MONTEREY MIDDLE	3	West Classrooms	720	Low	N/A	Completed		
61	Greater Victoria	6161049	MOUNT DOUGLAS SECONDARY	1	Main Classrooms	6,620	High	N/A	Completed		
61	Greater Victoria	6161049	MOUNT DOUGLAS SECONDARY	2	Old Gymnasium	720	High	N/A	Completed	N/A	
61	Greater Victoria	6161049	MOUNT DOUGLAS SECONDARY	3	New Gymnasium	830	Low	N/A	Completed		
61	Greater Victoria	6161049	MOUNT DOUGLAS SECONDARY	4	Cafeteria/Music	605	High	N/A	Completed	N/A	
61	Greater Victoria	6161049	MOUNT DOUGLAS SECONDARY	5	North Classroom/Shop	640	Low	N/A	Completed		
61	Greater Victoria	6161054	NORTHTRIDGE ELEMENTARY	1	North Classrooms	620	Moderate	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161054	NORTHTRIDGE ELEMENTARY	2	South Classrooms	360	Low	Low	Meets Structural Life Safety Requirements	Medium	
61	Greater Victoria	6161054	NORTHTRIDGE ELEMENTARY	3	Gymnasium	410	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161054	NORTHTRIDGE ELEMENTARY	4	Library/Offices	750	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161013	OAKLANDS ELEMENTARY	1	Original Building	1,430	High	Low	Meets Structural Life Safety Requirements	Low	
61	Greater Victoria	6161016	QUADRA ELEMENTARY	1	Original Building	1,870	High	N/A	Under Construction		Supported 2012.
61	Greater Victoria	6161016	QUADRA ELEMENTARY	2	Annex	180	High	N/A	Under Construction		
61	Greater Victoria	6161016	QUADRA ELEMENTARY	3	South/Central Classrooms	840	High	N/A	Under Construction	N/A	
61	Greater Victoria	6161016	QUADRA ELEMENTARY	4	South Classrooms	820	Moderate/High	N/A	Under Construction		
61	Greater Victoria	6161057	REYNOLDS SECONDARY	1	Main Bldg. and Classrooms	5,350	Moderate/High	High 2	Structural Upgrade Required		
61	Greater Victoria	6161057	REYNOLDS SECONDARY	3	North-East Classrooms	1,741	Moderate	High 2	Structural Upgrade Required		
61	Greater Victoria	6161057	REYNOLDS SECONDARY	6	Music Annex	155	High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161057	REYNOLDS SECONDARY	7	Gymnasium	?	Low	Low	Meets Structural Life Safety Requirements	High 2	
61	Greater Victoria	6161057	REYNOLDS SECONDARY	8	SW Classrooms	?	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161057	REYNOLDS SECONDARY	2	NW Shops	500	Moderate/High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161057	REYNOLDS SECONDARY	4	Power Machine Shop	195	Moderate	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161057	REYNOLDS SECONDARY	5	Covered Workshed	204	Moderate	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161056	ROCKHEIGHTS MIDDLE SCHOOL	1	Classrooms	4,070	Low	Low	Meets Structural Life Safety Requirements	Low	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
61	Greater Victoria	6199033	S J WILLIS EDUCATIONAL CENTRE	1	Main Administration	2,761	Moderate/High	High 1	Inactive		
61	Greater Victoria	6199033	S J WILLIS EDUCATIONAL CENTRE	2	Auditorium	1,371	Moderate/High	High 1	Inactive		
61	Greater Victoria	6199033	S J WILLIS EDUCATIONAL CENTRE	3	Gymnasium	1,006	High	Medium	Inactive		
61	Greater Victoria	6199033	S J WILLIS EDUCATIONAL CENTRE	4	Shops and Cont. Education Classrooms	1,363	Moderate/High	High 3	Inactive		
61	Greater Victoria	6199033	S J WILLIS EDUCATIONAL CENTRE	5	South Classrooms	2,236	Moderate	Medium	Inactive		
61	Greater Victoria	6199033	S J WILLIS EDUCATIONAL CENTRE	6	Addition 1958	610	Moderate	High 1	Inactive		
61	Greater Victoria	6199033	S J WILLIS EDUCATIONAL CENTRE	7	Cont. Education	407	Moderate	High 3	Inactive		
61	Greater Victoria	6199033	S J WILLIS EDUCATIONAL CENTRE	8	Compound	70	Moderate	Medium	Inactive		
61	Greater Victoria	6161058	SHORELINE COMMUNITY MIDDLE SCHOOL	1	North Classrooms	2,450	Low/Moderate	High 1	Supported 2013		April 2013 - to start 2014.
61	Greater Victoria	6161058	SHORELINE COMMUNITY MIDDLE SCHOOL	2	South Classrooms	800	Low	Medium	Supported 2013		
61	Greater Victoria	6161058	SHORELINE COMMUNITY MIDDLE SCHOOL	3	Activity Wing	2,000	Moderate/High	High 2	Supported 2013		
61	Greater Victoria	6161058	SHORELINE COMMUNITY MIDDLE SCHOOL	4	Band Room	300	Low	Low	Supported 2013		
61	Greater Victoria	6161058	SHORELINE COMMUNITY MIDDLE SCHOOL	5	Shops	400	Moderate/High	High 3	Supported 2013		
61	Greater Victoria	6161058	SHORELINE COMMUNITY MIDDLE SCHOOL	6	Walkway	?	Low	Low	Supported 2013		
61	Greater Victoria	6161002	SOUTH PARK ELEMENTARY	1	Main Building	2,170	High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161002	SOUTH PARK ELEMENTARY	2	Annex	750	High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161063	SPECTRUM COMMUNITY SCHOOL	1	Main Classrooms	6,880	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161063	SPECTRUM COMMUNITY SCHOOL	2	Gymnasium	1,250	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161063	SPECTRUM COMMUNITY SCHOOL	3	Shops	1,550	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161063	SPECTRUM COMMUNITY SCHOOL	4	Drama/Dance/Music	670	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161008	SUNDANCE ELEMENTARY	1	Administration and Offices	133	Moderate/High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161008	SUNDANCE ELEMENTARY	2	Classrooms	650	High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161008	SUNDANCE ELEMENTARY	3	Gymnasium	260	High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161020	TILICUM ELEMENTARY	3	South Wing Classrooms	1,417	High	High 1	Supported 2013		April 2013 - to start 2014.
61	Greater Victoria	6161020	TILICUM ELEMENTARY	1	Original Main Building	1,722	Moderate/High	Medium	Supported 2013		
61	Greater Victoria	6161020	TILICUM ELEMENTARY	2	North Wing (Library and Staff Room)	700	Moderate/High	Medium	Supported 2013		
61	Greater Victoria	6161020	TILICUM ELEMENTARY	4	Gymnasium	?	Low	Low	Supported 2013		
61	Greater Victoria	6161090	Tolmie Administration Centre	1	Original Building	1,550	High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161090	Tolmie Administration Centre	2	Boardroom	670	Low/Moderate	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161090	Tolmie Administration Centre	4	Annex - East	390	Low/Moderate	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161065	TORQUAY ELEMENTARY	1	Main Bldg and Classrooms	2,230	Low/Moderate	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161065	TORQUAY ELEMENTARY	2	Gymnasium	550	Low/Moderate	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161065	TORQUAY ELEMENTARY	3	Additional Classrooms 1980	375	Moderate/High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161006	VICTOR SCHOOL	1	Classrooms	1,200	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161006	VICTOR SCHOOL	2	Gymnasium	290	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161018	VICTORIA HIGH	1	Original Building	7,720	High	High 3	Supported		
61	Greater Victoria	6161018	VICTORIA HIGH	2	Auditorium	610	High	High 3	Supported		
61	Greater Victoria	6161018	VICTORIA HIGH	3	Gymnasium	2,150	Low	Low	Supported		
61	Greater Victoria	6161018	VICTORIA HIGH	4	East Shops	1,980	High	N/A	Completed		
61	Greater Victoria	6161018	VICTORIA HIGH	5	Centre Shops	1,760	High	N/A	Completed		
61	Greater Victoria	6161018	VICTORIA HIGH	6	West Shops	1,130	High	N/A	Completed		
61	Greater Victoria	6161018	VICTORIA HIGH	7	North Shops	?	Low	N/A	Completed		
61	Greater Victoria	6161004	VICTORIA WEST ELEMENTARY	1	Activity Wing South	370	Moderate	N/A	Under Construction		July 2013 - Under Construction
61	Greater Victoria	6161004	VICTORIA WEST ELEMENTARY	2	Classrooms West	1,240	Low	N/A	Under Construction		
61	Greater Victoria	6161004	VICTORIA WEST ELEMENTARY	3	Classrooms North	740	Moderate	N/A	Under Construction		
61	Greater Victoria	6161004	VICTORIA WEST ELEMENTARY	4	Classrooms East	520	High	N/A	Under Construction		
61	Greater Victoria	6161004	VICTORIA WEST ELEMENTARY	5	Activity Wing North	240	Moderate	N/A	Under Construction		
61	Greater Victoria	6161029	VIEW ROYAL ELEMENTARY	1	East Classroom Wing	1,039	High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161029	VIEW ROYAL ELEMENTARY	2	Centre Classroom Wing	650	High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161029	VIEW ROYAL ELEMENTARY	3	West Classroom Wing	520	Moderate	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161029	VIEW ROYAL ELEMENTARY	4	2 Storey NW Classroom Block	790	High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161029	VIEW ROYAL ELEMENTARY	5	Gymnasium	420	Low	Low	Meets Structural Life Safety Requirements		
61	Greater Victoria	6161029	VIEW ROYAL ELEMENTARY	6	Staff and Storage Block	270	High	Medium	Non Structural Upgrade Required		
61	Greater Victoria	6161021	WILLOWS ELEMENTARY	1	Original Building	2,750	High	N/A	Completed		
61	Greater Victoria	6161021	WILLOWS ELEMENTARY	2	North Classrooms	400	High	N/A	Completed		
61	Greater Victoria	6161021	WILLOWS ELEMENTARY	3	West Classrooms	2,000	High	N/A	Completed		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
62	Sooke	6262013	BELMONT SECONDARY	1	Shops	2,491	Moderate/High	N/A	Under Construction	N/A	
62	Sooke	6262013	BELMONT SECONDARY	2	South Wing	4,675	Moderate/High	N/A	Under Construction		
62	Sooke	6262013	BELMONT SECONDARY	3	Centre Wing	1,994	Moderate	N/A	Under Construction		
62	Sooke	6262013	BELMONT SECONDARY	4	North Wing (2 Storeys)	4,309	Moderate/High	N/A	Under Construction		
62	Sooke	6262013	BELMONT SECONDARY	5	Northeast Wing	2,093	Moderate/High	N/A	Under Construction		
62	Sooke	6262013	BELMONT SECONDARY	6	Bandroom	171	Low/Moderate	N/A	Under Construction		
62	Sooke	6262021	DAVID CAMERON ELEMENTARY	1	Gymnasium	630	Low	Low	Meets Structural Life Safety Requirements	Low	
62	Sooke	6262021	DAVID CAMERON ELEMENTARY	2	Classrooms	2,655	Low	Low	Meets Structural Life Safety Requirements		
62	Sooke	6262016	DUNSMUIR MIDDLE SCHOOL	1	Gymnasium	1,145	Low	Low	Supported 2013	High 2	April 2013 - to start 2014.
62	Sooke	6262016	DUNSMUIR MIDDLE SCHOOL	2	Administration	555	Low	Low	Supported 2013		
62	Sooke	6262016	DUNSMUIR MIDDLE SCHOOL	3	South Wing	2,370	Low	High 2	Supported 2013		
62	Sooke	6262016	DUNSMUIR MIDDLE SCHOOL	4	Shop Wing	1,185	Low	High 2	Supported 2013		
62	Sooke	6262016	DUNSMUIR MIDDLE SCHOOL	5	East Wing	1,960	Low	High 2	Supported 2013		
62	Sooke	6262016	DUNSMUIR MIDDLE SCHOOL	6	Bandroom	370	Moderate	Medium	Supported 2013		
62	Sooke	6262014	GLENLAKE ELEMENTARY	1	Gymnasium	531	High	High 1	Inactive	High 1	
62	Sooke	6262014	GLENLAKE ELEMENTARY	2	Classrooms	2,210	High	High 3	Inactive		
62	Sooke	6262002	HAPPY VALLEY ELEMENTARY	1	Gymnasium	380	Moderate	N/A	Completed	N/A	
62	Sooke	6262002	HAPPY VALLEY ELEMENTARY	2	North Section 2 Storey	745	Moderate	N/A	Completed		
62	Sooke	6262002	HAPPY VALLEY ELEMENTARY	3	South Section 1 Storey	1,335	High	N/A	Completed		
62	Sooke	6262020	JOHN MUIR ELEMENTARY	1	Gymnasium	376	Moderate	Medium	Non Structural Upgrade Required	Medium	
62	Sooke	6262020	JOHN MUIR ELEMENTARY	2	Classrooms	1,546	Moderate	Medium	Non Structural Upgrade Required		
62	Sooke	6262011	MILLSTREAM ELEMENTARY	1	Gymnasium	470	Moderate	Medium	Non Structural Upgrade Required	Medium	
62	Sooke	6262011	MILLSTREAM ELEMENTARY	2	Main Wing	882	Moderate	Medium	Non Structural Upgrade Required		
62	Sooke	6262011	MILLSTREAM ELEMENTARY	3	East Wing	866	Moderate	Medium	Non Structural Upgrade Required		
62	Sooke	6262005	PORT RENFREW ELEMENTARY	1	Gymnasium	717	High	Medium	Non Structural Upgrade Required	Medium	
62	Sooke	6262005	PORT RENFREW ELEMENTARY	2	Classrooms	628	High	Medium	Non Structural Upgrade Required		
62	Sooke	6262007	RUTH KING ELEMENTARY	1	South Section 1 Storey	1,263	Low/Moderate	Low	Supported 2013	High 2	April 2013 - to start 2015.
62	Sooke	6262007	RUTH KING ELEMENTARY	2	North Section 2 Storey	2,172	Low/Moderate	High 2	Supported 2013		
62	Sooke	6262010	SANGSTER ELEMENTARY	1	Gymnasium	343	Moderate/High	N/A	Under Construction	N/A	Supported 2012. November 2012 - Risk changed for Block 1 from M to H2.
62	Sooke	6262010	SANGSTER ELEMENTARY	2	Classrooms	1,178	Moderate/High	N/A	Under Construction		
62	Sooke	6262010	SANGSTER ELEMENTARY	3	West Wing Addition	354	Moderate/High	N/A	Under Construction		
62	Sooke	6262012	SASEENOS ELEMENTARY	1	Gymnasium	469	Moderate	Medium	Non Structural Upgrade Required	Medium	
62	Sooke	6262012	SASEENOS ELEMENTARY	2	Classrooms	1,710	Moderate	Medium	Non Structural Upgrade Required		
62	Sooke	6262015	SAVORY ELEMENTARY	1	Gymnasium	480	Moderate	Medium	Non Structural Upgrade Required	Medium	
62	Sooke	6262015	SAVORY ELEMENTARY	2	Classrooms	1,550	Moderate	Medium	Non Structural Upgrade Required		
62	Sooke	6262004	SOOKE ELEMENTARY	1	Gymnasium	710	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
62	Sooke	6262004	SOOKE ELEMENTARY	2	West Wing	700	Moderate	Medium	Non Structural Upgrade Required		
62	Sooke	6262004	SOOKE ELEMENTARY	3	North Wing	1,233	Moderate	Medium	Non Structural Upgrade Required		
62	Sooke	6262025	SPENCER MIDDLE SCHOOL	1	Main	7,865	Moderate/High	N/A	Completed	N/A	
62	Sooke	6262026	WILLWAY ELEMENTARY	1	Main	1,903	Moderate	High 3	Structural Upgrade Required	High 3	
62	Sooke	6262022	WISHART ELEMENTARY	1	Gymnasium	430	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
62	Sooke	6262022	WISHART ELEMENTARY	2	Classrooms (Extended)	1,614	Low	Low	Meets Structural Life Safety Requirements		
62	Sooke	6262022	WISHART ELEMENTARY	3	2 Storey Wing (Original)	951	Low	Low	Meets Structural Life Safety Requirements		
62	Sooke	6262022	WISHART ELEMENTARY	4	Library	153	Low	Low	Meets Structural Life Safety Requirements		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
63	Saanich	6363001	BEAVER LAKE ELEMENTARY	1	1961 Gymnasium/1971 Covered Play Area	393	Moderate	Medium	Non Structural Upgrade Required	Medium	
63	Saanich	6363001	BEAVER LAKE ELEMENTARY	2	1956 Main Building (1961/64/71/99 Additions)	800	Moderate	Medium	Non Structural Upgrade Required		
63	Saanich	6363001	BEAVER LAKE ELEMENTARY	3	1999 Addition	?	Low	Low	Meets Structural Life Safety Requirements		
63	Saanich	6363002	BRENTWOOD ELEMENTARY	1	1951 Original Building, 1956/61 Additions	1,050	Moderate	Medium	Non Structural Upgrade Required	Medium	
63	Saanich	6363002	BRENTWOOD ELEMENTARY	2	1970 Addition	1,180	Moderate	Medium	Non Structural Upgrade Required		
63	Saanich	6363002	BRENTWOOD ELEMENTARY	3	1951 Original Gymnasium	225	Moderate	Medium	Non Structural Upgrade Required		
63	Saanich	6363002	BRENTWOOD ELEMENTARY	4	1970 Gymnasium Addition	380	Low/Moderate	Low	Meets Structural Life Safety Requirements		
63	Saanich	6363002	BRENTWOOD ELEMENTARY	5	Covered Area	160	Low	Low	Meets Structural Life Safety Requirements		
63	Saanich	6363002	BRENTWOOD ELEMENTARY	6	1998 Addition	?	Low	Low	Meets Structural Life Safety Requirements		
63	Saanich	6363006	CHILDREN'S DEVELOPMENT CENTRE	1	1966 Main Building	425	Moderate/High	High 3	Structural Upgrade Required	High 3	
63	Saanich	6363021	CLAREMONT SECONDARY SCHOOL	1	1966 Addition (1994 Upgrade)	341	Low/Moderate	N/A	Completed	N/A	
63	Saanich	6363021	CLAREMONT SECONDARY SCHOOL	2	1961 N. Wing /1964 Addition (1994 Rebuild)	?	Low	N/A	Completed		
63	Saanich	6363021	CLAREMONT SECONDARY SCHOOL	3	1961 Gymnasium / 1966 Addition	1,018	Moderate/High	N/A	Completed		
63	Saanich	6363021	CLAREMONT SECONDARY SCHOOL	4	1961 S. Wing /1966 Addition /1975 Addition	1,240	Moderate	N/A	Completed		
63	Saanich	6363021	CLAREMONT SECONDARY SCHOOL	5	1966 Addition /1975 Addition	587	High	N/A	Completed		
63	Saanich	6363021	CLAREMONT SECONDARY SCHOOL	6	1994 Addition	?	Low	N/A	Completed		
63	Saanich	6363003	CORDOVA BAY ELEMENTARY	1	1956 Gymnasium / 1966 Addition (2003 Upgrade)	410	Low	Low	Supported 2013	High 2	April 2013 - to start 2013.
63	Saanich	6363003	CORDOVA BAY ELEMENTARY	2	1945 Main Building (1961/65/69 Additions)	2,251	Moderate	High 2	Supported 2013		
63	Saanich	6363003	CORDOVA BAY ELEMENTARY	3	1966 Covered Area / 1969 Addition (Upgrade)	234	Low	Low	Supported 2013		
63	Saanich	6363003	CORDOVA BAY ELEMENTARY	4	1966/69 Additions	153	Moderate	Medium	Supported 2013		
63	Saanich	6363003	CORDOVA BAY ELEMENTARY	5	1956/1965 Additions	62	Moderate/High	Low	Supported 2013	NA	
63	Saanich	6363004	DEEP COVE ELEMENTARY	1	1956 Original Building	210	Moderate	NA	Under Construction		Supported 2012
63	Saanich	6363004	DEEP COVE ELEMENTARY	2	1965 Addition	85	Moderate	NA	Under Construction		
63	Saanich	6363004	DEEP COVE ELEMENTARY	3	1965 Addition	225	Moderate/High	NA	Under Construction		
63	Saanich	6363004	DEEP COVE ELEMENTARY	4	1966 Addition	140	Low	NA	Under Construction		
63	Saanich	6363004	DEEP COVE ELEMENTARY	5	1966 Addition	150	Moderate	NA	Under Construction		
63	Saanich	6363004	DEEP COVE ELEMENTARY	6	1966/1982 Additions	530	Low/Moderate	NA	Under Construction		
63	Saanich	6363004	DEEP COVE ELEMENTARY	7	1969 Addition	350	Moderate/High	NA	Under Construction		
63	Saanich	6363004	DEEP COVE ELEMENTARY	8	1982 Addition	130	Low/Moderate	NA	Under Construction		
63	Saanich	6363004	DEEP COVE ELEMENTARY	9	1982 Addition	830	Low/Moderate	NA	Under Construction		
63	Saanich	6363004	DEEP COVE ELEMENTARY	10	1991 Addition	?	Low	NA	Under Construction		
63	Saanich	6363015	GREENGLADE ELEMENTARY	1	1975 Original Building	1,820	Low/Moderate	Low	Inactive	Medium	
63	Saanich	6363015	GREENGLADE ELEMENTARY	2	1989 Addition	665	Moderate	Medium	Inactive		
63	Saanich	6363499	KEATING ELEM ANNEX	1	1976 West Wing	212	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
63	Saanich	6363499	KEATING ELEM ANNEX	2	1976 East Wing	258	Low/Moderate	Low	Meets Structural Life Safety Requirements		
63	Saanich	6363007	KEATING ELEMENTARY	1	1963 NE Wing 1966 Addition (2001 Upgrade)	921	Low/Moderate	Low	Meets Structural Life Safety Requirements	High 3	
63	Saanich	6363007	KEATING ELEMENTARY	2	1969 Gymnasium Addition	628	Low/Moderate	Low	Meets Structural Life Safety Requirements		
63	Saanich	6363007	KEATING ELEMENTARY	3	1966 Covered Area (2001 Upgrade)	267	Low	Low	Meets Structural Life Safety Requirements		
63	Saanich	6363007	KEATING ELEMENTARY	4	1969 Addition	1,020	Moderate/High	High 3	Structural Upgrade Required		
63	Saanich	6363007	KEATING ELEMENTARY	5	1967/1969 Additions	414	Moderate/High	High 3	Structural Upgrade Required		
63	Saanich	6363007	KEATING ELEMENTARY	6	1966 Covered Play area	222	Low	High 3	Structural Upgrade Required		
63	Saanich	6363007	KEATING ELEMENTARY	7	1991 Addition	?	Low	Low	Meets Structural Life Safety Requirements		
63	Saanich	6363008	LOCHSIDE ELEMENTARY	1	1963/65 Main Building (2003 Upgrade)	585	Low/Moderate	Low	Supported 2013	High 2	April 2013 - to start 2015.
63	Saanich	6363008	LOCHSIDE ELEMENTARY	2	1963 Main Building /1971 Addition	543	Moderate/High	High 2	Supported 2013		
63	Saanich	6363008	LOCHSIDE ELEMENTARY	3	1991 Addition	?	Low	Low	Supported 2013		
63	Saanich	6363008	LOCHSIDE ELEMENTARY	4	1967 Gymnasium	287	Moderate/High	Medium	Supported 2013		
63	Saanich	6363009	MCTAVISH ELEMENTARY	1	1956 & 1966 Additions	185	Moderate	Medium	Inactive	High 1	
63	Saanich	6363009	MCTAVISH ELEMENTARY	2	1951 Original Building (1956/61/66 Additions)	365	Moderate	Medium	Inactive		
63	Saanich	6363009	MCTAVISH ELEMENTARY	3	1966 Gymnasium	280	Moderate/High	High 1	Inactive		
63	Saanich	6363009	MCTAVISH ELEMENTARY	4	1998 Addition	?	Low	Low	Inactive		
63	Saanich	6363026	NORTH SAANICH MIDDLE SCHOOL	1	Original Building (Pre 1954)/1954 Addition	2,820	Moderate/High	N/A	Completed	N/A	
63	Saanich	6363026	NORTH SAANICH MIDDLE SCHOOL	2	1956 Addition	575	Moderate/High	N/A	Completed		
63	Saanich	6363026	NORTH SAANICH MIDDLE SCHOOL	3	1962/64/74/99 Additions	386	Moderate/High	N/A	Completed		
63	Saanich	6363026	NORTH SAANICH MIDDLE SCHOOL	4	1967 & 1969 Additions	525	Moderate/High	N/A	Completed		
63	Saanich	6363026	NORTH SAANICH MIDDLE SCHOOL	5	1974 Addition	1,120	Moderate/High	N/A	Completed		
63	Saanich	6363026	NORTH SAANICH MIDDLE SCHOOL	6	1999 Addition	?	Low	N/A	Completed		
63	Saanich	6363026	NORTH SAANICH MIDDLE SCHOOL	7	2001 Addition	?	Low	N/A	Completed		
63	Saanich	6363026	NORTH SAANICH MIDDLE SCHOOL	8	2001 Addition (covered area)	?	Low	N/A	Completed		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
63	Saanich	6363022	PARKLAND SECONDARY SCHOOL	1	1973 Gymnasium	1,125	Low	Low	Supported 2013	High 2	April 2013 - to start 2014.
63	Saanich	6363022	PARKLAND SECONDARY SCHOOL	2	1973 Main Building (Fire Damage Repair 2004)	380	Low	Low	Supported 2013		
63	Saanich	6363022	PARKLAND SECONDARY SCHOOL	3	1973 Main Building	3,800	Moderate	High 2	Supported 2013		
63	Saanich	6363022	PARKLAND SECONDARY SCHOOL	4	2000 Addition	?	Low	Low	Supported 2013		
63	Saanich	6363022	PARKLAND SECONDARY SCHOOL	5	1973 Main Building (Upgraded 2000)	1,670	Moderate	High 2	Supported 2013		
63	Saanich	6363022	PARKLAND SECONDARY SCHOOL	6	1974 Addition	625	Moderate	High 2	Supported 2013		
63	Saanich	6363010	PROSPECT LAKE ELEMENTARY	1	1975 Covered Area (2003 Upgrade)	84	Low	N/A	Completed	N/A	
63	Saanich	6363010	PROSPECT LAKE ELEMENTARY	2	1963 Main Building (2003 Upgrade)	526	Low/Moderate	N/A	Completed		
63	Saanich	6363010	PROSPECT LAKE ELEMENTARY	3	1992 Addition	?	Low	N/A	Completed		
63	Saanich	6363010	PROSPECT LAKE ELEMENTARY	4	1967/75 Additions	150	Moderate/High	N/A	Completed		
63	Saanich	6363010	PROSPECT LAKE ELEMENTARY	5	1967 Gymnasium	232	Moderate/High	N/A	Completed		
63	Saanich	6363012	SAANICHTON ELEMENTARY	1	1963-66 Main Building (2001 Upgrade)	370	Low/Moderate	Low	Meets Structural Life Safety Requirements		
63	Saanich	6363012	SAANICHTON ELEMENTARY	2	1966/79 Additions (2003 Upgrade)	478	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
63	Saanich	6363012	SAANICHTON ELEMENTARY	3	1979 Addition	1,022	Moderate	Medium	Non Structural Upgrade Required		
63	Saanich	6363012	SAANICHTON ELEMENTARY	4	1969 Addition (Small 1993 Addition)	465	Moderate	Medium	Non Structural Upgrade Required		
63	Saanich	6363013	SANSBURY ELEMENTARY	1	1956 Original Building (1961/66 Additions)	660	Moderate	High 3	Inactive		
63	Saanich	6363013	SANSBURY ELEMENTARY	2	1966 Gymnasium	280	Moderate	High 1	Inactive	High 1	
63	Saanich	6363013	SANSBURY ELEMENTARY	3	1966 Addition	125	Moderate	Medium	Inactive		
63	Saanich	6363013	SANSBURY ELEMENTARY	4	1969 Addition	185	Moderate	Medium	Inactive		
63	Saanich	6363013	SANSBURY ELEMENTARY	5	Portable	?	Low	Low	Inactive		
63	Saanich	6363014	SIDNEY ELEMENTARY	1	1951 Original Building	1,135	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
63	Saanich	6363014	SIDNEY ELEMENTARY	2	1951 Original Building, 1964 Addition	385	Moderate/High	Medium	Non Structural Upgrade Required		
63	Saanich	6363014	SIDNEY ELEMENTARY	3	1956 Addition	225	Moderate/High	Medium	Non Structural Upgrade Required		
63	Saanich	6363014	SIDNEY ELEMENTARY	4	1966 Addition (2003 Upgrade)	450	Low/Moderate	Low	Meets Structural Life Safety Requirements		
63	Saanich	6363014	SIDNEY ELEMENTARY	5	1969 Addition	55	Moderate/High	Medium	Non Structural Upgrade Required		
63	Saanich	6363014	SIDNEY ELEMENTARY	6	1969 Addition	100	Moderate/High	Medium	Non Structural Upgrade Required		
63	Saanich	6363014	SIDNEY ELEMENTARY	7	1981 Addition	200	Moderate/High	Medium	Non Structural Upgrade Required		
63	Saanich	6363014	SIDNEY ELEMENTARY	8	1966 Addition (2002 Upgrade)	350	Low/Moderate	Low	Meets Structural Life Safety Requirements		
63	Saanich	6363014	SIDNEY ELEMENTARY	9	1969 Addition	825	Moderate	Medium	Non Structural Upgrade Required		
63	Saanich	6363020	STELLY'S SECONDARY SCHOOL	1	1976 Main Building	6,025	Moderate/High	N/A	Completed	N/A	
63	Saanich	6363020	STELLY'S SECONDARY SCHOOL	2	1976 Gymnasium	750	Moderate	N/A	Completed		
63	Saanich	6363020	STELLY'S SECONDARY SCHOOL	3	1992 Addition	?	Low	N/A	Completed		
63	Saanich	6363020	STELLY'S SECONDARY SCHOOL	4	1996 Addition	?	Low	N/A	Completed		
63	Saanich	6363020	STELLY'S SECONDARY SCHOOL	5	Permanent Portable	150	Low/Moderate	N/A	Completed		
64	Gulf Islands	6464007	FERNWOOD ELEMENTARY	1	Original 1977	1,365	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
64	Gulf Islands	6464007	FERNWOOD ELEMENTARY	2	Gymnasium /1989 Addition	630	Moderate/High	Medium	Non Structural Upgrade Required		
64	Gulf Islands	6464007	FERNWOOD ELEMENTARY	3	Multipurpose	161	Moderate/High	Medium	Non Structural Upgrade Required		
64	Gulf Islands	6464009	FULFORD ELEMENTARY	1	Gymnasium/Administration	882	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
64	Gulf Islands	6464009	FULFORD ELEMENTARY	2	Classrooms 1983	1,073	Moderate/High	Medium	Non Structural Upgrade Required		
64	Gulf Islands	6464009	FULFORD ELEMENTARY	3	Classrooms 1993	?	Low	Low	Meets Structural Life Safety Requirements		
64	Gulf Islands	6464005	GALIANO COMMUNITY SCHOOL	1	Classrooms	286	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
64	Gulf Islands	6464005	GALIANO COMMUNITY SCHOOL	2	1982 Expansion Inc. Gymnasium	700	Moderate	Medium	Non Structural Upgrade Required		
64	Gulf Islands	6464005	GALIANO COMMUNITY SCHOOL	3	1986 Expansion	306	Moderate	Medium	Non Structural Upgrade Required		
64	Gulf Islands	6464003	MAYNE ELEM-JR SEC	1	Old School	97	Moderate	Medium	Non Structural Upgrade Required	Medium	
64	Gulf Islands	6464003	MAYNE ELEM-JR SEC	2	1974 Addition	189	Moderate	Medium	Non Structural Upgrade Required		
64	Gulf Islands	6464003	MAYNE ELEM-JR SEC	3	1975-1976 Addition/Gym	637	Moderate/High	Medium	Non Structural Upgrade Required		
64	Gulf Islands	6464003	MAYNE ELEM-JR SEC	4	Shop (1982)	194	Moderate	Medium	Non Structural Upgrade Required		
64	Gulf Islands	6464003	MAYNE ELEM-JR SEC	5	Kindergarten (Portable)	?	Low	Low	Meets Structural Life Safety Requirements		
64	Gulf Islands	6464008	PENDER ISLANDS ELEM-SEC	1	Gymnasium/Classrooms	1,345	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
64	Gulf Islands	6464008	PENDER ISLANDS ELEM-SEC	2	Classroom Additions	605	Moderate/High	Medium	Non Structural Upgrade Required		
64	Gulf Islands	6464008	PENDER ISLANDS ELEM-SEC	3	2002 Expansion	?	Low	Low	Meets Structural Life Safety Requirements		
64	Gulf Islands	6464002	SALT SPRING ELEMENTARY	1	Original	2,000	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
64	Gulf Islands	6464002	SALT SPRING ELEMENTARY	2	1972 Addition/Gym	610	Moderate/High	Medium	Non Structural Upgrade Required		
64	Gulf Islands	6464002	SALT SPRING ELEMENTARY	3	1976 Addition	384	Moderate/High	Medium	Non Structural Upgrade Required		
64	Gulf Islands	6464006	SALT SPRING ISLAND MIDDLE SCHOOL	1	Gymnasium	742	Moderate/High	N/A	Completed	N/A	
64	Gulf Islands	6464006	SALT SPRING ISLAND MIDDLE SCHOOL	2	Classrooms	2,580	High	N/A	Completed		
64	Gulf Islands	6464006	SALT SPRING ISLAND MIDDLE SCHOOL	3	Modular/Music	290	Moderate	N/A	Completed		
64	Gulf Islands	6464006	SALT SPRING ISLAND MIDDLE SCHOOL	4	Vocational	1,400	Moderate/High	N/A	Completed		
64	Gulf Islands	6464004	SATURNA ISLAND ELEMENTARY	1	Original	54	Moderate	Medium	Non Structural Upgrade Required		
64	Gulf Islands	6464004	SATURNA ISLAND ELEMENTARY	2	Addition	71	Moderate/High	Medium	Non Structural Upgrade Required	Medium	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
68	Nanaimo/Ladysmith	6899021	5 ACRES ALTERNATE	1	Classrooms	669	Moderate	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868018	BAYVIEW ELEMENTARY	1	Classroom	1,748	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868018	BAYVIEW ELEMENTARY	2	Multipurpose Room	200	Low	Low	Meets Structural Life Safety Requirements	Medium	
68	Nanaimo/Ladysmith	6868018	BAYVIEW ELEMENTARY	3	Gymnasium	442	Moderate/High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868019	BRECHIN ELEMENTARY	1	Gymnasium 1992	391	Low	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868019	BRECHIN ELEMENTARY	2	Classrooms 1964, 1966	1,217	Moderate	High 3	Structural Upgrade Required	High 3	
68	Nanaimo/Ladysmith	6868019	BRECHIN ELEMENTARY	3	Classrooms 1992	1,765	Low/Moderate	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868022	CHASE RIVER ELEMENTARY	1	Gymnasium	350	Moderate	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868022	CHASE RIVER ELEMENTARY	2	Single Storey Classrooms	1,740	Moderate/High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868024	CILAIRE ELEMENTARY	1	Classrooms	1,739	Moderate/High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868024	CILAIRE ELEMENTARY	2	Gymnasium	416	Low/Moderate	Medium	Non Structural Upgrade Required	High 3	
68	Nanaimo/Ladysmith	6868024	CILAIRE ELEMENTARY	3	Concrete change rooms	348	High	High 3	Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868027	DAVIS ROAD ELEMENTARY	1	Gymnasium	235	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868027	DAVIS ROAD ELEMENTARY	2	Classrooms	863	Moderate	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868027	DAVIS ROAD ELEMENTARY	3	Classrooms	253	Low/Moderate	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868028	DEPARTURE BAY ELEMENTARY	1	Multipurpose Room	415	Low	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868028	DEPARTURE BAY ELEMENTARY	2	Two Storey Classroom	1,160	Moderate	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868028	DEPARTURE BAY ELEMENTARY	3	Classrooms	1,534	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868030	DUFFERIN CRESCENT ELEMENTARY	1	Gymnasium	535	High	Medium	Inactive		
68	Nanaimo/Ladysmith	6868030	DUFFERIN CRESCENT ELEMENTARY	2	2 Classrooms	2,569	High	Medium	Inactive	Medium	
68	Nanaimo/Ladysmith	6868036	FAIRVIEW ELEMENTARY	1	Gym/Activity Room	732	Moderate/High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868036	FAIRVIEW ELEMENTARY	2	East Classrooms	1,669	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868036	FAIRVIEW ELEMENTARY	3	West Classrooms	1,500	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868037	FOREST PARK ELEMENTARY	1	Classrooms 1	493	Moderate/High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868037	FOREST PARK ELEMENTARY	2	Classrooms 2	535	Low/Moderate	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868037	FOREST PARK ELEMENTARY	3	Administration, Library	460	Low	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868037	FOREST PARK ELEMENTARY	4	Gymnasium	414	Moderate	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868037	FOREST PARK ELEMENTARY	5	Services	526	Moderate/High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868037	FOREST PARK ELEMENTARY	6	Classrooms	935	Moderate/High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868040	GABRIOLA ELEMENTARY	1	1976 Gymnasium	500	Moderate/High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868040	GABRIOLA ELEMENTARY	2	East Classrooms	1,074	Moderate	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868040	GABRIOLA ELEMENTARY	3	Central Classrooms	810	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868041	GEORGIA AVENUE ELEMENTARY	1	Classrooms	2,172	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868041	GEORGIA AVENUE ELEMENTARY	2	Gymnasium	395	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
68	Nanaimo/Ladysmith	6868041	GEORGIA AVENUE ELEMENTARY	3	Classrooms and Administration	1,667	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868044	HAMMOND BAY ELEMENTARY	1	Gymnasium	315	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
68	Nanaimo/Ladysmith	6868044	HAMMOND BAY ELEMENTARY	2	Classrooms	2,511	Low	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868045	HAREWOOD ELEMENTARY	1	Gymnasium	385	Moderate/High	Medium	Inactive		
68	Nanaimo/Ladysmith	6868045	HAREWOOD ELEMENTARY	2	Classrooms	1,574	High	Medium	Inactive	Medium	
68	Nanaimo/Ladysmith	6868011	JOHN BARSBY COMMUNITY SCHOOL	1	Auditorium, Kitchen, Multi-purpose	856	High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868011	JOHN BARSBY COMMUNITY SCHOOL	2	1999 Addition 2 Storey	?	Low	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868011	JOHN BARSBY COMMUNITY SCHOOL	3	Classrooms Two Storey	3,259	High	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868011	JOHN BARSBY COMMUNITY SCHOOL	4	Single Storey	2,000	Moderate/High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868048	LADYSMITH INTERMEDIATE	1	Gymnasium 1955	343	High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868048	LADYSMITH INTERMEDIATE	2	Classrooms 1955/1995	2,010	High	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868048	LADYSMITH INTERMEDIATE	3	Library, Multi-Purpose 1995	451	Low	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868049	LADYSMITH PRIMARY	1	Gymnasium	460	High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868049	LADYSMITH PRIMARY	2	Original Classrooms	1,075	Moderate	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868049	LADYSMITH PRIMARY	3	Addition	1,120	Low	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868002	LADYSMITH SECONDARY	1	Gymnasium	2,500	Low	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868002	LADYSMITH SECONDARY	2	Auditorium/Lunch Room	1,150	High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868002	LADYSMITH SECONDARY	3	Two Storey Timber Frame	2,430	High	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868002	LADYSMITH SECONDARY	4	Single Storey Masonry	960	Moderate/High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868055	MCGIRR ELEMENTARY	1	Gymnasium	375	Low	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868055	MCGIRR ELEMENTARY	2	Classrooms	2,508	Low	Low	Meets Structural Life Safety Requirements	Low	
68	Nanaimo/Ladysmith	6868055	MCGIRR ELEMENTARY	3	Classrooms 1999	717	Low	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868053	MOUNT BENSON ELEMENTARY	1	Gymnasium, Multi-Purpose Room, Change Rooms	525	Low/Moderate	Low	Inactive		
68	Nanaimo/Ladysmith	6868053	MOUNT BENSON ELEMENTARY	2	Single Storey T-Frame	1,781	Moderate/High	Medium	Inactive	Medium	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
68	Nanaimo/Ladysmith	6868052	MOUNTAIN VIEW ELEMENTARY	1	Classrooms 1998	1,682	Moderate	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868052	MOUNTAIN VIEW ELEMENTARY	2	Gymnasium 1998	410	Low/Moderate	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868052	MOUNTAIN VIEW ELEMENTARY	3	Kindergarten 1982	370	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868052	MOUNTAIN VIEW ELEMENTARY	4	Multipurpose 1977	420	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868052	MOUNTAIN VIEW ELEMENTARY	5	Classrooms 1967,1969	215	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868510	N.D.S.S.ANNEX	1	Music Room - typical of six in district	1,290	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868001	NANAIMO DISTRICT SECONDARY	1	Gymnasium	1,680	High	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868001	NANAIMO DISTRICT SECONDARY	2	Library	2,020	Low	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868001	NANAIMO DISTRICT SECONDARY	3	Classrooms Two Storey	8,060	High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868001	NANAIMO DISTRICT SECONDARY	4	Shops	1,737	Moderate/High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868001	NANAIMO DISTRICT SECONDARY	5	Cafeteria	740	Moderate/High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868009	NORTH CEDAR INTERMEDIATE	1	Gymnasium	1,231	Moderate/High	High 3	Structural Upgrade Required	High 3	
68	Nanaimo/Ladysmith	6868009	NORTH CEDAR INTERMEDIATE	2	Two Storey	2,072	Moderate/High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868009	NORTH CEDAR INTERMEDIATE	3	Annex Building (Shop)	396	Low	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868009	NORTH CEDAR INTERMEDIATE	4	Band / Music	216	Low	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868058	NORTH OYSTER ELEMENTARY	1	Gymnasium	666	Moderate/High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868058	NORTH OYSTER ELEMENTARY	2	Classrooms Single Storey	947	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868058	NORTH OYSTER ELEMENTARY	3	Classrooms 1993 Addition	1,173	Low/Moderate	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868057	NORTHFIELD ALTERNATE	1	Classrooms	598	Moderate	Medium	Inactive	Medium	
68	Nanaimo/Ladysmith	6868061	PARK AVENUE ELEMENTARY	1	Gymnasium Change Rooms	676	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868061	PARK AVENUE ELEMENTARY	2	Single Storey Timber Frame	1,614	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868061	PARK AVENUE ELEMENTARY	3	1999 Addition Classrooms	?	Low	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868065	PAULINE HAARER ELEMENTARY	1	Classrooms	641	Moderate/High	N/A	Completed		
68	Nanaimo/Ladysmith	6868065	PAULINE HAARER ELEMENTARY	2	Classrooms 1950	305	Moderate/High	N/A	Completed		
68	Nanaimo/Ladysmith	6868065	PAULINE HAARER ELEMENTARY	3	Gymnasium	423	Low/Moderate	N/A	Completed	N/A	
68	Nanaimo/Ladysmith	6868065	PAULINE HAARER ELEMENTARY	4	Kindergarten	240	Low	N/A	Completed		
68	Nanaimo/Ladysmith	6868065	PAULINE HAARER ELEMENTARY	5	Library	423	Low	N/A	Completed		
68	Nanaimo/Ladysmith	6868066	PLEASANT VALLEY ELEMENTARY	1	Gymnasium	380	Low/Moderate	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868066	PLEASANT VALLEY ELEMENTARY	2	Two Storey Classroom	960	Moderate	High 3	Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868066	PLEASANT VALLEY ELEMENTARY	3	Library and Classrooms	524	Low/Moderate	Low	Meets Structural Life Safety Requirements	High 3	
68	Nanaimo/Ladysmith	6868066	PLEASANT VALLEY ELEMENTARY	4	Single Storey Classroom	1,030	Low	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868068	PRINCESS ROYAL ELEMENTARY	1	Gymnasium	240	Low/Moderate	Low	Inactive	Medium	
68	Nanaimo/Ladysmith	6868068	PRINCESS ROYAL ELEMENTARY	2	Single Storey Timber Frame	621	Moderate/High	Medium	Inactive		
68	Nanaimo/Ladysmith	6868071	QUARTERWAY ELEMENTARY	1	West Wing	1,464	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868071	QUARTERWAY ELEMENTARY	2	Gymnasium	409	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868071	QUARTERWAY ELEMENTARY	3	East Wing	1,440	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868076	ROCK CITY ELEMENTARY	1	Gymnasium	487	Low	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868076	ROCK CITY ELEMENTARY	2	Classrooms	1,086	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868076	ROCK CITY ELEMENTARY	3	Primary Annex	414	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
68	Nanaimo/Ladysmith	6868076	ROCK CITY ELEMENTARY	4	Classrooms	1,346	Low/Moderate	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868077	RUTHERFORD COMMUNITY	1	Gymnasium	427	Low/Moderate	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868077	RUTHERFORD COMMUNITY	2	Two Storey	1,596	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868077	RUTHERFORD COMMUNITY	3	Single Storey Timber Frame	705	Moderate/High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868077	RUTHERFORD COMMUNITY	4	Kindergarten and Multi-Purpose Room	?	Low	Low	Meets Structural Life Safety Requirements	Medium	
68	Nanaimo/Ladysmith	6868080	SEAVIEW ELEMENTARY	1	Gymnasium	1,220	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868080	SEAVIEW ELEMENTARY	2	Administration	884	Low/Moderate	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868080	SEAVIEW ELEMENTARY	3	Classrooms	449	Low/Moderate	Low	Meets Structural Life Safety Requirements		
68	Nanaimo/Ladysmith	6868081	SOUTH WELLINGTON ELEMENTARY	1	Classrooms	917	High	High 2	Inactive		High 2
68	Nanaimo/Ladysmith	6868086	UPLANDS PARK ELEMENTARY	1	Gymnasium	384	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
68	Nanaimo/Ladysmith	6868086	UPLANDS PARK ELEMENTARY	2	Classrooms	2,538	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6899022	VAST CENTRE	1	Classrooms	1,150	Moderate	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868084	WATERLOO ELEMENTARY	1	Gymnasium	269	Low	Low	Inactive	Low	
68	Nanaimo/Ladysmith	6868084	WATERLOO ELEMENTARY	2	Classrooms	683	Low/Moderate	Low	Inactive		
68	Nanaimo/Ladysmith	6868015	WELLINGTON SECONDARY	1	Block A science wing (1967)	2,266	High	NA	Under Construction	NA	November 2012 - SPIR's completed and risk upgraded to H1 for most blocks. Block D Gym portion Low risk.
68	Nanaimo/Ladysmith	6868015	WELLINGTON SECONDARY	2	Block B workshops (1967)	1,163	High	NA	Under Construction		
68	Nanaimo/Ladysmith	6868015	WELLINGTON SECONDARY	3	Block C classroom/multipurpose (2000)	?	Low	NA	Under Construction		
68	Nanaimo/Ladysmith	6868015	WELLINGTON SECONDARY	4	Block D change rooms/classrooms (1971) & gym (2000)	626	Low	NA	Under Construction		
68	Nanaimo/Ladysmith	6868015	WELLINGTON SECONDARY	5	Block E administration block (1981)	967	High	NA	Under Construction		
68	Nanaimo/Ladysmith	6868015	WELLINGTON SECONDARY	6	Block F central core (1969)	2,540	High	NA	Under Construction		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
68	Nanaimo/Ladysmith	6868085	WOODBANK PRIMARY	1	Classrooms	1,364	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868085	WOODBANK PRIMARY	2	Library/Classroom	1,092	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868085	WOODBANK PRIMARY	3	Gymnasium	397	Moderate	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868013	WOODLANDS SECONDARY	1	Classrooms	2,040	High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868013	WOODLANDS SECONDARY	2	Classrooms	3,714	High	Medium	Non Structural Upgrade Required	Medium	
68	Nanaimo/Ladysmith	6868013	WOODLANDS SECONDARY	3	Gymnasium	856	High	Medium	Non Structural Upgrade Required		
68	Nanaimo/Ladysmith	6868013	WOODLANDS SECONDARY	4	Shop & Cafeteria	1,233	High	Medium	Non Structural Upgrade Required		
69	Qualicum	6969012	BALLENAS SECONDARY	1	Classrooms 1991	756	Low	Low	Meets Structural Life Safety Requirements		
69	Qualicum	6969012	BALLENAS SECONDARY	2	Classrooms/Gym 1976	7,110	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
69	Qualicum	6969012	BALLENAS SECONDARY	3	Classrooms/Gym 2000	2,755	Low	Low	Meets Structural Life Safety Requirements		
69	Qualicum	6969015	BOWSER ELEMENTARY	1	Building A	822	Moderate	Medium	Non Structural Upgrade Required		
69	Qualicum	6969015	BOWSER ELEMENTARY	2	Gymnasium, MP Room, Library	877	Low	Low	Meets Structural Life Safety Requirements	Medium	
69	Qualicum	6969015	BOWSER ELEMENTARY	3	Classrooms	784	Low/Moderate	Low	Meets Structural Life Safety Requirements		
69	Qualicum	6969016	FALSE BAY SCHOOL	1	Classroom	517	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
69	Qualicum	6969002	FRENCH CREEK ELEMENTARY	1	Classrooms	1,385	Moderate	Medium	Non Structural Upgrade Required		
69	Qualicum	6969002	FRENCH CREEK ELEMENTARY	2	Gymnasium	301	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
69	Qualicum	6969014	KWALIKUM SECONDARY	1	Gymnasium	1,094	Low	Low	Meets Structural Life Safety Requirements		
69	Qualicum	6969014	KWALIKUM SECONDARY	2	Classrooms	3,480	Moderate/High	Medium	Non Structural Upgrade Required		
69	Qualicum	6969014	KWALIKUM SECONDARY	3	Classrooms	1,500	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
69	Qualicum	6969014	KWALIKUM SECONDARY	4	Classrooms	814	Low/Moderate	Low	Meets Structural Life Safety Requirements		
69	Qualicum	6969014	KWALIKUM SECONDARY	5	Classrooms	3,721	Low	Low	Meets Structural Life Safety Requirements		
69	Qualicum	6969001	PARKSVILLE ELEMENTARY	1	Gymnasium	382	High	N/A	Completed		
69	Qualicum	6969001	PARKSVILLE ELEMENTARY	2	Classrooms & Multi-Purpose Room	2,541	Moderate/High	N/A	Completed	N/A	
69	Qualicum	6969001	PARKSVILLE ELEMENTARY	3	1994 Addition	407	Low	N/A	Completed		
69	Qualicum	6969006	QUALICUM BEACH ELEMENTARY	1	Activity Room	420	Moderate	Medium	Non Structural Upgrade Required		
69	Qualicum	6969006	QUALICUM BEACH ELEMENTARY	2	Classrooms	447	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
69	Qualicum	6969006	QUALICUM BEACH ELEMENTARY	3	Classrooms/Administration	1,617	Moderate	Medium	Non Structural Upgrade Required		
69	Qualicum	6969006	QUALICUM BEACH ELEMENTARY	4	Classrooms 2000	455	Low	Low	Meets Structural Life Safety Requirements		
69	Qualicum	6969013	WINCHELSEA ELEMENTARY	1	Gymnasium	252	Low/Moderate	Low	Meets Structural Life Safety Requirements		
69	Qualicum	6969013	WINCHELSEA ELEMENTARY	2	Classrooms & MP Room	3,810	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
70	Alberni	7070004	A W NEILL MIDDLE SCHOOL	1	Gymnasium 56/76	927	High	Medium	Partially Complete?		
70	Alberni	7070004	A W NEILL MIDDLE SCHOOL	2	Two Storey 56/59	2,694	High	Medium	Partially Complete?	Medium	
70	Alberni	7070004	A W NEILL MIDDLE SCHOOL	3	One Storey 56/64	1,980	Moderate/High	Medium	Partially Complete?		
70	Alberni	7070004	A W NEILL MIDDLE SCHOOL	4	Music/Mechanical 56/73	241	Moderate/High	Medium	Partially Complete?		
70	Alberni	7070001	ALBERNI DISTRICT SECONDARY	1	Gymnasium	1,012	High	N/A	Completed		
70	Alberni	7070001	ALBERNI DISTRICT SECONDARY	2	Library	953	Low	N/A	Completed	N/A	Completed Fall 2012
70	Alberni	7070001	ALBERNI DISTRICT SECONDARY	3	Music Room	200	Low	N/A	Completed		
70	Alberni	7070001	ALBERNI DISTRICT SECONDARY	4	Community Services Building	1,419	Moderate	N/A	Completed		
70	Alberni	7070001	ALBERNI DISTRICT SECONDARY	5	Industrial Education	2,064	High	N/A	Completed		
70	Alberni	7070001	ALBERNI DISTRICT SECONDARY	6	Industrial Education	1,336	High	N/A	Completed		
70	Alberni	7070001	ALBERNI DISTRICT SECONDARY	7	Auditorium	750	High	N/A	Completed		
70	Alberni	7070001	ALBERNI DISTRICT SECONDARY	8	Main School	4,030	High	N/A	Completed		
70	Alberni	7070001	ALBERNI DISTRICT SECONDARY	9	Main School	2,943	High	N/A	Completed		
70	Alberni	7070006	ALBERNI ELEMENTARY	1	Activity Room	411	Moderate/High	Medium	Non Structural Upgrade Required		
70	Alberni	7070006	ALBERNI ELEMENTARY	2	Classrooms	3,254	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
70	Alberni	7070006	ALBERNI ELEMENTARY	3	Field House	641	High	Medium	Non Structural Upgrade Required		
70	Alberni	7070011	EIGHTH AVENUE ELEMENTARY	1	Gymnasium	448	Moderate/High	Medium	Non Structural Upgrade Required		
70	Alberni	7070011	EIGHTH AVENUE ELEMENTARY	2	Annex	560	Moderate	Medium	Non Structural Upgrade Required	Medium	
70	Alberni	7070011	EIGHTH AVENUE ELEMENTARY	3	1997 Classrooms	?	Low	Low	Meets Structural Life Safety Requirements		
70	Alberni	7070002	ERIC J DUNN MIDDLE SCHOOL	1	Gymnasium/Auditorium	1,157	Moderate/High	Medium	Non Structural Upgrade Required		
70	Alberni	7070002	ERIC J DUNN MIDDLE SCHOOL	2	Building D South Side Classrooms	1,810	Moderate/High	Medium	Non Structural Upgrade Required		
70	Alberni	7070002	ERIC J DUNN MIDDLE SCHOOL	3	Building A, F	1,658	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
70	Alberni	7070002	ERIC J DUNN MIDDLE SCHOOL	4	Building B, E	442	Moderate/High	Medium	Non Structural Upgrade Required		
70	Alberni	7070014	GILL ELEMENTARY	1	Activity Room	470	Moderate/High	Medium	Non Structural Upgrade Required		
70	Alberni	7070014	GILL ELEMENTARY	2	2 Storey Timber Frame	1,287	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
70	Alberni	7070018	JOHN HOWITT ELEMENTARY	1	Gymnasium	443	Moderate/High	Medium	Non Structural Upgrade Required		
70	Alberni	7070018	JOHN HOWITT ELEMENTARY	2	Classrooms	1,900	Moderate/High	Medium	Non Structural Upgrade Required	Medium	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
70 Alberni		7070020	MAQUINNA ELEMENTARY	1	Building 1 Gymnasium	366	High	N/A	Completed	N/A	
70 Alberni		7070020	MAQUINNA ELEMENTARY	2	Building 1 Classrooms	1,044	Moderate/High	N/A	Completed		
70 Alberni		7070020	MAQUINNA ELEMENTARY	3	Building 2 - Classroom	375	Moderate/High	N/A	Completed		
70 Alberni		7070020	MAQUINNA ELEMENTARY	4	Building 3 - Classroom	856	High	N/A	Completed		
70 Alberni		7070026	UCLUELET ELEMENTARY	1	Gymnasium	580	Moderate	Medium	Non Structural Upgrade Required	Medium	January 2013 - Risk review in progress.
70 Alberni		7070026	UCLUELET ELEMENTARY	2	Classrooms	1,880	Moderate	Medium	Non Structural Upgrade Required		
70 Alberni		7070005	UCLUELET SECONDARY	1	North Classroom Wing	660	Moderate/High	Medium	Non Structural Upgrade Required	Medium	January 2013 - Risk review in progress.
70 Alberni		7070005	UCLUELET SECONDARY	2	Activity Room and Offices	650	Moderate/High	Medium	Non Structural Upgrade Required		
70 Alberni		7070005	UCLUELET SECONDARY	3	Two Storey West Wing	1,150	High	Medium	Non Structural Upgrade Required		
70 Alberni		7070005	UCLUELET SECONDARY	4	Shops and Gymnasium Building	1,570	Moderate/High	Medium	Non Structural Upgrade Required		
70 Alberni		7070005	UCLUELET SECONDARY	5	Bandroom/Cafeteria Building	460	Low/Moderate	Low	Meets Structural Life Safety Requirements		
70 Alberni		7070024	WICKANINISH COMMUNITY SCHOOL	1	Main Building	2,560	Low	High 3	Structural Upgrade Required	High 3	H3 Risk confirmed at SD request.
70 Alberni		7070025	WOOD ELEMENTARY	1	1965 Gymnasium	441	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
70 Alberni		7070025	WOOD ELEMENTARY	2	1969 Library	149	Low/Moderate	Low	Meets Structural Life Safety Requirements		
70 Alberni		7070025	WOOD ELEMENTARY	3	1958, 1963, 1965 Classrooms	1,967	Moderate/High	Medium	Non Structural Upgrade Required		
71 Comox Valley		7171077	AIRPORT ELEMENTARY	1	Gymnasium/Stage	340	Low	Low	Meets Structural Life Safety Requirements	Medium	
71 Comox Valley		7171077	AIRPORT ELEMENTARY	2	Classrooms - South Wing	800	Moderate/High	Medium	Non Structural Upgrade Required		
71 Comox Valley		7171077	AIRPORT ELEMENTARY	3	Classrooms - North Wing	1,250	Moderate/High	Medium	Non Structural Upgrade Required		
71 Comox Valley		7171060	ARDEN ELEMENTARY	1	Gymnasium	480	Low	Low	Meets Structural Life Safety Requirements	Low	
71 Comox Valley		7171060	ARDEN ELEMENTARY	2	Original and 1989 Classrooms	2,370	Low	Low	Meets Structural Life Safety Requirements		
71 Comox Valley		7171060	ARDEN ELEMENTARY	3	1994 Classrooms	?	Low	Low	Meets Structural Life Safety Requirements	Medium	
71 Comox Valley		7171063	BROOKLYN ELEMENTARY	1	Gymnasium	416	Low	Low	Meets Structural Life Safety Requirements		
71 Comox Valley		7171063	BROOKLYN ELEMENTARY	2	Classrooms 1963	1,170	Moderate/High	Medium	Non Structural Upgrade Required		
71 Comox Valley		7171063	BROOKLYN ELEMENTARY	3	Classrooms 1981	925	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
71 Comox Valley		7171063	BROOKLYN ELEMENTARY	4	Change Rooms	119	Low	Low	Meets Structural Life Safety Requirements		
71 Comox Valley		7171064	COMOX ELEMENTARY	1	Gymnasium	580	Low	Low	Inactive		
71 Comox Valley		7171064	COMOX ELEMENTARY	2	1965 Classrooms	750	High	Medium	Inactive	Medium	
71 Comox Valley		7171064	COMOX ELEMENTARY	3	1966 Classrooms	1,530	High	Medium	Inactive		
71 Comox Valley		7171065	COURTENAY ELEMENTARY	1	Gymnasium	730	Moderate/High	Medium	Non Structural Upgrade Required	High 3	August 2013; confirmed risk for school as a H3.
71 Comox Valley		7171065	COURTENAY ELEMENTARY	2	1960 Classrooms	3,200	High	High 3	Structural Upgrade Required		
71 Comox Valley		7171065	COURTENAY ELEMENTARY	3	Classroom Addition	280	Moderate	Medium	Non Structural Upgrade Required		
71 Comox Valley		7171066	CUMBERLAND ELEMENTARY	1	Entire 1972 Building	1,900	Low	Low	Meets Structural Life Safety Requirements	Medium	
71 Comox Valley		7171066	CUMBERLAND ELEMENTARY	2	Music Room	140	Low/Moderate	Low	Meets Structural Life Safety Requirements		
71 Comox Valley		7171066	CUMBERLAND ELEMENTARY	3	Annex	200	Moderate	Medium	Non Structural Upgrade Required		
71 Comox Valley		7171053	CUMBERLAND ELEM-JR SEC	1	Gymnasium	740	Low	Low	Meets Structural Life Safety Requirements	Low	
71 Comox Valley		7171053	CUMBERLAND ELEM-JR SEC	2	1964 Classrooms, 1970/1976/1992 Additions	1,950	Low	Low	Meets Structural Life Safety Requirements		
71 Comox Valley		7171053	CUMBERLAND ELEM-JR SEC	3	1993 Classroom Addition and Renovation	?	Low	Low	Meets Structural Life Safety Requirements		
71 Comox Valley		7171067	DENMAN ISLAND ELEMENTARY	1	Gymnasium	320	Low	Low	Meets Structural Life Safety Requirements	Low	
71 Comox Valley		7171067	DENMAN ISLAND ELEMENTARY	2	Classroom	800	Low	Low	Meets Structural Life Safety Requirements		
71 Comox Valley		7171071	ECOLE PUNTLEDGE PARK ELEMENTARY	1	Classroom / Admin (North)	560	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
71 Comox Valley		7171071	ECOLE PUNTLEDGE PARK ELEMENTARY	2	Gymnasium	440	Low	Low	Meets Structural Life Safety Requirements		
71 Comox Valley		7171071	ECOLE PUNTLEDGE PARK ELEMENTARY	3	Classrooms / Library	1,330	Moderate/High	Medium	Non Structural Upgrade Required		
71 Comox Valley		7171071	ECOLE PUNTLEDGE PARK ELEMENTARY	4	Classrooms	668	High	Medium	Non Structural Upgrade Required		
71 Comox Valley		7171071	ECOLE PUNTLEDGE PARK ELEMENTARY	5	Classrooms (2000)	?	Low	Low	Meets Structural Life Safety Requirements	N/A	
71 Comox Valley		7171050	ECOLE ROBB ROAD	1	Gymnasium	820	Low	N/A	Completed		
71 Comox Valley		7171050	ECOLE ROBB ROAD	2	Annex	750	Moderate/High	N/A	Completed		
71 Comox Valley		7171050	ECOLE ROBB ROAD	3	1959 2-Storey	1,480	High	N/A	Completed		
71 Comox Valley		7171050	ECOLE ROBB ROAD	4	1971 Masonry Addition	950	High	N/A	Completed		
71 Comox Valley		7171050	ECOLE ROBB ROAD	5	Circa 1955 - Single Storey	900	Moderate/High	N/A	Completed		
71 Comox Valley		7171050	ECOLE ROBB ROAD	6	Band Room	170	Moderate/High	N/A	Completed		
71 Comox Valley		7171040	GEORGES P VANIER SECONDARY	1	Shops Wing (1966 / 1971) and Arts Wing (1989)	2,934	NA	High 1	Supported (May 2012)		
71 Comox Valley		7171040	GEORGES P VANIER SECONDARY	2	Original School, Home Econ's, Music & Drama Rms	4,383	NA	High 1	Supported (May 2012)		
71 Comox Valley		7171040	GEORGES P VANIER SECONDARY	3	Science Block (1966/1968)	2,205	NA	High 1	Supported (May 2012)		
71 Comox Valley		7171040	GEORGES P VANIER SECONDARY	4	Library/Classroom (1968/1989)	2,088	NA	High 2	Supported (May 2012)		
71 Comox Valley		7171040	GEORGES P VANIER SECONDARY	5	Const 12 Shop	215	Moderate	Medium	Supported (May 2012)		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments	
71	Comox Valley	7171069	GLACIER VIEW ELEMENTARY	1	Classrooms	420	Moderate	Medium	Inactive	Medium		
71	Comox Valley	7171069	GLACIER VIEW ELEMENTARY	2	Classrooms/Administration	305	Moderate	Medium	Inactive			
71	Comox Valley	7171069	GLACIER VIEW ELEMENTARY	3	Gymnasium	440	Moderate/High	Medium	Inactive			
71	Comox Valley	7171069	GLACIER VIEW ELEMENTARY	4	Classrooms	590	Low/Moderate	Low	Inactive			
71	Comox Valley	7171069	GLACIER VIEW ELEMENTARY	5	Gym Change Rooms	285	Moderate	Medium	Inactive			
71	Comox Valley	7171069	GLACIER VIEW ELEMENTARY	6	Annex Classrooms	190	Low/Moderate	Low	Inactive			
71	Comox Valley	7171069	GLACIER VIEW ELEMENTARY	7	East Wing 1999	?	Low	Low	Inactive			
71	Comox Valley	7171069	GLACIER VIEW ELEMENTARY	8	Band Room - Portable on permanent fdn-1999	?	Low	Low	Inactive			
71	Comox Valley	7171041	HIGHLAND SECONDARY	1	Gymnasium 1978	1,720	High	N/A	Completed	N/A		
71	Comox Valley	7171041	HIGHLAND SECONDARY	2	Academic Block 1978	4,136	High	N/A	Completed			
71	Comox Valley	7171041	HIGHLAND SECONDARY	3	Shops 1978	815	High	N/A	Completed			
71	Comox Valley	7171041	HIGHLAND SECONDARY	4	Academic Block 1998	?	Low	N/A	Completed			
71	Comox Valley	7171041	HIGHLAND SECONDARY	5	Band Addition 1998	?	Low	N/A	Completed			
71	Comox Valley	7171070	HORNBY ISLAND ELEMENTARY	1	Gymnasium	290	Moderate	Medium	Non Structural Upgrade Required	Medium		
71	Comox Valley	7171070	HORNBY ISLAND ELEMENTARY	2	Classrooms	1,005	Low/Moderate	Low	Meets Structural Life Safety Requirements			
71	Comox Valley	7171052	LAKE TRAIL MIDDLE	1	Old Gym (1960's)	730	Moderate/High	Medium	Non Structural Upgrade Required	High 2	August 2013 - Increased risk of Block 2 from Low to H3, and Block 4 from Medium to H2.	
71	Comox Valley	7171052	LAKE TRAIL MIDDLE	2	Administration/Multi Fine Arts - Classrooms (1960's)	3,200	Low/Moderate	High 3	Structural Upgrade Required			
71	Comox Valley	7171052	LAKE TRAIL MIDDLE	3	2 Storey Classrooms (1955/58/64)	2,400	High	Medium	Non Structural Upgrade Required			
71	Comox Valley	7171052	LAKE TRAIL MIDDLE	4	Science/Shops/Arts (1964/71/74)	1,110	High	High 2	Structural Upgrade Required			
71	Comox Valley	7171052	LAKE TRAIL MIDDLE	5	New Gym/Library 1999	?	Low	Low	Meets Structural Life Safety Requirements			
71	Comox Valley	7171079	MIRACLE BEACH ELEMENTARY	1	Gymnasium	400	Moderate	Medium	Non Structural Upgrade Required	Medium		
71	Comox Valley	7171079	MIRACLE BEACH ELEMENTARY	2	Classrooms	1,550	Moderate	Medium	Non Structural Upgrade Required			
71	Comox Valley	7171079	MIRACLE BEACH ELEMENTARY	3	Classrooms (Post 1992)	?	Low	Low	Meets Structural Life Safety Requirements	Medium		
71	Comox Valley	7171072	ROYSTON ELEMENTARY	1	Gymnasium	300	Low	Low	Meets Structural Life Safety Requirements			
71	Comox Valley	7171072	ROYSTON ELEMENTARY	2	Classroom - 1967	560	Low	Low	Meets Structural Life Safety Requirements			
71	Comox Valley	7171072	ROYSTON ELEMENTARY	3	Classrooms - 1952/63	975	Moderate	Medium	Non Structural Upgrade Required			
71	Comox Valley	7171072	ROYSTON ELEMENTARY	4	Classrooms - 1990	650	Low	Low	Meets Structural Life Safety Requirements	Medium		
71	Comox Valley	7171074	TSOLUM ELEMENTARY	1	1953 Block - Gymnasium	550	Low	Low	Inactive			
71	Comox Valley	7171074	TSOLUM ELEMENTARY	2	1955 Block	1,250	Moderate/High	Medium	Inactive	Medium		
71	Comox Valley	7171074	TSOLUM ELEMENTARY	3	Annex	825	Moderate	Medium	Inactive			
71	Comox Valley	7171075	UNION BAY ELEMENTARY	1	Original Classrooms	690	Low	Low	Meets Structural Life Safety Requirements	Low		
71	Comox Valley	7171075	UNION BAY ELEMENTARY	2	1953 Addition, Classrooms	505	Low	Low	Meets Structural Life Safety Requirements			
71	Comox Valley	7171080	VALLEY VIEW ELEMENTARY	1	1993 Building	3,100	Low	Low	Meets Structural Life Safety Requirements	Low		
71	Comox Valley	7171080	VALLEY VIEW ELEMENTARY	2	2000 Building	?	Low	Low	Meets Structural Life Safety Requirements			
71	Comox Valley	7171076	VILLAGE PARK ELEMENTARY	1	Classroom / Admin	1,085	Low/Moderate	Low	Inactive	Medium		
71	Comox Valley	7171076	VILLAGE PARK ELEMENTARY	2	Gymnasium / Covered play area	340	Moderate	Medium	Inactive			
71	Comox Valley	7171076	VILLAGE PARK ELEMENTARY	3	Classrooms / Change rooms	575	Moderate	Medium	Inactive			
72	Campbell River	7272010	CARIHI SECONDARY	1	Building A - Circa 1965	2,540	High	N/A	Completed	N/A		
72	Campbell River	7272010	CARIHI SECONDARY	2	Building A - 1971 Addition	873	High	N/A	Completed			
72	Campbell River	7272010	CARIHI SECONDARY	3	Building B - 1966	955	High	N/A	Completed			
72	Campbell River	7272010	CARIHI SECONDARY	4	Building C - 1966 Shops	990	High	N/A	Completed			
72	Campbell River	7272010	CARIHI SECONDARY	5	Building D - Gymnasium (1967)	2,075	Low	N/A	Completed			
72	Campbell River	7272010	CARIHI SECONDARY	6	Building D - Cafeteria (1967)	560	High	N/A	Completed			
72	Campbell River	7272010	CARIHI SECONDARY	7	Building C - 1973 Shops Addition	1,350	Moderate	N/A	Completed			
72	Campbell River	7272010	CARIHI SECONDARY	8	1999 Addition	?	Low	N/A	Completed			
72	Campbell River	7272030	CEDAR ANNEX	1	Gymnasium	230	High	Medium	Non Structural Upgrade Required	Medium		
72	Campbell River	7272030	CEDAR ANNEX	2	Classrooms	950	Moderate	Medium	Non Structural Upgrade Required			
72	Campbell River	7272029	CEDAR ELEMENTARY	1	Gymnasium	870	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium		
72	Campbell River	7272029	CEDAR ELEMENTARY	2	Classrooms and Activity Room	1,830	Moderate	Medium	Non Structural Upgrade Required			
72	Campbell River	7272017	CORTES ISLAND ELEM-JR SEC	1	Gymnasium	294	Moderate	Medium	Non Structural Upgrade Required	Medium		
72	Campbell River	7272017	CORTES ISLAND ELEM-JR SEC	2	Gym Auxiliary Services	126	Moderate/High	Medium	Non Structural Upgrade Required			
72	Campbell River	7272017	CORTES ISLAND ELEM-JR SEC	3	Administration	217	Moderate	Medium	Non Structural Upgrade Required			
72	Campbell River	7272017	CORTES ISLAND ELEM-JR SEC	4	Classrooms	792	Moderate/High	Medium	Non Structural Upgrade Required			
72	Campbell River	7272033	DISCOVERY PASSAGE ELEMENTARY	1	Gymnasium	260	Moderate	Medium	Non Structural Upgrade Required	Medium		
72	Campbell River	7272033	DISCOVERY PASSAGE ELEMENTARY	2	South Classrooms	790	Moderate	Medium	Non Structural Upgrade Required			
72	Campbell River	7272033	DISCOVERY PASSAGE ELEMENTARY	3	North Classrooms	460	High	Medium	Non Structural Upgrade Required			

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
72	Campbell River	7272031	ECOLE DES DEUX MONDES ELEMENTARY	1	1966 Classrooms	1,210	High	N/A	Completed	N/A	
72	Campbell River	7272031	ECOLE DES DEUX MONDES ELEMENTARY	2	1972 Addition	510	High	N/A	Completed		
72	Campbell River	7272031	ECOLE DES DEUX MONDES ELEMENTARY	3	1975 Addition	320	Moderate/High	N/A	Completed		
72	Campbell River	7272031	ECOLE DES DEUX MONDES ELEMENTARY	4	Gymnasium (1966)	440	Low	N/A	Completed		
72	Campbell River	7272014	ECOLE PHOENIX MIDDLE	1	Science Wing	1,807	Low/Moderate	High 2	Proceeding to Construction	High 1	December 2012 - Risk reviewed at SD request. Overall risk increased from M to H1. April 2013 - to start 2013.
72	Campbell River	7272014	ECOLE PHOENIX MIDDLE	2	Gymnasium	634	Moderate	High 3	Proceeding to Construction		
72	Campbell River	7272014	ECOLE PHOENIX MIDDLE	3	Change Rooms	815	Low/Moderate	High 3	Proceeding to Construction		
72	Campbell River	7272014	ECOLE PHOENIX MIDDLE	4	Shops	770	Low	Medium	Proceeding to Construction		
72	Campbell River	7272014	ECOLE PHOENIX MIDDLE	5	Commerce and Administration	1,100	Moderate	High 2	Proceeding to Construction		
72	Campbell River	7272014	ECOLE PHOENIX MIDDLE	6	Classrooms	933	Moderate	High 1	Proceeding to Construction		
72	Campbell River	7272014	ECOLE PHOENIX MIDDLE	7	Library	400	Moderate/High	High 3	Proceeding to Construction		
72	Campbell River	7272014	ECOLE PHOENIX MIDDLE	8	General Instruction - 1999	?	Low	Low	Proceeding to Construction		
72	Campbell River	7272062	OYSTER RIVER ELEMENTARY	1	Gymnasium	395	Low	Low	Meets Structural Life Safety Requirements	Medium	
72	Campbell River	7272062	OYSTER RIVER ELEMENTARY	2	Classrooms	1,490	Moderate	Medium	Non Structural Upgrade Required		
72	Campbell River	7272062	OYSTER RIVER ELEMENTARY	3	Classroom Addition	?	Low	Low	Meets Structural Life Safety Requirements	Medium	
72	Campbell River	7272066	PENFIELD ELEMENTARY	1	Gymnasium	395	Low	Low	Meets Structural Life Safety Requirements		
72	Campbell River	7272066	PENFIELD ELEMENTARY	2	Classrooms / Admin	1,640	Moderate	Medium	Non Structural Upgrade Required	Medium	
72	Campbell River	7272065	PINECREST ELEMENTARY	1	1966 Structure	1,025	Low	Low	Meets Structural Life Safety Requirements		
72	Campbell River	7272065	PINECREST ELEMENTARY	2	1969 Addition	450	Low	Low	Meets Structural Life Safety Requirements		
72	Campbell River	7272065	PINECREST ELEMENTARY	3	1972 Addition	535	High	Medium	Non Structural Upgrade Required		
72	Campbell River	7272065	PINECREST ELEMENTARY	4	1976 Addition	465	High	Medium	Non Structural Upgrade Required		
72	Campbell River	7272065	PINECREST ELEMENTARY	5	1975 Addition	190	Moderate	Medium	Non Structural Upgrade Required		
72	Campbell River	7272065	PINECREST ELEMENTARY	6	1978 Addition	330	Moderate/High	Medium	Non Structural Upgrade Required		
72	Campbell River	7272069	QUADRA ELEMENTARY	1	Gymnasium	715	Low	Low	Meets Structural Life Safety Requirements		
72	Campbell River	7272069	QUADRA ELEMENTARY	2	East Classrooms & Library	760	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
72	Campbell River	7272069	QUADRA ELEMENTARY	3	South Classrooms	400	Moderate	Medium	Non Structural Upgrade Required		
72	Campbell River	7272069	QUADRA ELEMENTARY	4	SW Classrooms/Multi/Admin	?	Low	Low	Meets Structural Life Safety Requirements		
72	Campbell River	7272015	ROBRON MIDDLE SCHOOL	1	Classrooms	2,900	Moderate	Medium	Inactive	Medium	
72	Campbell River	7272015	ROBRON MIDDLE SCHOOL	2	Shops	750	Low/Moderate	Low	Inactive		
72	Campbell River	7272015	ROBRON MIDDLE SCHOOL	3	Change Rooms	460	Low	Low	Inactive		
72	Campbell River	7272015	ROBRON MIDDLE SCHOOL	4	Gymnasium	880	Low	Low	Inactive		
72	Campbell River	7272015	ROBRON MIDDLE SCHOOL	5	1982 Classrooms	1,580	Low/Moderate	Low	Inactive		
72	Campbell River	7272015	ROBRON MIDDLE SCHOOL	6	1982 Shops	345	Moderate/High	Medium	Inactive		
72	Campbell River	7272077	ROCKLAND ELEMENTARY	1	Gymnasium	450	High	Medium	Inactive	Medium	
72	Campbell River	7272077	ROCKLAND ELEMENTARY	2	Classrooms	2,420	Moderate/High	Medium	Inactive		
72	Campbell River	7272078	SANDOWNE ELEMENTARY	1	Gymnasium	620	Low	Low	Meets Structural Life Safety Requirements	Low	
72	Campbell River	7272078	SANDOWNE ELEMENTARY	2	Classroom / Admin	2,570	Low/Moderate	Low	Meets Structural Life Safety Requirements		
72	Campbell River	7272078	SANDOWNE ELEMENTARY	3	1992 Classrooms	?	Low	Low	Meets Structural Life Safety Requirements		
72	Campbell River	7272016	SOUTHGATE MIDDLE SCHOOL	1	1971 Original Block	2,500	High	N/A	Completed	N/A	
72	Campbell River	7272016	SOUTHGATE MIDDLE SCHOOL	2	1975 Shop Wing	1,015	High	N/A	Completed		
72	Campbell River	7272016	SOUTHGATE MIDDLE SCHOOL	3	1975 Classroom Block	1,390	Moderate/High	N/A	Completed		
72	Campbell River	7272016	SOUTHGATE MIDDLE SCHOOL	4	1976 Block	575	Moderate/High	N/A	Completed		
72	Campbell River	7272016	SOUTHGATE MIDDLE SCHOOL	5	Gymnasium - 1971	500	Low	N/A	Completed		
72	Campbell River	7272016	SOUTHGATE MIDDLE SCHOOL	6	1976 Activity/Music	335	Low	N/A	Completed		
72	Campbell River	7272016	SOUTHGATE MIDDLE SCHOOL	7	1999 Addition	?	Low	N/A	Completed		
72	Campbell River	7272085	SURGE NARROWS ELEMENTARY	1	Classrooms & Administration	280	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
72	Campbell River	7272085	SURGE NARROWS ELEMENTARY	2	Community Hall, Gymnasium	335	High	Medium	Non Structural Upgrade Required		
72	Campbell River	7272097	WILLOW POINT ELEMENTARY	1	Gymnasium	435	Low	N/A	Completed	N/A	
72	Campbell River	7272097	WILLOW POINT ELEMENTARY	2	Classrooms	1,700	Moderate	N/A	Completed		
75	Mission	7575028	ALBERT MCMAHON ELEMENTARY	1	Gymnasium	470	Moderate	Medium	Non Structural Upgrade Required	Medium	
75	Mission	7575028	ALBERT MCMAHON ELEMENTARY	2	Classrooms (East)	2,190	Moderate	Medium	Non Structural Upgrade Required		
75	Mission	7575028	ALBERT MCMAHON ELEMENTARY	3	Classrooms (West)	710	Low/Moderate	Low	Meets Structural Life Safety Requirements		
75	Mission	7575012	CEDAR VALLEY SCHOOL	1	Multi-Purpose	209	Moderate	Medium	Non Structural Upgrade Required	Medium	
75	Mission	7575012	CEDAR VALLEY SCHOOL	2	Classroom/Administration	365	Low/Moderate	Low	Meets Structural Life Safety Requirements		
75	Mission	7575012	CEDAR VALLEY SCHOOL	3	Classroom (West)	260	Low/Moderate	Low	Meets Structural Life Safety Requirements		
75	Mission	7575012	CEDAR VALLEY SCHOOL	4	Classroom (South)	449	Moderate	Medium	Non Structural Upgrade Required		
75	Mission	7575023	CHERRY HILL ELEMENTARY	1	Gymnasium	553	Moderate	Medium	Non Structural Upgrade Required	Medium	
75	Mission	7575023	CHERRY HILL ELEMENTARY	2	Classrooms	2,060	Moderate	Medium	Non Structural Upgrade Required		
75	Mission	7575023	CHERRY HILL ELEMENTARY	3	Classrooms (1999)	?	Low	Low	Meets Structural Life Safety Requirements		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
75	Mission	7575006	DEWDNEY ELEMENTARY	1	1940 Classrooms	720	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
75	Mission	7575006	DEWDNEY ELEMENTARY	2	1959 Classrooms	730	Moderate	Medium	Non Structural Upgrade Required		
75	Mission	7575006	DEWDNEY ELEMENTARY	3	1992 Gym Addition	?	Low	Low	Meets Structural Life Safety Requirements		
75	Mission	7575026	DURIEU ELEMENTARY	1	Classroom (East & West Wing)	520	Moderate	Medium	Non Structural Upgrade Required	Low	
75	Mission	7575026	DURIEU ELEMENTARY	2	Administration	437	Low/Moderate	Low	Meets Structural Life Safety Requirements		
75	Mission	7575026	DURIEU ELEMENTARY	3	Gymnasium	245	Low/Moderate	Low	Meets Structural Life Safety Requirements		
75	Mission	7575015	EDWIN S RICHARDS ELEMENTARY	1	Gymnasium	465	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
75	Mission	7575015	EDWIN S RICHARDS ELEMENTARY	2	Classroom - Centre	1,390	Low/Moderate	Low	Meets Structural Life Safety Requirements		
75	Mission	7575015	EDWIN S RICHARDS ELEMENTARY	3	Classroom - North	770	Low/Moderate	Low	Meets Structural Life Safety Requirements		
75	Mission	7575015	EDWIN S RICHARDS ELEMENTARY	4	Classroom - South/East	580	Low/Moderate	Low	Meets Structural Life Safety Requirements		
75	Mission	7575015	EDWIN S RICHARDS ELEMENTARY	5	Classroom (2000) - North/East	?	Low	Low	Meets Structural Life Safety Requirements		
75	Mission	7575011	FERNDALE ELEMENTARY	1	Gymnasium	557	Low	Low	Meets Structural Life Safety Requirements	Low	
75	Mission	7575011	FERNDALE ELEMENTARY	2	Classroom, Administration	560	Low	Low	Meets Structural Life Safety Requirements		
75	Mission	7575011	FERNDALE ELEMENTARY	3	Classrooms, Library (1995)	?	Low	Low	Meets Structural Life Safety Requirements		
75	Mission	7575025	FRASERVIEW ELEMENTARY	1	Gymnasium	400	Moderate	Medium	Inactive	Medium	
75	Mission	7575025	FRASERVIEW ELEMENTARY	2	Classrooms (Central)	1,585	Moderate	Medium	Inactive		
75	Mission	7575025	FRASERVIEW ELEMENTARY	3	Classrooms/Change rooms (East)	575	Low/Moderate	Low	Inactive		
75	Mission	7575025	FRASERVIEW ELEMENTARY	4	Classrooms/Multipurpose (2000)	?	Low	Low	Inactive		
75	Mission	7575001	HATZIC ELEMENTARY	1	Classrooms (South)	494	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
75	Mission	7575001	HATZIC ELEMENTARY	2	Library	302	Moderate/High	Medium	Non Structural Upgrade Required		
75	Mission	7575001	HATZIC ELEMENTARY	3	Classroom (Central)	1,100	Moderate/High	Medium	Non Structural Upgrade Required		
75	Mission	7575001	HATZIC ELEMENTARY	4	Gymnasium	390	Moderate	Medium	Non Structural Upgrade Required		
75	Mission	7575001	HATZIC ELEMENTARY	5	Classroom (North)	301	Moderate	Medium	Non Structural Upgrade Required		
75	Mission	7575022	HATZIC SECONDARY SCHOOL	1	Classroom/Administration	4,080	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
75	Mission	7575022	HATZIC SECONDARY SCHOOL	2	Gymnasium	615	Moderate/High	Medium	Non Structural Upgrade Required		
75	Mission	7575022	HATZIC SECONDARY SCHOOL	3	Classroom	905	Moderate	Medium	Non Structural Upgrade Required		
75	Mission	7575022	HATZIC SECONDARY SCHOOL	4	Gymnasium	1,750	Moderate	Medium	Non Structural Upgrade Required		
75	Mission	7575022	HATZIC SECONDARY SCHOOL	5	Classroom (West)	2,780	Moderate	Medium	Non Structural Upgrade Required		
75	Mission	7575027	HILLSIDE ELEMENTARY	1	Gymnasium	400	Moderate	Medium	Non Structural Upgrade Required	Medium	
75	Mission	7575027	HILLSIDE ELEMENTARY	2	Administration/Library	880	Moderate	Medium	Non Structural Upgrade Required		
75	Mission	7575027	HILLSIDE ELEMENTARY	3	Classrooms	1,070	Low	Low	Meets Structural Life Safety Requirements		
75	Mission	7575027	HILLSIDE ELEMENTARY	4	Classrooms (1997)	?	Low	Low	Meets Structural Life Safety Requirements	Low	
75	Mission	7575007	MISSION CENTRAL ELEMENTARY	1	Gymnasium	490	Low	Low	Meets Structural Life Safety Requirements		
75	Mission	7575007	MISSION CENTRAL ELEMENTARY	2	Classrooms	2,650	Low	Low	Meets Structural Life Safety Requirements	Low	
75	Mission	7575007	MISSION CENTRAL ELEMENTARY	3	Classrooms/Music (1999)	?	Low	Low	Meets Structural Life Safety Requirements		
75	Mission	7575014	MISSION SECONDARY	1	Gymnasium (West)	790	Low/Moderate	Low	Meets Structural Life Safety Requirements		High 3
75	Mission	7575014	MISSION SECONDARY	2	Gymnasium (East)	765	Low/Moderate	Low	Meets Structural Life Safety Requirements		
75	Mission	7575014	MISSION SECONDARY	3	2-Storey Classroom (West)	3,360	Moderate	Medium	Non Structural Upgrade Required		
75	Mission	7575014	MISSION SECONDARY	4	2-Storey Classroom (South)	3,700	Low	Low	Meets Structural Life Safety Requirements		
75	Mission	7575014	MISSION SECONDARY	5	Cafeteria/Library	1,190	Low/Moderate	Medium	Non Structural Upgrade Required		
75	Mission	7575014	MISSION SECONDARY	6	1-Storey Classrooms (Central)	1,100	Low/Moderate	Low	Meets Structural Life Safety Requirements		
75	Mission	7575014	MISSION SECONDARY	7	Shops	715	Moderate/High	High 3	Structural Upgrade Required		
75	Mission	7575014	MISSION SECONDARY	8	Bandroom/Administration	625	Moderate/High	Medium	Non Structural Upgrade Required		
75	Mission	7575019	SILVERDALE ELEMENTARY	1	Gymnasium	395	Moderate	Medium	Non Structural Upgrade Required	Medium	
75	Mission	7575019	SILVERDALE ELEMENTARY	2	Classroom (West Wing)	455	Low/Moderate	Low	Meets Structural Life Safety Requirements		
75	Mission	7575019	SILVERDALE ELEMENTARY	3	Classroom	516	Moderate	Medium	Non Structural Upgrade Required		
75	Mission	7575019	SILVERDALE ELEMENTARY	4	Classroom/Admin. (1992 addition)	?	Low	Low	Meets Structural Life Safety Requirements		
75	Mission	7575018	WEST HEIGHTS ELEMENTARY	1	Gymnasium	415	Low	Low	Meets Structural Life Safety Requirements	Low	
75	Mission	7575018	WEST HEIGHTS ELEMENTARY	2	Classrooms	2,630	Low/Moderate	Low	Meets Structural Life Safety Requirements		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
78	Fraser-Cascade	7876003	AGASSIZ ELEM-SEC	1	North Wing	1,100	Moderate/High	Medium	Non Structural Upgrade Required		
78	Fraser-Cascade	7876003	AGASSIZ ELEM-SEC	2	Gymnasium (Const 2000)	?	Low	Low	Meets Structural Life Safety Requirements		
78	Fraser-Cascade	7876003	AGASSIZ ELEM-SEC	3	South Wing	810	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
78	Fraser-Cascade	7876003	AGASSIZ ELEM-SEC	4	Administration	360	Moderate/High	Medium	Non Structural Upgrade Required		
78	Fraser-Cascade	7876003	AGASSIZ ELEM-SEC	5	Technical School (Const 1993)	?	Low	Low	Meets Structural Life Safety Requirements		
78	Fraser-Cascade	7832004	BOSTON BAR ELEM-SEC	1	Gymnasium	940	Low/Moderate	Low	Meets Structural Life Safety Requirements		
78	Fraser-Cascade	7832004	BOSTON BAR ELEM-SEC	2	Classroom/admin north wing	740	Moderate	Medium	Non Structural Upgrade Required	Medium	
78	Fraser-Cascade	7832004	BOSTON BAR ELEM-SEC	3	West Classroom wing	650	Moderate/High	Medium	Non Structural Upgrade Required		
78	Fraser-Cascade	7832004	BOSTON BAR ELEM-SEC	4	south shops wing	350	Moderate	Medium	Non Structural Upgrade Required		
78	Fraser-Cascade	7832011	C E BARRY INTERMEDIATE SCHOOL	1	Gymnasium	700	Moderate/High	Medium	Supported (May 2012)		
78	Fraser-Cascade	7832011	C E BARRY INTERMEDIATE SCHOOL	2	Classrooms	1,650	High	High 2	Supported (May 2012)	High 2	
78	Fraser-Cascade	7832006	COQUIHALLA ELEMENTARY	1	Gymnasium	500	Low	Low	Meets Structural Life Safety Requirements		
78	Fraser-Cascade	7832006	COQUIHALLA ELEMENTARY	2	Classrooms West	800	High	Medium	Non Structural Upgrade Required		
78	Fraser-Cascade	7832006	COQUIHALLA ELEMENTARY	3	Classrooms East	500	High	Medium	Non Structural Upgrade Required	Medium	
78	Fraser-Cascade	7832006	COQUIHALLA ELEMENTARY	4	Classrooms North	410	Low/Moderate	Low	Meets Structural Life Safety Requirements		
78	Fraser-Cascade	7832006	COQUIHALLA ELEMENTARY	5	Middle Wing	450	Low	Low	Meets Structural Life Safety Requirements		
78	Fraser-Cascade	7899053	DISTRICT ALTERNATE SEC PROG	1	Entire Building	304	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
78	Fraser-Cascade	7876002	HARRISON HOT SPRINGS ELEMENTARY	1	Gymnasium	250	Moderate	Medium	Non Structural Upgrade Required		
78	Fraser-Cascade	7876002	HARRISON HOT SPRINGS ELEMENTARY	2	Class Rooms	650	High	Medium	Non Structural Upgrade Required	Medium	
78	Fraser-Cascade	7832003	HOPE SECONDARY	1	Classroom Wing	1,662	High	N/A	Completed		
78	Fraser-Cascade	7832003	HOPE SECONDARY	2	Gymnasium	1,655	High	N/A	Completed		
78	Fraser-Cascade	7832003	HOPE SECONDARY	3	centre Block	1,053	High	N/A	Completed	N/A	
78	Fraser-Cascade	7832003	HOPE SECONDARY	4	Industrial Shops	1,224	High	N/A	Completed		
78	Fraser-Cascade	7876007	KENT ELEMENTARY	1	East & Library Upgrade 1994	?	Low	Low	Meets Structural Life Safety Requirements		
78	Fraser-Cascade	7876007	KENT ELEMENTARY	2	Gymnasium	650	High	Medium	Non Structural Upgrade Required		
78	Fraser-Cascade	7876007	KENT ELEMENTARY	3	West Wing	1,175	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
78	Fraser-Cascade	7876007	KENT ELEMENTARY	4	East Wing	650	High	Medium	Non Structural Upgrade Required		
78	Fraser-Cascade	7876006	MCCAFFREY ALTERNATE	1	McCaffrey Elem school	280	High	Medium	Non Structural Upgrade Required	Medium	
78	Fraser-Cascade	7832007	YALE ELEMENTARY	1	North Block - Gymnasium	393	Low	Low	Meets Structural Life Safety Requirements		
78	Fraser-Cascade	7832007	YALE ELEMENTARY	2	Center Block - Administration	170	Low	Low	Meets Structural Life Safety Requirements	Low	
78	Fraser-Cascade	7832007	YALE ELEMENTARY	3	south block - classroom	390	Low/Moderate	Low	Meets Structural Life Safety Requirements		
79	Cowichan Valley	7966011	AB GREENWELL ELEMENTARY	1	Gymnasium	250	High	High 3	Inactive		
79	Cowichan Valley	7966011	AB GREENWELL ELEMENTARY	2	Single Storey Classrooms	1,017	Low	Low	Inactive	High 3	
79	Cowichan Valley	7965025	ALEX AITKEN	1	Gymnasium	393	Low/Moderate	Low	Meets Structural Life Safety Requirements		
79	Cowichan Valley	7965025	ALEX AITKEN	2	1992 & 2000 Classrooms	1,415	Low	Low	Meets Structural Life Safety Requirements	Medium	
79	Cowichan Valley	7965025	ALEX AITKEN	3	Pre-1992 Classrooms	600	Moderate/High	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965014	ALEXANDER ELEMENTARY	1	Gymnasium	622	Low	Low	Meets Structural Life Safety Requirements		
79	Cowichan Valley	7965014	ALEXANDER ELEMENTARY	2	Main Block	1,336	Moderate/High	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965014	ALEXANDER ELEMENTARY	3	West Block	788	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
79	Cowichan Valley	7965014	ALEXANDER ELEMENTARY	4	Open Area	535	Moderate/High	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965007	BENCH ELEMENTARY	1	Gymnasium	401	Low/Moderate	Low	Meets Structural Life Safety Requirements		
79	Cowichan Valley	7965007	BENCH ELEMENTARY	2	Masonry Addition	740	Moderate	Medium	Non Structural Upgrade Required	Medium	
79	Cowichan Valley	7965007	BENCH ELEMENTARY	3	1999 Addition	993	Low	Low	Meets Structural Life Safety Requirements		
79	Cowichan Valley	7965007	BENCH ELEMENTARY	4	Single Storey Timber Frame	1,300	Moderate/High	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965033	CHEMAINUS SECONDARY	1	Timber Frame -Auditorium	452	Moderate/High	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965033	CHEMAINUS SECONDARY	2	Structural Steel Post & Beam - gymnasium	1,460	Low/Moderate	Low	Meets Structural Life Safety Requirements		
79	Cowichan Valley	7965033	CHEMAINUS SECONDARY	3	Two Storey Timber Frame - classrooms	2,634	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
79	Cowichan Valley	7965033	CHEMAINUS SECONDARY	4	Single Storey Timber Frame	1,360	Low/Moderate	Low	Meets Structural Life Safety Requirements		
79	Cowichan Valley	7965030	COBBLE HILL 1	1	Two-storey woodframe 1938	244	Moderate/High	Medium	Inactive	Medium	
79	Cowichan Valley	7965009	COWICHAN SECONDARY	1	Gymnasium	1,018	High	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965009	COWICHAN SECONDARY	2	Two Storey Classroom	4,606	High	High 3	Structural Upgrade Required		
79	Cowichan Valley	7965009	COWICHAN SECONDARY	3	One storey classroom	1,597	Moderate/High	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965009	COWICHAN SECONDARY	4	Shop Building	1,550	Moderate	Medium	Non Structural Upgrade Required	High 3	
79	Cowichan Valley	7965009	COWICHAN SECONDARY	5	Commercial Building	1,412	Moderate/High	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965009	COWICHAN SECONDARY	6	Band Building	152	Low	Low	Meets Structural Life Safety Requirements		
79	Cowichan Valley	7965001	COWICHAN STATION ELEMENTARY	1	Gymnasium	276	Moderate	Medium	Inactive		
79	Cowichan Valley	7965001	COWICHAN STATION ELEMENTARY	2	Classrooms	1,086	High	High 3	Inactive	High 3	
79	Cowichan Valley	7965001	COWICHAN STATION ELEMENTARY	3	Annex	578	Low	Low	Inactive		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
79	Cowichan Valley	7965006	CROFTON ELEMENTARY	1	Activity Room	244	High	N/A	Completed		
79	Cowichan Valley	7965006	CROFTON ELEMENTARY	2	Single Storey Classroom	975	Moderate/High	N/A	Completed	N/A	
79	Cowichan Valley	7965006	CROFTON ELEMENTARY	3	Single Storey Timber Frame (2)	975	Moderate/High	N/A	Completed		
79	Cowichan Valley	7965037	DISCOVERY ELEMENTARY	1	Classrooms	2,001	Low	Low	Meets Structural Life Safety Requirements	Low	
79	Cowichan Valley	7965037	DISCOVERY ELEMENTARY	2	Gymnasium	393	Low/Moderate	Low	Meets Structural Life Safety Requirements		
79	Cowichan Valley	7965505	DISTRICT RESOURCE CENTRE	1	Classrooms	560	Moderate	Medium	Non Structural Upgrade Required	Medium	
79	Cowichan Valley	7965024	DRINKWATER ELEMENTARY	1	Activity Room	433	Moderate/High	N/A	Completed		
79	Cowichan Valley	7965024	DRINKWATER ELEMENTARY	2	Single Storey Classrooms 1	619	High	N/A	Completed	N/A	
79	Cowichan Valley	7965024	DRINKWATER ELEMENTARY	3	Music Building and Classrooms	2,610	Low	N/A	Completed		
79	Cowichan Valley	7965024	DRINKWATER ELEMENTARY	4	Gymnasium	?	Low	N/A	Completed		
79	Cowichan Valley	7965002	DUNCAN ELEMENTARY	1	Gymnasium	415	Moderate/High	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965002	DUNCAN ELEMENTARY	2	MckLrdy Building	635	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
79	Cowichan Valley	7965002	DUNCAN ELEMENTARY	3	Original School - Upgraded	1,596	Low	Low	Meets Structural Life Safety Requirements		
79	Cowichan Valley	7965002	DUNCAN ELEMENTARY	4	Original Gymnasium	415	Moderate/High	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965010	ELSIE MILES ELEMENTARY	1	Single Storey Timber Frame	489	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
79	Cowichan Valley	7965015	GEORGE BONNER MIDDLE SCHOOL	1	Gymnasium	589	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
79	Cowichan Valley	7965015	GEORGE BONNER MIDDLE SCHOOL	2	Single Storey Timber Frame	1,550	High	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965023	KHOWHEMUN ELEMENTARY	1	Gymnasium	450	Low	Low	Meets Structural Life Safety Requirements		
79	Cowichan Valley	7965023	KHOWHEMUN ELEMENTARY	2	Original Construction	835	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
79	Cowichan Valley	7965023	KHOWHEMUN ELEMENTARY	3	1993, 1999 Addition	1,572	Low	Low	Meets Structural Life Safety Requirements		
79	Cowichan Valley	7965017	KOKSILAH ELEMENTARY	1	Classrooms	1,100	Moderate/High	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965017	KOKSILAH ELEMENTARY	2	Gymnasium	300	Moderate	Medium	Non Structural Upgrade Required	High 3	
79	Cowichan Valley	7965017	KOKSILAH ELEMENTARY	3	Two Storey Masonry	760	Moderate/High	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965017	KOKSILAH ELEMENTARY	4	Kindergarten	250	High	High 3	Structural Upgrade Required		
79	Cowichan Valley	7966004	LAKE COWICHAN SECONDARY	1	Gymnasium	1,344	Low/Moderate	N/A	Completed		
79	Cowichan Valley	7966004	LAKE COWICHAN SECONDARY	2	Phase I Renovation - Administration	1,664	High	N/A	Completed		
79	Cowichan Valley	7966004	LAKE COWICHAN SECONDARY	3	Phase II Renovation - Classrooms	2,548	Moderate/High	N/A	Completed		
79	Cowichan Valley	7966004	LAKE COWICHAN SECONDARY	4	Industrial Arts Wing	1,013	Low/Moderate	N/A	Completed	N/A	
79	Cowichan Valley	7966004	LAKE COWICHAN SECONDARY	5	Music Building	174	Moderate	N/A	Completed		
79	Cowichan Valley	7966004	LAKE COWICHAN SECONDARY	6	Woodwork Shop	350	Low	N/A	Completed		
79	Cowichan Valley	7966004	LAKE COWICHAN SECONDARY	7	Continuing Education	314	Moderate/High	N/A	Completed		
79	Cowichan Valley	7965003	MILL BAY ELEMENTARY	1	Block 1 Gymnasium	246	Moderate	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965003	MILL BAY ELEMENTARY	2	Block 2 Classrooms	409	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
79	Cowichan Valley	7965003	MILL BAY ELEMENTARY	3	Block 3 Two Storey Annex	662	Low/Moderate	Low	Meets Structural Life Safety Requirements		
79	Cowichan Valley	7965003	MILL BAY ELEMENTARY	4	Block 4 Pre-1958	200	Moderate/High	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965018	MOUNT PREVOST MIDDLE	1	Two Storey Timber Frame	2,414	High	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965018	MOUNT PREVOST MIDDLE	2	Single Storey Timber Frame	1,435	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
79	Cowichan Valley	7965018	MOUNT PREVOST MIDDLE	3	1994 renovation addition and seismic upgrade	?	Low	Low	Meets Structural Life Safety Requirements		
79	Cowichan Valley	7966012	PALSSON ELEMENTARY	1	Gymnasium	246	Low	Low	Meets Structural Life Safety Requirements	Low	
79	Cowichan Valley	7966012	PALSSON ELEMENTARY	2	Classrooms	1,199	Low	Low	Meets Structural Life Safety Requirements		
79	Cowichan Valley	7965021	QUAMICHAN MIDDLE	1	2001 Addition & Seismic Upgrade	3,136	Low	Low	Meets Structural Life Safety Requirements		
79	Cowichan Valley	7965021	QUAMICHAN MIDDLE	2	Two Storey Timber Frame	1,950	High	Medium	Non Structural Upgrade Required	Medium	
79	Cowichan Valley	7965021	QUAMICHAN MIDDLE	3	Single Storey Timber Frame	930	Moderate/High	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965011	SOMENOS ELEMENTARY	1	Activity Room	212	Moderate	Medium	Non Structural Upgrade Required	Medium	
79	Cowichan Valley	7965011	SOMENOS ELEMENTARY	2	Single Storey T-Frame	1,160	Moderate/High	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965016	TANSOR ELEMENTARY	1	Classrooms / Gymnasium	1,087	Low	Low	Meets Structural Life Safety Requirements		
79	Cowichan Valley	7965016	TANSOR ELEMENTARY	2	Classrooms / Kindergarten	544	Low	Low	Meets Structural Life Safety Requirements	Medium	
79	Cowichan Valley	7965016	TANSOR ELEMENTARY	3	Classrooms / Multi-Purpose	430	Moderate/High	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965016	TANSOR ELEMENTARY	4	Classroom / Administration	426	Moderate	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7965032	THETIS ISLAND ELEMENTARY	1	Two Room School	181	Low	Low	Meets Structural Life Safety Requirements	Low	
79	Cowichan Valley	7966002	YOUNT ELEMENTARY	1	Gymnasium	232	Moderate	Medium	Non Structural Upgrade Required		
79	Cowichan Valley	7966002	YOUNT ELEMENTARY	2	Classrooms	1,228	High	Medium	Non Structural Upgrade Required	Medium	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
82	Coast Mountains	8288028	BEAR VALLEY SCHOOL	1	1 Storey Classroom	2,486	Moderate	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8288028	BEAR VALLEY SCHOOL	2	Gymnasium	1,040	Low	Low	Meets Structural Life Safety Requirements	Medium	
82	Coast Mountains	8288024	CALEDONIA SR SECONDARY	1	1967 2-storey classroom	5,880	Moderate	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8288024	CALEDONIA SR SECONDARY	2	1967 Shops	963	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
82	Coast Mountains	8288024	CALEDONIA SR SECONDARY	3	1975 automotive shop	317	Moderate	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8288024	CALEDONIA SR SECONDARY	4	1967 gymnasium	1,250	Moderate	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8288013	CASSIE HALL ELEMENTARY	1	1957 1-storey classroom	2,250	Moderate	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8288013	CASSIE HALL ELEMENTARY	2	1957 Gymnasium	416	Moderate	Medium	Non Structural Upgrade Required	Medium	
82	Coast Mountains	8288013	CASSIE HALL ELEMENTARY	3	2001 classroom	?	Low	Low	Meets Structural Life Safety Requirements		
82	Coast Mountains	8288016	CLARENCE MICHIEL ELEMENTARY	1	1968 1-storey classroom	520	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
82	Coast Mountains	8288016	CLARENCE MICHIEL ELEMENTARY	2	1-storey classrooms	3,460	Moderate/High	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8288021	E T KENNEY ELEMENTARY	1	1966 1-storey classroom	2,160	Moderate/High	Medium	Inactive		
82	Coast Mountains	8288021	E T KENNEY ELEMENTARY	2	1974 Gymnasium	425	Moderate/High	Medium	Inactive	Medium	
82	Coast Mountains	8288006	HAZELTON SECONDARY	1	Block 'E'	1,536	Low	Low	Meets Structural Life Safety Requirements		
82	Coast Mountains	8288006	HAZELTON SECONDARY	2	Block 'D'	1,650	Low	Low	Meets Structural Life Safety Requirements		
82	Coast Mountains	8288006	HAZELTON SECONDARY	3	Block 'C'	1,420	Low	Low	Meets Structural Life Safety Requirements	Low	
82	Coast Mountains	8288006	HAZELTON SECONDARY	4	Block 'B'	1,550	Low	Low	Meets Structural Life Safety Requirements		
82	Coast Mountains	8288006	HAZELTON SECONDARY	5	Block 'A'	1,945	Low	Low	Meets Structural Life Safety Requirements		
82	Coast Mountains	8288018	JOHN FIELD ELEMENTARY	1	Original Classroom Block	500	Low	Low	Meets Structural Life Safety Requirements		
82	Coast Mountains	8288018	JOHN FIELD ELEMENTARY	2	Classroom Block Addition	570	Low	Low	Meets Structural Life Safety Requirements	Low	
82	Coast Mountains	8288018	JOHN FIELD ELEMENTARY	3	Gym Block	450	Low/Moderate	Low	Meets Structural Life Safety Requirements		
82	Coast Mountains	8288018	JOHN FIELD ELEMENTARY	4	1964 Classroom Block	600	Low/Moderate	Low	Meets Structural Life Safety Requirements		
82	Coast Mountains	8280004	KILDALA ELEMENTARY	1	1956 2-storey classroom	2,375	Moderate/High	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8280004	KILDALA ELEMENTARY	2	1956 gymnasium	470	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
82	Coast Mountains	8280004	KILDALA ELEMENTARY	3	1965 2-storey classroom	1,625	Moderate/High	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8280004	KILDALA ELEMENTARY	4	1965 1-storey addition	866	Moderate	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8288020	KITI K'SHAN ELEMENTARY	1	1965 2-storey classroom	950	Moderate	Medium	Inactive		
82	Coast Mountains	8288020	KITI K'SHAN ELEMENTARY	2	1971 2-storey classroom	700	Moderate/High	Medium	Inactive		
82	Coast Mountains	8288020	KITI K'SHAN ELEMENTARY	3	1973 Gymnasium	570	Moderate/High	Medium	Inactive	Medium	
82	Coast Mountains	8288020	KITI K'SHAN ELEMENTARY	4	1991 1-storey classroom	400	Low/Moderate	Low	Inactive		
82	Coast Mountains	8288020	KITI K'SHAN ELEMENTARY	5	2001 1-storey classroom	?	Low	Low	Inactive		
82	Coast Mountains	8288030	KITWANGA ELEM-JR SEC	1	Kitwanga Primary	650	Low	Low	Meets Structural Life Safety Requirements		
82	Coast Mountains	8288030	KITWANGA ELEM-JR SEC	2	Secondary	1,900	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
82	Coast Mountains	8288030	KITWANGA ELEM-JR SEC	3	Gymnasium & Community Hall	1,000	Low/Moderate	Low	Meets Structural Life Safety Requirements		
82	Coast Mountains	8280002	MOUNT ELIZABETH SECONDARY	1	1955 2-storey classroom	2,580	Moderate/High	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8280002	MOUNT ELIZABETH SECONDARY	2	1966 2-storey classroom	1,620	High	Medium	Non Structural Upgrade Required	Medium	
82	Coast Mountains	8280002	MOUNT ELIZABETH SECONDARY	3	1956 gymnasium	930	High	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8280002	MOUNT ELIZABETH SECONDARY	4	1973 Gymnasium	630	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
82	Coast Mountains	8280002	MOUNT ELIZABETH SECONDARY	5	1979 Theatre	1,350	Low/Moderate	Low	Meets Structural Life Safety Requirements		
82	Coast Mountains	8280002	MOUNT ELIZABETH SECONDARY	6	1956 1-storey classroom	6,620	Moderate	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8280001	NECHAKO ELEMENTARY SCHOOL	1	1954 1-storey classroom	1,775	Moderate	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8280001	NECHAKO ELEMENTARY SCHOOL	2	1954 2-storey classroom	2,150	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
82	Coast Mountains	8280001	NECHAKO ELEMENTARY SCHOOL	3	1954 gymnasium	495	Moderate	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8288008	NEW HAZELTON ELEMENTARY	1	Gymnasium Block	395	Low	Low	Meets Structural Life Safety Requirements		
82	Coast Mountains	8288008	NEW HAZELTON ELEMENTARY	2	Classroom / Admin Block	1,050	Low	Low	Meets Structural Life Safety Requirements	Low	
82	Coast Mountains	8288025	PARKSIDE SECONDARY	1	1969 1-storey classroom	1,325	High	Medium	Inactive		
82	Coast Mountains	8288025	PARKSIDE SECONDARY	2	1969 gymnasium	465	Moderate/High	Medium	Inactive	Medium	
82	Coast Mountains	8288499	R.E.M. LEE THEATRE (CALEDONIA SR. SEC)	1	1973 Auditorium	1,140	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
82	Coast Mountains	8280005	ROY WILCOX ELEMENTARY	1	1957 2-storey classroom	2,540	Moderate	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8280005	ROY WILCOX ELEMENTARY	2	1957 Gymnasium	470	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
82	Coast Mountains	8288014	THORNHILL ELEMENTARY	1	1-storey classroom	2,800	Moderate	Medium	Non Structural Upgrade Required	Medium	
82	Coast Mountains	8288029	THORNHILL JR SECONDARY	1	1972 1-storey classroom	3,935	High	Medium	Inactive		
82	Coast Mountains	8288029	THORNHILL JR SECONDARY	2	1972 Gymnasium	845	High	Medium	Inactive	Medium	
82	Coast Mountains	8288022	THORNHILL PRIMARY	1	1967 1-storey classroom	1,810	Moderate	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8288022	THORNHILL PRIMARY	2	1974 1-storey classroom	820	Moderate	Medium	Non Structural Upgrade Required	Medium	
82	Coast Mountains	8288022	THORNHILL PRIMARY	3	1974 Gymnasium	420	Moderate	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8288012	UPLANDS ELEMENTARY	1	1957 1-storey classroom	1,680	Moderate	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8288012	UPLANDS ELEMENTARY	2	1970 1-storey classroom	380	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
82	Coast Mountains	8288012	UPLANDS ELEMENTARY	3	1959 Gymnasium	425	Moderate	Medium	Non Structural Upgrade Required		
82	Coast Mountains	8288012	UPLANDS ELEMENTARY	4	1991 1-storey classroom	750	Low	Low	Meets Structural Life Safety Requirements		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
84	Vancouver Island West	8484022	CAPTAIN MEARES ELEM-SEC	1	Sec. Classrooms/Shops/Administration	1,852	Moderate/High	Medium	Non Structural Upgrade Required		
84	Vancouver Island West	8484022	CAPTAIN MEARES ELEM-SEC	2	Elem. Classrooms/Kindergarten	840	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
84	Vancouver Island West	8484022	CAPTAIN MEARES ELEM-SEC	3	Gymnasium/Library/Music	1,138	High	Medium	Non Structural Upgrade Required		
84	Vancouver Island West	8484012	GOLD RIVER SECONDARY	1	Classrooms/Shops	2,708	Moderate/High	N/A	Completed	N/A	
84	Vancouver Island West	8484012	GOLD RIVER SECONDARY	2	Gymnasium	1,107	Moderate/High	N/A	Completed		
84	Vancouver Island West	8484041	KYUQUOT ELEM-SEC	1	Classrooms/Admin.	496	Low	Low	Meets Structural Life Safety Requirements		
84	Vancouver Island West	8484041	KYUQUOT ELEM-SEC	2	Gymnasium	160	Low	Low	Meets Structural Life Safety Requirements	Medium	
84	Vancouver Island West	8484041	KYUQUOT ELEM-SEC	3	Portables	360	Moderate/High	Medium	Non Structural Upgrade Required		
84	Vancouver Island West	8484011	RAY WATKINS ELEMENTARY	1	Gymnasium	600	High	Medium	Non Structural Upgrade Required	Medium	
84	Vancouver Island West	8484011	RAY WATKINS ELEMENTARY	2	Classroom/Administration	?	Low	Low	Meets Structural Life Safety Requirements		
84	Vancouver Island West	8484031	ZEBALLOS ELEM-SEC	1	Classrooms/Admin	503	Low	N/A	Completed		Completed Fall 2012
84	Vancouver Island West	8484031	ZEBALLOS ELEM-SEC	2	Gymnasium/Art Room	272	Low	N/A	Completed	N/A	
84	Vancouver Island West	8484031	ZEBALLOS ELEM-SEC	3	Portables	180	Moderate/High	N/A	Completed		
85	Vancouver Island North	8585001	A J ELLIOTT ELEMENTARY	1	Central Classrooms	690	Low/Moderate	Low	Meets Structural Life Safety Requirements		
85	Vancouver Island North	8585001	A J ELLIOTT ELEMENTARY	2	North Addition	270	Low/Moderate	Low	Meets Structural Life Safety Requirements	Low	
85	Vancouver Island North	8585001	A J ELLIOTT ELEMENTARY	3	Gymnasium	515	Low/Moderate	Low	Meets Structural Life Safety Requirements		
85	Vancouver Island North	8585008	ALERT BAY ELEMENTARY	1	Gymnasium	510	Moderate	Medium	Non Structural Upgrade Required		
85	Vancouver Island North	8585008	ALERT BAY ELEMENTARY	2	North Classrooms	1,090	Moderate	Medium	Non Structural Upgrade Required		
85	Vancouver Island North	8585008	ALERT BAY ELEMENTARY	3	South Classrooms	1,710	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
85	Vancouver Island North	8585008	ALERT BAY ELEMENTARY	4	Primary Classrooms	990	High	Medium	Non Structural Upgrade Required		
85	Vancouver Island North	8585008	ALERT BAY ELEMENTARY	5	Primary Gymnasium	256	High	Medium	Non Structural Upgrade Required		
85	Vancouver Island North	8585029	CHESLAKEES ELEMENTARY	1	GYMNASIUM	486	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
85	Vancouver Island North	8585029	CHESLAKEES ELEMENTARY	2	CLASSROOM	1,180	Low/Moderate	Low	Meets Structural Life Safety Requirements		
85	Vancouver Island North	8585003	COAL HARBOUR ELEMENTARY	1	Classrooms	1,044	Moderate/High	Medium	Non Structural Upgrade Required		
85	Vancouver Island North	8585003	COAL HARBOUR ELEMENTARY	2	Gymnasium	312	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
85	Vancouver Island North	8585003	COAL HARBOUR ELEMENTARY	3	Link	32	High	Medium	Non Structural Upgrade Required		
85	Vancouver Island North	8585023	EAGLE VIEW ELEMENTARY	1	MAIN BUILDING - EAST CLASSROOM	2,183	High	N/A	Completed	N/A	
85	Vancouver Island North	8585023	EAGLE VIEW ELEMENTARY	2	GYMNASIUM/ACTIVITY ROOM	588	Low	N/A	Completed		
85	Vancouver Island North	8585023	EAGLE VIEW ELEMENTARY	3	WEST CLASSROOMS	626	Low	N/A	Completed		
85	Vancouver Island North	8585015	ECHO BAY ELEMENTARY	1	School and Teacherage	147	Moderate/High	Medium	Inactive	Medium	
85	Vancouver Island North	8585017	FORT RUPERT ELEMENTARY	1	East Classrooms	676	Moderate	Medium	Non Structural Upgrade Required		
85	Vancouver Island North	8585017	FORT RUPERT ELEMENTARY	2	West Classrooms	475	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
85	Vancouver Island North	8585017	FORT RUPERT ELEMENTARY	3	Gymnasium	565	High	Medium	Non Structural Upgrade Required		
85	Vancouver Island North	8585018	NORTH ISLAND SECONDARY	1	MUSIC/DRAMA	490	Low	Low	Meets Structural Life Safety Requirements		
85	Vancouver Island North	8585018	NORTH ISLAND SECONDARY	2	GYMNASIUM CHANGE ROOMS	490	Moderate/High	Medium	Non Structural Upgrade Required		
85	Vancouver Island North	8585018	NORTH ISLAND SECONDARY	3	GYMNASIUM	1,343	Low	Low	Meets Structural Life Safety Requirements	Medium	
85	Vancouver Island North	8585018	NORTH ISLAND SECONDARY	4	SHOPS	598	Low	Low	Meets Structural Life Safety Requirements		
85	Vancouver Island North	8585018	NORTH ISLAND SECONDARY	5	SOUTH CLASSROOMS	?	Low	Low	Meets Structural Life Safety Requirements		
85	Vancouver Island North	8585018	NORTH ISLAND SECONDARY	6	WEST CLASSROOMS	?	Low/Moderate	Low	Meets Structural Life Safety Requirements		
85	Vancouver Island North	8585018	NORTH ISLAND SECONDARY	7	EAST CLASSROOMS	?	Low/Moderate	Low	Meets Structural Life Safety Requirements		
85	Vancouver Island North	8585026	PORT HARDY SECONDARY	1	SHOPS/CLASSROOMS	3,840	Low	Low	Meets Structural Life Safety Requirements		
85	Vancouver Island North	8585026	PORT HARDY SECONDARY	2	GYMNASIUM	1,098	Low	Low	Meets Structural Life Safety Requirements		
85	Vancouver Island North	8585026	PORT HARDY SECONDARY	3	SE. CLASSROOM ADD.	505	Low	Low	Meets Structural Life Safety Requirements		
85	Vancouver Island North	8585026	PORT HARDY SECONDARY	4	SW. MPR + DRAMA	596	Low	Low	Meets Structural Life Safety Requirements	Low	
85	Vancouver Island North	8585026	PORT HARDY SECONDARY	5	ART ROOM ADD.	174	Low	Low	Meets Structural Life Safety Requirements		
85	Vancouver Island North	8585026	PORT HARDY SECONDARY	6	NW CLASSROOM ADD.	240	Low	Low	Meets Structural Life Safety Requirements		
85	Vancouver Island North	8585002	QUATSINO ELEMENTARY	1	Main Building	372	Low	Low	Meets Structural Life Safety Requirements	Low	
85	Vancouver Island North	8585011	ROBERT SCOTT ELEMENTARY	1	GYMNASIUM	580	High	Medium	Inactive		
85	Vancouver Island North	8585011	ROBERT SCOTT ELEMENTARY	2	CLASSROOMS	2,829	Moderate/High	Medium	Inactive	Medium	
85	Vancouver Island North	8585020	SEA VIEW ELEM-JR SEC	1	Intermediate Classrooms	704	Low/Moderate	Low	Meets Structural Life Safety Requirements		
85	Vancouver Island North	8585020	SEA VIEW ELEM-JR SEC	2	Covered Walkways	277	Moderate	Medium	Non Structural Upgrade Required		
85	Vancouver Island North	8585020	SEA VIEW ELEM-JR SEC	3	Gymnasium	267	Low/Moderate	Low	Meets Structural Life Safety Requirements		
85	Vancouver Island North	8585020	SEA VIEW ELEM-JR SEC	4	Covered Play Area	89	High	Medium	Non Structural Upgrade Required	Medium	
85	Vancouver Island North	8585020	SEA VIEW ELEM-JR SEC	5	Primary Building	885	High	Medium	Non Structural Upgrade Required		
85	Vancouver Island North	8585020	SEA VIEW ELEM-JR SEC	6	Jr. Secondary Classrooms	778	High	Medium	Non Structural Upgrade Required		
85	Vancouver Island North	8585020	SEA VIEW ELEM-JR SEC	7	Shop	260	High	Medium	Non Structural Upgrade Required		
85	Vancouver Island North	8585028	SUNSET ELEMENTARY	1	GYMNASIUM	1,004	Moderate/High	Medium	Non Structural Upgrade Required		
85	Vancouver Island North	8585028	SUNSET ELEMENTARY	2	CENTRAL CLASSROOM BLOCK	1,520	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
85	Vancouver Island North	8585028	SUNSET ELEMENTARY	3	NORTH CLASSROOM BLOCK	678	Moderate	Medium	Non Structural Upgrade Required		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (updated October 2013)

SD	SD Name	Facility #	Facility Name	Block #	Block Name	Area (m ²)	2004 Risk	Current Risk	Status	School Risk	Comments
85	Vancouver Island North	8585016	WOSS LAKE ELEMENTARY	1	Gymnasium	396	Moderate	Medium	Non Structural Upgrade Required	Medium	
85	Vancouver Island North	8585016	WOSS LAKE ELEMENTARY	2	West Classrooms	271	Low/Moderate	Low	Meets Structural Life Safety Requirements		
85	Vancouver Island North	8585016	WOSS LAKE ELEMENTARY	3	East Classrooms	648	Moderate	Medium	Non Structural Upgrade Required		
85	Vancouver Island North	8585016	WOSS LAKE ELEMENTARY	4	Link	220	Low/Moderate	Low	Meets Structural Life Safety Requirements		
85	Vancouver Island North	8585016	WOSS LAKE ELEMENTARY	5	Covered Play Area	160	High	Medium	Non Structural Upgrade Required		
85	Vancouver Island North	8585016	WOSS LAKE ELEMENTARY	6	West Classroom Addition	73	Low/Moderate	Low	Meets Structural Life Safety Requirements		
87	Stikine	8787010	ATLIN SCHOOL	1	1981 Single-Storey Classroom	1,150	Moderate	Medium	Non Structural Upgrade Required	Medium	
87	Stikine	8787010	ATLIN SCHOOL	2	1981 Gymnasium	368	Low	Low	Meets Structural Life Safety Requirements		
87	Stikine	8787011	DEASE LAKE SCHOOL	1	Classroom/ Admin Block	1,110	Low	Low	Meets Structural Life Safety Requirements	Low	
87	Stikine	8787011	DEASE LAKE SCHOOL	2	Gymnasium	472	Low/Moderate	Low	Meets Structural Life Safety Requirements		
87	Stikine	8787011	DEASE LAKE SCHOOL	3	1991 Addition	466	Low	Low	Meets Structural Life Safety Requirements		
87	Stikine	8787003	TAHLTAN SCHOOL	1	Classroom/ Admin Block	1,060	Low	Low	Meets Structural Life Safety Requirements	Low	
87	Stikine	8787003	TAHLTAN SCHOOL	2	Gymnasium	566	Low/Moderate	Low	Meets Structural Life Safety Requirements		
92	Nisga'a	9292009	LAKALZAP ELEMENTARY	1	Gymnasium	190	Low	Low	Meets Structural Life Safety Requirements	Low	
92	Nisga'a	9292009	LAKALZAP ELEMENTARY	2	Classrooms	1,020	Low	Low	Meets Structural Life Safety Requirements		
92	Nisga'a	9292008	NATHAN BARTON ELEMENTARY	1	Gymnasium	287	Low	Low	Meets Structural Life Safety Requirements	Low	
92	Nisga'a	9292008	NATHAN BARTON ELEMENTARY	2	Classrooms	670	Low	Low	Meets Structural Life Safety Requirements		
92	Nisga'a	9292007	NISGA'A ELEM/SECONDARY	1	Gymnasium	1,245	Low/Moderate	Low	Meets Structural Life Safety Requirements	Medium	
92	Nisga'a	9292007	NISGA'A ELEM/SECONDARY	2	Primary Classroom	410	Low	Low	Meets Structural Life Safety Requirements		
92	Nisga'a	9292007	NISGA'A ELEM/SECONDARY	3	Classroom	3,450	Moderate	Medium	Non Structural Upgrade Required		
93	Conseil Scolaire Francophone	9339111	ECOLE ANNE HEBERT	1	(1964) ORIGINAL	1,313	Moderate/High	High 3	Structural Upgrade Required	High 3	
93	Conseil Scolaire Francophone	9339111	ECOLE ANNE HEBERT	2	(1989) EXTENSION	1,491	Low/Moderate	Low	Meets Structural Life Safety Requirements		
93	Conseil Scolaire Francophone	9337031	ECOLE DE BOIS-JOLI	1	Gymnasium	400	Moderate/High	Medium	Non Structural Upgrade Required	Medium	
93	Conseil Scolaire Francophone	9337031	ECOLE DE BOIS-JOLI	2	Classrooms	1,900	Moderate/High	Medium	Non Structural Upgrade Required		
93	Conseil Scolaire Francophone	9347006	ECOLE COTE DU SOLIEL	1	Gymnasium	490	NA	High 3	Supported 2013	High 1	November 2012 - All blocks assessed. Overall school risk is H1. April 2013 - to start 2014.
93	Conseil Scolaire Francophone	9347006	ECOLE COTE DU SOLIEL	2	1 storey classroom	1,090	NA	High 3	Supported 2013		
93	Conseil Scolaire Francophone	9347006	ECOLE COTE DU SOLIEL	3	2 storey classroom	830	NA	Medium	Supported 2013		
93	Conseil Scolaire Francophone	9347006	ECOLE COTE DU SOLIEL	4	Activity Room/Band	160	NA	Low	Supported 2013		
93	Conseil Scolaire Francophone	9347007	ECOLE COTE DU SOLIEL	5	1 storey masonry	700	NA	High 1	Supported 2013		
93	Conseil Scolaire Francophone	9347008	ECOLE COTE DU SOLIEL	6	1 storey former shops	340	NA	Low	Supported 2013		
93	Conseil Scolaire Francophone	9375920	ECOLE DES DEUX RIVES	1	Gymnasium	250	Low	Low	Meets Structural Life Safety Requirements	Low	
93	Conseil Scolaire Francophone	9375920	ECOLE DES DEUX RIVES	2	Classroom (North)	846	Low/Moderate	Low	Meets Structural Life Safety Requirements		
93	Conseil Scolaire Francophone	9375920	ECOLE DES DEUX RIVES	3	Classroom (South)	455	Low/Moderate	Low	Meets Structural Life Safety Requirements		
93	Conseil Scolaire Francophone	9343092	ECOLE DES PIONNIERS	1	2-Storey Classrooms	4,500	High	High 1	Proceeding to Construction	High 1	December 2012 - SPIRs completed. Block 3 increased from H3 to H1
93	Conseil Scolaire Francophone	9343092	ECOLE DES PIONNIERS	2	Gymnasium	950	Moderate/High	Low	Proceeding to Construction		
93	Conseil Scolaire Francophone	9343092	ECOLE DES PIONNIERS	3	Shops Wing	1,380	Moderate/High	High 3	Proceeding to Construction		
93	Conseil Scolaire Francophone	9343092	ECOLE DES PIONNIERS	4	East Wing	2,960	Moderate	Medium	Proceeding to Construction		
93	Conseil Scolaire Francophone	6868067	ECOLE OCEAN (Princess Anne Elementary)	1	Gymnasium	224	High	Medium	Non Structural Upgrade Required	Medium	
93	Conseil Scolaire Francophone	6868067	ECOLE OCEAN (Princess Anne Elementary)	2	Classrooms	1,334	Moderate	Medium	Non Structural Upgrade Required		
93	Conseil Scolaire Francophone	9339092	ECOLE ROSE-DES-VENTS	1	Classroom - West	580	Moderate/High	N/A	Completed	N/A	
93	Conseil Scolaire Francophone	9339092	ECOLE ROSE-DES-VENTS	2	Classroom - North/West	350	Moderate/High	N/A	Completed		
93	Conseil Scolaire Francophone	9339092	ECOLE ROSE-DES-VENTS	3	Classroom - East	475	Moderate/High	N/A	Completed		
93	Conseil Scolaire Francophone	9339092	ECOLE ROSE-DES-VENTS	4	Gymnasium	150	Moderate	N/A	Completed		
93	Conseil Scolaire Francophone	9339092	ECOLE ROSE-DES-VENTS	5	Classroom - North/East	350	Moderate	N/A	Completed		
93	Conseil Scolaire Francophone	9333002	LA VERENDRYE ELEMENTARY	1	Classroom	600	Moderate	Medium	Non Structural Upgrade Required	Medium	
93	Conseil Scolaire Francophone	9333002	LA VERENDRYE ELEMENTARY	2	Portables	?	Low	Low	Meets Structural Life Safety Requirements		
93	Conseil Scolaire Francophone	9335028	LES VOYAGEURS	1	Gymnasium	255	Moderate	Medium	Non Structural Upgrade Required	Medium	
93	Conseil Scolaire Francophone	9335028	LES VOYAGEURS	2	Classrooms	730	Moderate/High	Medium	Non Structural Upgrade Required		